

COMFORTDELGRO ENGINEERING PTE LTD

VEHICLE NO : SHA 4017B

MAKE :

MODEL : HYUNDAI SONATA

CARMA

DATE 24/7/2018 10:33

the Repairer of the following:

• To resurvey the car after spray painting

• To display damaged part(s) during resurvey

• Parts to be repaired subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper / <i>TV</i>			\$ 578.40
	Rear Bumper Clip / <i>MC</i>			\$ 22.00
	Rear Fender (LH) <i>X repair.</i>			\$ 1,935.90
	Rear Fender Inner Lining (LH) / <i>GA</i>			\$ 74.10
	Rear Windscreen Moulding <i>X NN</i>			\$ 60.00
	Rear Door (LH) / <i>GB</i>			\$ 1,294.70
	Front Door (LH) / <i>GB</i>			\$ 1,344.50
	Front Door Mirror (LH) / <i>PS</i>			\$ 545.50
	Frt & Rear Tyre Rim (LH) <i>X NN</i>		\$ 284.70	\$ 569.40
	Frt & Rear Wheel Hup-Cap (LH) /		\$ 145.00	\$ 290.00
	Front Fender (LH) / <i>Bul</i>			\$ 593.10
	Front Fender Shield (LH) / <i>el</i>			\$ 86.00
	Front Bumper Cover / <i>el</i>			\$ 538.80
	Front Bumper Bracket Top (LH) / <i>MC</i>			\$ 22.40
	Headlamp (LH) / <i>SCR</i>			\$ 797.90
	SUB TOTAL			\$ 8,752.70
	LESS 20%			\$ 1,750.54
	DISCOUNTED TOTAL			\$ 7,002.16
	Rear Bumper Rubber Mat / <i>MC</i>			\$ 50.00 Nett
	Rear Fender Advertisement Logo (LH) / <i>MC</i>			\$ 100.00 Nett
	Rear Windscreen Sealant <i>X NN</i>			\$ 46.00 Nett
	Rear Door Tel No. Sticker (LH) /			\$ 10.00 Nett
	Front Door Coloured Comfort Logo (LH) / <i>ave</i>			\$ 75.00 Nett
	Front Door Advertisement Logo (LH) /			\$ 100.00 Nett
	Front Fender Advertisement Logo(LH) /			\$ 100.00 Nett
				\$ 481.00
	Labour Charge			
	Panel Beating			\$ 1,200.00 <i>600</i>
	Spray Painting Charge			\$ 1,200.00 <i>1100</i>
	Wiring Charge			\$ 50.00 <i>30</i>
	Tuff Kote			\$ 50.00 <i>1</i>
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 <i>60</i>
	Remove/Refix Rear Windscreen Glass			\$ 120.00 <i>X NN</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>40</i>
	Transfer of Door		\$ 120.00	\$ 240.00 <i>120</i>
	Four Wheel Alignment			\$ 120.00 <i>60</i>
	TOTAL LABOUR			\$ 3,250.00
	ESTIMATE TOTAL			\$ 10,733.16

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.