
















































PAR Automotive Consultancy

Regn. No. 92980974

Thomson Rd Post Office PO Box 029 Singapore 915701 Tel: 645 31173 Fax: 645 36131

Report No: 0375-16-TCA

05 September 2016

ACCIDENT VEHICLE SURVEY REPORT

Plus Car Rental & Trading
4 Petain Road Petain Court
Singapore 208086

VEHICLE INFORMATION:

<i>Vehicle Reg No.</i>	SGL7588D	<i>Odometer:</i>	177692km
<i>Make & Model:</i>	Toyota Corolla Altis 1.6A	<i>Colour:</i>	Silver
<i>Chassis number:</i>	MR053ZEC107129730	<i>Date of accident:</i>	30/03/2016
<i>Year of Regn.:</i>	27/09/2006	<i>Date inspected:</i>	31/03/2016
<i>Repairer at:</i>	Twincar Automotive Pte Ltd Blk 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921		

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.



