

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 6675Y

DATE 26/7/2018 10:22

MAKE :

MODEL : MERCEDES BENZ

Ally

Chong

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 1,510.00
	Rear Bumper Reinforcement ?			\$ 1,150.00
	Rear Bumper Bracket Lower (LH/RH) ?		\$ 135.00	\$ 270.00
	Rear Bumper Bracket Top (LH/RH) ?		\$ 125.00	\$ 250.00
	Rear Bumper Retainer Mounting (LH/RH) ?		\$ 115.00	\$ 230.00
	Rear Bumper Covering ?			\$ 55.00
	Rear Panel End X			\$ 1,380.00
	Rear Panel Inner Garnish X			\$ 240.00
	Rear Panel Inner Garnish Clip (10pcs) X			\$ 40.00
	<i>Boat lid ✓</i>			
	SUB TOTAL			\$ 5,125.00
	LESS 20%			\$ 1,025.00
	DISCOUNTED TOTAL			\$ 4,100.00
	Rear Bumper Sensor ✓			\$ 388.00
	Rear Bumper Rubber Mat ✓			\$ 50.00
				\$ 438.00
	Labour Charge			
	Panel Beating			\$ 300
	Spray Painting Charge			\$ 400.00
	Wiring Charge			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
				\$ 820.00
	TOTAL LABOUR			\$ 820.00
	ESTIMATE TOTAL			\$ 5,358.00
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company

TOTAL LABOUR

Acknowledged by Repairer

Signature:

ESTIMATE TOTAL

Ka hui 1 CLK
26/7/18 11:35hrs.
3 Days
P/P
Before Paint photo.

300
~~*400.00*~~
~~*50.00*~~
~~*120.00*~~
300