

INSURANCE

INS. CASE OWNER:

SAHHA

CCP/AIG1801

7681, G 7683

LKK  
IDAC

Surveyor:

XGL

DOE:

ASSIGNMENT

14/3/18

Date / Time:

14/3/18

Registered in Merimen:

14/3/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SUM 7409A

Name of Insured:

POH LEE YONG

Insured Tel No.:

HP:

90094554

Excess Sec II :SS

D.O.A.:

26/3/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

Claim No.:

017194772666

Policy No.:

200505426

Make / Model:

KEA

Place of Accident:

LEE

OI GIA REPORT: YES NO : TP GIA REPORT: YES NO

Insured Liability:

Final ? Yes / No

SJL 8606T



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

GURT



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/Time

11/3/18

TIN

SJL 8606T-X

SUM 7409A-X

OI VIDEO UNLOCKED BY HIS IN KITCHEN

OI rear-ended to TP, send Email to OI.

MINUTED.

TP LOD IN BY EMAIL

20/02/19  
21/02/19

SEND 1ST OFFER TO TP  
TP ACCEPTED OFFER.  
ALL LOSS IN ORDER.  
TO CLOSE.

STAGE	DATE / PIC
Non-Reporting 1st (1st)	
Non-Reporting 1st (2nd)	
Non-Reporting 1st (Final)	
Notification 1st (if non-pickup)	
Call OI:	
After call 1st to OI:	
Documentation Check List: Handler	Typist
Notification 1st (if non-pickup)	
After call 1st to OI:	
Authorisation To Act	
Release Voucher	
Final Repair Bill	
Car Rental Invoice	
Towing Invoice	
OTA/GIA	
Medical Bill	
PIR	
Mandate/Reject Instruction	
LOD	
Payment Breakdown Form	
Post-Repair Photos	
Others	

<b>PRELIMINARY ADVICE</b> Date/Time:		Sent By:		Confirm by:	
<b>FINALIZATION</b> Date/Time:		Confirm with:		Email <input type="checkbox"/> Call <input type="checkbox"/>	
Repair Cost:	US \$2,000.00	4	days	Reduction:	83 %
<b>FINAL SETTLEMENT</b> Date/Time:		Confirm with:		Email <input type="checkbox"/> Call <input type="checkbox"/>	
Final Liability:	%	100 (Agreed / Assessed) BCIA S/N No. : 27			
Repair Cost: (w/60%)	SS \$2,140.00				
Loss of Rental (LOR):	SS -	( )	days		
Loss of Use (LOU):	SS \$500.00	5	x 35	days	
Loss of Income (LOI):	SS -	( )	x	days	
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/> LOR + LOI <input type="checkbox"/> LOR + LO <input type="checkbox"/>	[Tick only one]				
GIA/TA Search	SS \$7.49				
Medical:	SS -				
Disbursement:	SS -	(e.g. Tow/ Independent)			
Legal Cost	SS -				
Total:	SS \$2,147.49	Global Sum SS:	-		
<b>FINAL PAYMENT</b> Date/Time:		Confirm with:		Email <input type="checkbox"/> Call <input type="checkbox"/>	
Payee 1:	SS \$2,147.49	Name 1:	GURT AUTOMOTIVE SERVICES PTE LTD		
Payee 2: (Strike if N/A)	SS -	Name 2:	-		
Payee 3: (Strike if N/A)	SS -	Name 3:	-		

COPY SENT

URGENT

1) Claim status: Normal/Reject/Private Settle  
2) Report Format:  
3) Survey fee: \$520.00

SUNAMIT

Xhel.

REF:

AG.

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: 20 \$ 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SIL 8606 T

Yr Reg:

21 Jun 2016

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Elantra

1.6

1591

Colour:

Black

A/C

Insured / Std / NI / NA

Sp. Reading:

34589

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMH D 841 CM HU/92771

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

NEXEN

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

D.O.I.

Survey held at

W/S

27-07-18

4pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Finalized \$2000 with ~~Esther~~ Esther.  
(Rev: \$9,974.04 / 83%)

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + RS \$

) Permit

) Other

)

TOTAL

Report Format :

Lump Sum / L.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC4/AIG18013681/Gub3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 27-07-2018



Code : AIG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLM 3409A	Veh. Inspected	SJL 8606T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	27/07/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	26/07/2018	Inspection Date	27/07/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

# Part 4 - Spare Parts / Material Usage

To be completed by Service Advisor, ARC

Item	Parts Description	Qty	Cost Price (\$)	PARTS DISCOUNT	Final Price (\$)	Repair (R) Replace (/)
1	REAR BOOT X Repair	1	\$ 1,167.80	20%	\$ 950.24	
2	REAR BOOT INNER TRIM X	1	\$ 245.30	20%	\$ 196.24	
3	REAR BOOT REFLECTOR X	2	\$ 786.40	20%	\$ 629.12	
4	REAR BOOT WEATHERSTRIP X	1	\$ 203.40	20%	\$ 162.72	
5	REAR BOOT LOCK X	1	\$ 189.30	20%	\$ 151.44	
6	TAILAMPS X	2	\$ 1,050.60	20%	\$ 840.48	
7	TAILAMP PANEL LH X	1	\$ 48.00	20%	\$ 38.40	
8	REAR END PANEL X Repair	1	\$ 582.90	20%	\$ 466.32	
9	END PANEL TOP GARNISH X NN	1	\$ 135.80	20%	\$ 108.64	
10	REAR BUMPER / Mis	1	\$ 558.70	20%	\$ 446.96	/
11	REAR BUMPER REINFORCEMENT / OT	1	\$ 306.80	20%	\$ 245.44	/
12	REAR BUMPER REINFORCEMENT BRACKETS X NN	2	\$ 188.60	20%	\$ 150.88	
13	REAR BUMPER RETAINERS / AC	2	\$ 96.20	20%	\$ 76.96	/
14	REAR FENDER INNER COWLING X NN	2	\$ 188.60	20%	\$ 150.88	
15	REAR BUMPER LOWER COVER X NN	1	\$ 272.60	20%	\$ 218.08	
16	REAR BUMPER RELECTORS / Mis	2	\$ 96.80	20%	\$ 77.44	/
17	REAR FENDER X NN	2	\$ 1,320.80	20%	\$ 1,056.64	
18	REAR FENDER AIR DUCT X NN	2	\$ 66.40	20%	\$ 53.12	
19	REAR SILENCER BOX X	1	\$ 499.60	20%	\$ 399.68	
20	REAR EXHAUST INSULATOR SHIELD X NN	1	\$ 106.30	20%	\$ 85.04	
21	REAR EXHAUST MOUNTING X NN	1	\$ 33.60	20%	\$ 26.88	
22	REAR EXHAUST TIP X	1	\$ 108.20	20%	\$ 84.96	
23	REAR EXHAUST HANGER X	1	\$ 38.10	20%	\$ 30.48	

Special Nett Items	Parts Description	Qty				
	FRONT NUMPER PLATE WITH CASING X NN	1 SET	\$ 50.00		\$ 50.00	
	REAR BUMPER CLIPS / AC	1 SET	\$ 30.00		\$ 30.00	/
	REAR FENDER COWLING CLIPS X	2 SETS	\$ 60.00		\$ 60.00	
	REAR FENDER INNER TRIM CLIPS X	1 SET	\$ 30.00		\$ 30.00	
	REAR BUMPER LOWER COVER CLIPS X	1 SET	\$ 30.00		\$ 30.00	
	REAR END PANEL TOP GARNISH CLIPS X	1 SET	\$ 30.00		\$ 30.00	
	REAR BOOT STOPPER X	2	\$ 60.00		\$ 60.00	
	END PANEL TOP GARNISH CLIPS X	1 SET	\$ 30.00		\$ 30.00	
	REAR BOOT INNER TRIM CLIPS X	1 SET	\$ 30.00		\$ 30.00	
	REVERSE SENSORS / Mis	1 SET	\$ 250.00		\$ 250.00	/ 200
	REAR BOOT HYUNDAI LOGO	1	\$ 55.00		\$ 55.00	/
	REAR BOOT "ELANTRA" EMBLEM / AC	1	\$ 55.00		\$ 55.00	/
	REAR BOOT "GLS" EMBLEM /	1	\$ 40.00		\$ 40.00	/
TOTAL MATERIALS			\$ 9,058.80		\$ 7,397.04	

Surveyor Remark:

## Part 1 - Labour Works

Job Scope	Quotation from ARC	
To renew damaged parts, replace and realign end panel, and aligned all parts	\$ 1,600.00	<del>200</del> 400
Total Labour Cost	\$ 1,600.00	\$ <del>600</del>

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	
To respray affected areas	\$ 1,600.00	600
Spray Painting	\$ 1,600.00	

## Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	
Towing	\$ 80.00	28
Windscreen sealant	\$ 100.00	X
To tuffcoat affect areas	\$ 150.00	X } NW
To renew front/ windscreen glass		
To renew engine mountings and gear box mounting		
To remove /refit aircon condensor, pipings, vacuum and recharge aircon gas		
To remove/refit replace dashboard		
To remove and refit interior upholstery	\$ 120.00	60
To remove and replace steering column		
To remove /refit wiring check	\$ 80.00	20
To remove/refit rear windscreen for rear fender replacement	\$ 150.00	X
To remove/replace exhaust silencer box and straighten centre pipe	\$ 300.00	X } NW
To remove/replace reverse sensors and distance settling	\$ 150.00	40
To remove and transfer rear boot mechanism	\$ 150.00	X
To re-programing all necessary system	\$ 100.00	X } NW
Total Other Costs	\$ 1,380.00	

~~200~~ 8 2663.84 <sup>1/30</sup>  
 2000 2000

### REQUEST FOR SUPPLEMENTS PARTS

Accident Case Number		Date of Collection	/ /
Vehicle No	SJL8606T	Date of Request	01.08.2018
Vehicle Model	HYUNDAI ELANTRA	Number of Days to Extend (If any)	

S/N	Part Number	Part Description	Quantity	LIST PRICE
1		REAR BUMPER LOWER GARNISH /	1	\$321.30
		mis		20%:
				257.04

<<< Please submit photographs for damaged parts >>>- (MISSING)

I, (Name) \_\_\_\_\_

(Position) \_\_\_\_\_

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the said vehicle.

\_\_\_\_\_  
Signature of person making this declaration  
(to be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC/ Reservation / Number
Photo Submitted	YES / NO	Date of submission

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1513A
Vehicle Details	
Vehicle No.:	SJL8606T
Vehicle to be Exported:	No
Intended De-registration Date:	30 Jul 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA AD 1.6 GLS AT
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	G4FGGU186901
Chassis No.:	KMHD841CMHU192771
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$13,071.00
Original Registration Date:	21 Jun 2016
First Registration Date:	21 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$13,071.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Jun 2026
PARF Rebate Amount:	\$9,803.00
Intended COE Rebate Details	
COE Expiry Date:	20 Jun 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,694.00
COE Rebate Amount:	\$42,373.00
<b>Total Rebate Amount:</b>	<b>\$52,176.00</b>

The information contained herein is correct as at 30 Jul 2018

OK



## SMRT Vehicle Repair Estimate

Group : Buses / Taxis / Private Car

Reg. No. : SJL8606T

Ref. No. \_\_\_\_\_

Make / Model : HYUNDAI ELANTRA

Reg. Date : 21.05.2016

Chassis No : KMHD841CMHU192771

Mileage \_\_\_\_\_

Name of Driver : ABNER KOH MINGFENG

Rental/Replacement Vehicle : Yes/No

Date/Time of Accident 26.07.2016

Surveyor is Required ? **YES** / NO

If Yes, VICOM / LKK / AIS / Other MSIG : \_\_\_\_\_

Vehicle is Towed Back **YES** / NO Date / Time : \_\_\_\_\_

Accident reporting date 26.07.2016

Type of Accident : Skid / Head-Rear / Head-On / Side Swipe / Others

Special Instruction to ARC, if any :

TP CLAIM AIG

The damages on the vehicle are as indicated in the following diagram :



Signed : \_\_\_\_\_

Date : \_\_\_\_\_

Accident Repair Job Card : \_\_\_\_\_

Date Prepared : \_\_\_\_\_

Summary of Repair Estimates

Repair Completed : \_\_\_\_\_

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labour Charge : \$ 1,600.00

\$ -

Total Spray Painting Charge \$ 1,600.00

\$ -

Total Material Charge : \$ 7,397.04

\$ -

Other Charges : \$ 1,380.00

\$ -

**TOTAL** : \$ 11,977.04

\$ -

Lump Sum Repair, if any : \_\_\_\_\_

No. of Repair Days : [ 8 ] days

( ) days

Signature : \_\_\_\_\_

Prepared by: \_\_\_\_\_

Adjusted by: \_\_\_\_\_

QN No. \_\_\_\_\_ Invoice No. \_\_\_\_\_

Signed : \_\_\_\_\_

Date : \_\_\_\_\_



**Part 1 - Labour Works**

Job Scope	Quotation from ARC	
To renew damaged parts, replace and realign end panel, and aligned all parts	\$	1,600.00
<b>Total Labour Cost</b>	\$	1,600.00

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	
To respray affected areas	\$	1,600.00
<b>Spray Painting</b>	\$	1,600.00

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Page ( 3

Job Scope	Quotation from ARC	
Towing	\$	80.00
Windscreen sealant	\$	100.00
To tuffcoat affect areas	\$	150.00
To renew front/ windscreen glass		
To renew engine mountings and gear box mounting		
To remove /refit aircon condensor, pipings, vacuum and recharge aircon gas		
To remove/refit replace dashboard		
To remove and refit interior upholstery	\$	120.00
To remove and replace steering column		
To remover /refit wiring check	\$	80.00
To remove/refit rear windscreen for rear fender replacement	\$	150.00
To remove/replace exhaust silencer box and straighten centre pipe	\$	300.00
To remove/replace reverse sensors and distance settling	\$	150.00
To remove and transfer rear boot mechanism	\$	150.00
To re-programing all necessary system	\$	100.00
<b>Total Other Costs</b>	\$	1,380.00

**Part 4 - Spare Parts / Material Usage**

To be completed by Service Advisor, ARC						
Item	Parts Description	Qty	Cost Price (\$)	PARTS DISCOUNT	Final Price (\$)	Repair (R) Replace ( / )
1	REAR BOOT	1	\$ 1,187.80	20%	\$ 950.24	
2	REAR BOOT INNER TRIM	1	\$ 245.30	20%	\$ 196.24	
3	REAR BOOT REFLECTOR	2	\$ 788.40	20%	\$ 629.12	
4	REAR BOOT WEATHERSTRIP	1	\$ 203.40	20%	\$ 162.72	
5	REAR BOOT LOCK	1	\$ 189.30	20%	\$ 151.44	
6	TAILAMPS	2	\$ 1,050.60	20%	\$ 840.48	
7	TAILAMP PANEL LH	1	\$ 48.00	20%	\$ 38.40	
8	REAR END PANEL	1	\$ 582.90	20%	\$ 466.32	
9	END PANEL TOP GARNISH	1	\$ 135.80	20%	\$ 108.64	
10	REAR BUMPER	1	\$ 558.70	20%	\$ 446.96	
11	REAR BUMPER REINFORCEMENT	1	\$ 306.80	20%	\$ 245.44	
12	REAR BUMPER REINFORCEMENT BRACKETS	2	\$ 188.60	20%	\$ 150.88	
13	REAR BUMPER RETAINERS	2	\$ 96.20	20%	\$ 76.96	
14	REAR FENDER INNER COWLING	2	\$ 188.60	20%	\$ 150.88	
15	REAR BUMPER LOWER COVER	1	\$ 272.60	20%	\$ 218.08	
16	REAR BUMPER RELECTORS	2	\$ 96.80	20%	\$ 77.44	
17	REAR FENDER	2	\$ 1,320.80	20%	\$ 1,056.64	
18	REAR FENDER AIR DUCT	2	\$ 66.40	20%	\$ 53.12	
19	REAR SILENCER BOX	1	\$ 499.60	20%	\$ 399.68	
20	REAR EXHAUST INSULATOR SHIELD	1	\$ 106.30	20%	\$ 85.04	
21	REAR EXHAUST MOUNTING	1	\$ 33.60	20%	\$ 26.88	
22	REAR EXHAUST TIP	1	\$ 106.20	20%	\$ 84.96	
23	REAR EXHAUST HANGER	1	\$ 38.10	20%	\$ 30.48	

	Parts Description	Qty				
<b>Special Nett Items</b>						
	FRONT NUMPER PLATE WITH CASING	1 SET	\$ 50.00		\$ 50.00	
	REAR BUMPER CLIPS	1 SET	\$ 30.00		\$ 30.00	
	REAR FENDER COWLING CLIPS	2 SETS	\$ 60.00		\$ 60.00	
	REAR FENDER INNER TRIM CLIPS	1 SET	\$ 30.00		\$ 30.00	
	REAR BUMPER LOWER COVER CLIPS	1 SET	\$ 30.00		\$ 30.00	
	REAR END PANEL TOP GARNISH CLIPS	1 SET	\$ 30.00		\$ 30.00	
	REAR BOOT STOPPER	2	\$ 60.00		\$ 60.00	
	END PANEL TOP GARNISH CLIPS	1 SET	\$ 30.00		\$ 30.00	
	REAR BOOT INNER TRIM CLIPS	1 SET	\$ 30.00		\$ 30.00	
	REVERSE SENSORS	1 SET	\$ 250.00		\$ 250.00	
	REAR BOOT HYUNDAI LOGO	1	\$ 55.00		\$ 55.00	
	REAR BOOT "ELANTRA" EMBLEM	1	\$ 55.00		\$ 55.00	
	REAR BOOT "GLS" EMBLEM	1	\$ 40.00		\$ 40.00	
<b>TOTAL MATERIALS</b>			\$ 9,058.80	-	\$ 7,397.04	

**Surveyor Remark:**

- PO New Assignment - SLM3409A (DJ) VS SJL8606T (TP) DOA 26/07/2018

From: Mithrasingh, Aashweenjeetkaur

To: admin-a@kkauto.com; assignments@kkauto.com

Cc: Tan, Lily (AIG); Fong, Andy-EY; Kaur, Beji; Chin, Lee-Ying; Abu Kassim; Noor Marissa; Md Isahak; Mohd Imran; Lim, Sheng Yang; Supramaniam, Denshen; Azlan, Syazandina; Chan, Yoke Si

Sent: 27/7/2018 9:47:17 AM

Attachments: SJL8606T Estimate.pdf; SJL8606T.PDF

Hi,

Claim number : 01319933255G

Case owner : WAN NUR SALHA BINTE SYED YUSOFF

Thanks and regards,

Aashweenjeet Kaur (Aashween)

AIG

Express Claims Adjuster II

SG Claims Operations | AIG Shared Services

From: Esther Tey Chor Keng (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) [mailto:TeyChorKeng@smrt.com.sg]

Sent: Friday, July 27, 2018 9:11 AM

To: AIG SGP, Claims-Survey; Chin, Lee-Ying; karyong.loo@aig.com

Cc: Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); Peh Eng Hock (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Subject: TP CLAIMS AGAINST AIG: SJL8606T

Attention Motor Claims Dept

Your Reference : SLM3409A

Our Reference : SJL8606T WL/JUL2018/003

DOA : 26/07/2018

RE: 3rd PARTY AGAINST YOUR INSURED'S VEHICLE SLM3409A  
ON 26/07/2018 ALONG CTE TOWARDS CITY BEFORE TUNNEL

Attached is our client's SAS report and our Estimate cost of repair (based on our visual inspection only) for our client's vehicle, SJL8606T for your perusal.

Kindly arrange to survey SJL8606T by today. Vehicle currently park at 60 Woodlands Industrial Park E4, Singapore 757705.

We request Single joint expert as per below:

AutoProbe Consultants

LKK

We thank you in advance for your assistance in this matter.

Regards,

Esther

(Tel: 6555-5556)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

10.20am @ 27/7/18  
person @ 28/07/18  
vehicle In

## SATISFACTION FORM

I, Abner Koh Ming Feng, hereby acknowledge having received from SMRT Automotive Services Pte Ltd my vehicle bearing registration number SJL8606T which has been repaired to my satisfaction and acceptance. And I agree that the payment of the account for such repairs to SMRT Automotive Services Pte Ltd. shall be in full discharge of all claims under policy number D28965896 QMY in respect of the damage caused in the accident which occurred on 26/7/2018.



SF121513A

Signature, NRIC No. & Date

Co. Stamp (If applicable)



SMRT AUTOMOTIVE SERVICES PTE LTD  
60 Woodlands Industrial Park E4  
Singapore 757705  
Tel : 65 6482 3888  
Fax : 65 6368 7421  
www.smrt.com.sg

AIG ASIA PACIFIC INSURANCE PTE LTD  
78 Shenton Way  
#09-16 AIG Building  
Singapore 079120

Our Ref.: WL/JUL2018/003 SJL8606T  
Your Ref.: SLM3409A

Dear Sirs / Madam,

**ACCIDENT INVOLVING SJL8606T AND SLM3409A ON 26 JULY 2018**

LETTER OF CLAIM

We claim on behalf of ABNER KOH MINGFENG, owner of the vehicle no.: SJL8606T. Your driver's negligent driving has caused the above accident. As a result, my client has suffered the following losses:-

- |  |   |             |
|--|---|-------------|
| 1. Cost of Repair (invoice EV180900499)        | : | \$ 2,140.00 |
| 2. Loss of Use for 5 days @ S\$80.00 /day      | : | \$ 400.00   |
| 3. Loss of Rental for days @ S\$/day           | : | -           |
| 4. Loss of Income for ____ days @ S\$ ____/day | : | -           |
| 5. Police Report/ SAS Report/ LTA Search Fee   | : | \$ 7.49     |


**Total Claims : \$ 2,547.49**

We enclose the following documents your perusal:

- |   |   |
|---|---|
| <input checked="" type="checkbox"/> Repair Invoice          | <input checked="" type="checkbox"/> Letter of Authorisation |
| <input type="checkbox"/> Survey Report                      | <input checked="" type="checkbox"/> LTA Search result       |
| <input type="checkbox"/> Photographs ____ pcs               | <input type="checkbox"/> Others :                           |
| <input type="checkbox"/> Investigation results              | 1. <u>Satisfaction Form</u>                                 |
| <input type="checkbox"/> Proof of Loss of Use/Rental/Income | 2. _____  |
| <input type="checkbox"/> Police / SAS report of _____       | 3. _____  |

We look forward to your confirmation to settle our claims within 15 days from the date of this letter. Payment by cheque shall be crossed and made payable to SMRT AUTOMOTIVE SERVICES PTE LTD for amount of \$2,547.49

Yours sincerely,  
**SMRT AUTOMOTIVE SERVICES PTE LTD**

  
\_\_\_\_\_  
For Manager,  
Claims Department

## Thin Thin (LKKAUTO)

---

**From:** Thin Thin (LKKAUTO)  
**Sent:** Friday, 3 August 2018 2:51 PM  
**To:** 'cheeyong\_poh84@yahoo.com.sg'  
**Subject:** ACCIDENT INVOLVING SLM 3409A & SJL 8606T ON 26/07/2018



Auto  
Consultants  
Pte Ltd

---

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG18013681/Gub3

03 AUGUST 2018

**POH CHEE YONG**

Dear Sir/Madam,

### **ACCIDENT INVOLVING SLM 3409A & SJL 8606T ON 26/07/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING  
Case Handler  
DID: 6841 2360  
FAX: 6741 4108  
Email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

## LETTER OF AUTHORITY

ACCIDENT ON 26/7/2018 INVOLVING SJL8606T AND SLM3409A

BY THIS LETTER OF AUTHORITY given on the 27/07/18, I/we, Abner Koh Ming Feng who is the owner of motorcar bearing registration number SJL8606T do hereby confirm that I/we have appointed SMRT Automotive Services Pte Ltd. to represent me/us and to do all or any of the following acts and things:

- i) To submit, resolve and make any claim(s) which I/we may have against the other party/parties to the Accident and under the insurance policy/policies taken up by such party/parties in respect of the cost of repairs, loss of use and all other costs and expenses, etc. suffered by me/us arising from the Accident (the "loss and damage");
- ii) To carry out direct negotiation with any third party insurer(s) in respect of the cost of repairs, loss of use and all other costs and expenses, etc. arising from the accident involving the third party insured;
- iii) To agree to any compensation or enter into any settlement or compromise as it deems fit, in the best interests of me/us, and to do all things or acts, as may deem necessary or expedient for the purpose of settlement of the claims;
- iv) To receive all monies payable to me/us, such payment to be made by way of cheque in favour of "SMRT Automotive Services Pte Ltd" and to give a valid receipt and discharge therefor;
- v) To execute and sign on my/our behalf, any discharge voucher or any other documents in connection with the settlement and/or payment of the Claim(s) to give good discharge.

I/We further confirm that the acceptance by SMRT Automotive Services Pte Ltd. of the settlement amount in respect of such claim shall constitute the full discharge of my/our claim(s) in respect of such loss and damage.



S8221515A

Signature & NRIC No.

-

Co. Stamp (if applicable)

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, **SMRT AUTOMOTIVE SERVICES PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$2,140.00** ((Repair Cost), **S\$300.00** (Loss of Rental/Use), **S\$ 7.49** (Disbursement), for vehicle no. **SJL 8606T** that was damaged pursuant to the accident which occurred on **26/07/2018** (date) along **CTE TOWARDS CITY** (location) involving vehicle no/s **SLM 3409A**. This is pursuant to the inspection conducted on **27/07/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **ABNER KOH MINGFENG** ("the third party claimant") of vehicle no. **SJL 8606T** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SJL 8606T** (vehicle no.) as a result of the accident.


We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 21 (day) of 02 (month) **2019** (year)

 **LKK**

Signed by appointed surveyor



Signed by "the workshop" (with chop)





SMRT Automotive Services Pte Ltd  
251 North Bridge Road Singapore 179102  
Tel: 65 63311000 Fax: 65 63340247

## Tax Invoice

Customer Code: 3000415

AIG Asia Pacific Insurance Pte Ltd  
MOTOR CLAIM DEPT  
Block Unit #08-16  
AIG BUILDING  
78 SHENTON WAY  
SINGAPORE 079120

GST Reg No. : MR-8500001-7  
CRN : 1990042802  
Invoice No. : EV180900499  
Date : 30.09.2018  
Vehicle No. : SJL8606T  
Your Ref No. : WL/JUL2018/003  
Our Ref No. : 24097895  
Terms : 30 Days

Description	Qty	Unit Cost	Add \$	/ (Discount) Amount	Amount
Others					
REPAIR COST AS APPROVED BY SURVEYOR	1.00	\$2000.00	0.00	\$ 0.00	\$ 2000.00

TOTAL BEFORE GST	\$	2,000.00
ADD GST @ 07 %	\$	140.00
GRAND TOTAL	\$	2,140.00

Remark :

Make/Model :  
Accident Date : 26.07.2018

N.B. Payment by cheque should be crossed and  
made payable to 'SMRT Automotive Services Pte Ltd'.  
No receipt will be issued unless requested.

  
\_\_\_\_\_  
Authorised Signature  
for SMRT Automotive Services Pte Ltd

## Enquire Transaction History

### Transaction History Details

Log Date/Time:	26 Jul 2018 / 14:00:29	Transaction Amount:	\$7.49
Asset Type:	Vehicle	Channel:	External Agency
Asset ID:	SLM3409A	Business Transaction Reference No.:	20180726140029003291
Transaction Type:	18.32 Insurance Enquiry (GIRO Payment)		
User ID:	ESASBAH0 - BALQISH BINTE ABDUL HALIL		

Search Date / Time: 26 Jul 2018 09:45:00

Insurance Company: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Information displayed is correct as at the log date and time.

Enquire Related Logs

Back to List

Please do not use your browser's Back or Forward buttons as this may result in information loss

Last updated: 15 Jul 2018

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane



















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Jul 2018 <a href="#">Edit Reg</a>		27 Jul 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$2,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>POH CHEE YONG (FU ZHIYONG)</b> , ID: S8431444G								
Main Claimant:	<b>ABNER KOH MINGFENG</b> , ID: S8221513A								
Vehicle Reg. No.:	<b>SJL8606T</b>	Date of Loss:	26/07/2018 09:00 - :59 [25 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 0131993326SG</b>	Policy/Cover Note No.:	2100505426 (Comprehensive) Coverage: 28/03/2018 - 27/03/2019						
Vehicle Reg. No. (Insured):	<b>SLM3409A</b>	Policy No. (Claimant):	D28965896QMY						
		Excess:							
Repairer:	<b>SMRT Automotive Services Pte Ltd (Woodlands)</b> 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Syed-Yusoff, Saliha</b> ] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 07/08/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SJL8606T (0131993326SG)**  
**[SLM3409A]**  
**TP**  
**ABNER KOH MINGFENG**  
**Jul 26 2018 9:00AM**  
**[POH CHEE YONG (FU ZHIYONG)]**  
**SMRT Automotive Services Pte Ltd**

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Video															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print		
1	31/07/18 17:16	Video - Accident From:OD - Reg. No: SLM3409A, Claimant: POH CHEE YONG													Load MP4			
2	31/07/18 17:16	Video - Accident From:OD - Reg. No: SLM3409A, Claimant: POH CHEE YONG													Load MP4			
3	31/07/18 17:16	Video - Accident From:OD - Reg. No: SLM3409A, Claimant: POH CHEE YONG													Load MP4			
Letters/Correspondences															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown													Edit			
Assessment Reports															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print		
1	31/07/18 11:34	Accident Statement From:OD - Reg. No: SLM3409A, Claimant: POH CHEE YONG													Load HTM			
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	03/09/18 08:45	General View													Load JPG	<input checked="" type="checkbox"/>		
2	03/09/18 08:45	General View													Load JPG	<input checked="" type="checkbox"/>		
3	03/09/18 08:45	General View													Load JPG	<input checked="" type="checkbox"/>		
4	03/09/18 08:45	General View													Load JPG	<input checked="" type="checkbox"/>		
5	03/09/18 08:45	General View													Load JPG	<input checked="" type="checkbox"/>		
6	03/09/18 08:45	General View													Load JPG	<input checked="" type="checkbox"/>		
7	03/09/18 08:45	General View													Load JPG	<input checked="" type="checkbox"/>		
8	03/09/18 08:45	General View													Load JPG	<input checked="" type="checkbox"/>		
9	03/09/18 08:45	General View													Load JPG	<input checked="" type="checkbox"/>		
10	03/09/18 08:45	General View													Load JPG	<input checked="" type="checkbox"/>		
11	03/09/18 08:45	General View													Load JPG	<input checked="" type="checkbox"/>		
12	03/09/18 08:45	General View													Load JPG	<input checked="" type="checkbox"/>		
13	03/09/18 08:45	General View													Load JPG	<input checked="" type="checkbox"/>		
14	03/09/18 08:45	General View													Load JPG	<input checked="" type="checkbox"/>		
15	03/09/18 08:45	General View													Load JPG	<input checked="" type="checkbox"/>		
16	03/09/18 08:45	General View													Load JPG	<input checked="" type="checkbox"/>		
17	03/09/18 08:45	General View													Load JPG	<input checked="" type="checkbox"/>		
18	03/09/18 08:45	General View													Load JPG	<input checked="" type="checkbox"/>		
19	03/09/18 08:45	General View													Load JPG	<input checked="" type="checkbox"/>		
20	03/09/18 08:45	General View													Load JPG	<input checked="" type="checkbox"/>		
21	03/09/18 08:45	General View													Load JPG	<input checked="" type="checkbox"/>		
22	03/09/18 08:45	General View													Load JPG	<input checked="" type="checkbox"/>		
23	03/09/18 08:45	General View													Load JPG	<input checked="" type="checkbox"/>		

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
24	03/09/18 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
25	03/09/18 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
26	03/09/18 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
27	03/09/18 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
28	03/09/18 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
29	03/09/18 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
30	03/09/18 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
31	03/09/18 08:45	General View	 Load JPG	<input checked="" type="checkbox"/>
32	03/09/18 08:45	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
33	03/09/18 08:45	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/07/18 12:51	EMAIL FROM AIG DD 27072018	 Load PDF	
2	27/07/18 12:51	TP ESTIMATE	 Load PDF	
3	27/07/18 12:51	TP GIA REPORT	 Load PDF	
4	25/02/19 12:16	WORKSHOP INVOICE	 Load PDF	
5	25/02/19 12:16	AUTHORISATION TO ACT FORM	 Load PDF	
6	25/02/19 12:16	Release Voucher	 Load PDF	
7	25/02/19 12:16	LTA SEARCH	 Load PDF	
8	25/02/19 12:16	LETTER TO OI	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLM3409A (Insd veh)	Model:	HYUNDAI ELANTRA 1.6 AD
	SJL8606T (TP veh)		GLS (A)
Date of Accident:	26/07/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	14,937.31	
Final Repair Cost	:	\$	2,140.00	
Loss of Use	:	\$	300.00	5.00 days at \$60.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	7.49	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	2,447.49	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)				
A) For <u>Non GIA Registered Workshop</u> : Agreed Liability ____ 100 ____ (%)				
B) For <u>GIA Registered Workshop</u> : BOLA Applicable: Yes/ No BOLA Scenario No: ____				
BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)				
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	SMRT Automotive Services Pte Ltd	:	\$ 2,447.49
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

25 Feb  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18013681/GHB3Q2

Date: 25/02/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100505426  
**Claimant Vehicle No :** SJL8606T **Insured Vehicle No :** SLM3409A  
 Date of Loss: 26/07/2018 Nature of Claim: TP Claim No: 0131993326SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SJL8606T**  
 Make & Model: HYUNDAI ELANTRA, 1.6 AD GLS (A) Engine No: G4FGGU186901  
 Reg. Date: 21/06/2016 (Man. Year: 2016) Chassis No: KMHD841CMHU192771  
 Colour: Black Odometer: 34589 km  
 Engine Capacity: 1591 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
 Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm  
 Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,380.10	1,483.84	7,896.26	84.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,580.00	1,130.00	3,450.00	75.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,960.10</b>	<b>2,613.84</b>	<b>11,346.26</b>	<b>81.28</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,000.00</b>		
(S\$)	13,960.10	2,000.00	11,960.10	85.67
<b>+ GST 7.00/7.00% (S\$)</b>	977.21	140.00	837.21	85.67
<b>Nett Amount (S\$)</b>	<b>14,937.31</b>	<b>2,140.00</b>	<b>12,797.31</b>	<b>85.67</b>
<b>+ Loss of Use (5.0 x S\$60.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		7.49		
<b>Nett Liability (S\$)</b>		<b>2,447.49</b>		

## INSPECTION

Date of Assignment: 27/07/2018  
 Date Inspected: 27/07/2018 Inspected At: SMRT Automotive Services Pte Ltd (Woodlands)

60 Woodlands Industrial Park E4  
Singapore 757705

Estimated Period of Repair: 4.0 days

---

**Adjuster:** XING GUO QIANG

**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Missing	558.70 F	*558.70 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	306.80 F	*306.80 FL
3	2		*REAR BUMPER RETAINERS	Necessary	96.20 F	*96.20 FL
4	2		*REAR BUMPER REFLECTORS	Missing	96.80 F	*96.80 FL
5	1		*REAR BOOT	Repair	1,187.80 F	*- FL
6	1		*REAR BOOT INNER TRIM	Not Necessary	245.30 F	*- FL
7	2		*REAR BOOT REFLECTOR	Not Necessary	786.40 F	*- FL
8	1		*REAR BOOT WEATHERSTRIP	Not Necessary	203.40 F	*- FL
9	1		*REAR BOOT LOCK	Not Necessary	189.30 F	*- FL
10	2		*TAILAMPS	Not Necessary	1,050.60 F	*- FL
11	1		*TAILAMP PANEL LH	Not Necessary	48.00 F	*- FL
12	1		*REAR END PANEL	Repair	582.90 F	*- FL
13	1		*END PANEL TOP GARNISH	Not Necessary	135.80 F	*- FL
14	1		*REAR BUMPER REINFORCEMENT BRACKETS	Not Necessary	188.60 F	*- FL
15	2		*REAR FENDER INNER COWLING	Not Necessary	188.60 F	*- FL
16	1		*REAR BUMPER LOWER COVER	Not Necessary	272.60 F	*- FL
17	2		*REAR FENDER	Not Necessary	1,320.80 F	*- FL
18	2		*REAR FENDER AIR DUCT	Not Necessary	66.40 F	*- FL
19	1		*REAR SILENCER BOX	Not Necessary	499.60 F	*- FL
20	1		*REAR EXHAUST INSULATOR SHIELD	Not Necessary	106.30 F	*- FL
21	1		*REAR EXHAUST MOUNTING	Not Necessary	33.60 F	*- FL
22	1		*REAR EXHAUST TIP	Not Necessary	106.20 F	*- FL
23	1		*REAR EXHAUST HANGER	Not Necessary	38.10 F	*- FL
24	1		*SET FRONT NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
25	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
26	2		*SETS REAR FENDER COWLING CLIPS	Not Necessary	60.00 FS	*- FS
27	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	30.00 FS	*- FS
28	1		*SET REAR BUMPER LOWER COVER CLIPS	Not Necessary	30.00 FS	*- FS
29	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
30	2		*REAR BOOT STOPPER	Not Necessary	60.00 FS	*- FS
31	1		*SET END PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
32	1		*SET REAR BOOT INNER TRIM CLIPS	Not Necessary	30.00 FS	*- FS
33	1		*SET REVERSE SENSORS	Missing	250.00 FS	*200.00 FS
34	1		*REAR BOOT HYUNDAI LOGO	Necessary	55.00 FS	*55.00 FS
35	1		*REAR BOOT ELANTRA EMBLEM	Necessary	55.00 FS	*55.00 FS
36	1		*REAR BOOT GLS EMBLEM	Necessary	40.00 FS	*40.00 FS
37	1		*REAR BUMPER LOWER GARNISH	Missing	321.30 F	*321.30 FL

F=Franchise part, S=SpcNett, L=ListItemDisc

Sub Total (\$\$)	9,380.10	1,759.80
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	275.96
<b>Total Parts (\$\$)</b>	<b>9,380.10</b>	<b>1,483.84</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RENEW DAMAGED PARTS ,REPLACE AND REALIGN END PANEL AND ALIGNED ALL PARTS	New	1,600.00	400.00
2	TO RESPRAY AFFECTED AREAS	New	1,600.00	600.00
3	TOWING	New	80.00	0.00
4	WINDSCREEN SEALANT	New	100.00	0.00
5	TO TUFFCOAT AFFECT AREAS	New	150.00	0.00
6	TO RENEW FRONT WINDSCREEN GLASS (NPA)	New	0.00	0.00
7	TO RENEW ENGINE MOUNTINGS AND GEAR BOX MOUNTING (NPA)	New	0.00	0.00
8	TO REMOVE/REFIT AIRCON CONDENSOR ,PIPING ,VACUUM AND RECHARGE AIRCON GAS (NPA)	New	0.00	0.00
9	TO REMOVE/REFIT REPLACE DASHBOARD (NPA)	New	0.00	0.00
10	TO REMOVE AND REFIT INTERIOR UPHOLSTERY	New	120.00	60.00
11	TO REMOVE AND REPLACE STEERING COLUMN (NPA)	New	0.00	-
12	TO REMOVER /REFIT WIRING CHECK	New	80.00	30.00
13	TO REMOVE/REFIT REAR WINDSCREEN FOR REAR FENDER REPLACEMENT	New	150.00	0.00
14	TO REMOVE /REPLACE EXHAUST SILENCER BOX AND STRAIGHTEN CENTRE PIPE	New	300.00	0.00
15	TO REMOVE/REPLACE REVERSE SENSOR AND DISTANCE SETTING	New	150.00	40.00
16	TO REMOVE AND TRANSFER REAR BOOT MECHANISM	New	150.00	0.00
17	TO RE-PROGRAMING ALL NECESSARY SYSTEM	New	100.00	0.00
Gross Labour Cost (S\$)			<b>4,580.00</b>	<b>1,130.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;