



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 09/11/2018

Survey Details:

Date of loss	21-Jul-18
Date of appointment	27-Jul-18
Date of survey	27-Jul-18
Location of survey	UNITED SG AUTOMOBILE PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	PA 8025G
Make and Model	TOYOTA HIACE COMMUTER 3.0 GLA 2892cc
Date of registration	28-Aug-08
Excess	
Market Value (est)	\$8,000.00
Parf Rebate (est)	\$350.00
Nett Loss (est)	\$7,650.00

Repair details:

Initial Estimate	\$ 5,722.63
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 851.85
Check items (estimate)	\$ -
Labour	\$ 510.00
Total	\$ 1,361.85
Lump Sum(if applicable)	\$ 1,100.00

Number of days for repair	<u>2 DAY</u>
---------------------------	--------------



Remarks:

We have not authorized repairs. It was reported that Insured had overtook the turning TP at the junction. As such, a letter was sent out to the Insured to notify of TP claim. Insured replied and agreed to settle TP claim. TP LOD IN. For mandate approval.

Mandate:

Liability(TP)	100%	
Proposed Repair Cost	\$ 1,177.00	w/gst
Loss of Use	\$ -	no. of days
Loss of Rental	\$ 600.00	\$150 x 4 days
Loss of Income	\$ -	no. of days
LTA search fees	\$ 7.45	
Others	\$ -	
Proposed Total	\$ 1,784.45	

***TBC - To Be Confirmed