

REPAIR ESTIMATE

26/7/2018 15:50

VEHICLE NO : SHC 1450S

MAKE :

MODEL : TOYOTA PRIUS

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
PANEL SUB-ASSY, FRONT DOOR, LH <i>x repair</i>			\$ 1,264.00
REAR TYRE RIM (LH) <i>hinged</i>			\$ 1,555.00
<i>Rear Door (LH) ✓ Det</i>	<i>\$ 124.30</i>		
<i>Front Fender Emblem - ne \$ 86.50</i>			\$ 2,819.00
SUB TOTAL			\$ 704.75
LESS 25%			\$ 2,114.25
DISCOUNTED TOTAL			
REAR DOOR COMFORT & APPS STICKER <i>ne</i>			\$ 80.00
<i>Front Door sticker - ne \$ 75</i>			
<i>Fuel Tank sticker - ne \$ 10</i>			
LABOUR CHARGE			
Panel Beating			\$ 850.00
Spray Painting Charge			\$ 800.00 600
Tuff Kote			\$ 50.00 20
Transfer of Door			\$ 120.00 50
TOTAL LABOUR			\$ 1,520.00
ESTIMATE TOTAL			\$ 3,714.25

Kahar iKKK

27/7/18 1026h

2 Bx

P/P

Before Part photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

[illegible]