

13/05/2002

ASS. REC. BY:

REF: C/TPD18013749/Zc

Special Instruction:

Survivor:

ASSIGNMENT (Office)

From (Person): Kamaliah Kowle of SPF

Date/Time: 10/5/2018

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: XB5657C

Insured:

at Workshop m/s

Tel:

of

Policy No: MHASPF06000010269

Claim No: TP/IF/23799/2018

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A 18/4/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
28/8/18	XB5657C-X - 10 Midayn - 65476423 called - no answer
31/8/18	Moorkhidaaph - abdullah@ppf.gov.sg emailed her. waiting for reply

8/8007

4 17

XB 5657 C

Vilton Hia
Senior Investigation Officer
Fatal Accident Investigation Team
Traffic Police
Singapore Police Force
DID: (65) 6547 6228 | FAX: (65) 6547 6352

Received on 10th May 2018



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Rohaizal (LKKAuto) [mailto:Rohaizal@lkkauto.com]
Sent: Friday, 29 June 2018 5:55 PM
To: Vilton HIA (SPF) <Vilton_HIA@spf.gov.sg>
Subject: RE: Mechanical Inspection Report Request

Bro,
Pls email to me cc bryan in the future. Thx

Best Regards,
Mr Rohaizal A. Rahim | Technical Investigator
LKK Auto Consultants
phone: 6256-3561 email: Rohaizal@lkkauto.com | fax: 6256-4315
Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Vilton HIA (SPF) [mailto:Vilton_HIA@spf.gov.sg]
Sent: Friday, 29 June 2018 2:44 PM
To: Rohaizal (LKKAuto)
Subject: FW: Mechanical Inspection Report Request

Bro,

Sent in 10 May 2018.

(a) Case IAFP-IB-20180504-Mechanical Inspection of Motor Van, GBA1055G (TP/IP/21857/2018)

On 6/4/2018 at about 11.45 am, the said motor van (GBA1055G) driver was found was found unconscious in his driver seat where half of his van (left) was found on the left kerb and another half (right) was found on the road with engine running along Seletar Road towards TPE. He was conveyed to KTPH and pronounced dead on the same day at 3.41 pm

GBA1055G - Driver (Deceased)

IO In-Charge: SIO Vilton

Vilton Hia
Senior Investigation Officer
Fatal Accident Investigation Team
Traffic Police
Singapore Police Force
DID: (65) 6547 6228 | FAX: (65) 6547 6352

Mark Copy - Received on 10/5/18 (Bryan)
7 vehicles



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance therein. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Kamaliah KAMIS (SPF)
Sent: Thursday, 10 May 2018 9:35 AM
To: Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>
Cc: SPF-TP FAIT <SPF-TP_FAIT@spf.gov.sg>; Nor Hidayu ABDUL SAMAD (SPF) <Nor_Hidayu_Abdul_Samad@spf.gov.sg>
Subject: Mechanical Inspection Report Request

Hi Sir,

May I seek your assistance to perform a detailed mechanical inspection of the vehicle below:

(a) Case IAFP-IB-20180504-Mechanical Inspection of Motor Car, SKD5410R (TP/IP/25859/2018)

On 1 May 2018 (Tuesday) at or about 1.06 a.m., the Deceased was driving his motorcar along East Coast Parkway Expressway towards Airport, 3.5 KM, lamp post 447F on lane 1 of 3 lanes when the Deceased was believed to have lost control of his motor car, resulting in the motor car veering to the right, collided onto the flower pots before toppling to its right. Due to the accident, the Deceased was pronounced dead at scene at 2.14 a.m. by the attending paramedic, WO Choo.

SKD5410R - Driver (Deceased)

IO In - Charge: IO Clarence

(b) Case IAFP-IB-20180504-Mechanical Inspection of Motor Car, SKC280L (TP/IP/25259/2018)

(c) Case IAFP-IB-20180504-Mechanical Inspection of Malaysian Motorcycle JQE4779 (TP/IP/25259/2018)

On 25 April 2018 (Wednesday) at or about 9.26 a.m., the Deceased was travelling along the slip road on lane 2 of 2 and the Involved Party was travelling on lane 1. The Deceased was slightly ahead of the Involved Party. When the 2 lanes merged, the rear wheel of the Deceased's motorcycle side-swiped the left front portion of the Involved Party's motor car. As a result of the collision, the Deceased was conveyed unconscious to Khoo Teck Puat Hospital and was pronounced dead at KTPH on 29/04/2018 at 1122hrs by Dr Nay Zar Win Maung. The Involved Party was not injured.

SKC280L - Driver (Not injured)

JQE4779 - Rider (Deceased)

IO In - Charge: IO Clarence

(d) Case IAFP-IB-20180504-Mechanical Inspection of Tipper XB5657C (TP/IP/23799/2018)

On 18 April 2018 (Wednesday) at or about 11.07 a.m., a case of major road traffic accident which happened along Defu Lane 9 towards Defu Lane 7, involving one m/lorry & a pedestrian. The driver **claimed** that he was driving along the above mentioned location and subsequently looked through his right side mirror and noticed the right crane stand protruding out from the vehicle which had collided onto a pedestrian. The driver did not claim of any mechanical fault on the vehicle as he was only told to drive the vehicle from one point to another.

XB5657C - Driver (Not injured)
Pedestrian - Injured

IO In - Charge: IO Hidayu

(e) Case IAFP-IB-20180504-Mechanical Inspection of Motor Van, GBA1055G (TP/IP/21857/2018)

On 6/4/2018 at about 11.45 am, the said motor van (GBA1055G) driver was found was found unconscious in his driver seat where half of his van (left) was found on the left kerb and another half (right) was found on the road with engine running along Seletar Road towards TPE. He was conveyed to KTPH and pronounced dead on the same day at 3.41 pm

GBA1055G - Driver (Deceased)

IO In-Charge: SIO Vilton

(f) Case IAFP-IB-20180424-Mechanical Inspection of Motor Car, SLD3604A (TP/IP/24523/2018)

On 22 April 2018 (Sunday) at about 12.59 a.m., Motor car was making a right turn from Jalan Anak Bukit into PIE (AP) when traffic light was showing green only without any right turn green arrow. As such, SMRT bus from opposite direction who was travelling straight in green light collided onto motor car's left side. Deceased (rear left passenger), front passenger and car driver were conveyed to NUH. Both front passenger and car driver had already discharged from NUH while Deceased succumbed to her injuries on the same day in NUH.

SLD3604A - Driver (Slightly injured, discharged)
Rear left passenger (Deceased),
Front passenger (Slightly injured, discharged)

IO In-Charge: SIO Vilton

(g) Case IAFP-IB-20180424-Mechanical Inspection of Motor Lorry, GBF4388A (TP/IP/24713/2018)

On 23 April 2018 (Monday) at about 9.37 a.m., motor lorry was travelling along Ang Mo Kio Avenue 6 towards Marymount Road on the centre lane of 3 lanes road when his lorry had veered to his left for unknown reason, mounted the left kerb, collided onto the left railing before collided onto the 3 Deceased (pedestrians) whom were walking along the footway. Due to the accident, 3 pedestrians were pronounced dead at the scene.

GBF4388A - Driver (Slightly injured, warded in KTPH)
3 Pedestrians - All Deceased

IO In-Charge: IO Kamaliah

2. These request has been approved by my management.
3. Thank you Sir.

Cc: FAIT Team & Hidayu, fyip

Best regards,

Kamallah Kamis (Miss)
Investigation Officer | Fatal Accident Investigation Team
Traffic Police | Singapore Police Force
DID: (65) 6547 6435 | FAX: (65) 6547 6352



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."