



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer: WZF002 / MS FIRST CAPITAL
Chassis No: MRHGM6660GP000440
License No: SLB4559B
Mileage: 24788
Engine No: L15Z12720065

Document No: SVO18045078
Printed By: ARYCHUA
Order Date: 2. August 2018
Order Time: 8:58:10 AM
Service Advisor: ARY CHUA WAI NGE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 70979) OWNER: CHUA OON CHENG CAROL @ CAROL YAP OWNER INSURER: LIBERTY INSURANCE ACC DATE: 28/07/18 SURVEYED BY: MARCUS (LKK) DATE: 31/7/18 @ 11.00AM REF NO: D18005744MFSH TP INSURER: MS FIRST CAPITAL INS. LIMITED TP VEH: SHC7841H						
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	3	11.20	25	25.20	1.76	26.96
73227-T9A-T00	RUBBER CWINDSHIELD DAMPER	1	17.30	25	12.97	0.91	13.88
91501-S70-003	FASTENER BW/SHIELD	2	3.20	25	4.80	0.34	5.14
91536-SS0-J01	FASTENER AW/SHIELD	2	3.50	25	5.25	0.37	5.62
91568-TF0-003	CLIPFR.WINDSHIELD.UPPER.	2	2.80	25	4.20	0.29	4.49
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
04655-T9A-T00ZZ	PANEL SETRR.FLOOR	1	408.80	25	306.60	21.46	328.06
65513-T9A-T00ZZ	STIFFENERRR.JACK UP	1	93.10	25	69.82	4.89	74.71
65540-T9A-T10ZZ	STIFFENER COMPR.RR.FRAME	1	165.00	25	123.75	8.66	132.41
65590-T9A-T10ZZ	STIFFENER COMPL.RR.FRAME	1	165.00	25	123.75	8.66	132.41
65770-T9A-T00ZZ	CROSSMEMBER COMPRR.FLOOR RR.	1	109.10	25	81.82	5.73	87.55
65612-T9A-T00ZZ	FRAME BR.RR.	1	75.30	25	56.47	3.95	60.42
65619-T5A-300ZZ	FLANGERR.FRAME END	2	10.80	25	16.20	1.13	17.33
65662-T9A-T00ZZ	FRAME BL.RR.	1	79.20	25	59.40	4.16	63.56
66100-T9A-T50ZZ	PANEL COMPRR.	1	323.90	25	242.92	17.00	259.92
04646-T9A-T00ZZ	PANEL SETL.RR.OUTSIDE	1	1,134.80	25	851.10	59.58	910.68
63720-T9A-T00ZZ	GUTTER COMP L.RR.	1	70.40	25	52.80	3.70	56.50
68500-T9A-T30ZZ	LID COMPTRUNK	1	444.50	25	333.37	23.34	356.71
74865-T9A-T01	WEATHERSTRIPTRUNK LID	1	71.60	25	53.70	3.76	57.46
74851-T2A-003	LOCK ASSYTRUNK	1	89.90	25	67.42	4.72	72.14
71501-T9A-T00ZZ	FACERR.BUMPER	1	463.70	25	347.77	24.34	372.11
71503-T9A-T00	COVERRR.BUMPER EX.PIPE	1	9.60	25	7.20	0.50	7.70
71593-T9A-J00	SPACER R.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-T9A-J00	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER	4	2.00	25	6.00	0.42	6.42
75722-T9A-T00	EMBLEMRR.CITY	1	11.30	25	8.47	0.59	9.06
75701-T9A-000	EMBLEM H	1	11.00	25	8.25	0.58	8.83
75725-T9A-T00	EMBLEMRR.I-VTEC	1	11.90	25	8.92	0.62	9.54
84640-T9A-T01ZA	LINING ASSYRR.PANEL	1	66.60	25	49.95	3.50	53.45
84521-T9A-T10	LID COMPSPARE TIRE	1	43.70	25	32.77	2.29	35.06
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
33500-T9A-T01	TAILLIGHT ASSYR.	1	205.70	25	154.27	10.80	165.07
34150-T9A-T01	LIGHT ASSYR.LID	1	72.80	25	54.60	3.82	58.42
33550-T9A-T01	TAILLIGHT ASSYL.	1	205.70	25	154.27	10.80	165.07
34155-T9A-T01	LIGHT ASSYL.LID	1	72.80	25	54.60	3.82	58.42
74940-SZW-003	BUZZER ASSYSMART	1	60.10	25	45.07	3.15	48.22
72841-SH3-315	OILSHEET	1	39.90	25	29.92	2.09	32.01
	SUM PARTS:				3,850.84	269.53	4,120.37
BOSUN	0672	1	20.00		20.00	1.40	21.40

WD = 15



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer:	WZF002 / MS FIRST CAPITAL	Document No:	SVO18045078
Chassis No:	MRHGM6660GP000440	Printed By:	ARYCHUA
License No:	SLB4559B	Order Date:	2. August 2018
Mileage:	24788	Order Time:	8:58:10 AM
Engine No:	L15Z12720065	Service Advisor:	ARY CHUA WAI NGEE

	SUNDRIES					
BOJSE	0672	1	300.00	300.00	21.00	321.00
	BODY JOINT SEALANT.					
BOBC	EXT-YBH	1	100.00	100.00	7.00	107.00
	BODY UNDERSIDE COATING (N)					
BP00R	EXT-YBH	1	250.00	250.00	17.50	267.50
	APPLY BODY UNDERSIDE COATING (N).					
BML02I	EXT-YJ	1	80.00	80.00	5.60	85.60
	INSPECT RR LIGHTING MECHANISMS.					
	PERFORM WATER					
	TEST.(N)					
BG02D	EXT-YJ	1	300.00	300.00	21.00	321.00
	REMOVE & INSTALL RR. WINDSCREEN.					
	(N)					
BMI02D	EXT-YJ	1	320.00	320.00	22.40	342.40
	REMOVE & INSTALL SPEAKER BOARD					
	RR SEATS TRUNK					
	LININGS GARNISHES & ETC.(N)					
BKOT00R	EXT-YJ	1	250.00	250.00	17.50	267.50
	REMOVE & RENEW RR FLOOR					
	INSULATOR.(N)					
BMF00D	EXT-YJ	1	180.00	180.00	12.60	192.60
	RREMOVE & INSTALL FUEL TANK FUEL					
	PIPES.(N)					
BOMISC1	EXT-YJ	1	300.00	300.00	21.00	321.00
	REMOVE, REPLACE AND INSTALL					
	SMART ENTRY SENSOR.					
	RESET MEMORY. (N)					
BA02R	EXT-YJ	1	120.00	120.00	8.40	128.40
	REMOVE & RENEW REVERSE					
	SENSORS-4 PCS (N)					
BKRP02M	EXT-YJ	1	4,480.00	4,480.00	313.60	4,793.60
	CUT OFF & RENEW RR PANEL, FLOOR					
	AND BOTH FENDER.					
	RENEW DAMAGE PARTS.					
BP06R	EXT-YBH	1	3,100.00	3,100.00	217.00	3,317.00
	SPRAY PAINTING ON REPAIRED OR					
	REPLACED AREAS. (6P)					
			SUM LABOUR:	9,800.00	686.00	10,486.00
			TOTAL SGD	13,650.84	955.53	14,606.37
			Total Payable (SGD)	14,606.37		

GST Amount is calculated from individual line(s)