



Premium Automobiles Pte Ltd

Audi Centre Singapore
 281 Alexandra Road
 Singapore 159938
 Main Telephone 6836 2223
 Main Telefax 6471 3733
 Page 1 17:13

Alexandra Service Centre
 281 Alexandra Road
 Singapore 159938
 Telephone 6388 2223
 Telefax 6475 1023

Ubi Service Centre
 55 Ubi Road 1
 Singapore 408699
 Telephone 6388 2223
 Telefax 6641 1183

Customer Service
 Service Appointment 6366 2323
 24-hour Breakdown Service 9828 1233
 Email customer.care@premiumauto.com.sg

INSURANCE INVOICE
 Company Ref No. 199902271W
 GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012948 Date : 17/09/2018 Order : SLJ9060Y Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLJ9060Y (V 31691) Regn Date: 29/12/2016 Mileage: 29473 WIP No.: 19289
 Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V4H1016366 Engine: CHZ 142479 Dept: U
 VSB No.:
 You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE FRONT BUMPER, LHS HEADLIGHT AND LHS FRONT FENDER. RENEW LHS HEADLIGHT. REPAIR FRONT BUMPER. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	750.00	1.00	750.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER	550.00	1.00	550.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	ABV0941773D	HEADLIGHT Less 020%	1.00	4888.00	3,910.40

Parts 3,910.40	Sub-Total	5,162.40
Labour 0.00	7% GST	361.37
Sublet 1,852.00	Grand Total	5,523.77
Menus 0.00		
Lubricant 0.00		



Received by

For & on behalf of
 Premium Automobiles Pte Ltd

Customer