

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 9990H

DATE 30/7/2018 10:07

ALG
LKK
JM

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✓			\$ 1,349.50
	Boot Lid Rubber ✗			\$ 110.90
	Boot Lid Lock Upper ✗			\$ 132.10
	Boot Lid Lock Lower ✗			\$ 30.30
	Boot Lid Sonata Plate ✓			\$ 43.60
	Boot Lid Hyundai Plate ✓			\$ 24.20
	Boot Lid 'H' Emblem ✓			\$ 26.10
	Boot Lid CRDI Plate ✓			\$ 22.70
	Boot Lid Lamp (LH/RH) <i>Ux RM</i>		\$ 230.20	\$ 460.40
	Boot Lid Trimboard ✗			\$ 165.40
	Boot Lid Trimboard Clips (10pcs) ✗			\$ 10.00
	Rear Bumper ✓			\$ 578.40
	Rear Bumper Reinforcement ✓			\$ 483.30
	Rear Bumper Clip ✓			\$ 22.00
	Rear Bumper Sponge ✓			\$ 137.40
	Rear Bumper Under Cover ✗			\$ 185.80
	Rear Bumper Protector (LH/RH) ✗ <i>RM</i>		\$ 38.00	\$ 76.00
	Tail Lamp (LH/RH) ✗		\$ 344.00	\$ 688.00
	Rear Panel ✗ <i>Repair</i>			\$ 391.80
	Rear Panel Garnish ?			\$ 95.80
	SUB TOTAL			\$ 5,033.70
	LESS 20%			\$ 1,006.74
	DISCOUNTED TOTAL			\$ 4,026.96
	Boot Lid City Cab Logo & Tel No. Sticker ✓			\$ 30.00 Nett
	Boot Lid Advertisement Logo ✗			\$ 100.00 Nett
	Rear No. Plate ✓			\$ 25.00 Nett
	Rear Bumper Reverse Sensor ✓			\$ 135.70 Nett
				\$ 290.70
	Labour Charge			
	Panel Beating			\$ 850.00 <i>600</i>
	Spray Painting Charge			\$ 750.00 <i>600</i>
	Wiring Charge			\$ 50.00 <i>20</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>30</i>
	TOTAL LABOUR			\$ 1,820.00
	ESTIMATE TOTAL			\$ 6,137.66

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1/2/18 LKK
30/7/18 10:20h
3 Dm
4/5
Alfa Repair p/h

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.