

WORLD AUTO PTE LTD

47 Jalan Persempin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD

143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department

Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000254

Date : 28/07/2018
 Vehicle Num. : SLH 395B (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 13/06/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	REAR BOOT LID		1,300.00 <i>bt</i>
2.	1	REAR BOOT HYBRID EMBLEM (VEZEL)		89.00 <i>na</i>
3.	1	REAR BOOT VEZEL EMBLEM (VEZEL)		89.00 <i>na</i>
4.	1	REAR BOOT INNER TRIM BOARD		345.00 <i>x</i>
5.	1	REAR BOOT WEATHER STRIP		188.00 <i>x</i>
6.	1	REAR WINDSCREEN GLASS MOULDING		250.00 <i>na</i>
7.	2/LH RH	REAR BOOT REFLECTOR LAMP	700.00	1,400.00 <i>x</i>
8.	1	REAR BUMPER		900.00 <i>de</i>
9.	2/LH RH	REAR TAIL LAMP	700.00	1,400.00 <i>x</i>
10.	1	REAR END PANEL		860.00 <i>x</i>
11.	1	REAR END PANEL TOP GARNISH		260.00 <i>x</i>
12.	1	REAR COMPARTMENT BOX		280.00 <i>x</i>
13.	1	REAR COMPARTMENT BOX BACK COVER		160.00 <i>x</i>
List Total S\$:				7,521.00
20.00% Discount S\$:				1,504.20
				6,016.80

SPECIAL NETT ITEMS :				
1.	1	REAR BOOT INNER TRIM BOARD CLIP		40.00 <i>x</i>
2.	1	REAR WINDSCREEN SEALANT		100.00 <i>na 40</i>
3.	1	REAR BUMPER CLIP		40.00 <i>na 30</i>
4.	1	REAR END PANEL TOP GARNISH CLIPS		40.00 <i>x</i>
5.	1	REVERSE SENSOR		280.00 <i>200?</i>
Special Nett Total S\$:				500.00

LABOUR :
 TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES

180.00 *60*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

CONTINUE / ...

Taufik 9749 5749

WP

30/7/18 e 1730

3-4 days

su@lkkauto.com

* Resurvey before paint

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department
 Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000254

Date : 28/07/2018
 Vehicle Num. : SLH 395B (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 13/06/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		REMOVE & REFIT REAR WINDSCREEN GLASS	180.00	120
		LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.	1,200.00	400
		PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER)	1,000.00	400
		Labour Total S\$:		2,560.00

E. & O.E.

Total S\$: 9,076.80

=====

for WORLD AUTO PTE LTD