



SMRT Automotive Service Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63665592

Estimator Telephone Number : 68662623


Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

II L/S

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB45G
Ref. No : BUS/07/18/1020
Reg. Date : ~~26/07/2018~~ 15/12/2008
Vehicle Type : BUS -12M
Make : MBOC500 (MERCEDES)
Model : MERCEDES MBOC500
Name of Driver : Soo Lian Hwa
Type of Accident : SIDE SWIPE
Date / Time of Accident : 25/07/2018 08:10:00 AM
Accident Reported Date / Time : 25/07/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : India Inter Ins Pte Ltd
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No :
Special Instruction to ARC, if any :
SMB45G - RIGHT CENTRE PORTION
PC418Z (TP) - INSURED WITH III.
Prepared Date : 26/07/2018 09:13:42 AM



Chassis No :
Work Shop :

Mileage : 0
Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	1,590.00	0.00
Total Spray Painting Charges	956.00	0.00
Total Material Charges	0.00	0.00
Other Charges	960.00	0.00
TOTAL	3,506.00	0.00
Lum Sum Total	3,500.00	0.00
No. of Repair Days	3.00	0.00
Prepared / Adjusted By		
Arc / Surveyor Sing Off Date	31/07/2018 09:19:42 AM	01/01/1900 12:00:00 AM

57

Prepared / Adjusted Date :
Remarks :

Prepared Date : 31/07/2018 09:19:42 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :
Quotation Date :
Invoice Amount :

Invoice No :
Invoice Date :
Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	1,590.00	0.00 1325
Total Labour	1,590.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	956.00	0.00 800
Total Spray Painting & Panel Beating	956.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
ADVERTISEMENT STICKER	960.00	0.00 / waiting for actual price
Total Other Costs	960.00	0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to their approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

NA2 LKK
2/8/18 1040
L/S
3 DAYS
AFTER REPAIR PHOTO

TOTAL MATERIALS(Discounted)

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									
• <i>Additional materials used for the installation of the system</i>									

- Zoonosen sind Krankheiten, die normalerweise von Tieren auf den Menschen übertragen werden
- Die meisten zoonotischen Erreger sind Bakterien
- Eine Zoonose ist ein zoonotischer Krankheitsprozess
- Zoonosen sind eine wichtige Ursache für die menschliche Gesundheit
- Zoonosen sind eine wichtige Ursache für die menschliche Gesundheit