

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

SOMPO INSURANCE SINGAPORE PL Ref: CS3/SMO18014014/Gz4d3e2

Page No.:1 of 1

50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWER SINGAPORE 048623			Date:	20-08-2018	
			Code:	SMO	
1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SKK 9668B	Veh. Ir	nspected	YN 6288C
	Policy No.		Coverage (\$)		0.00
	Claim No.	CMTD1803171/GPL	Excess (\$)		0.00
	Assign From	GRACE TEO	Assign Date		31/07/2018
2. Vehicle Particulars & Condition					
	Make & Model	MITSUBISHI CANTER	c.c		2998
	Engine No.	HIDDEN	Year o	of Reg.	2014
	Chassis No.	hassis No. FEB21EA00928		r	WHITE
	Odometer	293885 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195 R15	CONTI	NENTAL	5 mm
	L/H Front Tyre	195 R15	CONTI	NENTAL	5 mm
	R/H Rear Tyre	195 R15 (D)	HIFLY		5/5 mm
	L/H Rear Tyre	195 R15 (D)	HIFLY		5/5 mm
4. Description of Damages					
	THE VEHICLE SU	STAINED DAMAGES AT THE REAR PORTION.			
5. General Information					
	Accident Date	23/07/2018 Inspect Date / Time 17/08/			17/08/2018 (11:30 AM)
	Survey held at	SIN HOCK LEE MOTOR REPAIR			
	51 UBI AVENUE 1 #01-09 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933				
5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				

Report Ref No. CS3/SMO18014014/Gz4d3e2

Estimate Days of Repair

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

5b.

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A **Automotive Assessor** BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

4 Working Days

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.