

ASS. REC. BY:

REF:

CS/FCI18014051/Urd3/n2

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time:

2/8/18 @ 8.20am

Estimated Cost:

Bill to:

OD TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SKB 35594

Insured:

SH 7716E

at Workshop m/s

Ever 8en Auto

Tel:

6743 7111

of

Blk 3022A, Ubi Rd 1 #01-49

Policy No:

Claim No:

D18005786 MPST

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/07/2018

CA / REV / REP. / REV 24 HRS

(DS)

3/8/2018 @ Afternoon

H.O.D. Endorsement:

Date/Time: 9:57am @ 2/8/18

Person Contacted:

Ah beng

Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SKB 35594-X
	SH 7716E-CC3/AIG14018082/H/rm3y2 DUA: 20/9/2014
6/8/18	Email preli. revised to FCI

(08/11/13) wef
ASS. REC. BY:

REF: FCI

ASSIGNMENT

From: _____ Date: 3/8/18
Estimated Cost: _____
OD/TP/WS/TP RES/OD RES/EVA/INV/MV
To Inspect Vehicle No: SKB 35594
at Workshop m/s Evergen
of 81K 3022A, Ubi Rd 1 #01-49
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record) Afternoon
Make of Veh: _____

(Policy Condition)


Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 39
IDAC Accident Rpt: Consistent?: Yes or No
GIA / PR Seen: Consistent?: Yes or No
Est. Repairs: 5 days Res.: Yes or No
Lum Sum: 2 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS CDS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKB35594 Yr Regn: 5 11
Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA/
Make: Mercedes 3/60 c.c 1498
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 126197 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WDD2452312J718277
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: _____ R: 215/45-225
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front 6 mm Rear 6 mm
R/Bal. 6 mm L/Bal. 6 mm
D.O.A. 28/7/18 D.O.I. 3/8/18
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S Rear
The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time	Action / Instruction
17/8/18	LTA 26869 24/5 mch. net 12131 4/5 4400 confirmed with AH Leg. (Red 3446, 4490)
	RECEIVED 17 AUG 2018

Date/Time, File Pass to? ☐ : Preli. Report
1) ☐ : Final Report

Days Of Repair: 5
Resurvey No. of Trip: -

Date/Time, File Return to?
2) 17/8- typist

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:	150
Transportation:	50
S + RS, SI	41
Photos	
Others	
TOTAL	241

Report Format : CWS
Lump Sum / I.B.I: (\$ 4400/2)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18014051/Uvd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 02-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7716E	Veh. Inspected	SKB 3559U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005786MFSH	Excess (\$)	0.00	
Assign From	CWS (KAREN TAN)	Assign Date	02/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/07/2018	Inspection Date	03/08/2018	
Survey held at	EVER SEN AUTO SERVICE BLK 3022A UBI ROAD 1 #01-49 SINGAPORE 408716			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18005786MFSH

Our ref: CS/FCI18014051/Uvd3

DATE: 6/8/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO. SKB 3559U


We thank for your instruction on 2/8/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 3/8/2018 at the premises of M/s EVER SEN AUTO SERVICE and have the following to report:-

Workshop Estimate Amount	: S\$7,846.00
Revised Estimate Amount	: S\$5,904.00
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s rear portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	31-07-2018	Our Ref No. D18005786MFSH
Accident Date	28-07-2018	Claim Type. Third Party
Insured Vehicle	SH7716E	Third Party Vehicle. SKB3559U
Survey Location	BLK 3022A UBI ROAD 1 #01-49	
Contact Person.	TAN T S	
Contact No.	67437111/ 0	Fax No. 67489611
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	EVER SEN AUTO SERVICE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242868)



PRI Documents



Close



PRI Header Details

Claim No	D18005786MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & EVER SEN
Workshop Name	EVER SEN AUTO SERVICE (Contact Person : TAN T S)	Survey Location & Contact Details	BLK 3022A UBI ROAD 1 #01-49 Mobile: 0 , Phone: 67437111 , Fax: 67489611 EmailId: EVERSENAUTO@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH7716E	TP Vehicle No	SKB3559U
PRI Recieved Date	31-07-2018 06:01:37 PM	Surveyor Appointed Date	02-08-2018 08:19:15 AM	Surveyor Accept Date	02-08-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	02-08-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 6 August 2018 2:47 PM
To: 'Claim Workflow System'
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005786MFSH/1, SKB 3559U
Attachments: SKB 3559U PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKB 3559U
Date of survey: 3/8/2018
Number of days :5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 2 August 2018 10:01 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005786MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Thursday, 2 August 2018 8:19 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005786MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.

www.avg.com



UOB

THERE'S A CARD FOR EVERYONE.

Get up to \$5250 cash credit* or 10,000 miles when you sign up now!

APPLY NOW

*T&Cs apply.

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)

New 5 Years Coe Renewal Toyota Estima 2.4A



\$5800 Downpayment Monthly
From \$938 Onwards. Lowest
3.68%P.A@Gv Cars Financing
GV Credit Pte Ltd StarAd.



ABWIN **ONE-STOP**
MOTORING SOLUTIONS

[VIEW OUR PEOPLE](#)

Browse by Category Sort by Date Posted 20 results/page

6 vehicles

mercedes benz b160

Advanced Search  Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	mercedes benz b160		Any	Any	2011	Any	Any	Any	Available
	Mercedes-Benz B-Class B160		\$46,800	\$10,640 /yr	04-Nov-2011	1,498 cc	-	Hatchback	Available
Original Condition, Huge Interior And Space, Stability And Easy Handling, Cabin Height Suitable For Elderly In And Out. In-House Or Bank Loan Available, Please Contact Our Friendly Sales Staff For Arr...									
Henly Enterprises Co									
Posted: 03-Aug-2018 Tags: 2011 Mercedes-Benz B160, Mercedes-Benz B160, Mercedes-Benz, B160, Used Mercedes-Benz									
	Mercedes-Benz B-Class B160		\$41,800	\$10,530 /yr	27-May-2011	1,498 cc	89,000 km	Hatchback	Available
Cheapest! Fully Agent Maintained! Excellent Condition! Guaranteed No Repair Needed! Low Down Payment! 100% Accident Free! Up To 90% Loan! Flexible Financial Package For All Requirements, High Trade In...									
Autotruster Traders Pte Ltd									
Posted: 31-Jul-2018 Tags: 2011 Mercedes-Benz B160, Mercedes-Benz B160, Mercedes-Benz, B160, Used Mercedes-Benz									
	Mercedes-Benz B-Class B160		\$44,800	\$10,690 /yr	02-Sep-2011	1,498 cc	105,000 km	Hatchback	Available
New Arrival. Lady Owner Very Well Kept And Maintained Pristine Condition From Inside Out! View To Believe! New Car Plate With Nice Number.									
Benefit Auto Enterprise Pte Ltd									
Posted: 30-Jul-2018 Tags: 2011 Mercedes-Benz B160, Mercedes-Benz B160, Mercedes-Benz, B160, Used Mercedes-Benz									
	Mercedes-Benz B-Class B160		\$41,800	\$9,950 /yr	26-Jul-2011	1,498 cc	116,000 km	Hatchback	Available
Excellent Condition! Guaranteed NO Repair Needed! Low Down Payment! 100% Accident Free! Flexible Financial Package For All Requirements, High Trade In Welcome, Call Now, View It To Believe!									
ABWIN (1994) Pte Ltd									
Posted: 28-Jul-2018 Tags: 2011 Mercedes-Benz B160, Mercedes-Benz B160, Mercedes-Benz, B160, Used Mercedes-Benz									
Car Buying Car Selling Car Ownership									
Car Aftermarket On The Move Lifestyle									
Buy Tyres Online! Latest Special Offers from Tyrepac!									
	Mercedes-Benz B-Class B160		\$42,800	\$10,770 /yr	17-Jun-2011	1,498 cc	101,000 km	Hatchback	Available
Well Maintain By Ex Owner. Luxury, Spacious And Comfortable Ride For You And Your Family. Flexible Financial Package For All Requirements. Please Call Or Visit Us Now For Further Details.									
Posted: 27-Jul-2018 Tags: 2011 Mercedes-Benz B160, Mercedes-Benz B160, Mercedes-Benz, B160, Used Mercedes-Benz									
	Mercedes-Benz B-Class B160		\$42,800	\$11,010 /yr	25-May-2011	1,498 cc	101,888 km	Hatchback	Available
Well Maintained By C&C In Original Condition, Smooth Drive. 100% Accident Free. Regularly Serviced. Please Call For An Appointment.									
Posted: 21-Jun-2018 Tags: 2011 Mercedes-Benz B160, Mercedes-Benz B160, Mercedes-Benz, B160, Used Mercedes-Benz									

Save this search criteria, to get email alerts whenever a match is found.

[Compare](#)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 8967D

Vehicle Details

Vehicle No.: SKB3559U

Vehicle to be Exported: No

Intended De-registration Date: 03 Aug 2018

Vehicle Make: MERCEDES BENZ

Vehicle Model: B 160

Primary Colour: Black

Manufacturing Year: 2011

Engine No.: 26692030912238

Chassis No.: WDD2452312J718277

Maximum Power Output: 70.0 kW (93 bhp)

Open Market Value: \$24,329.00

Original Registration Date: 23 May 2011

First Registration Date: 23 May 2011

Transfer Count: 1

Actual ARF Paid: \$24,329.00 12/64

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 22 May 2021

PARF Rebate Amount: \$14,597.00

Intended COE Rebate Details

COE Expiry Date: 22 May 2021

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$43,813.00

COE Rebate Amount: \$12,272.00

Total Rebate Amount: \$26,869.00

The information contained herein is correct as at 03 Aug 2018

OK

EVER SEN AUTO SERVICE

BLK 3022A UBI ROAD 1 #01-49

SINGAPORE 408716

Tel No. : 67437111 Fax No. : 67489611

E-Mail : eversenauto@singnet.com.sg

Buss. Reg. No. : B24044500/K

marcus chue @ lkk auto . com

FIRST CAPITAL INSURANCE LIMITED

6 RAFFLES QUAY #21-00

SINGAPORE 048580

30 ROBINSON RD #10-01 ROBINSON TOWER S048546

Attention : Motor Claim Department

Contact : 62222311 65073848 Motor claim Fax No. : 62223547 65073849

Estimate : TI18/013

Date : 30/07/2018

Vehicle Num. : SKB 3559 U

Make/Model : MERCEDES B 160

Chassis/Eng# :

Accident Date : 28/07/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.		DOOR ASSY REAR RH	1536.00	1,800.00
2.		DOOR PROTECTOR - REAR RH	150.00	150.00
3.		CHROME MOULDING	125.00	125.00
4.		DOOR WEATHERSTRIP - REAR RH	230.00	230.00
5.		DOOR LOCK INNER REAR RH	585.00	585.00
6.		DOOR HINGE REAR RH	285.00	285.00
7.		FENDER - REAR RH	3,100.00	3,100.00
8.		FENDER PROTECTOR - REAR RH	100.00	100.00
9.	RH	SIDE SKIRTING	370.00	370.00
10.		SEAL KIT QUATER GLASS	100.00	100.00
List Total S\$:				6,845.00
20.00% Discount S\$:				1,369.00
				5,476.00

LABOUR :

ACCIDENT REPAIR PANEL BEATING
TRANSFER ACCESSORIES TO NEW DOOR
RESPRAY PAINT WORK ON REPAIR AREA
WIRING SERVICE
COMPUTER RESET AND CALIBRATION FUNCTION

700	900.00
80	200.00
600	880.00
20	150.00
11X	80.00

CONTINUE / ...

P-5211-f3

202

4169.46

5569.46

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Authorized
Inch
H/S # 4400/2
3/8/18

EVER SEN AUTO SERVICE

BLK. 3022A UBI ROAD 1 #01-49

SINGAPORE 408716

Tel No. : 67437111 Fax No. : 67489611

E-Mail : eversenauto@singnet.com.sg

Buss. Reg. No. : B24044500/K

FIRST CAPITAL INSURANCE LIMITED

6 RAFFLES QUAY #21-00

SINGAPORE 048580

30 ROBINSON RD #10-01 ROBINSON TOWER S048546

Attention : Motor Claim Department

Contact : 62222311 65073848 Motor claim Fax No. : 62223547 65073849

Estimate : T118/013

Date : 30/07/2018

Vehicle Num. : SKB 3559 U

Make/Model : MERCEDES B 160

Chassis/Eng# :

Accident Date : 28/07/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		REMOVE AND REFIX QUATER GLASS		115 160.00 X
		Labour Total S\$:		2,370.00

SingDollars : Seven Thousand Eight Hundred Forty-Six Only

Total S\$: 7,846.00

=====

EVER SEN AUTO SERVICE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18014051/Uvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7716E	Veh. Inspected	SKB 3559U	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18005786MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	02/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ B160 (A)	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WDD2452312J718277	Colour	BLACK	
Odometer	126197	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 ZR17	DUNLOP	6 mm	
L/H Front Tyre	215/45 ZR17	DUNLOP	6 mm	
R/H Rear Tyre	215/45 ZR17	DUNLOP	6 mm	
L/H Rear Tyre	215/45 ZR17	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/07/2018	Inspection Date	03/08/2018	
Survey held at	EVER SEN AUTO SERVICE BLK 3022A UBI ROAD 1 #01-49 SINGAPORE 408716			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKB 3559U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	DOOR ASSY REAR RH	BADLY DENTED	1,800.00	1,556.21
1	DOOR PROTECTOR-REAR RH	BENT	150.00	150.00
1	CHROME MOULDING	NECESSARY	125.00	85.00
1	DOOR WEATHERSTRIP-REAR RH	NECESSARY	230.00	230.00
1	DOOR LOCK INNER REAR RH	NOT NECESSARY	585.00	-
1	DOOR HINGE REAR RH	NOT NECESSARY	285.00	-
1	FENDER-REAR RH	BADLY DENTED / BUCKLED	3,100.00	3,090.62
1	FENDER PROTECTOR-REAR RH	CUT	100.00	100.00
1	RH SIDE SKIRTING	TO REPAIR SEE LABOUR	370.00	-
1	SEAL KIT QUATER GLASS	NOT NECESSARY	100.00	-
	LESS 20% DISCOUNT		-1,369.00	-1,042.37
			5,476.00	4,169.46
	LABOUR			
	ACCIDENT REPAIR PANEL BEATING INCLUSIVE OF THE REPAIR OF RH SIDE SKIRTING.		900.00	700.00
	TRANSFER ACCESSORIES TO NEW DOOR.		200.00	80.00
	RESPRAY PAINT WORK ON REPAIR AREA.		880.00	600.00
	WIRING SERVICE.		150.00	20.00
	COMPUTER RESET AND CALIBRATION FUNCTION.	NOT NECESSARY	80.00	-
	REMOVE AND REFIX QUATER GLASS.	NOT NECESSARY	160.00	-
			2,370.00	1,400.00
	GRAND TOTAL		7,846.00	5,569.46
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,400.00

Report Ref No. CS/FCI18014051/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.