

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4126J
 Ref. No : TAX/07/18/2127
 Reg. Date : 08/11/2013
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : KOH TIEN HUAT
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 27/07/2018 07:34:00 AM
 Accident Reported Date / Time : 27/07/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024097243
 Special Instruction to ARC, if any :
 SLH4549Z - AIG - LKK
 Prepared Date : 27/07/2018 10:58:28 AM



LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Tanjoh 27485749
 'wp'
 Lurpsun.
 Resurvey after repair.
 06 days
 Surelkhawto.wm.
 30/7/18 0615.

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U30-5703150

Mileage

: 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,690.00	0.00
Total Spray Painting Charges	: 2,754.00	0.00
Total Material Charges	: 12,418.75	12,418.75
Other Charges	: 2,025.00	0.00
TOTAL	: 18,887.75	0.00
Lum Sum Total	: 18,900.00	0.00
No. of Repair Days	: 10.00	0.00
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 28/07/2018 09:09:20 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 28/07/2018 09:07:42 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 7/28/2018 9:08:15 AM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,690.00	0.00
Total Labour	1,690.00	0.00 800

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 100
TO RESPRAY SPOILER	180.00	0.00 100
TO RESPRAY REAR PANEL	180.00	0.00 100
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00 100
TO RESPRAY REAR MEMBER,LH	180.00	0.00 X
TO RESPRAY REAR MEMBER,RH	180.00	0.00 X
TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0.00 14 X
TO RESPRAY BATTERY PANEL	180.00	0.00 X
TO RESPRAY TROUGH BACK DOOR RH	180.00	0.00 X
TO RESPRAY REAR FENDER RH	378.00	0.00 X
Total Spray Painting & Panel Beating	2,754.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 30
TO REMOVE / REFIT SEAT	120.00	0.00 X
TO REMOVE & REFIT EXHAUST	120.00	0.00 X
TO ALIGN CHASSIS	350.00	0.00 X
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 ✓
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00 X
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 60
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00 120
TO REMOVE AND REFIT WIRE HARDESS	250.00	0.00 X
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 60
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	2,025.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace <i>de</i>	No
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace <i>de</i>	No
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace <i>de</i>	No
76087-47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace ?	No
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace <i>de</i>	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace <i>bt</i>	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace <i>bt</i>	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace ?	No
39997-30070			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10.00	141.66	Replace	Replace ?	No
52592-47021			BUMPER SEAL, RR LH	1	88.90	25.00	66.67	Replace	Replace ?	No
52591-47021			BUMPER SEAL, RR RH	1	65.70	25.00	49.27	Replace	Replace ?	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace <i>de</i>	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace <i>de</i>	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace <i>de</i>	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace <i>de</i>	No
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	25.00	385.87	Replace	Replace <i>de</i>	No
58327-47020			EXHAUST HEAT SHIELD, REAR	1	107.40	25.00	80.55	Replace	Replace ?	No
7430-47380			EXHAUST TAIL PIPE	1	656.20	25.00	492.15	Replace	Replace X	No
7565-2030			SUPPORT, EXHAUST REAR	2	33.60	25.00	50.40	Replace	Replace X	No
7005-7241			TAILGATE ASY	1	1,007.90	25.00	755.92	Replace	Replace <i>bt</i>	No
5574-7020			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25.00	22.05	Replace	Replace <i>de</i>	No
5573-7080			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25.00	22.05	Replace	Replace <i>de</i>	No
5575-7030			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25.00	22.05	Replace	Replace <i>de</i>	No
	COMMO N		SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Replace <i>de</i>	No
8810-7010			TAILGATE DOOR HINGE LH/RH	2	58.30	25.00	87.45	Replace	Replace <i>bt</i>	No
9350-7030			TAILGATE DOOR LOCK	1	444.10	25.00	333.07	Replace	Replace <i>bt</i>	No
9415-7020			TAILGATE LOCK, COVER	1	15.70	25.00	11.77	Replace	Replace ?	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
8960- W532			TAILGATE DOOR STAY LH	1	241.50	25.00	181.12	Replace	Replace ☒	No
8950- W542			TAILGATE DOOR STAY RH	1	241.50	25.00	181.12	Replace	Replace ☒	No
7881- 17022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace <i>ant</i> ☒	No
7751- 17040C0			TAILGATE TRIM, LOWER	1	180.70	25.00	135.52	Replace	Replace ☒	No
7750- 17071C0			TAILGATE, BOARD ASSY	1	246.90	25.00	185.17	Replace	Replace ☒	No
76801- 17070-B0			TAILGATE OUTSIDE GARNISH	1	504.90	25.00	378.67	Replace	Replace <i>?</i> ☒	No
75310- 17020		6505639	EMBLEM REAR	1	60.30	25.00	45.22	Replace	Replace <i>ant</i> ☒	No
75374- 17051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace <i>ne</i> ☒	No
75442- 17030			NAME PLATE (PRIUS)	1	60.80	25.00	45.60	Replace	Replace <i>ne</i> ☒	No
75443- 17030			NAME PLATE (TOYOTA)	1	51.90	25.00	38.92	Replace	Replace <i>ne</i> ☒	No
	REAR		NUMBER PLATE	1	30.00	0.00	30.00	Replace	Replace <i>bt</i> ☒	No
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace <i>dp</i> ☒	No
1271- 13011		6505463	LICENSE PLATE LAMP	2	35.70	10.00	64.26	Replace	Replace ☒	No
19431- 17010			STRIKER, BACK DOOR	1	48.90	25.00	36.67	Replace	Replace <i>bt</i> ☒	No
14840- 18040	REAR		SWITCH ASSY, BACK DOOR OPENER	1	146.10	10.00	131.49	Replace	Replace ☒	No
12184- 17370			WIRE, BACK DOOR, NO.1	1	582.40	10.00	524.16	Replace	Replace ☒	No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace <i>ner</i> ☒	No
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace <i>ne</i> ☒	No
18307- 17060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace <i>bt</i> ☒	No
14718- 17031B0			END PANEL COVER, DECK TRIM HOLE	1	46.10	25.00	34.57	Replace	Replace <i>?</i> ☒	No
14716- 17031B0			END PANEL COVER, DECK TRIM, RR	1	121.10	25.00	90.82	Replace	Replace <i>?</i> ☒	No
18336- 2090			REINFORCEMENT, RR	2	34.60	25.00	51.90	Replace	Replace <i>?</i> ☒	No
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace <i>ner</i> ☒	No
16085- 17910		6505620	SPOILER REAR	1	953.70	25.00	715.27	Replace	Replace ☒	No
18311- 17071		6505523	SPARE TYRE PANEL	1	667.70	25.00	500.77	Replace	Replace <i>KY</i> ☒	No
17604- 17030			MEMBER SUB-ASSY, RR LH	1	174.10	25.00	130.57	Replace	Replace ☒	No
17603- 17030			MEMBER SUB-ASSY, RR RH	1	174.10	25.00	130.57	Replace	Replace ☒	No
11931- 17020			CARRIER, SPARE	1	19.70	25.00	14.77	Replace	Replace ☒	No
14778- 17050			PROTECTOR, SPARE	1	143.70	25.00	107.77	Replace	Replace ☒	No
14777- 17090			CUSHION, SPARE WHEEL	1	230.80	25.00	173.10	Replace	Replace ☒	No
			BATTERY	1	278.00	10.00	250.20	Replace	Replace ☒	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
4481-17050			BATTERY CLAMP	1	16.10	25.00	12.07	Replace	Replace ☒	No
4440-17030			BATTERY TRAY	1	42.80	25.00	32.10	Replace	Replace ☒	No
2161-17B22			WIRE, FLOOR	1	1,675.00	10.00	1,507.50	Replace	Replace ☒	No
8302-17030			FLOOR PANEL RR/RH	1	209.90	25.00	157.42	Replace	Replace ☒	No
4993-17020			BOX, DECK FLOOR, RR	1	649.70	25.00	487.27	Replace	Replace ☒	No
8416-17030B3			BOX, RR FLOOR, BOARD	1	679.60	25.00	509.70	Replace	Replace ☒	No
8427-17040			SPACER, RR FLOOR	1	130.60	25.00	97.95	Replace	Replace ☒	No
8490-17140B0			BOARD ASSY, RR RH	1	379.20	25.00	284.40	Replace	Replace ☒	No
8415-17030			BOARD, RR FLOOR	1	392.30	25.00	294.22	Replace	Replace ☒	No
4740-17031B2			PANEL ASSY, DECK LH	1	307.00	25.00	230.25	Replace	Replace ☒	No
4730-17031B2			PANEL ASSY, DECK RH	1	307.00	25.00	230.25	Replace	Replace ☒	No
2563-17010			TAIL LAMP BRACKET, LH	1	30.70	25.00	23.02	Replace	Replace ☒	No
1561-17170		6505461	TAIL LAMP LH	1	548.40	10.00	493.56	Replace	Replace ☒	No
2562-17010			TAIL LAMP BRACKET, RH	1	30.70	25.00	23.02	Replace	Replace ☒	No
1551-17180		6505462	TAIL LAMP RH	1	557.80	10.00	502.02	Replace	Replace ☒	No
1621-17030			TROUGH, BACK DOOR	1	110.90	25.00	83.17	Replace	Replace ☒	No
1604-17090			FENDER RR/RH	1	766.80	25.00	575.10	Replace	Replace ☒	No
5637-17021		6505480	FENDER LINER RR/RH	1	141.30	25.00	105.97	Replace	Replace ☒	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ☒	No
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ☒	No
2710-17130			QUARTER GLASS RR/RH	1	846.50	25.00	634.87	Replace	Replace ☒	No
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace ☒	No
2940-6060			DUCT ASSY, QUARTER	1	70.40	25.00	52.80	Replace	Replace ☒	No
TOTAL MATERIALS								15,523.63	15,523.44	
TOTAL MATERIALS(Discounted)							12,418.75	12,418.75		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									