



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18014204/Nea3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:JAS TAN			Date : 10-11-2020	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 330S	Veh. Inspected	SG 1034J	
Policy No.	GA192199	Coverage (\$)	0.00	
Claim No.	S8M00QV6	Excess (\$)	0.00	
Assign From		Assign Date	03/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ CITARO MB	c.c	6374	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WEB62808323130288	Colour	WHITE	
Odometer	193288	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/70 R22.5	FIRENZA	5 mm	
L/H Front Tyre	275/70 R22.5	FIRENZA	5 mm	
R/H Rear Tyre	275/70 R22.5	FIRENZA	6 mm	
L/H Rear Tyre	275/70 R22.5	FIRENZA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/08/2018	Inspection Date	03/08/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		0.500 Working Days		