



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18014206/Aga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 25-09-2020



ATTN:VALE

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLM 9841U	Veh. Inspected	SLU 3332U
Policy No.	VPA/P1929871	Coverage (\$)	0.00
Claim No.	S8M00Q9B	Excess (\$)	0.00
Assign From		Assign Date	03/08/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA ODYSSEY	c.c	2356
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	RC11127407	Colour	RED
Odometer	14391	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	DUNLOP	6 mm
L/H Front Tyre	215/55 R17	DUNLOP	6 mm
R/H Rear Tyre	215/55 R17	DUNLOP	6 mm
L/H Rear Tyre	215/55 R17	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	29/07/2018	Inspection Date	06/08/2018
Survey held at	JACK CARS ENTERPRISE PTE LTD BLK 3007 UBI ROAD 1 #01-450 SINGAPORE 408700		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-------------------------------------	-----------------------