

2/03/2001

ASS. REC. BY:

REF:

C/10018014211/Zc

Special instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Kawafale Kamea

of

SPF

Date/Time:

2/8/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FQ6299E

Insured:

at Workshop m/s

Tel:

of

Policy No:

MHASPF06000004093

Claim No:

TP/1P/42503/2018

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/7/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction ( ) Estimate

FQ6299E-X.

SSD/8

③

M/cycle FQ6629E

Rohaizal (LKKAUTO)

**From:** Kamaliah KAMIS (SPF) <Kamaliah\_KAMIS@spf.gov.sg>  
**Sent:** Thursday, 2 August 2018 1:02 PM  
**To:** Rohaizal (LKKAUTO)  
**Cc:** Bryan Ang (LKKAUTO); SPF-TP FAIT  
**Subject:** Mechanical Inspection Report Request

Hi Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the 10 vehicles below:

a) Case IAFP-IB-20180731 - Mechanical Inspection of Motor Car, SDV234D (TP/IP/40617/2018)

On 17.7.2018 at about 6.58 am, motor car was driving along Crawford Street towards Republic Avenue on the right lane of 2 lanes road when after the pedestrian crossing, his front left portion collided onto a pedestrian (deceased) whom had crossed from his right to left. Pedestrian sustained head injuries and conveyed to TTSH. He was pronounced dead on the same day at 12.55 pm.

Vehicle to be inspected: SDV234D – Driver (Accused)

IO In-Charge: SIO Vilton

b) Case IAFP-IB-20180731 - Mechanical Inspection of Motor Car, SJW6686S (TP/IP/42503/2018)  
c) Case IAFP-IB-20180731 - Mechanical Inspection of Motorcycle, FQ6629E (TP/IP/42503/2018)

On 27 July 2018 (Friday) at or about 8.46 p.m., the Accused was driving the motor car, SJW 6686 S, on the centre lane of the 3 lanes road along Lentor Avenue towards Yishun Avenue 1. The Accused then change lane to the right and encroached into the travelling path of the Deceased's motorcycle. Due to the encroachment, the Deceased lost control of the motorcycle and skidded to its right along the centre divider.

Vehicle to be inspected: SJW6686S – Driver (Accused)

Vehicle to be inspected: FQ6629E – Rider (Deceased)

IO In-Charge: SIO Shahril

d) Case IAFP-IB-20180731 - Mechanical Inspection of Motor Taxi, SHB2124H (TP/IP/38041/2018)

On 30 June 2018 (Saturday) at or about 7.39 p.m., the accused was driving his motor taxi SHB2124H along Republic Avenue towards the direction of Republic Boulevard when he lost control of his motor taxi and collided into the motorcycle who was travelling on the opposite direction. The accused claimed that that the front tyre had punctured thus causing the motor taxi to veer to the right.

Vehicle to be inspected: SHB2124H – Driver (Accused)

IO In-Charge: SIO Shahril

e) Case: IAFP-IB-20180731 - Mechanical Inspection of Motor Lorry; YN2898T (TP/IP/38773/2018)

On 8 July 2018 at about 11.32pm, motor lorry YN 2898 T was travelling on the right lane of 2 lanes road along Jurong East Avenue 1 towards the direction of Toh Guan Road. Somewhere after lamp post 66, motor

## Celine Fong (LKKAUTO)

From: Kamaliah KAMIS (SPF) <Kamaliah\_KAMIS@spf.gov.sg>  
Sent: Thursday, 2 August 2018 1:02 PM  
To: Rohaizal (LKKAUTO)  
Cc: Bryan Ang (LKKAUTO); SPF-TP FAIT  
Subject: Mechanical Inspection Report Request

Hi Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the 10 vehicles below:

a) **Case IAFP-IB-20180731 - Mechanical Inspection of Motor Car, SDV234D (TP/IP/40617/2018)**

On 17.7.2018 at about 6.58 am, motor car was driving along Crawford Street towards Republic Avenue on the right lane of 2 lanes road when after the pedestrian crossing, his front left portion collided onto a pedestrian (deceased) whom had crossed from his right to left. Pedestrian sustained head injuries and conveyed to TTSH. He was pronounced dead on the same day at 12.55 pm.

**Vehicle to be inspected: SDV234D – Driver (Accused)**

IO In-Charge: SIO Vilton

b) **Case IAFP-IB-20180731 - Mechanical Inspection of Motor Car, SJW6686S (TP/IP/42503/2018)**

c) **Case IAFP-IB-20180731 - Mechanical Inspection of Motorcycle, FQ6629E (TP/IP/42503/2018)**

On 27 July 2018 (Friday) at or about 8.46 p.m., the Accused was driving the motor car, SJW 6686 S, on the centre lane of the 3 lanes road along Lentor Avenue towards Yishun Avenue 1. The Accused then change lane to the right and encroached into the travelling path of the Deceased's motorcycle. Due to the encroachment, the Deceased lost control of the motorcycle and skidded to its right along the centre divider.

**Vehicle to be inspected: SJW6686S – Driver (Accused)**

**Vehicle to be inspected: FQ6629E – Rider (Deceased)**

IO In-Charge: SIO Shahril

d) **Case IAFP-IB-20180731 - Mechanical Inspection of Motor Taxi, SHB2124H (TP/IP/38041/2018)**

On 30 June 2018 (Saturday) at or about 7.39 p.m., the accused was driving his motor taxi SHB2124H along Republic Avenue towards the direction of Republic Boulevard when he lost control of his motor taxi and collided into the motorcycle who was travelling on the opposite direction. The accused claimed that that the front tyre had punctured thus causing the motor taxi to veer to the right.

**Vehicle to be inspected: SHB2124H – Driver (Accused)**

IO In-Charge: SIO Shahril

e) **Case: IAFP-IB-20180731 - Mechanical Inspection of Motor Lorry; YN2898T (TP/IP/38773/2018)**

On 8 July 2018 at about 11.32pm, motor lorry YN 2898 T was travelling on the right lane of 2 lanes road along Jurong East Avenue 1 towards the direction of Toh Guan Road. Somewhere after lamp post 66, motor lorry spotted the deceased crossing the road from the right to the left side. Motor Lorry applied brakes but could

not stop in time and collided onto Deceased. As a result of the accident, Deceased became unresponsive and started to bleed from the right side of his head. He was conveyed by ambulance in an unconscious state to National University Hospital (NUH). On 9 July 2018 at about 2.48am, Deceased succumbed to his injuries and was pronounced dead by Dr. Cheng Tai Win in NUH.

**Vehicles to be inspected: YN2898T – Driver (Potential Defendant)**

IO In-Charge: SIO Yazid

**f) Case: IAFP-IB-20180731 - Mechanical Inspection of Motorcycle; DBC8052 (TP/IP/40567/2018)**

On 17 July 2018 (Tuesday) sometime before 6.21 a.m., the rider of motorcycle DBC 8052 was believed to have self-skidded. The Deceased was sent to the Ng Teng Fong General Hospital (NTFGH) however, he succumbed to his injuries and was pronounced dead in hospital by Dr Chu Yap Sun, Michael at 7.25 a.m.

**Vehicle to be inspected: DBC8052 - Rider (Deceased)**

IO In-Charge: SIO Yazid

**g) Case IAFP-IB-20180731-Mechanical Inspection of Motorcycle; FBF228E (TP/IP/41029/2018)**

On 19/07/2018 at about 4.13 am, the Deceased was riding motor cycle FBF 228 E along Bartley Road East towards Tampines Avenue 10, near to lamp post 29/1AF, when he lost control and self-skidded. The rider (Deceased) suffered fatal injuries and passed away at scene. He was pronounced dead by paramedic, Shafiee at 4.36 am.

**Vehicle to be inspected: FBF228E - Rider (Deceased)**

IO In-Charge: SIO Farhan

**h) Case IAFP-IB-20180731-Mechanical Inspection of Motor Lorry; GBD9032D (TP/IP/39647/2018)**

**i) Case IAFP-IB-20180731-Mechanical Inspection of Motor Taxi; SHA7941M (TP/IP/39647/2018)**

**j) Case IAFP-IB-20180731-Mechanical Inspection of Motorcycle; NCY1262 (TP/IP/39647/2018)**

On 12 July 2018 at about 5.11 pm, motor taxi's video footage revealed that the deceased was riding on his motorcycle along PIE (Tuas), 36.5 km on left of the 2-lanes road when the deceased suddenly collided into the rear of a motor lorry that was travelling on left lane, directly ahead of the deceased. Due to the impact, the deceased skidded to the right side and encroached into the travel path of the incoming motor taxi that was travelling on right lane, diagonally behind the deceased. As it was too sudden, the motor taxi was unable to brake in time hence collided into the deceased. As a result of the accident, the deceased was conveyed in a critical condition to National University Hospital by an ambulance. However on the same day at 6.53 pm, the deceased succumbed to his injuries and he was pronounced dead by Dr Chai Chew Yen in the said hospital.

**Vehicle to be inspected: GBD9032D - Driver (Involved Party)**

**Vehicle to be inspected: SHA7941M - Driver (Involved Party)**

**Vehicle to be inspected: NCY1262- Rider (Deceased)**

IO In-Charge: IO Kamaliah Kamis

2. These request has been approved by my management.

3. Thank you Sirs.

Cc: Bryan Ang (LKK) & FAIT Team, fyip

Best regards,

Kamaliah Kamis (Miss)  
Investigation Officer | Fatal Accident Investigation Team  
Traffic Police | Singapore Police Force  
DID: (65) 6547 6435 | FAX: (65) 6547 6352



**HOME TEAM**  
TRANSFORMATION 2025  
One Home, One Team  
Building Our Future Together

**WARNING** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."