

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Chin Kiat

Date: 07 Aug 2018

Preliminary Advice

Vehicle No	: GBD5548J	Accident Date	: 31/07/2018
Make	: MITSUBISHI CANTER	Policy No.	: 29086229MKC
Assignment Date	: 06/08/2018	Excess	: S\$600.00
Date of Inspection	: 06/08/2018	Est. Duration of Repair	: 10.00
Inspection At	: SMRT AUTOMOTIVE SERVICES PTE LTD (WOODLANDS) 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	31,504.46
Revised Amount	:S\$	8,137.38
Check Items (Estimated)	:S\$	20,828.50
Total	:S\$	28,965.88
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	56,000.00
COE / PARF Rebate	:S\$	25,584.00
Salvage Value	:S\$	
Margin for Repair	:S\$	30,416.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.