

REPAIR ESTIMATE

VEHICLE NO : SH 9179S

30/7/2018 15:01

MAKE :

MODEL : TOYOTA PRIUS

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
PANEL SUB-ASSY, REAR DOOR, RH <i>X repair</i>			\$ 1,227.00
REINFORCE SUB-ASSY, ROCKER, OUTER RH <i>X repair</i>			\$ 519.80
<i>Front Door (RH) X repair</i>			
<i>Rear Fender (RH) X repair</i>			
SUB TOTAL			\$ 1,746.80
LESS 25%			\$ 436.70
DISCOUNTED TOTAL			\$ 1,310.10
REAR DOOR COMFORT & APPS STICKER <i>✓</i>			\$ 80.00
<i>Front Door</i>			
LABOUR CHARGE			
Panel Beating			\$ 300 350.00
Spray Painting Charge			\$ 1000.00 800
Wiring Charge			\$ 50.00 <i>X</i>
Towing Charge			\$ 60.00 <i>X</i>
Transfer of Door			\$ 120.00 <i>X</i>
TOTAL LABOUR			\$ 1,080.00
ESTIMATE TOTAL			\$ 2,470.10

NETT

*Kaharick**1/8/18 1600h.**20/7/18**PIR**Atk Rpi p Lts*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.