

REF: C93/FCL7019415/610⁵²

Special Instruction:

US: ~~\$116000~~ ~~\$2600~~
46600

ASSIGNMENT (Office)

From (Person): Karen Tan of FCL Date/Time: 02082018
Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: Impact Analysis

Workshop: Triple-T Automotive

OD/FP Re-inspection / Evaluation

To Inspect Vehicle No: YN 6837T Insured: SHB 6376X
at Workshop m/s Triple-T Automotive Tel: Irene 63851171
of Blk 6 Defu Lane 10 #01-556

Policy No: Claim No: D17009514MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 07-10-2017
(Client's Record)

08082018 (Tuesday) @ 4:30pm

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 16 days)

Date/Time: Submit Final Fig 42950, 12 days (Red \$ 4400 / 9 %; Original days)

Date/Time	Action/Instruction
	19 Defu Lane 8 Singapore 539320
	YN 6837T - C93/FCL7019415/WB52
	SHB 6376X - NS/INC16023139/HIGH2
	Front portion: L/S \$9876.84
	Rear portion: PIP \$32,350.00
	Repair days: 12 days
	Total: \$42200.00

[Signature]
2/10/2018

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 03 OCT 2018

Para(3) : Nett Value

36x15=540
540+170=710

Market Value :	Inspected/ Evaluated by:	Fee Charged:	Date:
Salvage Value :		Basic & Add	710
Nett Value :		Transport	50
		Photos	15
		Others	
		Total	825

- 1) Date/Time 3/10/18 File Pass to type 2) Date/Time File Return to
3) Date/Time File Pass to 4) Date/Time File Return to
5) Date/Time File Pass to 6) Date/Time File Return to

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s:

of:

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

	
N/S	O/S

Bal. or Market Value:

\$65K Probk

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12

days:

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

YN6837T

Yr Regn:

19 Nov 2014

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mit Canter

c.c.

2998

Colour:

yellow

A/C:

Insured / Std / NI / NA

Sp. Reading:

139938

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

FEB71GA 000 33

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M/L / S/Rim / STD A/Rim or

Tyre Size:

F:

215/75 R 17.5

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Ling long

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

08-08-18

Survey held at:

19 Refu lane 8

4:30pm


Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

limit \$23K + \$30K


2/10/2018

Date/Time: File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time: File Return to?

2)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

\$ - RS - \$

Photos

Others

TOTAL

ASSIGNMENT

Form 1000

DATE

Vehicle YN683TT 2014 NOV 19

Estimated Cost

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Vehicle No. YN683TT

Make Mitsubishi

2014

Description Triple - T Automobile

Colour Yellow

A.D. Insured: Std / N / NA

19 Date Lane 8

Sp Reading 109172

T.P. Insured: Std / N / NA

Insurance

Eng No.

Policy No.

C.No. FEB71GA 00033

Claims No.

Gen. Cond. Good / Fair / Poor / Burnt

Car Insured

Excess

Steering Normal / Jammed / Leaked / Burnt or

(Owners Record)

Brake Normal / Jammed / Leaked / Burnt or

Make of Vehicle

Mod. Nil / S/Rim / STD A/Bump

Body Condition

Remark: The veh had commenced its repair at the time of inspection.

Tyre Size F 215 / 75R17.5
R 215 / 75R17.5 (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Bpl. or Market Value

D&C Accident Report

Consistent? Yes or No

G.A. PR Seen

Consistent? Yes or No

Est. Repairs

days Res. Yes or No

Lump Sum

to 3 Val. Yes or No

CA / REV / REP. / 24 HRS

*, Vehicle IN / OUT

Date

Person Contacted

Front

Rear

R.Bal

2

mm

R.Bal

2

mm

L.Bal

2 / 2

mm

L.Bal

2 / 2

mm

D.O.A

7/10/2017

D.O.A

10/10/2017

Survey held at

19 Date Lane 8 1039m

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt and Back

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Accident Report Not Available.

Do not put market value at the moment - celine / catharine

Print the P & Pass to

02-11-2017

Print the P & Return to



Prel. Report



Final Report

Days Of Repair

Resurvey No. of Trip:

Survey Fee

Transport

Fuel

Other

Total

Report Format

PRS.

Lump Sum / L.B.

Add Fee:



Site Insp. \$



Inter. Insp. \$



Tech. Insp. \$



Legal Fee \$



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/10/2017 14:52
Date Of Accident	07/10/2017 03:30
Exact Location Of Accident	CTE TOWARDS CITY 7.5 KM
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN6837T
Insured/Policyholder	
Name Of Registered Owner	CHYE THIAM MAINTENANCE PTE LTD
Co Reg No	198801700E
Email Address	CLARENCE_SEAH@CHYETHIAM.COM
Mobile Phone No	(LOCAL) +65-87814020
Alternative Phone No	OFFICE-87814020
Vehicle Particulars	
Manufacturer	MAZDA
Model	CANTER
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5071086573-02
Cover Note Number	
Driver	
Name of Driver	OH BOON CHYE
NRIC No	S6838965H
Date Of Birth	03/10/1968
Occupation	OUTDOOR
Date Of Driving Pass	02/06/1992
Driving Experience	25 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 109 ANG MO KIO AVE 4 #10-10 S(560109)

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? YES

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name KEBUN BARU NPP

Police Station Address ROAD: 111 ANG MO KIO AVE 4 , POSTCODE: 560111 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: - FAX NO:

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHB6376X

Vehicle Make/Model/Colour MERE220

Details Of Properties

Name of Driver CHOW KIN TONG

NRIC/Passport Number S1330737G

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 1

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number YN5541C
Vehicle Make/Model/Colour CANTER-3.0 D FE83 (M)
Details Of Properties
Name of Driver
NRIC/Passport Number S6838390J
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver) 4

Details of Witness

Name
Phone Number
Email Address

DETAILS OF INJURED PERSON 1

Name OH BOON CHYE
Approximate Age
Injuries Sustain
Injured person in which vehicle? YN6837T
Were seat belts worn? YES
Was injured conveyed to hospital by ambulance?
Address
Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurers or insurers to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any late reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claim and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, repairs or notices) to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or talk to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
Date & Time: 3.20 PM 9/10

Reporting Centre - Personal's Signature
Name: Louis Siew
Date & Time:

Sketch Plan #2

SKETCH PLAN


A-YN6837T

B-SHB6376X

C-YN5541C

Date - 07/10/17

Time - 0330



CTE Towards City 7.5km

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As according to Police Report:

A large, stylized handwritten signature, likely of the reporting officer, written across the middle of the accident description section.

DECLARATION



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Officer's Signature
Name:
RPLC/TAN No.:

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20171008/2051

Police Station Of Origin:
Kebun Baru NPP
111 Ang Mo Kio Avenue 4 SINGAPORE
560111
Tel No. 1800-4589999

1 of 3

Report No. T/20171008/2051

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/10/2017 14:43		Vide Report No.:		Station Diary No.: 37	
Informant's Particulars					
Name of Informant: OH BOON CHYE			Address: APT BLK 109 ANG MO KIO AVENUE 4 #10-10 SINGAPORE 560109		
ID Type / ID No.: NRIC NO / S6638965H			Contact No.: Home/Office: Mobile: 87814020		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 49	Date of Birth: 03/10/1968	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Highway Maintenance			Driving Licence Information: Class: 4 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 07/10/2017 03:30	Type of Location:
Location: Along Road 1 CENTRAL EXPRESSWAY				
Towards AYE				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHB6376X	Car				Seriously Damaged	0
YN5541C	Truck				Seriously Damaged	0
YN6637T	Truck				Slightly Damaged	3

POLICE REPORT



SINGAPORE
POLICE FORCE



T/20171008/2051

Police Station Of Origin:
Kebun Baru NPP
111 Ang Mo Kio Avenue 4 SINGAPORE
560111
Tel No: 1800-4589999

2 of 3

Report No. T/20171008/2051

CONTINUATION OF REPORT

Brief Details.

On 7/10/17 at around 0330hrs, I (YN6837T) was doing highway maintenance together with Mr Wee Kwang Ching) which was in front of me. Out of a sudden a taxi (SHB6376X, S1330737G, Chow Kin Tong) came from the rear and collided with me and then my truck collided with Mr Wee's truck. I was inside YN6837T and the collision caused me to be injured at my back and I felt giddy. The attachment (TMA) behind Mr Wee's truck was damaged. Both my truck and my attachment (TMA) behind was seriously damaged.

I was then conveyed to TTSH and was given 2 days of MC. Mr Wee was also injured at his back and neck area due to the impact. Mr Wee then went to Faith Healthcare (Tampines) and was given 3 days of MC. TP was at scene. Ref: E/20171007/0068. Case in-charge: TP IO Yus Mastari Tel: 65476214.

POLICE REPORT



SINGAPORE
POLICE FORCE



T/20171008/2051

Police Station Of Origin:
Kebun Baru NPP
111 Ang Mo Kio Avenue 4 SINGAPORE
560111
Tel No: 1800-4589999

3 of 3
Report No. T/20171008/2051

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
F /
Sgt 2 LIM ZHI CONG

Signature Of Informant:

[Handwritten signature]

Signature Of Interpreter:
Not applicable

Date/Time:
08/10/2017 14:43

Officer In Charge Of Case:
TP / GIT /
Sr Staff Sgt ONG YONG HOCK
Contact No.: 65476435

Classification Of Case:

Authentication Stamp
N/168

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	1700E D.O.A → 7/10/2017
Vehicle Details	
Vehicle No.	YN6837T 18 11 2017 ¹ 4 ¹⁰
Vehicle to be Exported	No 7 10 2017
Intended De-registration Date	01 Nov 2017 11 1 7
Vehicle Make	MITSUBISHI (0.4 month)
Vehicle Model	CANTER FEB71GR4SDED (CBU)
Primary Colour	White
Manufacturing Year	2014 Bd → 7 yrs 1.4 month
Engine No.	4P10B32215
Chassis No.	FEB71GA00033
Maximum Power Output	-
Open Market Value	\$34,158.00
Original Registration Date	19 Nov 2014
First Registration Date	19 Nov 2014
Transfer Count	0
Actual ARF Paid	\$1,708.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	18 Nov 2024
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	10
QP Paid	\$61,000.00
COE Rebate Amount	\$42,988.00
Total Rebate Amount	\$42,988.00

The information contained herein is correct as at 01 Nov 2017

OK

sgCARMART.COM
THE ONLY PLACE FOR SMART CAR BUYERS

sgCARMART
APP DOWNLOAD

All Car Make or Model

Search

HOME

NEW CARS

USED CARS

SELL CARS

MOTOR DIRECTORY

PRODUCT GUIDE

ARTICLES

FORUM

TOOLS & TIPS

- Who is SGB33338?
- Nissan QashQai 2014 Part 2
- Watches IV

Username / Email Add

password

Submit Q

Connect

Sign Up New Account

Forgot Password

Post an Advertisement
Sell it yourself Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Year Coo Renewal 07 Honda Stream 1.8A Sunroof



\$2800 Downpayment Monthly
From \$588 Onwards. Lowest
3.88% P.A. 5Gv Car Financing
GV Credit Pte Ltd. Starlink

PRIME MOTOR & LEASING

CHONG HONG CHIEH ENTERPRISES PTE LTD GROUP OF COMPANIES

With over 200 units of vehicles
to choose from, ranging from
all European to Japanese Makes

Browse by Category

Sort by Date Posted

40 results/page

12 vehicles

Mitsubishi Canter

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mitsubishi Canter		Any	Any	2014	Any	Any	Any	Available



Mitsubishi Fuso Canter FEB21

\$66,800

\$5,450 /yr

26-Nov-2014

2,998 cc

-

Truck

Available

Fuel Type: Diesel

We Provided 3 Months Warranty. Tip Top Condition 14Ft Fully Checker Plate Deck, Nice Number, Powerful Engine, No Repairs Needed, High Loan

ABWIN Bus Pte Ltd

Posted: 21-Oct-2017

Tags: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi

Details



Mitsubishi Fuso Canter FEB21

\$59,800

\$8,790 /yr

19-Aug-2014

2,996 cc

-

Truck

Available

Fuel Type: Diesel

Piced To Go, First Come First Serve Basis. Vehicle Ready With Full Retractable Canopy Suitable For Transportation Of Goods And Personnel.

Posted: 30-Oct-2017

Tags: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi

Details



Mitsubishi Fuso Canter FEB71

\$65,000

\$9,630 /yr

31-Jul-2014

2,998 cc

-

Truck

Available

Fuel Type: Diesel

Posted: 27-Oct-2017

Tags: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi

Details



Mitsubishi Fuso Canter FEA01

\$54,800

\$7,980 /yr

12-Sep-2014

2,996 cc

110,272 km

Truck

Available

Fuel Type: Diesel

New Paintwork. Condition As New. Very Well Maintained. Low Mileage. The Most Highly Sought After Japanese Commercial Vehicle That Canter Your Business Need. Best Economical Buy, Fuel Efficient Diesel ...

Car (S) Pte Ltd

Posted: 26-Oct-2017

Tags: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi

Details

Car Buying

Car Selling

Car Aftermarket

Buying a pre-owned car, but
Unsure of its Condition?
Get STA Car Evaluation

Car Ownership

On The Move

Lifestyle



Mitsubishi Fuso Canter FEB21

\$65,800

\$9,480 /yr

10-Oct-2014

2,998 cc

-

Truck

Available

Fuel Type: Diesel

Tip Top Condition 15Ft Wooden Deck, Power Engine, Powerful Aircon, New Paint Work, No Repair needed, High Trade And Up To 100% Loan, Call Now For Viewing And Test Drive.

Car (S) Pte Ltd

Posted: 21-Oct-2017

Tags: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi

Details



Mitsubishi Fuso Canter FEB21

-

N/A

18-Jul-2014

2,998 cc

239,277 km

Truck

Available

Fuel Type: Diesel

Auction Closing Time: 1st Nov 2017 at 11:00 PM

GST Registered. 1 Key Available. Road Tax Expiry On 17/07/2018. Mileage Of 239277km. Financing Up To 100% Possible Subject To Credit Approval. Call Us To Enquire.

Posted: 19-Oct-2017

Tags: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi

Details



Mitsubishi Fuso Canter FEB21

\$63,500

\$5,850 /yr

11-Apr-2014

2,998 cc

-

Truck

Available

Fuel Type: Diesel

Think One Automobile & Trading

Posted: 14-Oct-2017

Tags: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi

Details



Mitsubishi Fuso Canter FEA01 \$51,800 \$7,950 /yr 07-May-2014 2,998 cc - Truck Available

Fuel Type: Diesel

Full Loan. Wait No More. Under Warranty By Goldbell. Excellent Condition. New Road Tax. Free Servicing Remaining. No Income Proof Or Bank Statement Is Required. No Gimmicks. Genuine Dealer. Don't Miss...

Posted: 13-Oct-2017 Tags: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi

[Details](#)



Mitsubishi Fuso Canter FEB21 \$76,800 \$11,530 /yr 30-Jun-2014 2,998 cc - Truck Available

Fuel Type: Diesel

Class 3 With 14 Feet Freezer Truck. Well Taken Care By Owner.

Posted: 07-Oct-2017 Tags: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi

[Details](#)



Mitsubishi Fuso Canter FEB71 \$72,800 \$11,310 /yr 08-Apr-2014 2,998 cc - Truck Available

Fuel Type: Diesel

14P (4.20 Tons) With Full Canopy, VPC Required, High Trade In, High Loan, Competitive Insurance Premium. Call Now For Viewing!

Convince Auto

Posted: 20-Sep-2017 Tags: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi

[Details](#)



Mitsubishi Fuso Canter FEB21 \$61,800 \$9,130 /yr 07-Aug-2014 2,998 cc - Truck Available

Fuel Type: Diesel

Near New Condition Complete With Retractable Canopy, High Loan 100% Available

Posted: 07-Sep-2017 Tags: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi

[Details](#)



Mitsubishi Fuso Canter FEB21 \$63,500 \$9,850 /yr 11-Apr-2014 2,998 cc 91,589 km Truck Available

Fuel Type: Diesel

Think One Automobile & Trading

Posted: 04-Sep-2017 Tags: 2014 Mitsubishi Fuso, 2014 Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Mitsubishi Fuso, Fuso, Fuso, Used Mitsubishi

[Details](#)

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

40 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Mitsubishi Canter, Mitsubishi Canter Singapore, used Mitsubishi Canter Singapore, used Mitsubishi Canter, used vehicles Singapore or even buy used Mitsubishi Canter Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, massage services, real estate properties for sale, travel, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current; sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2017 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Compare

Catherine Chong (LKK Auto)

From: Irene <motor@iaconsulting.com.sg>
Sent: Thursday, 2 August, 2018 2:36 PM
To: 'Claim Workflow System'
Cc: karentan@msfirstcapital.com.sg; ASSIGNMENTS@LKKAUTO.COM; candy@iaconsultingsg.com; analysis impact
Subject: RE: Requesting for Re-Inspection Vehicle Number :YN6837T ;Our Ref No D17009514MFSH:Your Ref: CL17138 , YN6837T accident involving with SHB6376X on 07-10-2017

Dear Sir/Madam,

We refer to your email dated 11 July 2018.

We wish to inform you that our client's vehicle no. YN6837T will be available for resurvey as follow:-

Date : 08 August 2018 (Tuesday)

Time : 4:30pm

Place : 19 Defu Lane 8

Singapore 539320

Thank you.

Regards,
Irene Tan

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 11 July 2018 5:50 PM
To: motor@iaconsulting.com.sg
Cc: karentan@msfirstcapital.com.sg; ASSIGNMENTS@LKKAUTO.COM; admin-d@lkkauto.com; cwsmotorclaims@msfirstcapital.com.sg
Subject: Requesting for Re-Inspection Vehicle Number :YN6837T ;Our Ref No D17009514MFSH:Your Ref: CL17138 , YN6837T accident involving with SHB6376X on 07-10-2017

Without Prejudice

Dear Sirs,

RE-INSPECTION: THIRD PARTY VEHICLE NO: YN6837T.

We refer to the above matter.

Please note that we wish to carry out a re-inspection. Please advise the date, time, venue and person to contact at least 7 working days in advance of the appointment.

Thank you.

Yours Faithfully,

Motor Claims Department

First Capital Insurance Ltd

cwsmotorclaims@msfirstcapital.com.sg

Our reference: 1710-1415

Date: 15/11/2017

c/o Triple-T Automotive
Blk 6 Defu Lane 10
#01- 556
Singapore 539187

Dear Sirs

RE: Road Traffic Accident on 7/10/2017
Chye Thiam Maintenance Pte Ltd

In accordance with your instructions received in this office on 9/10/2017, we made arrangements to examine the vehicle on 9/10/2017 at above-mentioned address. The following data was recorded:


Vehicle details

Make	Mitsubishi	Registration	YN6837T
Model	Canter	Chassis	FEB71GA00033
Colour	Yellow	Gearbox	Manual
Odometer	109177km	Paintwork	Good
Steering	Good	Brakes	Good
Condition	Good		

Tyre Depths

Front left	215/75/17.5	85% Yokohama
Front right	215/75/17.5	85% Yokohama
Rear left	215/75/17.5	85% Yokohama
Rear right	215/75/17.5	85% Yokohama

Impact Direction & Area of Damage:



Status	REPAIRABLE
Magnitude	Medium
Legal status	Unroadworthy

Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$46,600.00 and 16 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Rear Portion

Our reference 1710-1415
Date 15/11/2017
Page 2

Section A: Damaged Parts Assessment

Part's Description	Qty	Condition As Inspected	Repairer's Estimate	Our Adjustment
Estimate cost for repair of TMA attached to YN6837T				
Model No. Alpha 70K - Truck Mounted Attenuator	1	damaged	43156.00	43156.00
Sub- Total costs			43156.00	43156.00
Percentage discount : 0%			0.00	0.00
Sub-Total costs for parts			43156.00	43156.00

Labour charges

Remove existing TMA and replace new TMA	\$1,200.00	\$1,200.00
Check Wiring & Tesitng commissiong	\$200.00	\$200.00
Remove & Refit rear deck to faciliate repair works	\$1,000.00	\$1,000.00
Specialist charges - Check alignment charges	\$450.00	\$450.00
	\$2,850.00	\$2,850.00

	Total parts	=	\$43,156.00
	Total labour	=	\$2,850.00
(Part-by-Part repair)	Total Amount	=	\$46,006.00

32350

Front Portion.

Our reference 1710-1415
Date 15/11/2017
Page 2

Section A: Damaged Parts Assessment

Part's Description	Qty	Condition As Inspected	Repairer's Estimate	Our Adjustment
--------------------	-----	------------------------	---------------------	----------------

List Items:

Front bumper (centre)	1	damaged	658.90	658.90
Front bumper side @\$250.00	2	damaged	500.00	500.00
Front bumper side fog lamp cover @\$65.50	2	damaged	131.00	131.00
Headlamp @\$552.3	2	damaged	1104.60	1104.60
Front side @\$225.50	2	damaged	451.00	451.00
Headlamp lower @\$306.50	2	damaged	613.00	613.00
Headlamp lower garnish @\$110.00	2	damaged	220.00	220.00
Front radiator grille	1	damaged	615.20	615.20
Front radiator grille logo	1	necessary	32.92	32.92
Front radiator grille emblem "MITSUBISHI"	1	necessary	108.51	108.51
Front panel	1	damaged	1015.46	X 1015.46 Repair
Front windscreen glass	1	damaged	1425.00	1425.00
Front windscreen glass rubber	1	necessary	475.21	475.21
Front door rh	1	damaged	2152.00	2152.00
Front door weatherstrip rh	1	necessary	298.00	298.00
Front door step garnish rh	1	damaged	175.90	175.90
Front door step garnish panel rh	1	damaged	285.00	X 285.00 Repair
Front aircon pipe	1 set	damaged	552.00	552.00
Tail gate	1	damaged	1688.00	1688.00
Rear side gate @\$1688.00	2	damaged	3376.00	X 3376.00
Rear deck platform	1	damaged	8000.00	X 8000.00 Repair
Rear chassis frame	1	damaged	9000.00	X 9000.00
Rear mudguard lh	1	damaged	165.00	X 165.00 N/V

Sub- Total costs

Percentage discount : 15%

Sub-Total costs for parts

33042.70	33042.70
4956.41	4956.41
28086.30	28086.30

11201.24
9521.05

Our reference 1710-1415
Date 15/11/2017

Special Nett Items:

Front number plate	1	damaged	50.00	50.00	10
Tail gate sticker 60km/h and 8 pax @\$20.00	2	necessay	40.00	40.00	30
Rear deck checker plate	1	damaged	2500.00	2500.00	X 100
Tail gate checker plate	1	damaged	850.00	850.00	250
Side gate checker plate @\$850.00	2	damaged	1700.00	1700.00	X 100
Rear canopy and cargo extender	1	damaged	15000.00	15000.00	X 100
Front door company advertisement rh	1	necessay	650.00	650.00	300
Front door LTA sticker rh	1	necessay	40.00	40.00	30
Front panel company logo	1	necessay	100.00	100.00	/
Rear deck underneath wooden frame	1	damaged	450.00	450.00	350
Front bumper clips @\$4.50	10	necessary	45.00	45.00	/
Sub-Total costs for parts			21425.00	21425.00	

1115

Parts Repair

*	*	*	0.00	0.00
Sub- Total costs			0.00	0.00
Total costs for parts			49511.30	49511.30

Our reference 1710-1415

Date 15/11/2017

Page 3

Section B: Labour Cost Calculation

	Hourly rate	Manhr. Req.	Total
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$ 48.00	65	\$ 3,120.00
Spray painting to adjacent panels. Job allowance. Paint / material.	Sub-contract work.		\$ 1,600.00
Apply rust proofing on the adjacent panels.	Sub-contract work.		\$ 250.00
Wiring / bulb checking	\$ 48.00	1	\$ 48.00
Remove / replace front windscreen glass (2-man job)	\$ 48.00	3	\$ 144.00
Remove and replace rear deck to facilitate the repair works	*	*	\$ 1,000.00
Transfer of existing front door mechanism to new door rh	\$ 48.00	1.8	\$ 86.40
Rear chassis alignment charges	*	*	\$ 650.00
Remove / refix aircon condenser and refill aircon gas	\$ 48.00	2.5	\$ 120.00
Total labour cost			\$ 7,018.40

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

Our reference 1710-1415

Date 15/11/2017


Page 4

Section C: Summary Table of Total Repair Cost

Description		Cost	
Damaged Parts Assessment (See section A)		\$49,511.30	
Replace parts		\$9,902.26	
Further discount	20%		
Recommended cost of parts replacement		\$39,609.04	(1)
Labour Cost Calculation (See section B)		\$7,018.40	(2)
Total Repair Cost (Round off to hundred)		\$46,600.00	(1) + (2)

We would recommend a sum of 92600 **\$46,600.00** and 16 working days for repair.
No further items will be approved without our expressed written agreement. Any significant additional items will be subject to a supplementary report.


Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)
B.Eng. (Hons, NUS)
Diploma.Mechanical, ITC. Mechanical & Electrical
NTC-2 Automovite Technology
Sr.MIES, Institution of Engineers, Singapore
MATAI, Maryland Association of Traffic Accident Investigators
IAARS, International Association of Accident Reconstruction Specialists
ARC #1649, CLI, CGI



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS3/FCI17019415/Grbs2-1	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 04-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SHB 6376X	Veh. Inspected	YN 6837T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17009514MFSH	Excess (\$)	0.00	
Assign From	KAREN TAN	Assign Date	02/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI CANTER	c.c	2998	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	FEB71GA00033	Colour	YELLOW	
Odometer	139938	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/75 R17.5	LING LONG	6 mm	
L/H Front Tyre	215/75 R17.5	LING LONG	6 mm	
R/H Rear Tyre	215/75 R17.5	LING LONG	6 mm	
L/H Rear Tyre	215/75 R17.5	LING LONG	6 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	07/10/2017	Inspection Date	08/08/2018	
Survey held at	19 DEFU LANE 8 SINGAPORE 539320			
Repairer	TRIPLE-T AUTOMOBILE			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 6837T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (CENTRE)	REPLACED	658.90	658.90
2	FRONT BUMPER SIDE @ \$250.00	REPLACED	500.00	500.00
2	FRONT BUMPER SIDE FOG LAMP COVER @ \$65.50	REPLACED	131.00	131.00
2	HEADLAMP @ \$552.30	REPLACED	1,104.60	1,104.60
2	FRONT SIDE @ \$225.50	REPLACED	451.00	451.00
2	HEADLAMP LOWER @ \$306.50	REPLACED	613.00	613.00
2	HEADLAMP LOWER GARNISH @ \$110.00	REPLACED	220.00	220.00
1	FRONT RADIATOR GRILLE	REPLACED	615.20	615.20
1	FRONT RADIATOR GRILLE LOGO	REPLACED	32.92	32.92
1	FRONT RADIATOR GRILLE EMBLEM "MITSUBISHI"	REPLACED	108.51	108.51
1	FRONT PANEL	REPAIRED SEE LABOUR	1,015.46	-
1	FRONT WINDSCREEN GLASS	REPLACED	1,425.00	1,425.00
1	FRONT WINDSCREEN GLASS RUBBER	REPLACED	475.21	475.21
1	FRONT DOOR RH	REPLACED	2,152.00	2,152.00
1	FRONT DOOR WEATHERSTRIP RH	REPLACED	298.00	298.00
1	FRONT DOOR STEP GARNISH RH	REPLACED	175.90	175.90
1	FRONT DOOR STEP GARNISH PANEL RH	REPAIRED SEE LABOUR	285.00	-
1	SET FRONT AIRCON PIPE	REPLACED	552.00	552.00
1	TAIL GATE	REPLACED	1,688.00	1,688.00
2	REAR SIDE GATE @ \$1688.00	REPAIRED SEE LABOUR	3,376.00	-
1	REAR DECK PLATFORM	REPAIRED SEE LABOUR	8,000.00	-
1	REAR CHASSIS FRAME	REPAIRED SEE LABOUR	9,000.00	-
1	REAR MUDGUARD LH	NOT NECESSARY	165.00	-
	LESS 15% DISCOUNT		-4,956.40	-1,680.19
			28,086.30	9,521.05
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE (SN)	REPLACED	50.00	10.00
2	TAIL GATE STICKER 60KM/H AND 8 PAX @ \$20.00 (SN)	REPLACED	40.00	30.00

Report Ref No. CS3/FCI17019415/Grbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR DECK CHECKER PLATE	NOT NECESSARY	2,500.00	-
1	TAIL GATE CHECKER PLATE (SN)	REPLACED	850.00	250.00
2	SIDE GATE CHECKER PLATE @ \$850.00 (SN)	NOT NECESSARY	1,700.00	-
1	REAR CANOPY AND CARGO EXTENDER (SN)	NOT NECESSARY	15,000.00	-
1	FRONT DOOR COMPANY ADVERTISEMENT RH (SN)	REPLACED	650.00	300.00
1	FRONT DOOR LTA STICKER RH (SN)	REPLACED	40.00	30.00
1	FRONT PANEL COMPANY LOGO (SN)	REPLACED	100.00	100.00
1	REAR DECK UNDERNEATH WOODEN FRAME (SN)	REPLACED	450.00	350.00
10	FRONT BUMPER CLIPS @ \$4.50 (SN)	REPLACED	45.00	45.00
			21,425.00	1,115.00
	LABOUR			
	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE 'PARTS REPAIR' COLUMN INCLUSIVE OF REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF FRONT PANEL, FRONT DOOR STEP GARNISH PANEL RH, REAR SIDE GATE, REAR DECK PLATFORM AND REAR CHASSIS FRAME.		3,120.00	600.00
	SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL.		1,600.00	600.00
	APPLY RUST PROOFING ON THE ADJACENT PANELS.	NOT NECESSARY	250.00	-
	WIRING / BULB CHECKING.		48.00	30.00
	REMOVE / REPLACE FRONT WINDSCREEN GLASS (2-MAN JOB)		144.00	120.00
	REMOVE AND REPLACE REAR DECK TO FACILITATE THE REPAIR WORKS.		1,000.00	300.00
	TRANSFER OF EXISTING FRONT DOOR MECHANISM TO NEW DOOR RH.		86.40	60.00
	REAR CHASSIS ALIGNMENT CHARGES.	NOT NECESSARY	650.00	-
	REMOVE / REFILL AIRCON CONDENSER AND REFILL AIRCON GAS.	NOT NECESSARY	120.00	-
	-		-	-
	-		-	-
	-		-	-
			7,018.40	1,710.00
	GRAND TOTAL		56,529.70	12,346.05

Report Ref No. CS3/FC117019415/Grbs2-1



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONSITION)(FRONT PORTION)			9,876.84
---	--	--	----------

Report Ref No. CS3/FCI17019415/Grbs2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 6837T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REPLACEMENT OF REAR PARTS	REPLACED		
	ATTENUATOR		43,156.00	30,000.00
			43,156.00	30,000.00
	LABOUR			
	REMOVE EXISTING TMA AND REPLACE NEW TMA.		1,200.00	1,000.00
	CHECK WIRING & TESTING COMMISSIONG.		200.00	150.00
	REMOVE & REFIT REAR DECK TO FACILITATE REPAIR WORKS.		1,000.00	800.00
	SPECIALIST CHARGES - CHECK ALIGNMENT CHARGES.		450.00	400.00
			2,850.00	2,350.00
GRAND TOTAL			46,006.00	32,350.00
RECOMMENDED COST OF REPAIRS (REAR PORTION)				32,350.00

Report Ref No. CS3/FCI17019415/Grbs2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.