



M/S AIG ASIA PACIFIC INS PTE LTD
78 SHENTON WAY
#07-16 AIG BLDG
SINGAPORE 079120

*not Authorized
LKR
2/5/8
7/8/18
take into After repair
body.*

Vfix Auto Service Pte Ltd
60 Kaki Bukit Ave 6 Ark@KB
Singapore 417892
Email : contact@vfixauto.com.sg
Tel : 6448 9268 Fax: 6445 2368
UEN / GST Reg No. : 201602964H

ESTIMATE

DATE : 06/08/2018
ACC DATE : 04/08/2018
REF NO : VFIX - TP20180509
POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO :XD7022K VOLVO FMX

DESCRIPTION		AMOUNT S\$	
1	2 SUSPENSION ARM R+L	2,300.00	4,600.00
2	2 SUSPENSION BELLOW	1,880.00	3,760.00 <i>Dis</i>
3	1 STEERING RACK		5,882.80 <i>ny</i>
4	1 TRACK ROD		1,985.00 <i>12</i>
5	1 CENTER BELLOW		1,852.00 <i>17</i>
			\$ 18,079.80
LESS 10%			\$ 1,807.98
			\$ 16,271.82

LABOUR & MISCELLANEOUS:		AMOUNT S\$	
1	To remove damaged parts with all necessary components/attachments apply hot-works where necessary straighten/repair rear chassis member repale new parts refit align into position with all necessary components attachments		4,000.00
2	To spray paint replaced/repared body panels inclusive of preparatory works and painting materials		1,800.00
3	To remove,replace rear steering rod with all necessary components attachments		850.00 <i>11</i>
4	To conduct rear wheel alignment		120.00 <i>17</i>
			\$ 6,770.00

GRAND TOTAL : \$ 23,041.82

SINGAPORE DOLLARS : TWENTY THREE THOUSAND FORTY ONE &
CENTS EIGHTY TWO ONLY

Vfix Auto Service Pte Ltd



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: