

DATE OF ISSUE OF IOD: 30 July 2018

JOD NO: FY 18/19/0019

TO: JOY IRENE/HIAO TONG

LKK AUTO CONSULTANTS PTE LTD

Instrument of demand to engage the services of an Insurance Claims Adjuster
(Period Contract No: (DEF000ECO12000060))

UNIT/ HUB	DATE OF ACCIDENT	MID & CIVILIAN INFORMATION			REMARK
		VEH NO	CIVILIAN	MILITARY	
East / Bedok Node	11/07/18 1100HRS		YP 2013U	MID 21325	ACCIDENT INVOLVING MID 21325 & YP 2013U along Upper East Coast Road opposite Kew Green Condo.
		DRIVER NRIC	G6782646P	S9543643I	
		DRIVER NAME	Mr Hossain Anwar	3SG Muhammad Syariz Bin Affandi	
		DAMAGE TO VEHICLE	Y	Y	

Requesting Officer



(SIGNATURE)

CPT Merlin Koh

Hd Traffic Accident Investigation & Edu Sect
HQ Transport

HQ TRANSPORT STAMP



DATE:

OA:

GRA:

FOR INFO:

RESTRICTED

HQ Transport

Kranji Camp III

151 Choa Chu Kang Way

Block 822 #01-04

Singapore 688248

Tel : 6307 4511

Fax : 6307 4520

Date: 31 / 07 / 2018

To: LKK Auto Consultants Pte Ltd

Attn: Ms Joy Irene/Ms Chew Hsiao Tong

Our Ref: FY 18 / 19 / 0019

Forwarding of Outstanding Document(s)

Accident involving MID 21325 & YP 20134 on 11 / 07 / 18

We are faxing over / dispatching document(s) with regards to the above matter.

Kindly acknowledge upon receiving the below mentioned document(s) and revert back to us.

Acknowledgement from LKK Auto			
S/N	Documents	Received On	Received By
1	SAF 1201 ✓	11/8/18	CH
2	SAF 1202		
3	Police Report		
4	Original Photographs		
5	Final Bill		



Thank You

Joe
PTE Joe Cheng

RESTRICTED

PEOPLE OF THE FLOPER
SINGAPORE



**SINGAPORE ARMED FORCES
STATEMENT OF ACCUSED**

ANNEX A

STATEMENT OF	3SG MUHAMMAD SYARIZ BIN AFFANDI						
NRIC NO	S9513984A	AGE	23	SEX	M		
EMPLOYMENT	NSF	DRIVING LICENSE NO	02635/17	NATIONALITY	SINGAPOREAN		
ADDRESS	BLK 118 PASIR RIS STREET 11 #02-503 S(510118)						
RECORDED BY	DARREN LEOW	RANK	2LT	DATE TIME	110718 1700H	SIGN	SENT VIA EMAIL
<p>I, S9513984A, 3SG MUHAMMAD SYARIZ BIN AFFANDI, was the driver for MID 21325 on the 11th JUL 18 and the vehicle passenger was PTE DARYL SHANE LEE RUI GUAN. The accident happened along UPPER EAST COAST RD just after junction of the bus interchange.</p> <p>I was driving in my own lane just after the junction and I saw this white lorry (YP2013P) coming in fast from my right mirror. When he was approaching my right side, I slowed down to avoid colliding into the vehicle. Unfortunately the vehicle made contact with mine. We then stopped at the bus stop which is the safest and nearest place to stop.</p> <p>I off the engine and put the wheel choke. We exchanged particulars and snapped photos of both vehicles. The lorry driver was apologetic about what happened and wanted to privately settle this incident but we told him that this is a military vehicle.</p> <p>It happened so fast and I did not expect that the lorry will overtake in that matter.</p>							
DATE	110718		SIGNATURE OF DRIVER/WITNESS		SENT VIA EMAIL		

SAF 1201/91

All statements and further statements are to be timed and dated. Witness will be re-warned immediately prior to the recording of further statement. Statements and further statements will be signed by the Recording Officer and Interpreter.

Statements of witness must be signed by the witness

**SINGAPORE ARMED FORCES
STATEMENT OF ACCUSED**

ANNEX B

STATEMENT OF	PTE DARYL SHANE LEE RUI GUAN						
NRIC NO	S9615703G	AGE	22	SEX	M		
EMPLOYMENT	NSF	DRIVING LICENSE NO	-	NATIONALITY	SINGAPOREAN		
ADDRESS	BLK 120 TAMPINES ST 11 #02-302						
RECORDED BY	DARREN LEOW	RANK	2LT	DATE TIME	110718 1700H	SIGN	SENT VIA EMAIL
<p>I, S9615703G, PTE DARYL SHANE LEE RUI GUAN, was the front passenger in MID 21325 on the 11th JUL 18 and the driver was 3SG MUHAMMAD SYARIZ BIN AFFANDI, S9513984A. Incident happened along UPPER EAST COAST RD just after the junction of the bus terminal towards Temasek Secondary. 3SG SYARIZ was in his own lane within the speed limit, as he approached the slight left bend after the junction, YP2013P, tried to overtake on our right at a higher speed and did not slow down enough to negotiate the bend. 3SG SYARIZ did indeed slow down to avoid contact, but unfortunately, YP2013P made contact with our vehicle. We came to a stop at the bus stop opposite Kew Green Condo to exchange particulars. The driver of YP2013P did apologise and wanted to settle it privately but we told him that its involving a MINDEF vehicle so it was not possible. 3SG SYARIZ could not have done anything more to avoid the collision, he handled the situation calmly and was always in control of this vehicle at all times.</p>							
DATE	110718		SIGNATURE OF DRIVER/WITNESS		SENT VIA EMAIL		

SAF 1201/91

All statements and further statements are to be timed and dated. Witness will be re-warned immediately prior to the recording of further statement. Statements and further statements will be signed by the Recording Officer and Interpreter.

Statements of witness must be signed by the witness