



Insured Vehicle No.

Name of Insured

Insured Tel No.

Excess Sec II : S\$

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$ 3450.00

(7 days)

Reduction:

4300/-

%

54

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

1360

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost:

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

If NO or B 28, Ass. Lia:

OI existing roundabout

while TP moving along.

Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

ASS. REC. BY

REF

CS3/AXA/1804354/62403

Special Instructions

Surveyor

Guo Qiang

ASSIGNMENT (Office)

From (Person)

AXA

Date/Time

7/8/18

Estimated Cost

Bill to

OD

(TP)

WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SJM 5872E

Insured

SKN 1808B (Long)

at Workshop n/a

Asia Motorsports
568 Guelph Road

Tel.

6745 3811 / 81006840

Policy No.

Claim No.

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A.

5/8/2018

Insp: 16 Kaki Bkt Rd 4 #01-53
Bentley Biz Center

H.O.D. Endorsement

CA / REV / REP. / REV 24 HRS

Date/Time

2:14pm 7/8/18

Person Contacted

Mr. Leo

Vehicle

(IN) OUT

Date/Time	Action/Instruction (X) Estimate
	SJM 5872E - X
	SKN 1808B - X
8/8/18	Dismantled.

Yml.

REF:

AXA

C 85946

ASSIGNMENT

(-2019)

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s: **Asia Motorsports**
 of: _____
 Insured: _____
 Policy No.: _____
 Claims No.: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: **\$8800**
 IDAC Accident Rpt.: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **7** days Res: Yes or No
 Lum Sum: **70** % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle IN / OUT

Veh No: **SJM5872E** Yr Regn: **09 Jan 2009**
 Type: **M/C** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Toyota AX10 1.5X** 1496
 Colour: **Blue** A/C: Insured / Std / NI / NA
 Sp. Reading: **164224** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **NZE 1416103004**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **In order** / Jammed / Leaked / Burnt or
 Brake: **In order** / Jammed / Leaked / Burnt or
 Modi: **Nil** / S/Rim / STD A/Rim or
 Tyre Size: F: **205/45 R16**
 R: **4**
 SS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **FIRENZA**
 Front: _____ Rear: _____
 R/Bal: **6** mm R/Bal: **6** mm
 L/Bal: **6** mm L/Bal: **6** mm
 D.O.A. _____ D.O.I. **07-08-18**
 Survey held at **w/s** **3:30pm**
 Des. of Damages: Fnt / Rear / **O/S** / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
01/8	Estimate given later.
14/8/18	Submit PRS report
23/8	Received estimate
24/8	Fax mark estimate to repairer.
27/8	Repairer accept our offer, finalised C.O.R. \$3,950 with 7 days of repair.
	46 \$3950- (Red = \$4700 / 54-1-)

Date/Time, File Pass to? ☐ : Prel. Report ☐ : Final Report

1) Date/Time, File Return to?

2)

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Site Insp (\$ ☐)

Interview (\$ ☐)

Tech Invs (\$ ☐)

Weekend (\$ ☐)

Photos _____

Others _____

TOTAL _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS3/AXA18014354/Gz4d3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 07-08-2018



Code : AXA2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SKN 1808B	Veh. Inspected	SJM 5872E
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	07/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	05/08/2018	Inspection Date	07/08/2018
Survey held at	16 KAKI BUKIT RD 4 #01-53		
Repairer	ASIA MOTORSPORTS SOLUTION PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Edison
6746570

Estimate For Vehicle SJM 5872 E (Toyota Axio 1.5)

from = Simon

Item	Description	Qty	Price list
1	Front door RH	1	\$1,125 1,721.00 BUC
2	Front side mirror RH	1	\$ 884.90 X R
3	Front door hinge upper RH	1	\$ 164.50 X SVC
4	Front door hinge lower RH	1	\$ 99.50 X SVC
5	Front door check RH	1	\$ 89.50 X SVC
6	Front door outer handle RH	1	\$ 178.70 X NN
7	Front door window glass weather-strip RH	1	\$ 167.50 X NN
8	Front door rubber RH	1	\$ 188 240.50 DD
9	Front door window motor RH	1	\$ 380.80 X SVC
10	Front door window regulator RH	1	\$279 444.00 BT
11	Front door mechanism lock RH	1	\$398 478.00 BT
12	Front door trim board RH	1	\$ 684.50 X NN
13	Side rocker sill garnish RH	1	\$782 1,481.00 DD
14	Rear door RH	1	\$973 1,200.00 BUC
15	Rear door upper hinge RH	1	\$ 164.50 X SVC
16	Rear door lower hinge RH	1	\$65 99.50 BT
17	Rear door rubber RH	1	\$168 240.50 DD
18	Rear door trim board RH	1	\$ 684.20 X NN
19	Rear door window glass weather-strip RH	1	\$ 167.50 X NN
			\$ 9,631.90 3978
	Less 25%		\$ 2,407.98 994.50
			\$ 7,223.92 2493.50
SUPPLY ITEM			
20	Front door frame tape RH	1	\$ 64 160.00 NEC
21	Front & rear door visor RH	1 set	\$ 150 200.00 NEC
22	Side rocker sill garnish clips RH	1 set	\$ 40 70.00 NEC
23	Front door inner trim board clips RH	1 set	\$ 25 30.00 NEC
24	Rear door inner trim board clips RH	1 set	\$ 25 30.00 NEC
	Parts Total :	\$	7,830.32 3,287.50
LABOUR CHARGES & MISC			
25	Check wiring, lighting, power window & centre locking system	\$	50.00 30
26	Remove damaged parts, knock out dents, straighten door pillar, remove & reinstall affected areas.	\$	1,400.00 800
27	Spray painting affected parts.	\$	1,200.00 650
28	Anti-rust proofing on affected panel.	\$	120.00 70
29	To transfer front & rear door mechanism & components.	\$	120.00 ✓
30	To conduct wheel alignment.	\$	120.00 X
	Labour Total :	\$	1,670 3,010.00
			7 days
	Sub Total :	\$	10,840.32 4,957.50
			LS \$3,950
	Lump sum repair adjustment	\$	8,650.00
	Estimated time required for repairs		9 days



ASIA MOTORSPORTS SOLUTION PTE LTD

Specialise in sales of new & reconditioned bikes

Co. Reg. No: 200507766N

No. 568, Geylang Road Singapore 389514 Tel: +65 6745 3811 Fax: +65 6746 5110 Website: www.asiamotorsports.com.sg

HAPPY DRIVER SG PTE LTD
201728594G

INVOICE NO: 2017/C086

DATE: 05/09/2018

VEHICLE NO: SJM 5872 E

ENGINE CAPACITY : 1496 CC

ENGINE NO : 1Nzd252013

MAKE : TOYOTA

CHASSIS NO : NZE1416103004

MODEL : COROLLA AXIO YEAR : 2008
1.5X SPECIAL
EDITION A

DESCRIPTION

AMOUNT

Total lump sum repair including supply of parts and labour

Adjusted total lump sum repair costs

S\$3,950.00

Total amount payable

S\$3,950.00



Asia Motorsports Solution Pte Ltd

> Back to OneMotoring

Land Transport Authority

Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 06 Aug 2018 / 15:50:17

Receipt Date/Time : 06 Aug 2018 / 15:50:17

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180806-001591

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-----	--	-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SKN1808B
As at 05 Aug 2018/12:00:00
Insurance Co: AXA INSURANCE PTE LTD

1	Insurance Enquiry - SKN1808B Enquiry Fee 20180806154926398669	7.00	0.49	7.49
---	---	------	------	------

Sub-Total	7.00	0.49	7.49
-----------	------	------	------

Total Before Rounding	7.00	0.49	7.49
-----------------------	------	------	------

Rounding Difference			0.04
---------------------	--	--	------

Total Amount Payable			7.45
----------------------	--	--	------

Paid By

20180806154935559	Direct Debit: eNETS Debit (Internet Banking)	7.45
-------------------	---	------

Total		7.45
-------	--	------

Cash Change		0.00
-------------	--	------

Tendered Amount		7.45
-----------------	--	------

Excess Refundable Amount		0.00
--------------------------	--	------

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

> Back to OneMotoring

D.O.A. 5/8/2018
Bal = 5.1 mths
M.V. \$15,000

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	8594G
Vehicle Details	
Vehicle No.:	SJM5872E
Vehicle to be Exported:	No
Intended De-registration Date:	08 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X SPECIAL EDITION A
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	1NZD252013
Chassis No.:	NZE1416103004
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$17,083.00
Original Registration Date:	09 Jan 2009
First Registration Date:	09 Jan 2009
Transfer Count:	1
Actual ARF Paid:	\$17,083.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Jan 2019 ✓
PARF Rebate Amount:	\$8,541.00 ✓
Intended COE Rebate Details	
COE Expiry Date:	08 Jan 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$5,001.00
COE Rebate Amount:	\$208.00
Total Rebate Amount:	\$8,749.00

The information contained herein is correct as at 08 Aug 2018

OK

limit 6,251

Att: Edison
Fax: 67465110

from = Simon

Estimate Repair For Vehicle SJM 5872 E (Toyota Axio 1.5)

Item	Description Parts	Qty	Price list	
1	Front door RH	1	\$1,125	1,721.80 BUC
2	Front side mirror RH	1	\$	884.90 X R
3	Front door hinge upper RH	1	\$	164.50 X SIC
4	Front door hinge lower RH	1	\$	99.50 X SIC
5	Front door check RH	1	\$	89.50 X SIC
6	Front door outer handle RH	1	\$	178.70 X NN
7	Front door window glass weather-strip RH	1	\$	167.50 X NN
8	Front door rubber RH	1	\$ 188	240.50 DD
9	Front door window motor RH	1	\$	380.80 X SIC
10	Front door window regulator RH	1	\$ 279	414.00 BT
11	Front door mechanism lock RH	1	\$ 398	478.00 BT
12	Front door trim board RH	1	\$	684.50 X NN
13	Side rocker panel RH	1	\$ 782	1,481.00 DD
14	Rear door RH	1	\$ 973	1,290.60 BUC
15	Rear door upper hinge RH	1	\$	164.50 X SIC
16	Rear door lower hinge RH	1	\$ 65	99.50 BT
17	Rear door rubber RH	1	\$ 168	240.50 DD
18	Rear door trim board RH	1	\$	684.20 X NN
19	Rear door window glass weather-strip RH	1	\$	167.50 X NN
			\$	9,631.90
			Less 25%	\$ 2,407.98
			\$	7,223.92
S/NETT ITEM				
20	Front door frame tape RH	1	\$ 64	160.40 NEC
21	Front & rear door visor RH	1 set	\$ 150	300.00 NEC
22	Side rocker sill garnish clips RH	1 set	\$ 40	70.00 NEC
23	Front door inner trim board clips RH	1 set	\$ 25	38.00 NEC
24	Rear door inner trim board clips RH	1 set	\$ 25	38.00 NEC
			Parts Total : \$	7,830.32

LABOUR CHARGES & MISC				
25	Check wiring, lighting, power window & centre locking system	\$	50.00	30
26	Remove damaged parts, knock out dents, straighten door pillar, remove & reinstall affected areas.	\$	1,400.00	800
27	Spray painting affected parts.	\$	1,200.00	650
28	Anti-rust proofing on affected panel.	\$	120.00	70
29	To transfer front & rear door mechanism & components.	\$	120.00	
30	To conduct wheel alignment.	\$	120.00	X
			Labour Total : \$	3,010.00

Sub Total : \$ 10,840.32

Lump sum repair adjustment \$ 8,650.00
Estimated time required for repairs 9 days

[Advanced Search](#)

Home » [Used Cars](#) » [Ka-Hup Vehicles Trading](#) » [Toyota Corolla Axio 1.5A X](#)

Resources

- [Car Buying](#)
- [Car Selling](#)
- [Car Ownership](#)
- [Car Aftermarket](#)
- [On The Move](#)
- [Lifestyle](#)

Car Tyres



Toyota Corolla Axio 1.5A X

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)

PREMIUM AD



ESTABLISHED SINCE 1989



[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)
[Report Error](#)
[More Actions](#)
[Share](#)

Car Details

Price	\$17,800	
Depreciation	\$10,550 /yr	?
	View models with similar depreciation	
Reg Date	29-Jul-2009	?
	(11mths 4days COE left)	
Manufactured	2008	?
Mileage	160,000 km (17.6k /yr)	
Transmission	Auto	
Engine Cap	1,496 cc	?
Road Tax	\$682 /yr	?
Power	81.0 KW (108 bhp)	?
	View specs of the Toyota Corolla	
Curb Weight	1,130 kg	?
Features	Powerful And Fuel Efficient 16V DOHC VVT-i Throttle Engine, CVT Auto Transmission Delivers 15.2km/L, ABS, Dual SRS Airbags.	
Accessories	Sports Rims, Leather Seats, DVD Audio System, Reverse Sensors, Solar Film, Retractable Side Mirrors.	
Description	Rare Silver Toyota Axio! Excellent Condition! High Loan & \$0 Driveway Available! Comes With DVD Player And Reverse Camera! Excellent Fuel Efficiency!	
COE	\$15,291	?
OMV	\$16,060	?
ARF	\$16,060	?
Dereg Value	\$9,446 as of today (change)	?
No. of Owners	2	?
Type of Veh	Mid-Sized Sedan	
Category	PARF Car, Premium Ad Car	
Availability	Available	PREMIUM AD

[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)

Posted on: 16-Aug-2018 | Last Updated on: 18-Aug-2018

Tags: Toyota Corolla, 2009 Toyota Corolla, Toyota, Corolla, Used Toyota



Seller Information

Company	Ka-Hup Vehicles Trading • dealer's pricelist • 90 vehs sold 43 vehs available	
Address	61 Ubi Avenue 2 #04-09 Search cars nearby this location	
Location	Automobile Megamart	
Office No	67480409	
Contact Person(s)	Kelvin Johnson	91017559 90722292
Enquiry	Contact Seller	

Upfront Payment

[» more Financial info](#)
[Compare](#)

\$25

[?](#)



CAR NUMBER PLATES FOR SALE!

Find the unique car number plate that represents you!

Click here to start the hunt!

Toyota Corolla

Price Range

Depreciation

2009

Vehicle Type

Advanced Search

Home » Used Cars » Car Guru.Com Pte Ltd » Toyota Corolla Axio 1.5A X (New 5-yr COE)

Resources

[Car Buying](#)
[Car Selling](#)
[Car Ownership](#)
[Car Aftermarket](#)
[On The Move](#)
[Lifestyle](#)

Car Leasing

CL LEASING
YOUR PREFERRED CAR LEASING
OPTION IN SINGAPORE

6769 7117 8729 5000 8720 8100

HUGE SAVINGS
✈️ + 🏠
COMBINE AND SAVE
SEE DEALS

Toyota Corolla Axio 1.5A X (New 5-yr COE)

[Overview](#) [Financial](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#)

[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)
[Report Error](#)
[More Actions](#)
[Share](#)

Car Details

Price	\$33,800	
Depreciation	\$6,760 /yr	?
Reg Date	06-Feb-2009 (5yrs COE left)	
Manufactured	2008	?
Mileage	-	
Transmission	Auto	
Engine Cap	1,496 cc	
Road Tax	\$682 /yr	?
Power	81.0 kW (108 bhp) View specs of the Toyota Corolla Axio (2007-2012)	
Curb Weight	1,130 kg	?
Features	1.5L 16 Valves 4 Cylinders VVTi DOHC Engine. Smooth CVT Auto Transmission, ABS, SRS Airbags, Immobilizer.	
Accessories	Leather Seats, Sports Rim, DVD Player W BT, Reverse Sensors, Retractable Side Mirrors.	
Description	Smooth Engine, Easy To Maintain Unit, Immaculate Condition, Depreciation Is Even Cheaper, Do Not Miss, Bank And In House Loan Available! Trade In Welcome. Call For Appointment For A Test Drive Now Before The Car Is Gone	
COE	-	?
OMV	\$11,694	?
ARF	\$6,072	?
No. of Owners	4	?
Type of Veh	Mid-Sized Sedan	
Category	COE Car	
Availability	Available	

[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)

Posted on: 06-Jul-2018 | Last Updated on: 16-Aug-2018


Tags: Toyota Corolla, 2009 Toyota Corolla, Toyota, Corolla, Used Toyota

Upfront Payment:

[» main Financial info](#)

Transfer Fee	\$25	
Down Payment	\$10,140 (change)	Maximum 70% Loan
1st Instalment	\$468	
Total Upfront Payment	\$10,633 (excluding insurance)	

Estimates based on 70% loan at 3.75% interest rate. Check with seller for exact figures.



Seller Information

Company	Car Guru.Com Pte Ltd * dealer's pricelist * 69 vehs sold 38 vehs available	
Address	210 Turf Club Road Lot A7/A8/A9 Search cars nearby this location	
Location	Car Mall @ The Grandstand	
Office No	67639595	
Contact Person(s)	Lawrence Jimmy	92228747 90079944

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Nivitha (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Tuesday, 7 August 2018 12:53 PM
To: assignments
Subject: FW: NOTICE OF ACCIDENT: ACCIDENT INVOLVING SJM 5872 E & SKN 1808 B ON 5 AUGUST 2018

Hi Nivitha,

Kindly assist.

TP AXA – Smart.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Asia Motorsports Solution Pte Ltd <asiamotorsports@hotmail.com>
Sent: Monday, 6 August, 2018 4:21 PM
To: customer.service@axa.com.sg; SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Subject: NOTICE OF ACCIDENT: ACCIDENT INVOLVING SJM 5872 E & SKN 1808 B ON 5 AUGUST 2018

Your Ref:

Our Ref: SJM 5872 E

6 August 2018

AXA Insurance Pte Ltd
8 Shenton Way
#27-01
AXA Tower
Singapore 068811

**PROPERTY CLAIM
(WITHOUT PREJUDICE
TO: Any Personal Injury
Claims)**

Attn: Claims Department

Dear Sir/Mdm,

NOTICE OF ACCIDENT: ACCIDENT INVOLVING SJM 5872 E & SKN 1808 B ON 5 AUGUST 2018

We are instructed to notify you of a road traffic accident on **5 August 2018** at about **12.00 pm** at **Jalan Ahmad Ibrahim towards AYE, roundabout** involving our client's vehicle registration number **SJM 5872 E** and vehicle registration number **SKN 1808 B** driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice and your proposed list of 10 recommended motor surveyors for our appointment.

Kindly note that if we do not hear from you by **8 August 2018 (Wednesday), 1630H**, we will be forwarding **our proposed list of 10 motor surveyors** for your appointment, in accordance to the new regulations.

Thank you and we hope to hear from you soonest.

Regards,

Asia Motorsports Solution Pte Ltd

6745 3811

6746 5110 (fax)

asiamotorsports@hotmail.com

Your Ref: DP.sl.10604.18.MIR
Our Ref: MT/CA/TP/019/1006071-002/JL/LC

25 Oct 2018

**Without Prejudice
to any claim for
personal injury**

DISCHARGE VOUCHER

I/We, NG KOK LEONG

hereby acknowledge and agree that payment by NTUC Income Insurance Co-operative Limited of the sum of S\$4,112.49 to DANIEL POON & CO shall be full satisfaction liquidation and discharge of all claims whatsoever competent upon HAPPY DRIVER SG PTE. LTD. &/OR AUTHORISED DRIVER in respect of all loss injury or damage whether now or hereafter to become manifest arising directly or indirectly from the above-captioned accident.

I/We acknowledge that this payment is made without any admission of liability on part of NTUC Income Insurance Co-operative Limited.

I/We understand and agree that the entitlement to receive the payment is non-transferrable and/or non-assignable to any third parties not named in this agreement.

Signature : [Signature]
Name : Ng Kok Leong
(Include company stamp if applicable)

NRIC/UEN : S7877067H
Date : 10/12/2018

Witness
Signature : [Signature]
Name : LEE SWEET LING
NRIC No : G2486492N
Address : 48 Tan Guan Road East
#04-126 Enterprise Hub
Singapore 608586

NB: COR \$3550 LOU \$420 @80% \$3176 SR \$550 GIA \$36.49 Cost \$ 350 Total\$4112.49



Re:RE: Re:S8M00R70 - CONDUCT PRI ONLY

Type

🔔 Question

Message

PLS INFORMED TP THAT INSURED HAD SUCCESSFULLY CLAIMED AGAINST TP AND REJECT TP CLAIM.

Reply

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Tuesday, 9 July 2019 10:58 AM
To: Asia Motorsports Solution Pte Ltd
Subject: RE: Re:(Fourth Reminder) ACCIDENT INVOLVING SJM 5872 E & SKN 1808 B ON 5 AUGUST 2018 - CALL FOR DIRECT SETTLEMENT *** LKK REF: CC4/ASM18014354/Gga3

Your Ref: **SJM 5872E** Without Prejudice
Our Ref: CC4/ASM18014354/Gga3

Dear Sirs/Madam,

ACCIDENT INVOLVING SJM 5872 E & SKN 1808 B ON 5 AUGUST 2018

We refer to the above matter.

We have reviewed the matter and we are of the view that our driver is not liable for the accident. Kindly note that Our Insured has counter claim against your client and the result is successful.

In view of the above, we have our principal instruction to deny liability and unable to look into your client's matter.

Thank you.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Joy Irene (LKKAuto)
Sent: Thursday, 27 June 2019 5:31 PM
To: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>
Subject: FW: Re:(Fourth Reminder) ACCIDENT INVOLVING SJM 5872 E & SKN 1808 B ON 5 AUGUST 2018 - CALL FOR DIRECT SETTLEMENT *** LKK REF: CC4/ASM18014354/Gja3

FYNA

From: Mei Kwan (LKKAuto)
Sent: Thursday, 13 December 2018 3:06 PM



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

28 June 2019

NG KOK LEONG
663C JURONG WEST ST 65
#15-251
SINGAPORE 643663

Dear Sir/ Mdm

OUR REF : CC4/ASM18014354/Gga3

YOUR REF : SKN 1808B

**ACCIDENT INVOLVING SKN 1808B AND SJM 5872E ALONG/AT PIONEER CIRCLE
ROUNDAABOUT ON 05/08/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from **ASIA MOTORSPORTS SOLUTION PTE LTD** acting on behalf of the owner of SJM 5872E against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in our favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to ceciliachong@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Driver's Work Permit
- Employment Letter/ Authorisation letter from your company
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6749 4274 or email us at ceciliachong@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely



Cecilia Chong
Case Handler
DID: 6749 4274
FAX: 6741 4108
EMAIL: ceciliachong@lkkauto.com

Cc *AXA Insurance Pte Ltd*
 (Motor Claims Dept)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18014354/Gga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:KIAN CHUAN

Date : 07-01-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKN 1808B	Veh. Inspected	SJM 5872E
Policy No.	GA344042	Coverage (\$)	0.00
Claim No.	S8M00R70	Excess (\$)	0.00
Assign From		Assign Date	07/08/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA AXIO 1.5X	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	NZE1416103004	Colour	BLUE
Odometer	164224	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/45Z R16	FIRENZA	6 mm
L/H Front Tyre	205/45Z R16	FIRENZA	6 mm
R/H Rear Tyre	205/45Z R16	FIRENZA	6 mm
L/H Rear Tyre	205/45Z R16	FIRENZA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	05/08/2018	Inspection Date	07/08/2018
Survey held at	16 KAKI BUKIT RD 4 #01-53		
Repairer	ASIA MOTORSPORTS SOLUTION PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 5872E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR RH (CONSISTENT)	BUCKLED	1,721.80	1,125.00
1	FRONT SIDE MIRROR RH (CONSISTENT)	TO REPAIR SEE LABOUR	884.90	-
1	FRONT DOOR HINGE UPPER RH (CONSISTENT)	SERVICEABLE	164.50	-
1	FRONT DOOR HINGE LOWER RH (CONSISTENT)	SERVICEABLE	99.50	-
1	FRONT DOOR CHECK RH (CONSISTENT)	SERVICEABLE	89.50	-
1	FRONT DOOR OUTER HANDLE RH (CONSISTENT)	NOT NECESSARY	178.70	-
1	FRONT DOOR WINDOW GLASS WEATHER STRIP RH (CONSISTENT)	NOT NECESSARY	167.50	-
1	FRONT DOOR RUBBER RH (CONSISTENT)	DENTED	240.50	188.00
1	FRONT DOOR WINDOW MOTOR RH (CONSISTENT)	SERVICEABLE	380.80	-
1	FRONT DOOR WINDOW REGULATOR RH (CONSISTENT)	BENT	414.00	279.00
1	FRONT DOOR MECHANISM LOCK RH (CONSISTENT)	BENT	478.00	398.00
1	FRONT DOOR TRIM BOARD RH (CONSISTENT)	NOT NECESSARY	684.50	-
1	SIDE ROCKER PANEL RH (CONSISTENT)	DENTED	1,481.00	782.00
1	REAR DOOR RH (CONSISTENT)	BUCKLED	1,290.50	973.00
1	REAR DOOR UPPER HINGE RH (CONSISTENT)	SERVICEABLE	164.50	-
1	REAR DOOR LOWER HINGE RH (CONSISTENT)	BENT	99.50	65.00
1	REAR DOOR RUBBER RH (CONSISTENT)	DENTED	240.50	168.00
1	REAR DOOR TRIM BOARD RH (CONSISTENT)	NOT NECESSARY	684.20	-
1	REAR DOOR WINDOW GLASS WEATHERSTRIP RH (CONSISTENT)	NOT NECESSARY	167.50	-
	LESS 25% DISCOUNT		-2,407.98	-994.50
			7,223.92	2,983.50
SPECIAL NETT ITEMS				
1	FRONT DOOR FRAME TAPE RH (SN) (CONSISTENT)	NECESSARY	160.40	64.00
1	SET FRONT & REAR DOOR VISOR RH (SN) (CONSISTENT)	NECESSARY	300.00	150.00
1	SET SIDE ROCKER SILL GARNISH CLIPS RH (SN) (CONSISTENT)	NECESSARY	70.00	40.00
1	SET FRONT DOOR INNER TRIM BOARD CLIPS RH (SN) (CONSISTENT)	NECESSARY	38.00	25.00

Report Ref No. CC4/ASM18014354/Gga3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR DOOR INNER TRIM BOARD CLIPS RH (SN) (CONSISTENT)	NECESSARY	38.00	25.00
			606.40	304.00
	LABOUR			
	CHECK WIRING ,LIGHTING ,POWER WINDOW & CENTRE LOCKING SYSTEM.		50.00	30.00
	REMOVE DAMAGED PARTS ,KNOCK OUT DENTS ,STRAIGHTEN DOOR PILLAR ,REMOVE & REINSTALL AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF FRONT SIDE MIRROR RH .		1,400.00	800.00
	SPRAY PAINTING AFFECTED PARTS.		1,200.00	650.00
	ANTI-RUST PROOFING ON AFFECTED PANEL.		120.00	70.00
	TO TRANSFER FRONT & REAR DOOR MECHANISM & COMPONENTS.		120.00	120.00
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
			3,010.00	1,670.00
GRAND TOTAL			10,840.32	4,957.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,950.00

Report Ref No. CC4/ASM18014354/Gga3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	SBM00R70
Reference	CC4/ASM18014354/Cga3a2
Loss Date	5 August 2018
Report Date	7 Aug 2018 9:13:20 AM
Request Date	7 August 2018
Due Date	

Vendor Name	LUK AUTO CONSULTANTS PTE LTD (TPN)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for: Approve Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	SJM5877E
Make	TPWD TOYOTA
Model	COROLLA AXIO 1.5X SPECIAL EDITION A
Service Address	
...	
Primary Contact/Insured	
NG KOH LEONG (HUANG GUOLING) BLK 643C JURONG WEST STREET 65, #15-251, 643663, Singapore 84683012 INSURANCE@DICKSON-AUTO.COM	

Claim Handler	
CHAN Kian Chuan 68805444 kianchuan.chan@axa.com.sg	

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
----------	----------	---------	-----------	------------	---------	-------

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
------	------	----------	--------	---------------

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1 (7).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	10 January 2020
LKKInspection (5).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 January 2020
LKKAdjustment1a (4).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	10 January 2020
REJECTION EMAIL TO TP.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 December 2019
OI counter claim DV from TP.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	8 July 2019
SKN 180818 - OI VIDEO.mp4	Evidence	Videos	LKK AUTO CONSULTANTS PTE LTD (TP)	24 May 2019
TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	29 August 2018
LKKPhotoah6-2.pdf	Evidence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	14 August 2018
LKKPhotoah6-1.pdf	Evidence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	14 August 2018
SJM5872E TP GIA REPORT.PDF	Reports & Statement	GIA Report	RATAN BHSOLE Prigati	7 August 2018
SKN180818 INSD GIA REPORT.PDF	Reports & Statement	GIA Report	RATAN BHSOLE Prigati	7 August 2018
PRI EMAIL RECIEVED FROM WORKSHOP.mng	Letters and Correspondence	Workshop	RATAN BHSOLE Prigati	7 August 2018