

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Thursday, 13 September 2018 9:05 AM  
**To:** 'Tan, Rachel'  
**Cc:** 'SUR'; 'Huey Yon (LKK Report)'  
**Subject:** RE: Survey Report & Invoice of Vehicle SH 7003D Ref: CLMOMVP000000815

Hi Rachel,

We refer to your below email above matter.

According to our surveyor, Calvin basing on the CCTV of the third party taxi, an impact was observed at 0.05sec indicated at the video clip.

Damages to the third party taxi rear bumper lower garnish (Black colour). Number plate frame lining was observed on it at the time of our inspection which corresponded to insured vehicle front number which could be seen slightly bend from the reporting photographs.

Thus it is low speed impact, and damages are consistent.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Tan, Rachel [mailto:[Rachel.Tan@sg.gaig.com](mailto:Rachel.Tan@sg.gaig.com)]  
**Sent:** Monday, 10 September 2018 9:31 AM  
**To:** Huey Yon (LKK Report) <[report@LKKAuto.com](mailto:report@LKKAuto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: Survey Report & Invoice of Vehicle SH 7003D Ref: CLMOMVP000000815

Dear Team

With regards to this damage can you help to check on the consistency.  
Our client claims that there is no impact. Attached is our client's GIA report, and front camera.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

---

**From:** Huey Yon (LKK Report) <[report@LKKAuto.com](mailto:report@LKKAuto.com)>  
**Sent:** Thursday, August 23, 2018 4:16 PM  
**To:** Tan, Rachel <[Rachel.Tan@sg.gaig.com](mailto:Rachel.Tan@sg.gaig.com)>  
**Cc:** Ng, Sharon <[Sharon.Ng@sg.gaig.com](mailto:Sharon.Ng@sg.gaig.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** [External] Survey Report & Invoice of Vehicle SH 7003D Ref: CLMOMVP000000815

Dear Sir / Madam,

Enclose Survey Report of SH 7003D

Thank you.

Best Regards,

Huey Yon | Reports

**LKK Auto Consultants Pte.Ltd.**

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: [report@lkkauto.com](mailto:report@lkkauto.com)

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933

---

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.