

A.S. REC. BY:

REF: CS/FCI18014380/Rlgds⁰²

Special Instruction:

Surveyor: RCSU1

ASSIGNMENT (Office)

From (Person): Lurene Jew

of FCI

Date/Time: 6/8/18 @ 7:18pm

Estimated Cost: _____ Bill to: _____

OD WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLP 6642G

Insured: SHC 7044S

at Workshop m/s Pegasus Engineering
of 74 Kim tek Rd

Tel: 6513 7748

Policy No: _____ Claim No: D18005911MFST

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 3/8/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS lup

H.O.D. Endorsement: _____

Date/Time: 11:22am @ 7/8/18 Person Contacted: Avin

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLP 6642G - X
08/8/18 @ 2:28pm	SHC 7044S - CS/FCI1700ISS2/H/g/h3n2 DOA: 19/01/2017 revised to Lurene by email.
78/12/18 @ 2:01pm	confirmed with Avin final fig \$ 3845. 4 days (Fed \$ 7369.80, 66%)

Singapore

John

REF:

72004

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLD 66424

at Workshop m/s PGEASUS

of _____

Insured: FCI

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLP 66424 Yr Regn: 2017 / Jun

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA U10S 1.5 GA c.c: 1496

Colour: GRGY A/C: Insured / Std / NI / NA

Sp. Reading: 100522 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MHFB29F3202011972

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/50R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 03/08/18 D.O.I. 07/08/18

Survey held at PGEASUS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 26 DEC 2018

Date/Time, File Pass to? : Preli. Report

1) 28/12/17 : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Survey Fee:

Transportation

S + RS \$

Photos

Others

TOTAL

170
15
30+50
45
330

Report Format: TP

Lump Sum / I.B.I.: (\$ 3845)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18014380/R1qd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 07-08-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 7044S	Veh. Inspected	SLP 6642G
Policy No.		Coverage (\$)	0.00
Claim No.	D18005911MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	07/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	03/08/2018	Inspection Date	07/08/2018
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005911MFSH

Date: 08 August 2018

Our Ref: CS/FCI18014380/R1qd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLP 6642G .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 07/08/2018 at the premises of M/s PEGASUS ENGINEERING . and have the following to report:-

Workshop Estimate Amount	: S\$ <u>11,214.80</u> .
Revised Estimate Amount	: S\$ <u>1,802.75</u> .
"Check" Items Amount	: S\$ <u>2,640.00</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the o/s front portion.



Yours faithfully

Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	06-08-2018	Our Ref No.	D18005911MFSH
Accident Date	03-08-2018	Claim Type.	Third Party
Insured Vehicle	SHC7044S	Third Party Vehicle.	SLP6642G
Survey Location	74 KIAN TECK ROAD		
Contact Person.	WEE		
Contact No.	65137748/ 0	Fax No.	62513161
Survey Type	WITHOUT PREJUDICE:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PEGASUS ENGINEERING & TRADING PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	LURENE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 28 December 2018 2:01 PM
To: 'Pegasus Engineering'
Cc: Lionel Chua <lionelchua@pegasusengrg.com.sg>; Lawrence Sim; Belinda Sim; josephyeh@vendaengrg.com.sg; Seng Kee Wong; SUR
Subject: RE: Finalise For SLP6642G (DOA 03/08/2018)

Dear Vivian,

WITHOUT PREJUDICE

Confirm final fig \$3,845.00 before GST and 4 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Pegasus Engineering <ar_claims@pegasusengrg.com.sg>
Sent: Saturday, 1 December 2018 11:32 AM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Cc: Lionel Chua <lionelchua@pegasusengrg.com.sg> <lionelchua@pegasusengrg.com.sg>; Lawrence Sim <lawrencesim@vendaengrg.com.sg>; Belinda Sim <belindasim@pegasusengrg.com.sg>; josephyeh@vendaengrg.com.sg; Seng Kee Wong <sengkee.wong@pegasusengrg.com.sg>
Subject: Finalise For SLP6642G (DOA 03/08/2018)

Dear Ms. Shiau Chan,

Please find the calculation for your confirmation.

Part by Part repair \$3,845.00 (before GST) and 6 days repair.

The attached copies of the documents for your attention.

Thank You

Best Regards,
Vivian Tan
Pegasus Engineering & Trading Pte Ltd
74 Kian Teck Road S628800
Office: 65137748
Fax: 62513161

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 8 August 2018 2:28 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005911MFSH/1
Attachments: CSFCI18014380R1qd3.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SLP 6642G.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 7 August 2018 11:29 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005911MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 6 August 2018 7:17 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005911MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7200G
Vehicle Details	
Vehicle No.:	SLP6642G
Vehicle to be Exported:	Yes
Intended De-registration Date:	06 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2NRX159309
Chassis No.:	MHFB29F3202011972
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$12,744.00
Original Registration Date:	14 Jun 2017
First Registration Date:	14 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$7,744.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jun 2027
PARF Rebate Amount:	\$5,808.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,600.00
COE Rebate Amount:	\$41,280.00
Total Rebate Amount:	\$47,088.00

The information contained herein is correct as at 06 Aug 2018

OK



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :
--	--

Quotation No. : QO18/08-1067	Quotation Date : 04/08/2018	Terms : 30 DAYS
Vehicle No. : SLP6642G	Chassis No. : MHFB29F3202011972	Third Party Insurer : FIRST CAPITAL
Model : VIOS	Date of Accident : 03/08/2018	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	FRONT FENDER RH	1	612.0000	612.00
2	FRONT FENDER SPLASH SHIELD RH	1	288.0000	288.00
3	FRONT FENDER SPLASH SHIELD CLIPS	10	4.5000	45.00
4	FRONT FENDER STAND GARNISH	1	60.0000	60.00
5	FRONT DOOR RH	1	1,090.6000	1,090.60
6	FRONT DOOR OUTER MOULDING	1	74.0000	74.00
7	FRONT DOOR HINGE TOP AND BOTTOM	2	176.0000	352.00
8	FRONT DOOR CHECKER RH	1	153.5000	153.50
9	FRONT DOOR WEATHERSTRIP RH	1	199.1000	199.10
10	FRONT DOOR STICKER	2	35.0000	70.00
11	FRONT DOOR GLASS RUBBER BEADING	1	55.0000	55.00
12	FRONT DOOR GLASS RUN RUBBER CHANNEL	1	65.0000	65.00
13	FRONT DOOR INNER TRIM RH	1	539.0000	539.00
14	FRONT DOOR INNER TRIM CLIPS	10	2.5000	25.00
15	FRONT DOOR INNER HOLE COVER	1	45.0000	45.00
16	FRONT DOOR INNER HOLE COVER SEALANT	1	40.0000	40.00
17	FRONT DOOR REGULATOR	1	230.0000	230.00
18	FRONT DOOR REGULATOR MOTOR	1	690.0000	690.00
19	FRONT SPORT RIM RH	1	1,685.2000	1,685.20
20	FRONT DRIVESHAFT RH	1	1,296.0000	1,296.00
21	FRONT LOWER ARM RH	1	1,013.0000	1,013.00
22	FRONT LOWER ARM BALL JOINT	1	60.0000	60.00
23	FRONT KNUCKLE ARM RH	1	550.0000	550.00

C/F 0.00



PEGASUS

ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :
--	--

Quotation No. : QO18/08-1067	Quotation Date : 04/08/2018	Terms : 30 DAYS
Vehicle No. : SLP6642G	Chassis No. : MHFB29F3202011972	Third Party Insurer : FIRST CAPITAL
Model : VIOS	Date of Accident : 03/08/2018	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
24	FRONT KNUCKLE ARM BEARING WITH HUB	1	493.0000	? BT - 493.00
25	FRONT SHOCK ABSORBER RH	1	379.0000	? BT - 379.00
26	FRONT SHOCK ABSORBER TOP MOUNT RH	1	83.0000	? X } 83.00
27	FRONT HEADLAMP RH	1	589.0000	? X } A1 589.00
28	FRONT HEADLAMP LOWER BRACKET RH	1	55.0000	? X } 55.00
29	FRONT HEADLAMP LOWER BRACKET CLIPS	4	2.5000	? X } 10.00
30	LESS 25% ON ITEM 1 - 29	1	2,756.6000	2711.60 } -2,756.60
31	FRONT WHEEL TYRE RH	1	250.0000	Xen 250.00
32	TO REFOCUS FRONT HEADLAMP	1	120.0000	30 120.00
33	TO DROP FRONT SUSPENSION UNDERCARRIAGE PARTS, REMOVE AND RENEWAL OF THE NECESSARY PARTS, TO PERFORM FINAL CHECKING AND TESTING	1	350.0000	150 350.00
34	TO TRANSFER OF FRONT RH WHEEL TYRE, RIM AND ON WHEEL BALANCING	1	180.0000	30 180.00
35	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	1	100.0000	60 100.00
36	TO RUST PROOFING OF THE AFFECTED PORTION	1	100.0000	40 100.00
37	TO TRANSFER OF FRONT RH DOOR FITTING, FIXTURE AND CONDUCT WATER SEEPAGE AND WINDS NOISE TEST	1	180.0000	Xnn 180.00
38	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND RELAIN THE SAME	1	800.0000	300 800.00
39	TO PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,000.0000	400 1,000.00

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :
--	--

Quotation No. : QO18/08-1067	Quotation Date : 04/08/2018	Terms : 30 DAYS
Vehicle No. : SLP6642G	Chassis No. : MHFB29F3202011972	Third Party Insurer : FIRST CAPITAL
Model : VIOS	Date of Accident : 03/08/2018	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00

Rasul
Hp 90010068
4 days
P/P
07/08/18 @ 1550
Resy by part

[Signature]
8/8/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Sub Total	11,214.80
GST(7.00%)	781.89
Total (SGD)	11,951.69

Please conduct the survey at
 Pegasus Engineering @ 74 Kian Teck Road Singapore 628800



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD
 74 KIAN TECK ROAD
 SINGAPORE 628800
 Officer in Charge : WEE TZE FAH
 Tel :
 Email :

Customer :
GRAB RENTALS PTE LTD
 18 SIN MING LANE
 #01-08 MIDVIEW CITY
 SINGAPORE 573960
 Attn :
 Tel :
 Fax No. :

Quotation No. : QO18/08-1067	Quotation Date : 04/08/2018	Terms : 30 DAYS
Vehicle No. : SLP6642G	Chassis No. : MHFB29F3202011972	Third Party Insurer : FIRST CAPITAL
Model : VIOS	Date of Accident : 03/08/2018	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	FRONT FENDER RH	1	612.0000	612.00
②	FRONT FENDER SPLASH SHIELD RH	1	288.0000	288.00
3	FRONT FENDER SPLASH SHIELD CLIPS	10	4.5000	45.00
4	FRONT FENDER STAND GARNISH	1	60.0000	60.00
5	FRONT DOOR RH	1	1,090.6000	1,090.60
6	FRONT DOOR OUTER MOULDING	1	74.0000	74.00
7	FRONT DOOR HINGE TOP AND BOTTOM	2	176.0000	352.00
8	FRONT DOOR CHECKER RH	1	153.5000	153.50
9	FRONT DOOR WEATHERSTRIP RH	1	199.1000	199.10
10	FRONT DOOR STICKER	2	35.0000	70.00
11	FRONT DOOR GLASS RUBBER BEADING	1	55.0000	55.00
12	FRONT DOOR GLASS RUN RUBBER CHANNEL	1	65.0000	65.00
13	FRONT DOOR INNER TRIM RH	1	539.0000	539.00
14	FRONT DOOR INNER TRIM CLIPS	10	2.5000	25.00
15	FRONT DOOR INNER HOLE COVER	1	45.0000	45.00
16	FRONT DOOR INNER HOLE COVER SEALANT	1	40.0000	40.00
17	FRONT DOOR REGULATOR	1	230.0000	230.00
18	FRONT DOOR REGULATOR MOTOR	1	690.0000	690.00
19	FRONT SPORT RIM RH	1	1,685.2000	1,685.20
20	FRONT DRIVESHAFT RH	1	1,296.0000	1,296.00
②1	FRONT LOWER ARM RH	1	1,013.0000	1,013.00
22	FRONT LOWER ARM BALL JOINT	1	60.0000	60.00
②3	FRONT KNUCKLE ARM RH	1	550.0000	550.00

Paul
 10/08/18
Reay

2508.00
 607.00
 1881.00

C/F 0.00
 Page 1 of 3



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :
--	--

Quotation No. : QO18/08-1067	Quotation Date : 04/08/2018	Terms : 30 DAYS
Vehicle No. : SLP6642G	Chassis No. : MHFB29F3202011972	Third Party Insurer : FIRST CAPITAL
Model : VIOS	Date of Accident : 03/08/2018	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
24	FRONT KNUCKLE ARM BEARING WITH HUB	1	493.0000	493.00
25	FRONT SHOCK ABSORBER RH	1	379.0000	379.00
26	FRONT SHOCK ABSORBER TOP MOUNT RH	1	83.0000	83.00
27	FRONT HEADLAMP RH	1	589.0000	589.00
28	FRONT HEADLAMP LOWER BRACKET RH	1	55.0000	55.00
29	FRONT HEADLAMP LOWER BRACKET CLIPS	4	2.5000	10.00
30	LESS 25% ON ITEM 1 - 29	1	-2,756.6000	-2,756.60
31	FRONT WHEEL TYRE RH	1	250.0000	250.00
32	TO REFOCUS FRONT HEADLAMP	1	120.0000	120.00
33	TO DROP FRONT SUSPENSION UNDERCARRIAGE PARTS, REMOVE AND RENEWAL OF THE NECESARY PARTS, TO PERFORM FINAL CHECKING AND TESTING	1	350.0000	350.00
34	TO TRANSFER OF FRONT RH WHEEL TYRE, RIM AND ON WHEEL BALANCING	1	180.0000	180.00
35	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	1	100.0000	100.00
36	TO RUST PROOFING OF THE AFFECTED PORTION	1	100.0000	100.00
37	TO TRANSFER OF FRONT RH DOOR FITTING, FIXTURE AND CONDUCT WATER SEEPAGE AND WINDS NOISE TEST	1	180.0000	180.00
38	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND RELAIN THE SAME	1	800.0000	800.00
39	TO PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,000.0000	1,000.00

Handwritten notes:
 872 W
 218 W
 654 W

Handwritten note: 1016

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer In Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :
---	---

Quotation No. : QO18/08-1067	Quotation Date : 04/08/2018	Terms : 30 DAYS
Vehicle No. : SLP6642G	Chassis No. : MHFB29F3202011972	Thrd Party Insurer : FIRST CAPITAL
Model : VIOS	Date of Accident : 03/08/2018	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
------	-------------	-----	------------	--------------

s/parts — # 2535.00
Additional info — # 300.00
Labour — # 1010.00
 P/P — # 3845.00

Resu
Hp 20010068
4 days
P/P
07/08/18 @ 1550
Resu by part

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/alter spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Sub Total	11,169.80
GST(7.00%)	781.89
Total (SGD)	11,951.69

Please conduct the survey at
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800

Stamford Tyres International Pte Ltd

19 Lok Yang Way
Singapore 628635

Phone Number: 6262 3355

Fax Number: 6262 1494

Customer:		Date:	8/7/2018 4:33 PM
Company:		VIN	
License No:	SLP6642G	Technician:	HENG
Odometer:	100523KM	Order No.:	

VEHICLE ALIGNMENT REPORT

TOYOTA, VIOS(Custom)(Custom), 2015-2017,

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	4°40'	1°20'	3°50'	4°43'
		Right	4°25'	1°20'	3°50'	4°29'
	Camber	Left	-0°39'	-1°00'	0°30'	-0°39'
		Right	-1°18'	-1°00'	0°30'	-1°18'
	Toe	Left	0°08'	-0°06'	0°06'	0°10'
		Right	0°08'	-0°06'	0°06'	0°09'
Total		0°16'	-0°11'	0°11'	0°19'	
Rear	Camber	Left	-1°01'	-1°45'	-0°15'	-1°01'
		Right	-0°54'	-1°45'	-0°15'	-0°53'
	Toe	Left	0°02'	----	----	0°02'
		Right	0°12'	----	----	0°14'
		Total	0°14'	0°00'	0°34'	0°16'
Thrust Angle		0°05'	----	----	0°06'	
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		11°34'	11°35'	11°35'	11°34'
	Right		11°45'	11°35'	11°35'	11°45'
Included Angle	Left		10°55'	----	----	10°55'
	Right		10°27'	----	----	10°27'
Toe Out On Turns	Left		----	----	----	----
	Right		----	----	----	----
Maximum Turns	Left		----	----	----	----
	Right		----	----	----	----
Toe Curve Change	Left		----	----	----	----
	Right		----	----	----	----
Setback	Front		5mm	----	----	8mm
	Rear		-1mm	----	----	-2mm
Track Width Diff.			-2mm			-1mm
Wheel Base Diff.			6mm			10mm
Front Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Rear Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Frame Angle						----




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18014380/R1qd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 31-12-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 7044S	Veh. Inspected	SLP 6642G
Policy No.		Coverage (\$)	0.00
Claim No.	D18005911MFSH	Excess (\$)	0.00
Assign From	LURENE	Assign Date	06/08/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA VIOS 1.5EA	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MHFB29F3202011972	Colour	GREY
Odometer	100522	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/50 R16	KUMHO	6 mm
L/H Front Tyre	195/50 R16	KUMHO	6 mm
R/H Rear Tyre	195/50 R16	KUMHO	6 mm
L/H Rear Tyre	195/50 R16	KUMHO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/08/2018	Inspection Date	07/08/2018
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 6642G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER RH	BENT	612.00	612.00
1	FRONT FENDER SPLASH SHIELD RH	CUT	288.00	288.00
10	FRONT FENDER SPLASH SHIELD CLIPS @\$4.50	NECESSARY	45.00	45.00
1	FRONT FENDER STAND GARNISH	NOT NECESSARY	60.00	-
1	FRONT DOOR RH	TO REPAIR SEE LABOUR	1,090.60	-
1	FRONT DOOR OUTER MOULDING	NOT NECESSARY	74.00	-
2	FRONT DOOR HINGE TOP AND BOTTOM @\$176.00	NOT NECESSARY	352.00	-
1	FRONT DOOR CHECKER RH	NOT NECESSARY	153.50	-
1	FRONT DOOR WEATHERSTRIP RH	NOT NECESSARY	199.10	-
2	FRONT DOOR STICKER @\$35.00	NOT NECESSARY	70.00	-
1	FRONT DOOR GLASS RUBBER BEADING	NOT NECESSARY	55.00	-
1	FRONT DOOR GLASS RUN RUBBER CHANNEL	NOT NECESSARY	65.00	-
1	FRONT DOOR INNER TRIM RH	NOT NECESSARY	539.00	-
10	FRONT DOOR INNER TRIM CLIPS @\$2.50	NOT NECESSARY	25.00	-
1	FRONT DOOR INNER HOLE COVER	NOT NECESSARY	45.00	-
1	FRONT DOOR INNER HOLE COVER SEALANT	NOT NECESSARY	40.00	-
1	FRONT DOOR REGULATOR	NOT NECESSARY	230.00	-
1	FRONT DOOR REGULATOR MOTOR	NOT NECESSARY	690.00	-
1	FRONT DRIVESHAFT RH	SERVICEABLE	1,296.00	-
1	FRONT LOWER ARM RH	BENT	1,013.00	1,013.00
1	FRONT LOWER ARM BALL JOINT	SERVICEABLE	60.00	-
1	FRONT KNUCKLE ARM RH	BENT	550.00	550.00
1	FRONT KNUCKLE ARM BEARING WITH HUB	BENT	493.00	493.00
1	FRONT SHOCK ABSORBER RH	BENT	379.00	379.00
1	FRONT SHOCK ABSORBER TOP MOUNT RH	NOT NECESSARY	83.00	-
1	FRONT HEADLAMP RH	NOT NECESSARY	589.00	-
1	FRONT HEADLAMP LOWER BRACKET RH	NOT NECESSARY	55.00	-
4	FRONT HEADLAMP LOWER BRACKET CLIPS @\$2.50	NOT NECESSARY	10.00	-
	LESS 25% DISCOUNT		-2,290.30	-845.00
			6,870.90	2,535.00

Report Ref No. CS/FCI18014380/R1qd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SPORT RIM RH (SN) LESS 25% DISCOUNT	SCRATCHED	1,685.20 -421.30	300.00 -
			1,263.90	300.00
	SPECIAL NETT ITEMS			
1	FRONT WHEEL TYRE RH (SN)	SERVICEABLE	250.00	-
			250.00	-
	LABOUR			
	TO REFOCUS FRONT HEADLAMP.		120.00	30.00
	TO DROP FRONT SUSPENSION UNDERCARRIAGE PARTS.REMOVE AND RENEWAL OF THE NECESSARY PARTS,TO PERFORM FINAL CHECKING AND TESTING.		350.00	150.00
	TO TRANSFER OF FRONT RH WHEEL TYRE,RIM AND ON WHEEL BALANCING.		180.00	30.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		100.00	60.00
	TO RUST PROOFING OF THE AFFECTED PORTION.		100.00	40.00
	TO TRANSFER OF FRONT RH DOOR FITTING,FIXTURE AND CONDUCT WATER SEEPAGE AND WINDS NOISE TEST.	NOT NECESSARY	180.00	-
	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF FRONT DOOR RH.		800.00	300.00
	TO PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,000.00	400.00
			2,830.00	1,010.00
GRAND TOTAL			11,214.80	3,845.00
RECOMMENDED COST OF REPAIRS				3,845.00

Report Ref No. CS/FCI18014380/R1qd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.