

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0551/2017
DATE : 18-DEC-2017

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 63387288
FAX : 68804838/ 3382522
MS LINA EXT: 824

OWNER'S NAME : FOO FANG ZERN JASON
ADDRESS : BLK 647 WOODLANDS RING ROAD
#11-68
S(730647)
TELEPHONE NO : 96892433

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100430696-02
VEHICLE NO : SKV1168Y
MODEL CODE : SJGCKK8
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20K904674
CHASSIS NO : JF1SJGK85FG055165
MILEAGE : 1 KM
DATE IN : 18/12/2017
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 16/12/2017

Print Date : 04/08/2018
Print Time : 14:52:56

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKV1168Y

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM AXA LOCATION TOA PAYOH LORONG 6 DATE 16/12/2017 TIME:1930 HRS		
3	ZZ/002	REPLACE/REFIX FRT LH FENDER, FRT LH DOOR, REAR LH DOOR	1680.00	2801
4	ZZ/003	RESPRAY FRT LH FENDER, FRT LH DOOR, REAR LH DOOR	1260.00	4201
5	ZZ/004	TRANSFER / BALANCE TYRE / RIM	nn 50.00	X
6	ZZ/005	TRANSFER DOOR (PER SIDE) MECHANISM	nn 400.00	X
7	ZZ/006	WHEEL ALIGNMENT	nn 200.00	X
8	ZZ/007	SUNDRIES	nn 100.00	X
TOTAL LABOUR CHARGES			3690.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKV1168Y

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
			NETT	LIST	S/NETT	S/LIST REMARKS
1	DISC WHEEL AL 18 18A	28111SG020	<i>R</i> 750.00	<i>X</i>		
2	FRT FENDER LH (W/O SIGNAL LP)	57120SG0309P	<i>R</i> 270.00	<i>X</i>		
3	TAPE DR SASH F F LH	90422SG010	<i>nn</i> 5.40	<i>X</i>		
4	TAPE DR SASH F M LH	90422SG030	<i>nn</i> 18.00	<i>✓</i>		
5	TAPE DR SASH F R LH	90422SG050	<i>nn</i> 18.00	<i>X</i>		
SUB TOTAL			1061.40	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			212.28	0.00	0.00	0.00
GRAND TOTAL			849.12	0.00	0.00	0.00
OVERALL TOTAL			849.12			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKV1168Y

TOTAL LABOUR CHARGES	3690.00
TOTAL SPARE PARTS CHARGES	849.12
GRAND TOTAL	4539.12 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

*Not Authorised
Resurvey After Repair
2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: