

Stacey | CC 4, Asm 180 14405, N 2037 | LKK IDAC 62125

ASSIGNMENT

Surveyor: N&Z

DOI: 8/8/2018

Date / Time: 7/8/2018

Registered in Meritum: _____

Pre-assign / CCU / FTE



Insured Vehicle No. : SJL3369K

Name of Insured : Enterprise Car Rental Plc

Insured Tel No. : _____

Excess Sec II :SS 1,500.00

Is driver the owner? (YES/NO) YES (NO)

If NO, Driver Name / Age : Mumuk Shah B. Md. Mughanti

Driver Tel No. : 91319449

Nature of Accident : _____

(VL: YES/NO) _____

Claim No. : 58MJOR6C

Policy No. : VFXIP2132888 LV

Make / Model : T. A110

Place of Accident : Orchard Rd

OI GIA REPORT: YES/NO ; TP GIA REPORT: YES/NO

Insured Liability : % Final ? Yes / No

SJL3369K

SJL2749R

SL62183m



INSRS: WSP: Tel: Liability: RMKS: 01



INSRS: WSP: world Auto Tel: Liability: TP RMKS: Proof!



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/ Time

12/8 show

SJL2749R - X; SJL3369K - MAT/ME18000562/23 : 100% 9/1/19

FRE REVIEW : 100% CC DID NOT.

LETTER SENT TO 01

EMAIL WSP LIABILITY CLAIM.

STAGE DATE / PIC

Non-Reporting ltr (1st)		
Non-Reporting ltr (2nd)		
Non-Reporting ltr (Final)		
Notification ltr (if non-pickup)		
Call OI: ASHER 0.9.18		
After call ltr to OI		
Documentation Check List:	Handler	Typist
Notification ltr (if non-pickup)		
After call ltr to OI	<input checked="" type="checkbox"/>	
Authorisation To Act	<input checked="" type="checkbox"/>	
Release Voucher: D=EDON.	<input checked="" type="checkbox"/>	
Final Repair Bill	<input checked="" type="checkbox"/>	
Car Rental Invoice		
Towing Invoice		
LTA / GIA :	<input checked="" type="checkbox"/>	
Medical Bill:		
PIR:		
Mandate/Reject Instruction:	<input checked="" type="checkbox"/>	
LOD	<input checked="" type="checkbox"/>	
Payment Breakdown Form:		
Post-Repair Photos:		
Others:		

PRELIMINARY ADVICE Date/Time: 6/8 Sent By: [Signature]

FINALIZATION Date/Time: Confirm with: Confirm by: NPS: Repair Cost: Pfy \$5 10,200 (9 days) Reduction: 53 % Email Call

FINAL SETTLEMENT Date/Time: 26-05-19 Confirm with: Email Call Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 28 If NO or B 28, Ass. Lia: 100%/-

Repair Cost: w/kgf \$5 10,914.14 3 VEH (1 ORO LOST) Loss of Rental (LOR): \$5 - (days) Loss of Use (LOU): \$5 500.00 (\$ 40 x 9 days) Loss of Income (LOI): \$5 - (\$ x days) LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: \$5 200 Medical: \$5 - Disbursement: \$5 - (e.g. Tow/ Independent) Legal Cost: \$5 - Total: \$5 11,458.14 Global Sum \$5: 1) Claim status: Normal/Reject/Private Settle 2) Report Format: TP 3) Survey fee: * 350

FINAL PAYMENT Date/Time: 26-05-19 Confirm with: S: P: A: Email Call

Payee 1: \$5 11,458.14 Name 1: WORLD AUTO PTE LTD Payee 2: (Strike if N.A.) \$5 Name 2: Payee 3: (Strike if N.A.) \$5 Name 3:

COMMENT 11/6/19

Surveysor NAZ

REF: AXA

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 85k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLJ 2749 R Yr Regn: 1 DEC 2016

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIUS HYBRID c.c. 1,798

Colour: SILVER A/C: Insured / Std / NI / NA

Sp. Reading: 70,674 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FYX03538315

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rrim or

Tyre Size: F: 195/65 R15

R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 5/8/18 D.O.I. 8/8/18

Survey held at WORLD AUTO

Des. of Damages Frnt / Rear / O/S / N/S / U/C / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

AXA PIP

Date / Time	Action / Instruction
	PIP: +10,200 (RSD: +11,649.25 50%)

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Survey Fee:	_____
Transportation:	_____
_____ \$ + RS _____ \$	_____
Photos	_____
Others	_____
Weekend (\$ _____)	_____
TOTAL	_____

Date/Time, File Return to? _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Report Format : _____
 Lump Sum / I.B.I: (\$ _____)

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, Singapore 577200
 Tel No. : 6451 3033 Fax No. : 6455 7676
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department
 Contact : 336 7288 Fax No. : 880 4828

Estimate : ES000266

Date : 06/08/2018
 Vehicle Num : SLJ 2749R(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng : 3TDK03F-K0153FJ15
 Accident Date : 05/08/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BOOT LID	1,400.00	1,400.00
2.	1	REAR BOOTLID OUTER GARNISH	630.00	630.00
3.	1	REAR BOOT HYBRID EMBLEM (PRIUS)	39.00	39.00
4.	1	REAR BOOT HYBRID EMBLEM (PRIUS)	39.00	39.00
5.	1	REAR WINDSCREEN GLASS MOULDING	250.00	250.00
6.	2/LH RH	REAR TAIL LAMP	600.00	1,200.00
7.	1	REAR BOOT INNER TRIM BOARD	345.00	345.00
8.	1	REAR BOOT WEATHER STRIP	230.00	230.00
9.	1	REAR BUMPER	900.00	900.00
10.	1	REAR BOOT LOCK ASSY	230.00	230.00
11.	2/LH RH	REAR BUMPER TAILLAMP	300.00	1,800.00
12.	1	REAR BUMPER TOW COVER	39.00	39.00
13.	1	REAR BUMPER REINFORCEMENT	345.00	345.00
14.	1	REAR LOWER BUMPER	570.00	570.00
15.	2/LH RH	REAR BUMPER EXTENSION FILLER	220.00	440.00
16.	2/LH RH	REAR BUMPER RETAINER	120.00	240.00
17.	1	REAR END PANEL	750.00	750.00
18.	1	FRONT BUMPER	550.00	550.00
19.	2/LH RH	FRONT HEADLAMP ASSY	2,550.00	5,100.00
20.	1	FRONT GRILLE EMBLEM	100.00	100.00
21.	2/LH RH	FRONT BUMPER TOW COVER RH	89.00	178.00
22.	2/LH RH	FRONT FOG LAMP	390.00	780.00
23.	1	FRONT BUMPER REINFORCEMENT	350.00	350.00
24.	1	FRONT BUMPER REINFORCEMENT FOAM	120.00	120.00
25.	1	FRONT NUMBER PLATE GARNISH	120.00	120.00
26.	1	FRONT BUMPER LOWER GRILLE	170.00	170.00
27.	1	FRONT RADIATOR GRILLE	340.00	340.00
28.	1	FRONT BUMPER LOWER BEAM	240.00	240.00
29.	1	FRONT BUMPER LOWER BEAM ABSORBER COVER	120.00	120.00

CONTINUE ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, Singapore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department
 Contact : 318 7288 Fax No. : 880 4828

Estimate : ES000266

Date : 05/08/2018
 Vehicle Num. : SLJ 2749R(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 05/08/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
38.	2/LH RH	FRONT BUMPER LOWER BEAM BRACKET	120.00	240.00
		List Total S\$:		19,335.00
		25.00% Discount S\$:		4,833.75
			5742	14,501.25
		SPECIAL NETT ITEMS :		
1.	1	REAR BOOTLID OUTER GARNISH CLIPS		40.00
2.	1	REAR NUMBER PLATE W/CASING		40.00
3.	2	REAR WINDSCREEN SEALANT	120.00	240.00
4.	1	REAR BOOT INNER TRIM BOARD CLIP		40.00
5.	1	REAR BUMPER CLIP		40.00
6.	1	REVERSE SENSOR		200.00
7.	1	REAR END PANEL TOP GARNISH CLIPS		40.00
8.	1	FRONT BUMPER CLIP		40.00
9.	1	FRONT NUMBER PLATE WITH CASING		40.00
		Special Nett Total S\$:	480	800.00
		LABOUR :		
		TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES		180.00
		REMOVE & REFIT REAR WINDSCREEN GLASS (2PC WINDSCREEN GLASS)		260.00
		LABOUR TO REMOVE REAR ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.		1,000.00
		PUTTY & SPRAY PAINT REAR & ALL AFFECTED AREAS		2,000.00
				3,300

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, Singapore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 142 Cecil Street #01-01 GB Building
 069542

Attention: Motor-Claims Department
 Contact : 338 7238 Fax No. : 880 4828

Estimate : ES000266

Date : 06/08/2018
 Vehicle Num: SLJ 2749R(LCR)
 Make/Model TOYOTA PRIUS HYBRID
 Chassis/Eng#
 Accident Date 05/08/2018
 Claim No.
 Reference :
 Policy No.

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

(INNER/ OUTER)

LABOUR TO REMOVE FRT ACCIDENT DAMAGED PARTS IN ORDER TO
 REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN
 PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.

1,200.00 800

PUTTY & SPRAY PAINT FRT & ALL AFFECTED AREAS
 (INNER/ OUTER)

1,300.00 900

TO CHECK ELECTRICAL WIRING AND FOCUS HEADLAMP

100.00 80

Labour Total S\$

6,020.00

PARTS 57656
 LHS 35% 57942
 3 NETT 440
 LABOUR 43980
 TOTAL 110,202 / 9 DAYS

1,250

E. & O.E.

Total S\$:

21,821.25

for WORLD AUTO PTE LTD

Customer hereby notifies and agrees to contact hence notify
 the Repairer of the following:
 • To receive information spray painting
 • To display damaged parts during recovery
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modifications to be allowed
 • Supplementary items must be insured and
 subject to final approval from Insurance Company

Authorised by Repairer
 Signature:
 Date:

NPZ LKR
 8/8/18 170.
 PIP
 9 DAYS
 BEFORE PAINTING TO
 4260V220
 Naz@lkk auto.com

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD

143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department
 Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000266

Date : 06/08/2018
 Vehicle Num. : SLJ 2749R(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 05/08/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BOOT LID		1,400.00
2.	1	REAR BOOTLID OUTER GARNISH		680.00
3.	1	REAR BOOT HYBRID EMBLEM (PRIUS)		89.00
4.	1	REAR BOOT HYBRID EMBLEM (PRIUS)		89.00
5.	1	REAR WINDSCREEN GLASS MOULDING		250.00
6.	2/LH RH	REAR TAIL LAMP	600.00	1,200.00
7.	1	REAR BOOT INNER TRIM BOARD		345.00
8.	1	REAR BOOT WEATHER STRIP		280.00
9.	1	REAR BUMPER		900.00
10.	1	REAR BOOT LOCK ASSY		280.00
11.	2/LH RH	REAR BUMPER TAILLAMP	900.00	1,800.00
12.	1	REAR BUMPER TOW COVER		89.00
13.	1	REAR BUMPER REINFORCEMENT		345.00
14.	1	REAR LOWER BUMPER		570.00
15.	2/LH RH	REAR BUMPER EXTENSION FILLER	220.00	440.00
16.	2/LH RH	REAR BUMPER RETAINER	120.00	240.00
17.	1	REAR END PANEL		750.00
18.	1	FRONT BUMPER		550.00
19.	2/LH RH	FRONT HEADLAMP ASSY	2,550.00	5,100.00
20.	1	FRONT GRILLE EMBLEM		100.00
21.	2/LH RH	FRONT BUMPER TOW COVER RH	89.00	178.00
22.	2/LH RH	FRONT FOG LAMP	980.00	1,960.00
23.	1	FRONT BUMPER REINFORCEMENT		350.00
24.	1	FRONT BUMPER REINFORCEMENT FOAM		120.00
25.	1	FRONT NUMBER PLATE GARNISH		120.00
26.	1	FRONT BUMPER LOWER GRILLE		170.00
27.	1	FRONT RADIATOR GRILLE		340.00
28.	1	FRONT BUMPER LOWER BEAM		240.00
29.	1	FRONT BUMPER LOWER BEAM ABSORBER COVER		120.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department
 Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000266

Date : 06/08/2018
 Vehicle Num. : SLJ 2749R(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 05/08/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
30.	2/LH RH	FRONT BUMPER LOWER BEAM BRACKET	120.00	240.00 ?
		List TotalS\$:		19,335.00
		25.00% Discount S\$:		4,833.75
				14,501.25
		SPECIAL NETT ITEMS :		
1.	1	REAR BOOTLID OUTER GARNISH CLIPS		40.00 / ncc
2.	1	REAR NUMBER PLATE W/CASING		40.00 / PT
3.	2	REAR WINDSCREEN SEALANT	120.00	240.00 / ncc
4.	1	REAR BOOT INNER TRIM BOARD CLIP		40.00 ?
5.	1	REAR BUMPER CLIP		40.00 / ncc
6.	1	REVERSE SENSOR		280.00 X SVE
7.	1	REAR END PANEL TOP GARNISH CLIPS		40.00 ?
8.	1	FRONT BUMPER CLIP		40.00 / ncc
9.	1	FRONT NUMBER PLATE WITH CASING		40.00 / DT
		Special Nett Total S\$:		800.00
		LABOUR :		
		TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES		180.00 100
		REMOVE & REFIT REAR WINDSCREEN GLASS (2PC WINDSCREEN GLASS)		360.00 200
		LABOUR TO REMOVE REAR ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.		1,600.00 1,000
		PUTTY & SPRAY PAINT REAR & ALL AFFECTED AREAS		1,600.00 900

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department
 Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000266

Date : 06/08/2018
 Vehicle Num. : SLJ 2749R(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 05/08/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		(INNER/ OUTER)		
		LABOUR TO REMOVE FRT ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.	1,200.00	800
		PUTTY & SPRAY PAINT FRT & ALL AFFECTED AREAS (INNER/ OUTER)	1,300.00	900
		TO CHECK ELECTRICAL WIRING AND FOCUS HEADLAMP.	180.00	80
		Labour Total S\$:		6,520.00

E. & O.E.

Total S\$:

21,821.25
 =====

for WORLD AUTO PTE LTD

Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

NAZ LKIC
 8/8/18 1740

PIP

9 DAYS

BEFORE PAINT PHOTO

98804220

Naz@lkkauto.com



MANDATE REQUEST FOR S8M00R6C

Type

🔔 Question

Message

Liability: Insured involved in 3 vehicle chain collision insured was the last vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$10,916.14 (w/GST) Loss of Use; \$720.00 (9days x \$80) LTA Search: \$2.00 Total: \$11,638.14 Immediate Advice with Mandate and revised estimate for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (15/02/2019)

Reply

<< **Re:RE: MANDATE IA (S8M00R6C)**

Type

Question

Message

pls proceed

Reply

Nivitha (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Tuesday, 7 August 2018 3:34 PM
To: assignments
Subject: FW: Request for Third Party Motor Claim Survey (SLJ2749R) DOA: 05-08-2018

Hi Nivitha,

Kindly assist.

TP AXA – Smart.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

4:22pm @ 7/8/18
person @ Ainee
vehicle in
amry on 08/08/18

From: ainee31@worldauto.com.sg <ainee31@worldauto.com.sg>
Sent: Monday, 6 August, 2018 4:48 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Cc: 'Daniel Tan' <worldautopl@yahoo.com.sg>
Subject: Request for Third Party Motor Claim Survey (SLJ2749R) DOA: 05-08-2018

Good morning/afternoon,

We would like to request for a third party motor claim survey, details as follow;

Our Vehicle: SLJ2749R

Your Insured: SJL3369K

DOA: 05-08-2018

Our vehicle is currently in the workshop, address as follow;

World Auto Pte Ltd

No.1, Kranji Loop

Singapore 739535

Please response immediately upon receiving this request, send us your list of Loss Adjustor for our choice within 48 hours.

Kindly note that should you fail to response to us within the above stipulated timeline, we may, at our discretion, appoint our own Loss Adjustor to perform this PRI.

Ainee
Thanks and Rgds,
World Auto Pte Ltd
Kranji: 63621776
Fax: 63631250



WORLD AUTO PTE LTD

47 JALAN PEMIMPIN #01-02/03

HALCYON 2

SINGAPORE 577200

12/01/2019

Your Ref :

Our Ref : TP/2160/2018

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #24-01 AXA TOWER
SINGAPORE 06811

Attn : Motor Claim Dept – Third Party

Dear Sirs,

ACCIDENT INVOLVING VEH.NO. SLJ2749R / SJL3369K ON 05/08/2018

Reference is made to the aforesaid matter (on behalf of our client M/S LCRF PL)

Enclosed herewith are the following documents for your information and necessary actions only :-

- a) Our Final Repair Bill

Please assist in our claims of :

Final Bill	\$ 10202.00	(already finalised)
GST 7%	\$ 714.14	
Search Fee	\$ 2.00	
Loss of Use (\$60x 9 days)	\$ 540.00	
	<hr/>	
Amount	\$ 11458.14	

Kindly let us have your reply and payment as soon as possible.

Thank you for your kind attention and much appreciated assistance.

Yours faithfully,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

12 SEPT 2018

ENTERPRISE CAR RENTAL PTE. LTD.
421 TAGORE INDUSTRIAL AVENUE
#01-20 TAGORE 8
SINGAPORE 787805

Dear Sir/ Mdm

OUR REF : CC4/ASM18014465/Nea3
YOUR REF : SJL 3369K
ACCIDENT INVOLVING SJL 3369K AND SLJ 2749R ALONG ORCHARD RD NEAR
CENTREPOINT ON 05/08/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s WORLD AUTO PTE LTD acting on behalf of the owner of SLJ 2749R against your motor insurance policy.

Basing on the circumstances of the accident reported by both parties, where your vehicle was involved in a three (3) vehicle chain collision, your vehicle was the 3rd vehicle rear-ended the Third Party Vehicle SLJ 2749R.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy. We also wish to advise that there is an excess of S\$1,500.00 attached with Third Party Claims.

AXA shall keep you informed of when to make the excess payment, which cheque is to be made in favor of "AXA Insurance Pte Ltd". Please indicate your vehicle registration number and the date of accident on the back of the cheque.

As Insurers, AXA shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following to cst@axa.com.sg **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to cst@axa.com.sg or deliver it by hand to AXA's Customer Care Centre.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact our Claims Service Team at 1800-880 4888 at our operating hours 9:00am to 5:30pm (press 1 for GI and option 3 for claims) or cst@axa.com.sg. Please quote our claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: ashersng@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

LETTER OF AUTHORISATION

In the matter of the following accident:-

DATE OF ACCIDENT : 05-08-2018

CLIENT'S VEHICLE NO : SLJ2749R

PLACE OF ACCIDENT : ORCHARD RD INFRONT CENTRE POINT

THIRD PARTY VEHICLE NO : SJL3369K

I/We, **LCRF PTE LTD**

ADDRESS: **29 PAYA LEBAR ROAD, PAYA LEBAR OFFICE CENTRE**

UEN/NRIC/FIN NO : **201624597K**

Tel. (O) _____ (H) _____ (MOBILE) _____

I/We hereby authorize and appoint World Auto Pte Ltd to act for me/us in respect of the above matter up to the final conclusion of the said matter.

I/We hereby authorize and appoint World Auto Pte Ltd to act for me/us for the purpose of negotiating and enter into settlement with the tortfeasor, their insurers or solicitors appointed by the tortfeasor/insurers without the need to commence action.

I/We hereby authorize World Auto Pte Ltd to receive on my/our behalf all settlement sums and disbursements including loss of use/rental to pay to yourselves all costs you may at any time receive in connection with the above mention matter.

DATED THIS 06TH DAY OF August YEAR 2018



Name: **LCRF PTE LTD**
UEN No: **201624597K**



Asher

AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SJL 3369K	(Insd veh)	Model: TOYOTA PRIUS HYBRID - 1.8 (A)
	SLJ 2749R	(TP veh)	
Date of Accident/ Time:	05/08/2018 / 13:30		

Repair Estimate	: \$	23,248.74	
Final Repair Cost	: \$	10,916.14	
Loss of Use	: \$	540.00	9 days at \$60.00 per day
Rental (if any)	: \$	-	days at \$ per day
LTA / GIA Search Fee	: \$	2.00	
Others:	: \$	-	
	: \$	-	
Final Settlement Sum	: \$	11,456.14	

Payee Name : WORLD AUTO PTE LTD

Is Third Party Workshop GIA Registered? [x] YES [] NO (Kindly indicate below)

A)	For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: <u>28</u>
	BOLA Liability: <u>100</u> (%)	Assessed Liability (*): <u>100</u> (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks:

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are **not received within 7 days** of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.



Signature of workshop representative / Workshop stamp

Name of Representative: Ceraldine Foong

Date: 22/5/2019

Signature of Witness / Workshop stamp (if applicable)

Name of Witness: Shirley Foo

Date: 22/5/2019



Naz

Signature of AXA's surveyor/representative:

Name of AXA's surveyor /Representative:

Date: 11/6/19

WORLD AUTO PTE LTD
 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG
 S'PORE 577200
 Tel No. : 64513933 Fax No. : 64557576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #24-01 AXA TOWER
 S'PORE 068811

Attention : Motor Claim Department
 Contact : 68804888 Fax No. : 68804838

Tax Invoice : F189098

Date : 11/01/2019
 Vehicle Num. : SLJ 2749R
 Make/Model : TOYOTA PRIUS, 1.8 HYBRID
 Chassis/Eng# :
 Accident Date : 05/08/2018
 Claim No. : TP/2160/2018
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	BOOTLID		1,200.00
2.	1	BOOTLID OUTER GARNISH		600.00
3.	1	BOOTLID 'HYBRID' EMBLEM		89.00
4.	1	BOOTLID 'PRIUS' EMBLEM		89.00
5.	1	REAR WINDSCREEN GLASS MOULDING		250.00
6.	1	REAR BOOT INNER TRIM BOARD		345.00
7.	1	REAR BOOT WEATHERSTRIP		280.00
8.	1	REAR BUMPER		700.00
9.	1	REAR BUMPER TOW COVER		89.00
10.	1	REAR BUMPER REINFORCEMENT		345.00
11.	1	REAR LOWER BUMPER		570.00
12.	1	REAR BUMPER EXTENSION FILLER		220.00
13.	1	REAR END PANEL		750.00
14.	1	FRONT BUMPER		550.00
15.	1	FRONT GRILLE EMBLEM		100.00
16.	1	FRONT BUMPER TOW COVER		89.00
17.	1	FOG LAMP		980.00
18.	1	FRONT BUMPER REINFORCEMENT FOAM		120.00
19.	1	FRONT NUMBER PLATE GARNISH		120.00
20.	1	FRONT BUMPER LOWER GRILLE		170.00
List Total S\$:				7,656.00
25.00% Discount S\$:				1,914.00
				<hr/>
				5,742.00
SPECIAL NETT ITEMS :				
1.	1SET	BOOTLID OUTER GARNISH CLIPS		40.00
2.	1SET	REAR NUMBER PLATE W/CASING		40.00
3.	2	REAR WINDSCREEN SEALANT	120.00	240.00
4.	1	REAR BOOT INNER TRIM BOARD CLIPS		40.00
5.	1SET	REAR BUMPER CLIPS		40.00
6.	1SET	FRONT BUMPER CLIPS		40.00
7.	1	FRONT NUMBER PLATE W/ CASING		40.00
Special Nett Total S\$:				480.00
LABOUR :				
TRANSFER REAR BOOTLID MECHANISM & ACCESSORIES				100.00

CONTINUE / ...

WORLD AUTO PTE LTD
 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG
 S'PORE 577200
 Tel No. : 64513933 Fax No. : 64557576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #24-01 AXA TOWER
 S'PORE 068811

Attention : Motor Claim Department
 Contact : 68804888 Fax No. : 68804838

Tax Invoice : F189098

Date : 11/01/2019
 Vehicle Num. : SLJ 2749R
 Make/Model : TOYOTA PRIUS, 1.8 HYBRID
 Chassis/Eng# :
 Accident Date : 05/08/2018
 Claim No. : TP/2160/2018
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		REMOVE & INSTALL REAR WINDSCREEN GLASS (x 2PCS)		200.00
		REMOVE & REPLACE REAR ACCIDENT DAMAGED PARTS FOR REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL		1,000.00
		PUTTY & SPRAY PAINT ON REAR & ALL AFFECTED AREAS		900.00
		REMOVE & REPLACE FRONT ACCIDENT DAMAGED PARTS FOR REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL		800.00
		PUTTY & SPRAY PAINT ON FRONT & ALL AFFECTED AREAS		900.00
		CHECK WIRING & FOCUS HEADLAMP		80.00
		Labour Total S\$:		3,980.00

Total S\$: 10,202.00
 GST 7% S\$: 714.14
 Amount Due S\$: 10,916.14

8/6/2018

Invoice



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

5 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-119995

Date of Request: 06/08/2018

Your Ref No: Online Purchase

World Auto Pte Ltd
47 Jln Pemimpin
#01-02/03 Halcyon 2
Singapore 577200

Dear Sir/Madam,

Enquiry Date: 06/08/2018
Enquiry By: Wong Yin Cheng
TP Vehicle No.: SJL3369K
Accident Date: 05/08/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJL3369K	AXA Insurance Pte Ltd	01/06/2018-31/05/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

8/8/2018

Invoice



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-119995

Date of Request: 06/08/2018

Your Ref No:

Online Purchase

World Auto Pte Ltd
47 Jln Pemimpin
#01-02/03 Halcyon 2
Singapore 577200

Dear Sir/Madam,

Enquiry Date: 06/08/2018
Enquiry By: Wong Yin Cheng
TP Vehicle No.: SJL3369K
Accident Date: 05/08/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

GIRO Cash Cheque

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SJL 3369K (Insd veh)	Model:	TOYOTA PRIUS HYBRID
	SLJ 2749R (TP veh)		
Date of Accident:	05/08/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	23,348.74	
Final Repair Cost	:	\$	10,916.14	
Loss of Use	:	\$	540.00	9days at \$60.00 per day
Rental (if any)	:	\$		days
LTA / GIA Search Fee	:	\$	2.00	
Others:	:	\$	0.00	

	:	\$	
Final Settlement Sum	:	\$	11,458.14

Is Third Party Workshop GIA Registered? YES NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ Ne BOLA Scenario No: _____
 28
 BOLA Liability: ___100___(%) Assessed Liability (*):___100___(%)
 * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	WORLD AUTO PTE LTD	:	\$ 11,458.14

 JOANNE LEE KHANG MIN
 LKK Auto Consultants Pte Ltd

 01/07/2019
 Date

Please attach all the supporting documents to the form.
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18014465/Nea3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:STACEY NG

Date : 01-07-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJL 3369K	Veh. Inspected	SLJ 2749R
Policy No.	VFX/P2132888	Coverage (\$)	0.00
Claim No.	S8M00R6C	Excess (\$)	0.00
Assign From		Assign Date	07/08/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS HYBRID	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTDKB3FUX03538315	Colour	SILVER
Odometer	70674	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	PIRELLI	6 mm
L/H Front Tyre	195/65 R15	PIRELLI	6 mm
R/H Rear Tyre	195/65 R15	PIRELLI	6 mm
L/H Rear Tyre	195/65 R15	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	05/08/2018	Inspection Date	08/08/2018
Survey held at	WORLD AUTO PTE LTD 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG SINGAPORE 577200		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 2749R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID (CONSISTENT)	BENT	1,400.00	1,200.00
1	REAR BOOTLID OUTER GARNISH (CONSISTENT)	DEFORMED	680.00	600.00
1	REAR BOOT HYBRID EMBLEM (PRIUS) (CONSISTENT)	NECESSARY	89.00	89.00
1	REAR BOOT HYBRID EMBLEM (PRIUS) (CONSISTENT)	NECESSARY	89.00	89.00
1	REAR WINDSCREEN GLASS MOULDING (CONSISTENT)	NECESSARY	250.00	250.00
2	LH / RH REAR TAIL LAMP @\$600.00 (CONSISTENT)	SERVICEABLE	1,200.00	-
1	REAR BOOT INNER TRIM BOARD (CONSISTENT)	CRACKED	345.00	345.00
1	REAR BOOT WEATHERSTRIP (CONSISTENT)	TORN	280.00	280.00
1	REAR BUMPER (CONSISTENT)	DENTED	900.00	700.00
1	REAR BOOT LOCK ASSY (CONSISTENT)	SERVICEABLE	280.00	-
2	LH / RH REAR BUMPER TAILLAMP @\$900.00 (CONSISTENT)	SERVICEABLE	1,800.00	-
1	REAR BUMPER TOW COVER (CONSISTENT)	CRACKED	89.00	89.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	345.00	345.00
1	REAR LOWER BUMPER (CONSISTENT)	DENTED	570.00	570.00
2	LH / RH REAR BUMPER EXTENSION FILLER @\$220.00 (CONSISTENT)	N/S CRACKED / O/S SERVICEABLE	440.00	220.00
2	LH / RH REAR BUMPER RETAINER @\$120.00 (CONSISTENT)	SERVICEABLE	240.00	-
1	REAR END PANEL (CONSISTENT)	DENTED	750.00	750.00
1	FRONT BUMPER (CONSISTENT)	CRACKED	550.00	550.00
2	LH / RH FRONT HEADLAMP ASSY @\$2550.00 (CONSISTENT)	SERVICEABLE	5,100.00	-
1	FRONT GRILLE EMBLEM (CONSISTENT)	NECESSARY	100.00	100.00
2	LH / RH FRONT BUMPER TOW COVER RH @\$89.00 (CONSISTENT)	O/S SCRATCHED	178.00	89.00
2	LH / RH FRONT FOG LAMP @\$980.00 (CONSISTENT)	O/S SCRATCHED	1,960.00	980.00
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	SERVICEABLE	350.00	-
1	FRONT BUMPER REINFORCEMENT FOAM (CONSISTENT)	DEFORMED	120.00	120.00
1	FRONT NUMBER PLATE GARNISH (CONSISTENT)	CRACKED	120.00	120.00
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	BENT	170.00	170.00
1	FRONT RADIATOR GRILLE (CONSISTENT)	SERVICEABLE	340.00	-

Report Ref No. CC4/ASM18014465/Nea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER LOWER BEAM (CONSISTENT)	SERVICEABLE	240.00	-
1	FRONT BUMPER LOWER BEAM ABSORBER COVER (CONSISTENT)	SERVICEABLE	120.00	-
2	LH / RH FRONT BUMPER LOWER BEAM BRACKET @\$120.00 (CONSISTENT)	SERVICEABLE	240.00	-
	LESS 25% DISCOUNT		-4,833.75	-1,914.00
			14,501.25	5,742.00
	SPECIAL NETT ITEMS			
1	REAR BOOTLID OUTER GARNISH CLIPS (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	REAR NUMBER PLATE W/CASING (SN) (CONSISTENT)	DENTED	40.00	40.00
2	REAR WINDSCREEN SEALANT @\$120.00 (SN) (CONSISTENT)	NECESSARY	240.00	240.00
1	REAR BOOT INNER TRIM BOARD CLIP (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	REVERSE SENSOR (SN) (CONSISTENT)	SERVICEABLE	280.00	-
1	REAR END PANEL TOP GARNISH CLIPS (SN) (CONSISTENT)	NOT NECESSARY	40.00	-
1	FRONT BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	FRONT NUMBER PLATE WITH CASING (SN) (CONSISTENT)	DENTED	40.00	40.00
			800.00	480.00
	LABOUR			
	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES.		180.00	100.00
	REMOVE & REFIT REAR WINDSCREEN GLASS (2PC WINDSCREEN GLASS)		360.00	200.00
	LABOUR TO REMOVE REAR ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.		1,800.00	1,000.00
	PUTTY & SPRAY PAINT REAR & ALL AFFECTED AREAS. (INNER / OUTER)		1,500.00	900.00
	LABOUR TO REMOVE FRT ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.		1,200.00	800.00

Report Ref No. CC4/ASM18014465/Nea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY & SPRAY PAINT FRT & ALL AFFECTED AREAS (INNER / OUTER).		1,300.00	900.00
	TO CHECK ELECTRICAL WIRING AND FOCUS HEADLAMP.		180.00	80.00
			6,520.00	3,980.00
GRAND TOTAL			21,821.25	10,202.00
RECOMMENDED COST OF REPAIRS				10,202.00

Report Ref No. CC4/ASM18014465/Nea3q2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

◀ Service Request Details

Claim

S8M00R6C

Reference

CC4/ASM18014465/Nea3q2 

Loss Date

5 August 2018

Report Date

6 Aug 2018 5:41:00 PM

Request Date

7 August 2018

Due Date

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident Vehicle Registration

SLJ2749R

Make

HYUNDAI PRIUS

Service Address

...

Primary Contact/Insured

ENTERPRISE CAR RENTAL PTE LTD
421 TAGORE INDUSTRIAL AVENUE, #01-20 TAGORE 8, 787805, Singapore

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)

Document Type

Document SubType

[+ Upload Documents](#)

NAME	 LKKAdjustment1a.pdf
TYPE	Forms / Claim Documents
SUB-TYPE	Others
AUTHOR	LKK AUTO CONSULTANTS PTE LTD (TP)
DATE UPLOADED	5 July 2019

NAME	 GIA SEARCH.pdf
TYPE	Forms / Claim Documents

AUTHOR LKK AUTO CONSULTANTS PTE LTD (TP)

DATE UPLOADED 5 July 2019

NAME  PAYMENT BREAKDOWN_EXPRESS SETTLEMENT FORM.pdf

TYPE Forms / Claim Documents

SUB-TYPE Satisfaction / Discharge Voucher

AUTHOR LKK AUTO CONSULTANTS PTE LTD (TP)

DATE UPLOADED 5 July 2019

NAME  LKKInspection.pdf

TYPE Forms / Claim Documents

SUB-TYPE Others

AUTHOR LKK AUTO CONSULTANTS PTE LTD (TP)

DATE UPLOADED 5 July 2019

NAME  LKKInvoice1 (3).pdf

TYPE Invoice

SUB-TYPE Surveyor/ Assessor expense

AUTHOR LKK AUTO CONSULTANTS PTE LTD (TP)

DATE UPLOADED 5 July 2019

NAME  PAYMENT BREAKDOWN_LKK.pdf

TYPE Forms / Claim Documents

SUB-TYPE Others

DATE UPLOADED 5 July 2019

NAME  LETTER TO OI.pdf

TYPE Letters and Correspondence

SUB-TYPE Policy Holders / Insured

AUTHOR LKK AUTO CONSULTANTS PTE LTD (TP)

DATE UPLOADED 5 July 2019

NAME  WORKSHOP INVOICE_0001.pdf

TYPE Invoice

SUB-TYPE Repairer

AUTHOR LKK AUTO CONSULTANTS PTE LTD (TP)

DATE UPLOADED 5 July 2019

NAME  AUTHORISATION TO ACT FORM.pdf

TYPE Forms / Claim Documents

SUB-TYPE POA / Authority Letter

AUTHOR LKK AUTO CONSULTANTS PTE LTD (TP)

DATE UPLOADED 5 July 2019

NAME  OI RENTAL CONTRACT.pdf

TYPE Forms / Claim Documents

SUB-TYPE Others

AUTHOR LKK AUTO CONSULTANTS PTE LTD (TP)

NAME	 LKK Resurvey Photo 1.pdf
TYPE	Reports & Statement
SUB-TYPE	Others
AUTHOR	LKK AUTO CONSULTANTS PTE LTD (TP)
DATE UPLOADED	15 February 2019

NAME	 Immediate Advice with Mandate.pdf
TYPE	Reports & Statement
SUB-TYPE	Others
AUTHOR	LKK AUTO CONSULTANTS PTE LTD (TP)
DATE UPLOADED	15 February 2019

NAME	 LKK Resurvey Photo.pdf
TYPE	Reports & Statement
SUB-TYPE	Others
AUTHOR	LKK AUTO CONSULTANTS PTE LTD (TP)
DATE UPLOADED	15 February 2019

NAME	 LKK Survey Photo.pdf
TYPE	Reports & Statement
SUB-TYPE	Others
AUTHOR	LKK AUTO CONSULTANTS PTE LTD (TP)

NAME  TP ESTIMATE MARKED - REVISED.pdf

TYPE Reports & Statement

SUB-TYPE Others

AUTHOR LKK AUTO CONSULTANTS PTE LTD (TP)

DATE UPLOADED 15 February 2019

NAME  TP ESTIMATE - MARKED.pdf

TYPE Reports & Statement

SUB-TYPE Estimate / Quotation

AUTHOR LKK AUTO CONSULTANTS PTE LTD (TP)

DATE UPLOADED 17 August 2018

NAME  P2132888_CI_TP XS \$1500.pdf

TYPE Forms / Claim Documents

SUB-TYPE Policy Schedule / Covernote / Certificate of insurance

AUTHOR NG Stacey

DATE UPLOADED 8 August 2018

NAME  P2132888_EN_00008_1.pdf

TYPE Forms / Claim Documents

SUB-TYPE Policy Schedule / Covernote / Certificate of insurance

AUTHOR NG Stacey

DATE UPLOADED 8 August 2018

TYPE Reports & Statement

SUB-TYPE GIA Report

AUTHOR RATAN BHOSALE Pragati

DATE UPLOADED 7 August 2018

NAME  SJL3369K INSD GIA REPORT.PDF

TYPE Reports & Statement

SUB-TYPE GIA Report

AUTHOR RATAN BHOSALE Pragati

DATE UPLOADED 7 August 2018

NAME  PRI EMAIL RECIEVED FROM WORKSHOP.msg

TYPE Letters and Correspondence

SUB-TYPE Workshop

AUTHOR RATAN BHOSALE Pragati

DATE UPLOADED 7 August 2018
