

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 7135H

DATE 6/8/2018 15:56

MAKE :

MODEL : HYUNDAI i40

PP

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper			\$ 603.60	
	Rear Bumper Reinforcement ?			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH)?		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket ?			\$ 49.00	
	Rear Bumper Clips			\$ 22.00	
	Rear Bumper Sponge ?			\$ 143.40	
	Rear Bumper Under Cover			\$ 225.00	
	SUB TOTAL			\$ 1,907.35	
	LESS 20%			\$ 381.47	
	DISCOUNTED TOTAL			\$ 1,525.88	
	Rear Bumper Reverse Sensor X			\$ 135.70	Nett
	Rear Bumper Rubber Mat			\$ 50.00	Nett
				\$ 185.70	
	Labour Charge				
	Panel Beating			\$ 350.00 200	
	Spray Painting Charge			\$ 250.00 200	
	Wiring Charge			\$ 50.00 X	
	R/Refix Reverse Sensor			\$ 120.00 30	
	TOTAL LABOUR			\$ 770.00	
	ESTIMATE TOTAL			\$ 2,481.58	
<p><i>Kalvin 16/11/14</i></p> <p><i>8/8/18 1310 hrs.</i></p> <p><i>200</i></p> <p><i>P/P</i></p> <p><i>Before Part photo</i></p>					
<p>KK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from insurance company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					