

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

Not Authorized
L1 Sup & ?
Assembly After Paint
6 days
8-8-18

REPAIR ESTIMATE FOR SLG1582B

No.	Qty	List Items			
1	1	Rear bumper	\$	739.00	✓
2	2	Rear bumper reflector	\$	68.00	✓
3	1	Rear bumper tow cover	\$	18.00	✓
4	1 set	Rear bumper clips	\$	30.00	✓
5	2	Rear bumper side retainer	\$	48.00	✓
6	1	Rear bumper inner top beam	\$	72.00	?
7	1	Rear bumper inner reinforcement	\$	184.00	?
8	2	Rear number plate lamp	\$	96.00	?
9	1	Rear boot lid	\$	778.20	✓
10	1	Rear boot centre "MITSUBISHI" logo	\$	48.00	✓
11	1	Rear boot "LANCER" emblem	\$	40.00	✓
12	1	Rear boot "EX" emblem	\$	34.00	✓
13	1 set	Rear boot inner trim clips	\$	50.00	✓
14	2	Rear boot lamp	\$	166.00	X
15	1	Rear boot top lock	\$	62.00	✓
16	1	Rear boot lower lock catch	\$	26.00	X
17	1	Rear tailgate weatherstrip	\$	134.00	sofa
18	2	Taillamp	\$	750.00	X
19	1	Rear end panel	\$	452.00	?
20	1	Rear end panel top garnish	\$	145.00	✓
21	1	Rear spare tyre top board	\$	141.00	?
22	1	Rear lower exhaust silencer	\$	442.00	?
23	3	Rear lower exhaust silencer mounting	\$	114.00	X
			\$	4,637.20	
			Less 10%	463.72	
			Total :	\$ 4,173.48	

Special Nett Items

24	1	Rear boot "C&C" emblem	\$	35.00	✓
25	1	Rear number plate	\$	45.00	✓
26	1 set	Rear end panel sealant	\$	50.00	?
27	1 set	Reverse sensors	\$	250.00	200.00
			Total :	\$ 380.00	

Labour

1	Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.	\$	1,200.00	700
2	To putty and spray Spray Paintings charges.	\$	1,200.00	800
3	To check wirings and lightings.	\$	40.00	200
4	To remove, refix reverse sensors.	\$	80.00	500
5	To remove, refit boot lid fittings.	\$	80.00	500

6	To remove, refit rear exhaust silencer.	\$	80.00	602
7	To supply and apply anti rust treatment	\$	80.00	601
Total :		\$	<u>2,760.00</u>	

Total Parts and Labour : \$ 7,313.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: