INS. CASE OWNER	AMMOST JUSTIN	S cc 1 / WR 180	450), V	pab Ol II	K- AC
	White	ASSIGN			10/8/8
210 AST 21	th sentence	DGA: 0	19/10 1)	into / Tirkio :	- 10/1
Pre-assign / CCU /	FTE		R	egistered in Merimen	12/8/17
Insured Vehicle No	W12	44504			
# #	tope	b11	Claim No:		
Name of Insured	C. In	110	Policy No. 1	. w 1.	2
Insured Tel No.	~	HP: 1540 154	Make / Model :	MAZOGA	5
Excess Sec II :SS		D'O'V: 7816 (8	Place of Accident	ralytin	Ra
Is driver the owner		Nature of Accident			
If NO, Driver Nan Driver Tel 1	No.:	(V/L: YES/NO)	Ol GIA REPORT Insured Liability :		AREPORT: 10S/NO nal? Yes/No
STC 6339	1 P			-	
Tel: Liability:	INSRI WSP: Tel: Limbil RMK	ity :	INSRS: WSP: Tel: Liability: RMKS:		INSRS: WSP. Tel: Liability: RMKS:
Date/Time					
12/1	CIMAYOU.	×.		TAGE	DATE / PIC
141	01 / 97725 7/	CC 1 T to the Class In		ion-Reporting ltr (1st).	
1211-121-121-1	I LL TAYOU . US	1 Kool 18 8 11 A JOR 1 A. P.	C. WALL LINE N	lon-Reporting ltr (Final)	
31/8/18 -	- OID WIT T	Pten rear lift po	White I	lotification ltr (if non-pi	H 2/11/18
11	White OID	wronted to change	lone. A	for call by to Ci.	a) intatt
1719118 -	10.2	type mandale	D	ocumentation Check	A STATE OF THE PARTY OF THE PAR
	1100	-)/~		lotification ltr (if non-pi ther call in to OI:	akinji)
3411/18 -	DV cuA	T A FILL .		utherisation To Act	
	DV sort	ILOCIATO I OU	2010	elease Voucher: mal Repair Bill:	
12/14/18	-Filepois to	Mi bua to clus		or Rental Invoice:	
			T	owing Invoice	
(4)				TA / OIA : fedical Bill	
	RECEIVED 1 3	DEC 2018			
			N.	and te Reject Instruc	rtion:
			L	OD syment Breakdown F	
PRELIMINARY ADVICE	Date/Time;	Sent By:		ost-Repair Photos:	101111
PROVINCE CONTRACTOR				thers:	
FINALIZATION Repair Cost:	Date/Time: SS /	Confirm with: days) Reduction:		Confirm by:	on Contract
FINAL SETTLEMENT	Date/Time: 30 11 15	Confirm with Jalan	56.	mail Call	all Call
Final Liability:	% 100) (Aurona)	/ A. Csed) BOLA S/N No. : N	100	NO B 28, Ass. Lin	
Repair Cost: W 46T.	55 11984.W	4 (14 (10)			
Loss of Use (LOU):	25 - (5 - x	4 days) × \$ 150.00			1 10
Loss of Income (LO)	S\$ - (\$ - x	days)		13	111/18
GIA/LTA Search	LOR+LOU I	LOR + LOI [Tick only one		()	1 1
Medical Medical	55 7. 15		1	Claim status: North	A/Reject/Private Settle
Disbursement:	SS -	(e.g. Tow Independen	1) 2		I/Reject/Private Settle
Legal Cost Total:	ss 12591.45	Global Sum S5: 2590.0	3	Survey fee:	320
FINAL PAYMENT	Date/Time;	Confirm with:		mail Call	
Payer 1:	SS 12594-W	Name 1: KIM China	Le AUTO PH		
" *** (Strike if N.A.)	SS	Name 2		-1.7.	
Payer J. Parketti (NA)	52	Nanc.			

ASSIGNMENT Van No. SLC 9330C Vr.Regal 6 10 Type Well May 1 preside No. SLC 9330C Vr.Regal 6 10 Type Well May 1 preside No. SLC 9330C And No. Suprementation of State No	* WSS REC. BY MOVELS REF:		Arh/		
Truck Tenther or Make Ma	φ.		7		
Truck I Tester or SID No VIS IT RESTORES (EVALINY INV Truck I Tester or Maha Man ST 31 os 259 Colour Shock Workshop his SI M 9 KO Colour Shock Shock Shirt I Truck I Tester or Maha Man ST 31 os 259 Colour Shock Accord Shirt I Specific Shirt No Specific Shirt I Specific	From Date:		Vall No. C/C	97701- VISAN	610
Truck/Trailer or Truck/Trailer or Truck/Trailer or Truck/Trailer or Truck/Trailer or Make BM W \$33 or \$159 or Insured Sed Ni Ni Ni Sp Randing 16 1665 Trandic hastered Sed Ni Ni Ni Sp Randing 16 1665 Trandic hastered Sed Ni Ni Ni Sp Randing 16 1665 Trandic hastered Sed Ni Ni Ni Sp Randing 16 1665 Trandic hastered Sed Ni Ni Ni Sp Randing 16 1665 Trandic hastered Sed Ni Ni Ni Sp Randing 16 1665 Trandic hastered Sed Ni Ni Ni Sp Randing 17 16 16 1665 Trandic hastered Sed Ni Ni Ni Sp Randing 18 16 1665 Trandic hastered Sed Ni Ni Ni Sp Randing 18 16 1665 Trandic hastered Sed Ni Ni Ni Sp Randing 18 16 1665 Trandic hastered Sed Ni Ni Ni Sp Randing 18 16 1665 Trandic hastered Sed Ni Ni Ni Sp Randing 18 16 1665 Trandic hastered Sed Ni Ni Ni Sp Randing 18 16 1665 Trandic hastered Sed Ni Ni Ni Sp Randing 18 16 1665 Trandic hastered Sed Ni Ni Ni Sp Randing 18 16 1665 Trandic hastered Sed Ni Ni Ni Sp Randing 18 16 1665 Trandic hastered Sed Ni Ni Ni Sp Randing 18 16 1665 Trandic hastered Sed Ni Ni Ni Sp Randing 18 16 1665 Trandic hastered Sed Ni Ni Ni Sp Randing 18 16 1665 Trandic hastered Sed Ni Ni Ni Sp Randing 18 16 1665 Trandic hastered Sed Ni Ni Ni Sp Randing 18 16 1665 Trandic hastered Sed Ni Ni Ni Tryce State 18 16 1665 Trandic hastered Sed Ni Ni Ni Tryce State 18 16 1665 Trandic hastered Sed Ni Ni Ni Tryce State 18 16 1665 Trandic hastered Sed Ni Ni Ni Tryce State 18 16 1665 Trandic hastered Sed Ni Ni Ni Tryce State 18 16 1665 Trandic hastered Sed Ni Ni Ni Tryce State 18 16 1665 Trandic hastered Sed Ni Ni Ni Tryce State 18 16 1665 Trandic hastered Sed Ni Ni Ni Tryce State 18 16 1665 Trandic hastered Sed Ni Ni Ni Tryce State 18 16 1665 Trandic hastered Sed Ni Ni Tryce State 18 16 1665 Trandic hastered Sed Ni Ni Tryce State 18 16 1665 Trandic hastered Sed Ni Ni Tryce State 18 16 1665 Trandic hastered Sed Ni Ni Tryce State 18 16 1665 Trandic hastered Sed Ni Ni Tryce State 18 16	Estimated Cost:		Type: M.Orr / M.Cycle	Bus / Van / Lorry / Text / Pr	rima Movari
Sp. Reading 16 1665 Tirkadic: Insured Sid 111 No Engine Portion No Claims No Sum Insured Excess: Engine Steering Injury Jammad Leaked Eurnal or Engine Steering Injury Stock Eurnamed Leaked Eurnal or Engine Steering Injury Stock Eurnamed Leaked Eurnal or Engine Steering	OD (1) WS / TP RES / OD RES / EVA / INV / A	IV.			
Sp. Reading 16 1665 Tirkadic: Insured Sid 111 No Engine Portion No Claims No Sum Insured Excess: Engine Steering Injury Jammad Leaked Eurnal or Engine Steering Injury Stock Eurnamed Leaked Eurnal or Engine Steering Injury Stock Eurnamed Leaked Eurnal or Engine Steering	To Inspect Vehicle No: SICS	3306	Make am	W 623;	1 49-
Sp. Reading 16 1665 Tirkadic: Insured Sid 111 No Engine Portion No Claims No Sum Insured Excess: Engine Steering Injury Jammad Leaked Eurnal or Engine Steering Injury Stock Eurnamed Leaked Eurnal or Engine Steering Injury Stock Eurnamed Leaked Eurnal or Engine Steering	at Workshop mis King	C/40.0			
EngiNo Claims No Chairs Record Excess: Steering lineary Jammed Leaked / Burnt or Modil Nill Skipp / STD AURIm or Tyre State F; 2 44 / 44 / 74 / 74 / 74 / 74 / 74 / 74	of				usured / Std / NI / NJ
Claims No. Sign Insured. Sign Insured. Sign Insured. Sign Insured. Excess: (Clear's Record) Mobile of Velt: (Policy Condition) Fignals: The velt had commenced its repair at the time of inspection. Fignals: The velt had commenced its repair at the time of inspection. Final Report: Consistent? Yes or No. East. Repetts. Toyo / York or Consistent? Yes or No. Lum Surr. Toyo / Rep. / 2 4 Hrs. Consistent? Yes or No. CA / REP. / 2 4 Hrs. Vehicle: IN / OUT Date: Person Contacted: Person Contacted: The UIC / Chassis frame / Body Structure affected due to collision. Ly A Story Ly Clumb. Pur (Yu. Next 6359) Contacted: Date: Person Contacted: The UIC / Chassis frame / Body Structure affected due to collision. Contacted: The UIC / Chassis frame / Body Structure affected due to collision. Contacted: Contacted: The UIC / Chassis frame / Body Structure affected due to collision. Contacted: Contacted: Contacted: The UIC / Chassis frame / Body Structure affected due to collision. Contacted: Contac	Insured: 52 m 9	407	100	700	
Claimer to No. Condition Claimer to No. Consistent? Yea or No. Claimer to No. Consistent? Yea or No. Claimer to No. Claimer to No. Consistent? Yea or No. Claimer to No. Consistent? Yea or No. Claimer to No. Cla	Policy No.		C/No: W	3AFA32070C	247230
Chent's Record Melie of Veh: Brake: Consistent of Leaked / Burnt or Medie of Veh: Medie of Veh: Medie of Veh: Medie of Veh: (Policy Condition) Farmark: The veh had commenced its repair at the time of inspection. Eat. or Market Value: File Fil	Claims No.		Gen. Cond. 969 / Fair	/ Poor / Burnt	24 10 30
Modil: of Veh: Modil: NIII (Skillp: / STD A/Rilm or Tyre Size: F: 2 4 5 / 45 / 8 / 8 8 1	Sum Insured. Excess:		Steering: Inocate / James	med / Leaked / Burnt or	
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Ball or Market Value: IDAC Accident Root: Consistent? : Yes or No Est Repairs. Todays Res.: Yes or No Lum Sum: Date: Person Contacted: Person Co			Brake: horter-Jami	ned / Leaked / Burnt or	
Remark: The web had commenced its repair at the time of inspection. Eal or Market Value: UDAC Accident Roort: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No CLUM Starr: Action / REV / REP. / 24 HRS Date: Person Contacted: Deta: Time Action / Instruction LTA 2664/ Lycock Action / Instruction LTA 2	Malie of Veh:		Modi NII (SKim /	STD A/Rim or	
Remark: The weh had commenced its repair at the time of inspection. Eal. or Market Value: Eal. or Market Value: UDAC Accident Roort: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No CLUM Starr: Action / REV / REP. / 24 HRS Date: Person Contacted: Deta / Time Action / Instruction LTA 2664/ Lycolor LTA 2664/ Lycolor Action / Instruction LTA 2664/ Lycolor Confision LTA 2664/ Lycolor Confision Lycolor Deta / Time Action / Instruction Lycolor Lycolor Clear Repair Days Of Repair: Resurvey No. of Trip: Consistent?: Survey Fest Street Inspection Clear Report Days Of Repair: Resurvey No. of Trip: Consistent? Sumit / Province Clear Report Days Of Repair: Resurvey No. of Trip: Consistent? Sumit / Province Clear Report Days Of Repair: Resurvey No. of Trip: Consistent? Survey Fest Transportation: Add Fee: Site Insp (6 See See See See See See See See See S	Val. 556 1 C 7 - 147 10 - 27 1		Tyre Size F;	248/xc	R40
repair at the time of inspection. Eal or Market Value: IDAC Accident Roort: GIA / PR Seen: Consistent?: Yes or No Lim Surr. Zo 3. SVal.: Yes or No Date: Person Contacted: Date: Person Contacted: IN / OUT Class I frame Body Structure affected due to collision Class I frame Action / Instruction Class I frame Body Structure affected due to collision Class I frame Body Structure affected due to collision Class I frame Body Structure affected due to collision Class I frame Body Structure affected due to collision Class I frame Body Structure affected due to collision Class I frame Body Structure affected due to collision Class I frame Body Structure affected due to collision Class I frame Body Structure affected due to collision Class I frame Body Structure affected due to collision Class I frame Body Structure affected due to collision Class I frame Body Structure affected due to collision Class I frame Body Structure affected due to collision Class I frame Body Structure affected due to collision Class I frame Body Structure affected due to collision Class I frame Body Structure affected due to collision Class I frame Body Structure affected due to collision Class I frame Body Structure affected due to collision Class I frame Body Structure affected due to collision Class I frame Body Structure affected due to			R:	1-13	44 0
Date Person Contacted:		N/S O/S	BS / DUN / EXNOVA / G	Y/FS/LEA/MIC/OHTSU	/PIR/SUMI/
Date: Person Contacted: Vehicle: IN / OUT Confirme File Pass to? Person Contacted: Vehicle: IN / OUT Date: Person Contacted: Vehicle: IN / OUT Date: Person Contacted: Vehicle: IN / OUT Date: Person Contacted: Vehicle: IN / OUT Confirme File Pass to? Person Contacted: Vehicle: IN / OUT Date: Person Contacted: Vehicle: IN / OUT Date: Time Action / Instruction Contacted: In / OUT Date: Time File Pass to? Person Contacted: Vehicle: IN / OUT Date: Time File Pass to? Person Contacted: Vehicle: IN / OUT Contacted: IN / OUT Date: Time File Pass to? Person Contacted: In / OUT Date: Time File Pass to? Person Contacted: In / OUT Contacted: In / OUT Date: Time File Pass to? Person Contacted: In / OUT Date: Time File Pass to? Person Contacted: In / OUT Date: Time File Pass to? Person Contacted: In / OUT Date: Time File Pass to? Person Contacted: In / OUT Date: Time File Pass to? Person Contacted: In / OUT Date: Time File Pass to? Person Contacted: In / OUT Date: Time File Pass to? Person Contacted: In / OUT Date: Time File Pass to? Person Contacted: In / OUT Date: Time File Pass to? Person Contacted: In / OUT Date: Time File Pass to? Person Contacted: In / OUT Date: Time File Pass to? Person Contacted: In / OUT Date: Time File Pass to? Person Contacted: In / OUT Date: Time File Pass to? Person Contacted: In / OUT Date: Ti	1101		TOYO/YOKO or	continent	6./
GIA / PR Seen: Consistent? Yes or No Est Repairs: 7 days Res.: Yes or No Lium Surn: 20 % 3 Val.: Yes or No Survey held at Date: Person Contacted: Vehicle: IN / OUT Date: Person Contacted: Vehicle: IN / OUT Date: Time Action / Instruction L7 A 266 Y/ 14/12000. Deta/Time, Fie Fass to? Prell. Report Deta/Time, Fie Fass to? Prell. Report Days Of Repair: Description: Survey Fee Fass to? Prell. Report Days Of Repair: Survey No. of Trip: Survey Fee Fass to? Prell. Report Survey No. of Trip: Survey Fee Fass to? Prell. Report Add Fee: Site Insp (\$			Front _	Rear	1
Est Repairs. 7 days Res.: Yes or No Dum Sum: 26 % 3 Vel.: Yes or No CA / REV / REP. / 24 HRS 3666A Date: Person Contacted: Vehicle: IN / OUT Date: Person Contacted: The U/C / Chassis frame / Body Structure affected dus to collision L7 A 266 Y/ Lyr Lond. Pup (YL. 126 16359 3/4/15 \$\frac{1}{3}\$ (1200 Confind with After.) CetalTime, File Pass io? Prell. Report Days Of Repair: Resurvey No. of Trip: Survey Fes Transportation: Add Fee: Site Insp (\$ 5.88.3) Interview (\$ 7.800.6) Tech, Invs (\$ 0.000.6) Photos Others		THE CO.		mm R/Bal	70
Date: Person Contacted: Vehicle: IN / OUT Date: Person Contacted: The U/C / Chassis frame / Body Structure affected dus to collision LTA 2564/ 14/1000 Confund with Alm. Claude (3876-34) Cl		secsotter.A	. 0,	mm L/Bat	6
Date: Person Contacted: Vehicle: IN / OUT Date: Person Contacted: The U/C / Chassis frame / Body Structure affected dus to collision L7A 26641 14/12006. Pup (41. Next) 16359 3/8/18 4/3 \$ (1200 Confined with Adm. Clean 18 Pass 107 Prell. Report Days Of Repair: Detertine, File Pass 107 Prell. Report Resurvey No. of Trip: Survey Fee Transportation: Add Fee: Site Insp (\$ 5.88 Si Photos Interview (\$ Photos Photos Others Others			1012110		10/8/14
Date: Person Contacted: Vehicle: IN / OUT Date / Time Action / Instruction L7A 266 4/ 14/1900 Pup (4L. North 16359) Clear Time, File Pass 107	20	7 000 4			
Date / Time Action / Instruction The U/C / Chassis frame / Body Structure effected due to collision L7A 2664 L7120 L	CA / REV / REP. / 24 HRS		Des. of Damages : Frt. /	Rear / O/S / N/S / U/C /	Rooftop or
L7A 26641 14/1000. Pup (41. Next) 16359 3/8/18 4/3 \$ 1/200 Confind with Alm. (Realth (38%-34) 55%) DeterTime, File Pass 107 : Prell. Report Days Of Repair: (Bealth (38%-34) 55%) DeterTime, File Pass 107 : Prell. Report Days Of Repair: (Bealth (38%-34) 55%) Add Fee: Site Inap (5	Date: Person Contacted:	venicle: IN / OUT	The HIC / Changing	le 1/5	
Cled State	The state of the s			rame / Body Structure affi	ected due to collision
Cled State	274 2864	1 lyronde			
Cled State	pep (41. re	44 16359			
Cecl 15 (3876-34) DeterTime, File Pass to? Prell. Report Days Of Repair: Resurvey No. of Trip: Survey Fee Transportation: Add Fee: Site Insp (\$)6+RSSI Interview (\$) Photos Transportation: Tech. Invs (\$) Others	2/0/10 2/10 1/200				
DeterTime, File Pass to? Prell. Report Days Of Repair: Resurvey No. of Trip: Survay Fee Transportation: Add Fee: Site Insp (\$)6+RSSI Interview (\$) Photos Jump Sum / I.B.I: /\$	16/10 134 11200 8	ortug a	ou you.		
DetelTame, File Pass to? Prell. Report Days Of Repair: Survey Fee Transportation Add Fee: Site Insp (\$)6 + RS8 Interview (\$) Photos Ump Sum / I.B.I: /\$			(Red	# 13826.34	18th
Days Of Repair: Final Report Resurvey No. of Trip: Survey Fee				1	1300
Days Of Repair: Final Report Resurvey No. of Trip: Survey Fee					
Transportation: Add Fee: :Site Insp (\$)6 > RS8 Report Format : : Tech. Invs (\$) Others	Dete/Time, File Pass to? : Prell. Report	Day	s Of Repair:		
Add Fee: : Site Insp (\$)5+RSSI Report Format : : Tech. Invs (\$) Others			5-00-01100	Supray Ear	
Add Fee: : Site Insp (\$)5 > RS8 Report Format : : Tech. Invs (\$) Others	Conte Time, File Return to?	_	7	77 (20)	
Report Format : Tech. Invs (\$) Photos Lump Sum / I.B.I: /S		Add Fee:	: Site Insp (\$		
Lump Sum / LB I: /S) Photos	
:Weekend (\$) Others	
	and same mental	3	:Weekend (\$)	

oshtrej - wel	REF:		
* ASS REC. BY: MOVELS	A Start o	Ara/	
,	2	ASSIGNMENT	
From			E VER-
Estimated Cost	Date:	Veh No. 52093300	
^	to the control of	Type: X.Car / M.Cycle / Bus / Van / L	orry (1831) Prime Mover i
OD (1F) WS/TP RES/OD RES/E		11000. 11200.0	
Yo Inspect Vehicle No.	4. mchies	Make RMW	231 = 6497
at Workshop mie	Kin chiel	- Block	A/C: Insured / Std / N: / R/
0	0.46.1	Sp.Reading 161665	T/Radio: Insured / Std / Nº / NA
Insurer: 5 A	m9407	Eng/No	
Policy fro.		CINO WBAFF3	20706257835
Claims No.		Gen. Cond. 9001 / Fair / Poor / Burn	0 100 30
Sum Insured:	Excess	Steering: Inorder / Jammed / Leaked	/ Burnt or
(Client's Record)		Brake: norther Jammed / Leaked	/ Burnt or
Make of Vehr		Modi: NII SKim / STD A/Rim o	
		Tyre Size: F: 2	45/45.R.+8
(Policy Condition)		R:	7/4.K.#8
Remark: The veh had commenced is	ts N/S O		
repair at the time of inspec	The state of the s	- GOTDONTEXNOVATGITESTEIZA	COUNTY .
Bai, or Market Value:		- (01	tinestil
III. DON: I MILLIONS (I. PONTS)	isistent? : Yes or No	Front 6	Rear
	isistent?: Yes or No	R/Bail mm	R/Bal mm
Participation of the second of		L/Bal mm	L/Bal 0 jym
	Res.: Yes or No	D.O.A. 10/8/18	D.O. 10/8/18
Lum Sunt %	3 Val.: Yes or No	Survey held at	- 10/10
CA / REV / REP. / 24 HRS	3888 A	Des. of Damages : Frt / Rear / O/S	N/S / U/C / Rooftop or
Date: Person Contac	Vehicle: IN / C		Ale
Date / Time Action / Instruction		The U/C / Chassis frame / Body	Structure affected due to collision.
PERMIT HISTOCHOT			
Date/Time, File Pass to?	Report	2000/02/24 100	
		Days Of Repair:	
Date/Time, File Return to?	Report	Resurvey No. of Trip:	Survey Fac
2)	Add F	201	Transportation:
4 20	Add F)\$+R\$\$I
Report Format :		: Interview (\$) Photos
Lump Sum / I.B.I: (\$: Tech. Invs (\$) Others
-DIMMASSIMA (MEMBAN))	: Weekend (\$)
			TOTAL

10/5 #11200/ 10/5 #11200/

KEM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

SLC9330E

OTH	DADTICUL AD	
QTY	PARTICULAR	1.11
1 PCS	BOOTLID /766.10	Bert/worked \$1,866.20
1 PCS	BOOTLID REAR LOGO	Nu \$68.50
1 PCS	BOOTLID '520I' EMBLEM	20 \$66.80
2 PCS	BOOTLID REFLECTORS @\$485.30 466 · 20	M(CM \$970.60!PC
1 PCS	BOOTLID INNER LOCK	11 \$299.08 X
1 PCS	BOOTLID WEATHERSTRIP 266.05	4w1 \$275.00
2 PCS	TAILLAMPS @\$688.50 JFT	N/CME \$1,377.00 12C
1 PCS	REAR BUMPER /5-Y5	7 - 1 \$1,866.20
1 PCS	REAR BUMPER LOWER SKIRTING	N 7 \$650.00 X
2 PCS	REAR BUMPER REFLECTORS @\$75.00	MS 510, \$150.00 & C
4 PCS	REAR BUMPER PDC SENSORS @\$305.00 >6	MI SHAM \$1,220.00 120
1 PCS	REAR BUMPER PDC SENSORS WIRE	AA \$313.54X
1 PCS	REAR BUMPER TOP GUIDE	Cru \$199.02
1 PCS	REAR BUMPER REINFORCEMNT 640.92	\$755.01
1 PCS	REAR BUMPER LOWER GUIDE	m \$185.13
2 PCS	REAR BUMPER SIDE RETAINERS @\$115.00	MSCM \$230.00 /de
1 PCS	REAR BUMPER INNER ADAPTER	4-7 \$185.00 ∝
1 PCS	REAR END PANEL 1018.57	Se 6,00 \$1,122.10
1 PCS	REAR END PANEL TOP GARNISH 2 88.01	7w1 \$311.20
1 PCS	REAR FENDER N/S	1412.304
1 PCS	REAR FENDER INNER TRIM N/S	Defug \$366.05 -
1 PCS	REAR FENDER INNER SIDE MEMBER N/S	34100 \$699.01
1 PCS	TAILLAMP SIDE GARNISH N/S	eu7 \$18.50 _
1 PCS	REAR AIR VENT N/S	か. / \$66.50 ―
1 PCS	REAR EXHAUST ASSY /810	W//2-1 \$1,880.10
1 PCS	REAR EXHAUST HEAT SHIELD N/S / \$4.30	715 \$299.20
1 PCS	REAR FENDER UNDER COVER N/S 295-10	2 13 \$322.20
1 PCS	REAR TAILLAMP HOUSING PANEL N/S /66-3-2	34 \$366.20
1 PCS	REAR WINDSCREEN MOULDING	47 \$148.50 ×
1 PCS	REAR SHOCK ABSORBER N/S	A 1 \$522.30 X
1 PCS	REAR WHEEL HUB BEARING N/S	17 \$645.10 D
		\$18,856.34
	S.NETT	7.0,000.01
1 PCS	REAR WINDSCREEN SEALANT	47 \$80.00 X
1 PCS	REAR END PANEL SEALANT	M \$80.00 LO
1 PCS	REAR FLOOR PANEL INSULATOR	nu \$380.00/w
	e conserva de sum establicações (ESV e ANTESATEIRO E ESTADORANTA ESTADORANTA ESTADORA	1000 4000.00/10

11198.46

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3888A
Vehicle Details	
Vehicle No.:	SLC9330E
Vehicle to be Exported:	No
Intended De-registration Date:	10 Aug 2018
Vehicle Make:	B.M.W.
Vehicle Model:	523I 2.5 AT ABS D/AB 2WD 4DR GAS/D
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	05787379N52B25AF
Chassis No.:	WBAFP32070C257835
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$38,510.00
Original Registration Date:	24 Jun 2010
First Registration Date:	24 Jun 2010
Transfer Count:	2
Actual ARF Paid: Intended PARF Rebate Details	\$38,510.00 (925]
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jun 2020
PARF Rebate Amount: Intended COE Rebate Details	\$21,180.00
COE Expiry Date:	23 Jun 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$39,911.00
COE Rebate Amount:	\$7,461.00

The information contained herein is correct as at 10 Aug 2018

OK

SGCARMART.COM

Login Sign up

New Gars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Post an Advertisement Self it yourself! Advertise it at just \$58 until it's SOLD!

Great Condition. Recently Overhaul, Problem Free, Drive With A Feace Of Mind. Direct Owner StarAd



Fost are Act

Advertises Logist

Ways of Selling

Browse by Category V

« Back (1 2) Next =

Sort by Date Posted

Submit I

✓ 20 results/page
✓

36 vehicles

bmw 523i

Price

Honda Accord Euro R (COE Till 01/2027)

Reg Date

Eng Cap

Mileage

Arry

Advanced Search 😾

Veh Type

Arry

Luxury

Status

Search Selection

bmw 5231

Model

2010

Available

BMW 5 Series 523i

\$47,800

\$13,470./yr White On Black Luxurious And Sporty F10 523! Regularly Serviced. Excellent Condition. Smooth & Responsive Engine. View To Believe

01-Oct-2010

2,497 cc

Luxury

Available

STATE OF STREET

Ery-1 Pte Ltd

Pointet: 10-Aug-2016 Tags: 2010 RMW 52(I), RMW 52(I), RMW, 52(I), Used RMW



BMW 5 Series 523i

545 000 -

514,120 /yr

30-Jun-2010

2,497 cc

89,231 km

Available

Drive With Assurance. Free 1 Year Warranty! New Facelift Easy Loan Approval With Financing Options! Down Payment \$5.9k Low Monthly Installment Plan At Only \$1,120, 1 Owner! Very Low Mileage Fully Main...

Posted: 10-Aug-2018 Tags: 3010 RMW 5231, RMW 5231, BMW, 5231, Used BMW



BMW 5 Series 523i Sunroof

549,999

\$13,870 /yr

01-Oct-2010

2,497 cc

Linury

Available

No Gimmicks! Price Negotiable, Low Mileage Done, 100% Beautiful Condition, Low Depreciation, Low Interest Rate, Most Worthy Buy, Call Now For Vlewing.

Pointed: 06-Aug-2018 Tags: 3010 8MW 523L 8HW 525L 8MW, 525L Used 8MW



BMW 5 Series 523i

642,800

\$12,900 /yr

28-Jun-2010

2.497 cc

Available

Linury \$0 Down Payment Available! Balloon Scheme Available! We Are sgCarMart Premium Dealer 2015 To 2017! Buy With Confidence! No Hidden Cost!

Posted: 07-Kug-2018 - Tags: 2010 8PW 523, BHW 523, 6HW, 523, Used BHW

Can Buying

Car Selling

100% Accident Free! In House Loan Or Bank Loan Available! No Nee...

Car Ownership

Buying a pre-owned car, but Unsure of its Condition?

Get, STA Car Evaluation

Car Aftermarket

On The Hove

Liferryte



BMW 5 Series 523i Highline

\$47,000

\$13,770 /yr

21-May-2010

158,000 km

Available Lincory

Original Grey With Dark Grey Interior, Very Clean, Non-smoker, Well-maintained, PML Records, Accident-free,

CHRISTO



BMW 5 Series 523i

\$42,800

\$13,260 /yr

02-Jun-2010

2,497 cc

2,497 cc

Linuary

Available

PML Unit! Havana Brown On Beige, The Sporty BMW 5 Series Sets Unsurpass Standards For Style And Dynamics, Maintaining The Leading Position As The Most Widely Sold Premium Car In The World. Immaculate ...

TS Wheeler Capital Pte Ltd

Posted: 07 Aug 2018 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW

Posted: 07-Aug-2018 Tags: 2010 BHW 523, 9HW 5231, 9HW, 5231, Used 9HHz

BMW 5 Series 523i

\$48,888

\$11,880 /yr 05-Nov-2010

2,497 €€

LUXURY

Available

Well Maintained By Owner, Workshop And STA Evaluation Welcomed, Bank And High Loan Available!

Compare

Pointed: 96-Aug-2018 Tags: 2010 BMW 523i, BMW 523i, BMW, 523i, Used BMW

http://www.sgcarmart.com/used_cars/listing.php?RGD=2010&MOD=bmw 523i&RPG=20&VEH=0&... 10-Aug-18

Hsiao Tong (LKKAuto)

From:

Hsiao Tong (LKKAuto)

Sent:

Sunday, 18 November 2018 10:41 AM

To:

'Ng, Jeffreysaykiat'

Subject:

<SEEK MANDATE> Your Ref: 24986897455G *Our Ref: CC6/LCR18014507/Upa3

[ACCIDENT INVOLVING SLM 9450P(OI) & SLC 9330E(TP) ON 10/08/2018]

Your Ref:

2498689745SG

Our Ref:

CC6/LCR18014507/Upa3

Without Prejudice

Dear Sirs,

ACCIDENT INVOLVING SLM 9450P(OI) & SLC 9330E(TP) ON 10/08/2018

We refer to the above matter.

The accident occurred when our insured driver changed lane and hit onto third party's rear left portion.

We seek your approval to offer to Third Party repairer, Kim Chwee Auto Pte Ltd is as follows: -

	Claimed	Revised
Cost of Repair (w/GST)	\$ 28,276.18	\$ 11,984.00
Loss of Rental (4days x \$180.00)	\$ 720.00	\$ 640.00 (4days x \$160.00)
3. LTA/ GIA Search Fee	\$ 7.45	\$ 7.45
TOTAL	\$ 29,003.63	\$ 12,631.45
Total amount of claim (Hability 100%)		\$ 12 421 AE

Total amount of claim (Liability 100%)

\$ 12,631.45

Market Value	: \$ 45,000.00 (est)
LTA Rebate	: \$ 28,641.00 (est)
Nett Value	: \$ 16,359.00 (est)

For your approval in Merimen please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From:

Ng, Jeffreysaykiat < Jeffreysaykiat.Ng@aig.com>

Sent:

Monday, 19 November 2018 7:53 AM

To:

Hsiao Tong (LKKAuto)

Subject:

RE: <SEEK MANDATE> Your Ref: 2498689745SG *Our Ref: CC6/LCR18014507/Upa3

[ACCIDENT INVOLVING SLM 9450P(OI) & SLC 9330E(TP) ON 10/08/2018]

Dear Hsiao Tong,

Approved in Merimen, thank you.

Jeffrey Ng

AIG

Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1916 | Fax +(65) 6835 7416

Jeffreysaykiat.Ng@aig.com | www.aig.com.sg

AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards. Click here to find out more.

Follow us:



IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Sunday, November 18, 2018 10:41 AM

To: Ng, Jeffreysaykiat

Subject: <SEEK MANDATE> Your Ref: 2498689745SG *Our Ref: CC6/LCR18014507/Upa3 [ACCIDENT INVOLVING

SLM 9450P(OI) & SLC 9330E(TP) ON 10/08/2018]

Your Ref:

2498689745SG

Our Ref:

CC6/LCR18014507/Upa3

Without Prejudice

Dear Sirs,

ACCIDENT INVOLVING SLM 9450P(OI) & SLC 9330E(TP) ON 10/08/2018

We refer to the above matter.

The accident occurred when our insured driver changed lane and hit onto third party's rear left portion.

We seek your approval to offer to Third Party repairer, Kim Chwee Auto Pte Ltd is as follows: -

	Amount Claimed Revised
Cost of Repair (w/GST) Loss of Rental (4days x \$180.00) LTA/ GIA Search Fee TOTAL	\$ 28,276.18 \$ 11,984.00 \$ 720.00 \$ 640.00 (4days x \$160.00) \$ 7.45 \$ 7.45 \$ 29,003.63 \$ 12,631.45
Total amount of claim (Liability 100%)	\$ 12,631.45

Total amount of claim (Liability 100%)

Market Value	: \$ 45,000.00 (est)
LTA Rebate	: \$ 28,641,00 (est)
Nett Value	: \$ 16,359.00 (est)

For your approval in Merimen please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Print Received Message

This mail is associated with:

*SLC9330E (2498689745SG) [SLM9450P] TP LIM LAY GEK Aug 10 2018 10:00AM [LCRF PTE LTD] Kim Chwee Auto Pte Ltd

From

AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 19/11/2018 07:52 AM.

To

LKK_HQ

Subject

Alert - Adj Mandate Approved (S\$12631.49) - SLC9330E - Claim Handler: Ng, Jeffrey-SK

Approved:12631,49.			

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

Date: 20.08.2018

AIG Asia Pacific Insurance Pte Ltd Chartis Building 78 Shenton Way #07-16 Singapore 079120

Attn: Motor Claims Department

ACCIDENT INVOLVING VEHICLE:

SLC 9330E

/ SLM 9450P

ON 10.08.2018

We are the authorized repair workshop for the owner of motor vehicle no: SLC 9330E , which was involved in the captioned accident with your insured vehicle no: SLM 9450P . The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1) Cost of Repair (inclusive of GST)

LTA Search Result

\$ 11,984.00 \$ 720.00

2) Rental

\$ 720,00 \$ 7.45 \$ 12,711.45

We enclosed herewith the following documents to support the claims:

a) Final Repair Invoice

e) Vehicle Registration Log Card

b) I/C & Driving License

f) Letter of Authorisation, etc...

c) GIA Report / LTA Search Result

g) Car Rental Invoice / Agreement

d) Insurance Certificate

h) Police Report

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you.

Yours faithfully,


Jason Tang (jason@fastechauto.com.sg)

KIM CHWEE AUTO PTE LTD









P. Parding as (3) 20/6/20/8

Tokio Marine Insurance Singapore Ltd.

Company Reg, No.: 192300014MI (GS1 Reg No.: M2-0000023-4) 20 McCallum Street #69-01 Tokic Marine Centre Singapore 069045

T. (65) 6221 6111 F. (65) 6221 4355 / (65) 6224 0895 E. tmis@tokiomarine.com.sg. W. www.tokiomarine.com

A interper of the Tokio Mirrire Group



Certificate of Insurance

FORM MX1

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA) MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Policy No.: MT103902 (Private Car)

Index Mark and Registration Number of Vehicle

SI C9330F

Chassis No.: WBAFP32070C257835

2 Name of Policyholder

LIM LAY GEK

Effective date of the Commencement of Insurance for the purposes of the Act

24/06/2018 (00:00:00)

Date of Expiry of Insurance

23/06/2019

Persons or Class of Persons entitled to drive"

(a) The Policyholder.

(b) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the Pastern driving is permitted in accordance with the Scorping of other less or regulations to drive the Masser Vehicle or has been so permitted and is not disqualified by order of a Court of subter the Road Traffic Act has not been cancelled all the less of the accident less or clamage.

Limitations as to use

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Triade.

digers endowed superance by Section E of the Music vehicles (Third Party Reas and Companions) Act (Display 180) and Section 65 of the Fixed Transport Act, 1967 (Malaysia), are not to be

We hereby confly that the Policy to which this Derebcen return is maked in accommon with the provinces of the Maker Vehicles (Think Purty Rose, and Compensation) Act (Chapter 183) and Part IV of the

use prior to the Policy Schoolie for full details, forms and consistent of the rea

IMPORTANT NOTICE

The Certificate is not imminished Guring in currency if the insurance is considered by advanced research, you must return the Certificate in Trace Marrier Imagenese List, within 7 days thread Act (Chapter 183).

Act (Chapter 183).

ADDITIONAL INFORMATION

Insurance Plan:

Comprehensive Approved Workshop Plan

Account No: 2580DDA

Limit for total loss or theft. Policy Excess:

Prevaling Market Value

Own Clamage Claims

SGD 1,000.00 SGD 500.00

(Original Excess | SGD 1,000.00)

Additional Excess for Unnamed

Oriver(s)
Additional Excess for Young or inexperience Driver(s)
WindScreen Excess

SGD 3.500.00

SGD 100.00

Financial Interest

WSJ CREDIT PTE L'TD

TOKIO MARINE INSURANCE SINGAPORE LTD.

Authorised Signature

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 3888A

Vehicle Details

Vehicle No.: SLC9330E

Vehicle to be Exported: Yes

Intended De-registration Date: 10 Aug 2018
Vehicle Make: B.M.W.

Vehicle Model: 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D

Primary Colour: Black
Manufacturing Year: 2010

Engine No.: 05787379N52B25AF
Chassis No.: WBAFP32070C257835

Maximum Power Output: 150.0 kW (201 bhp)

 Open Market Value:
 \$38,510.00

 Original Registration Date:
 24 Jun 2010

 First Registration Date:
 24 Jun 2010

Transfer Count: 2

Actual ARF Paid: \$38,510.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 23 Jun 2020 PARF Rebate Amount: \$21,180.00

Intended COE Rebate Details

COE Expiry Date: 23 Jun 2020

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

 QP Paid:
 \$39,911.00

 COE Rebate Amount:
 \$7,461.00

 Total Rebate Amount:
 \$28,641.00

The information contained herein is correct as at 10 Aug 2018

Hsiao Tong (LKKAuto)

From:

Hsiao Tong (LKKAuto)

Sent:

Tuesday, 20 November 2018 9:30 AM

To:

Jason Fastech Auto (jason@fastechauto.com.sg)

Subject:

Your ref: SLC 9330E *Our ref: CC6/LCR18014507/Upa3 [ACCIDENT INVOLVING SLM

9450P(AIG) & SLC 9330E ON 10/08/2018]

Your ref: SLC 9330E

Without Prejudice

Our ref: CC6/LCR18014507/Upa3

Dear Sirs/Mdm.

ACCIDENT INVOLVING SLM 9450P(AIG) & SLC 9330E ON 10/08/2018

We refer to the above matter.

We propose settlement at a global sum of \$12,590.00(all-in).

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From:

Jason Fastech Auto <jason@fastechauto.com.sg>

Sent:

Tuesday, 20 November 2018 11:41 AM

To:

Hsiao Tong (LKKAuto)

Subject:

RE: Your ref: SLC 9330E *Our ref: CC6/LCR18014507/Upa3 [ACCIDENT INVOLVING

SLM 9450P(AIG) & SLC 9330E ON 10/08/2018]

Without Prejudice

Dear Hsiao Tong,

We are pleased to accept your offer of global sum of \$12,590.00(all-in) Property claim only.

Thank you.

Best Regards

Jason Tang Kim Chwee Auto Pte Ltd 1 Kaki Bukit Ave 6 #01-46/48/50 AutoBay Singapore 417883 Tel: 67465405

Tel: 67465405 Hp: 98218445

jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Tuesday, November 20, 2018 9:30 AM

To: Jason Fastech Auto (jason@fastechauto.com.sg) < jason@fastechauto.com.sg>

Subject: Your ref: SLC 9330E *Our ref: CC6/LCR18014507/Upa3 (ACCIDENT INVOLVING SLM 9450P(AIG) & SLC 9330E

ON 10/08/2018]

Your ref: SLC 9330E

Without Prejudice

Our ref: CC6/LCR18014507/Upa3

Dear Sirs/Mdm,

ACCIDENT INVOLVING SLM 9450P(AIG) & SLC 9330E ON 10/08/2018

We refer to the above matter.

We propose settlement at a global sum of \$12,590.00(all-in),

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From:

Hsiao Tong (LKKAuto)

Sent:

Friday, 31 August 2018 2:07 PM

To:

'Eileen, May Hwee Yap'

Subject:

ACCIDENT INVOLVING SLM 9450P(AIG) & SLC 9330E ALONG/AT BALESTIER RD

(INFRONT OF WAI WING CENTRE) ON 10/08/2018

Your Ref: SLC 9330E

Our Ref: CC6/LCR18014507/Upa3

Dear Sirs/Madam,

ACCIDENT INVOLVING SLM 9450P(AIG) & SLC 9330E ALONG/AT BALESTIER RD (INFRONT OF WAI WING CENTRE) ON 10/08/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from SLC 9330E against your insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

AUTHORIZATION TO ACT (AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

l	LIMILA	Y GEK			("the	third party	oloim tii
of _	210 JURONO	EAST STREET	21 #02-367 S-600	210	(alo	umu party	The state of the s
owne	er of	SLC 9330E		(vehicle	no.)	hereby	(address)
_	KIM CHWEE	AUTO PTE LTD					
("the	workshop	") to act fo	or me with	respect to my	/ claim t	for repair co	sts and/or
renta	l and/or lo	ss of use ("claim") for	my vehicle n	10.	SLC 9330E	_that was
dama	ged pursu	ant to the	accident w	hich occurred	d on	10.08.2018	ate) along
BA	LESTIER TWDS	CTE		1.700/11(1711.14			(location)
involv	ing vehicle	e no/s	SLM 9450P				
							A 100 CO CO CO
	of the wo	107					
furthe	er acknow	vledge that	t any settl	ement the w	orkshop	may reac	h on my
behalf	is on a w	ithout preju	idice and v	vithout admis	sion of	liability basi	is insofar
as the	driver/owr	er/insurers	of the other	er vehicle/s is	concer	ned.	
	Date th	is(U	day of _		nth) 20_	(year)	
	1			CH	W.		
		1		(3) (1) (1) (1) (1) (1) (1) (1) (1) (1) (1	THE PARTY IN		
	D. Sh	7	-	6.01	130	Top-	
igned by	the third	party daimar	nt"	Signed b	y "the wo	orkshop"	

ř

RELEASE VOUCHER (AIG Asia Pacific - Express Third Party Claim)

"We/I, KIM CHWEE AUTO PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$12,590.00 (Global Sum) for vehicle no. SLC 9330E that was damaged pursuant to the accident which occurred on 10/08/2018 (date) along BALESTIER TOWARDS CTE involving vehicle no/s SLM 9450P.

This is pursuant to the inspection conducted on 10/08/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner <u>LIM LAY GEK</u> ("the third party claimant") of vehicle no. <u>SLC 9330E</u> make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLC 9330E (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

This Discharge Vencher applies only to the chierces's charge and will not effect to a imported charge and will not effect to a imported charge and the imported to the statement of the imported to the importance to the imported to the impo

TAX INVOICE

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Chassis/Eng# :

Tax Invoice

Vehicle No

Date

Accident Date : 10.08.2018

Make/Model : BMW

Claim No

:0818- 20472

:20472

:20.08.2018

:SLC 9330E

Reference

Policy No

Amount

To proceed on lump sum repair

Attn: Motor Claims Department

SS

11,200.00

E. & O. E. 11,200.00 Total : S\$ GST @ 7% : 784.00 SS 11,984.00 Amount Due

KIM CHWEE AUTO PTE LTD

All Invoices are subjected to GST

Dynamic Car Rental

1 KAKI BUKIT AVENUE 6, #01-46/48/50 AUTOBAY, SINGAPORE 417883.

TEL: (+65) 6741 7244, 6746 5405 FAX: (+65) 6745 8520, 6746 5786

Co. Reg. No. 52928467K

ore Lin 1	Lan Ger		REG. No.	MODE	MODEL: 1/CA	mw).
DORESS	han bek		634396			1 1 1
HHDEOR.		12	(N) 1 31 31	DIESE	DATE A ME NO	E 1/4 1/2 3/4
			IN.		14/8/18	J. 43
			OUT		10/8/18	11.40 d
			DRIVEN		TIME USED	
AMED DRIVER A	Obone		COMPANIE CONTRACTOR			
BIVIBIO I INCENDE NO	DATE OF EXPIREY	PLACE OF ISSUE		10011000		
G43888A				HOURS	0.55 (A) (A)	
ASSPORT NO	DATE OF ISSUE	PLACE OF ISSUE	7	DAYS	ess 180 -10	720.h
DD NAMED DRIVER			,	WEEKS	0.55	
RIVING LICENCE NO	DATE OF EXPIRY	PLACE OF ISSUE	N.	ONTHIS	0.55	
ASSPORT NO	DATE OF ISSUE	PLACE OF ISSUE	BY INITIALLING, F	ENTER	SUB-TOTAL	
			AGREES TO PAY A FOR COLLISION DA			
MPORTANT NOTES:	consensus celu		WAIVER (C.D.W.)			
a refund will be given for sehicle in a refund will be given for period lid	rturns early:				TOTAL HENTAL	
her is liable to pay first \$4000 unde under repair.	r section I & II in any according p	lus lites of earnings while consuped vehicle			DELIVERY FEE	
her is liable to pay all parting fee a					COLLECTION FEE	
shide return during office Year onl o Getylon on Public Hollony and S			X			
XCESS: let.1 - Used in 6 pore Chip (5002)	000		PER DAY PER	WEEK	PER MONTH	
Sex 6 - Used in Silpons Only (SGEX) Sex 6 - Used Dutaide (Epons Only)	2000 SGD-6000		3 3		*	
lant 9 - Used Outside II pure Only Aucresia Excess in 5 pone: 900010	10		BY INITIALLING, H AGREES TO PAY A			
Increes Excess Outside littere S DOTTONAL CONDITIONS:	G028G		FOR PERSONAL AC INSURANCE (P.A.I.)	CLOENT		
Geographical areas: Simplewe & Other Host Im:	West blokeyese.		311000000000000000000000000000000000000			
a) 18 years out and above to hooling a ualid relevant tiless of	f driving Noeme.		X			
Additional Own Carrage Excess I	of (\$81,000 to reprincable for any	nemediannemet shiers who:	PER DAY PER WEEK		PER MONTH	
ii) age 22 to 23 years old; to age 66 to 70 years old; to with diseas experience of 1 to	per to least finer 7 years in Tall	gapter in the relevant course of driving	5 5		5	
Scenee			PREPAYMENT		TOTAL CHARGE	
Additional All Claims excess of 50 a) in 15 years old to 21 years old.	anstor	will be a made of the same of the	CHECK		DEPOSIT	
ti) is 77 years plit and above and is with driving expensions of teas		ses of driving license.	CASH			
		all expensive and important barris to be sponsible for any reporting of each lesses.				
Here is laber to pay first \$4000 uts		plus loss of earning while damage vehicle	RECEIPT NO.		NETT CHARGE	
a under repair.						
iver is responsible for Addition	nel SA 000 00 Europe		AND DESIGNATIONS INC.	mileto.		
the THIRD PARTY DAMAGE			AMOUNT DUE / RE	- United		
HAVE READ THE TERMS /						
	MINISTER MINISTER					
IGNED BY THE PARTIES HE	ERETO ON THE		DAY OF			
	JA.			1		
	NT C		1	11 3		
	Nul a			/	1	

DYNAMIC CAR RENTAL

1 Kaki Bukit Ave 6 #01-46 Autobay

Singapore 417883

Tel No: 6741 7244 / 6746 5405 Fax No:67458520

Co. Reg No: 52928467K

To: LIM LAY GEK

Invoice : DCR-2018-08-06

Date : 14.08.2018

Agreement No : 20110

Ref : LOD

DESCRIPTION

AMOUNT

Rental charges for vehicle :

SKG3439G

0818-20472)

720.00

Rental Period from

10.08.2018

to

14.08.2018

E. & O. E.

Total

\$

720.00

Hayly Lee Pah Leng

for Dynamic Car Rental

> Back to OneMotoring

Land Transport Authority

Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time:

10 Aug 2018 / 11:27:56

Receipt Date/Time: 10 Aug 2018 / 11:27:56

Tax Invoice/Receipt

Receipt No.: ITNET-00000-180810-000730

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Resu	t of Insurance Enquiry - SLM9450P			()	()
As at	10 Aug 2018/10:42:00				
Insura	ance Co: AIG ASIA PACIFIC INSURAI	NCE PTE. LTD.			
1	Insurance Enquiry - SLM9450P				
	Enquiry Fee 20180810112706078548		7.00	0.49	7.49
		Sub-Total	7.00	0.49	7.49
		Total Before Rounding	7.00	0.49	7.49
		Rounding Difference			0.04
		Total Amount Payable			7.45
		Paid By			
		20180810112718994	Direct Debit: eNE (Internet Banking		7.45
		Total	William Chichest as condition	70.	7.45
		Cash Change			0.00
		Tendered Amount			7.45
		Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

...CLAIM SUBFOLDER...(Pending for Survey Report) Fastilane

LAIM SUB	FOLDER TRA	CKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status		
Main	10 Aug 2018 Edit Reg		10 Aug 2018 00:00 Edit Adj Rpt	S\$11,200.00 Edit Estimates	5\$11,200.00 View Rpt		Pending for Si Report Cancel Case	urvey	
	Main	R	eference	Claim De	tails	Documents	SI	lgw All	
CLAIM SU	BFOLDER DE	TAILS			[Create	d by adjuster]			
Insured:	LCRF PTE	LTD, Co. Reg. 1	to.: 201624597K						
Main Claimant:	LIM LAY	GEK, ID: S6943	A888						
Vehicle Reg No.:	SLC933	DE		Date of		018 10:00 - :59 ths and 17 Days Fro	m LTA Reg Date (M	an Yr)]	
Claim Type	TP / 249	8689745SG		Policy/C Note No		099994787 (Comprehensive)			
Vehicle Reg No. (Insured):	SLM9450	P		Policy N (Claima		MT103902			
				Excess					
Repairer:	Kim Chwe	e Auto Pte Ltd	(HQ) 1 Kaki Bukit Av	enue 6 #01-48, Au	toBay@Kaki Buk	it, 417883 Euros - T	el: 67465405/6741	7244	
Handling Insurer:	AIG Asia	Pacific Insuranc	e Pte. Ltd. (Expres	s) - Tel: 65-6419-3	000 [Handled	by Ng, Jeffrey-SK] Jeffreysaykiat.Ng(aig.com	
Claimant's Insurer:	Tokio Mar	ine Insurance 9	ingapore Ltd (HQ)	- Tel: 6221 6111					
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 625	66-3561 [Handle	by MARCUS C	HUA] [Final Rp	t due 21/08/20	18]	
ASSOCIAT	ED MAIL RE	CEIVED				Viev	w All Compose C	ase Mail	
			- Adj Mandate App load TP GIA Report		9) - SLC9330E	- Claim Handler: 1	Ng, Jeffre		
ALL ASSO	CIATED TAS	ks≘			View All	Search Tasks C	reate New Task	Complete	
Due Date	a Priority	Type Task	Group Subject	Handler A	ssigned By	Completed On	Created On	Done?	

Claim Documents

Let	ters/Corresponder	nces	1 per	page 💟	~
Na	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	0	Edit	
Pho	otos/Images		3 per	page V	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Siabilia	Thumbnail	-
1	10/08/18 17:16	Chassis Number	0	Load JPG	V
2	10/08/18 17:16	Odometer Reading	0	Load JPG	V
3	10/08/18 17:16	General View	0	Load JPG	V
4	10/08/18 17:16	General View	0	Load JPG	2
5	10/08/18 17:16	General View	0	Load 3PG	V
5	10/08/18 17:16	General View	0	Load JPG	V
7.	10/08/18 17:16	General View	0	Load JPG	V
В	10/08/18 17:16	General View	0	Load JPG	V
9	10/08/18 17:16	General View	0	Load JPG	V
10	10/08/18 17:16	General View	0	Load JPG	V
11	10/08/18 17:16	General View	0	Load JPG	V
12	10/08/18 17:16	General View	0	Load JPG	V
13	10/08/18 17:16	General View	0	Load JPG	V
14	10/08/18 17:16	General View	0	Load JPG	V
15	10/08/18 17:16	General View	0	Load JPG	V
16	10/08/18 17:16	General View	0	Load JPG	V
17	10/08/18 17:16	General View	0	Load JPG	7
18	10/08/18 17:16	General View	0	Load JPG	V
19	10/08/18 17:16	General View	0	Load JPG	V
20	10/08/18 17:16	General View	0	Load JPG	V
21	10/08/18 17:16	General View	0	Load JPG	V
22	10/08/18 17:16	General View	0	Load JPG	V
23	10/08/18 17:16	General View	0	Load JPG	Ø
24	10/08/18 17:16	General View	0	Load JPG	V
25	10/08/18 17:16	General View	0	Load JPG	V
26	10/08/18 17:16	General View	0	Load JPG	V
27	10/08/18 17:15	General View	0	Load JPG	V
28	10/08/18 17:16	General View	0	Load JPG	V
29	10/08/18 17:16	General View	0	Load JPG	V
30	10/08/18 17:16	General View	0	Load JPG	V
31	10/08/18 17:16	General View	0	Load JPG	V
32	10/08/18 17:16	General View	0	Load JPG	1
33	10/08/18 17:16	General View	0	Load JPG	2
34	10/08/18 17:16	General View	0	Load JPG	

Let	ters/Corresponde	nces	1 per page	~ ~
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbr	errore a speciment with the
20	10000000000000			2
35	10/08/18 17:16	General View	1 Load JP	-
36	10/08/18 17:16	General View	1 Load JP	_
37	10/08/18 17:16	General View	€ Load 3P	
38	10/08/18 17:16	General View	D Load 3P	_
39	10/08/18 17:16	General View	Load JP	
40	10/08/18 17:16	General View	Load JP	_
41	10/08/18 17:16	General View	1 Load JP	-
42	10/08/18 17:16	General View	Load JP	-
43	10/08/18 17:16	General View	10 Load JP	
44	10/08/18 17:16	General View	1 Load JP	
45	10/08/18 17:16	General View	■ Load JP	-
46	10/08/18 17:16	General View	Equal JP	-
47	10/08/18 17:16	General View	■ Load JP	G 😾
48	10/08/18 17:16	General View	■ Load JP	■
49	10/08/18 17:16	General View	■ Load JP	3 2
50	10/08/18 17:16	General View	■ Load JP	5 2
51	10/08/18 17:16	General View	Load JP	3 🗸
52	10/08/18 17:16	General View	■ Load JP	3 2
53	10/08/18 17:16	General View	Load JP	9
54	10/08/18 17:16	General View	■ Load 3P	-
55	10/08/18 17:16	General View	■ Load JP	3 🗸
56	10/08/18 17:16	General View	Load JP	4700
57	10/08/18 17:17	Reinspection Photo	Load JP	-
58	10/08/18 17:17	Reinspection Photo	Load JP	
59	10/08/18 17:17	Reinspection Photo	O Load JP	
50	10/08/18 17:17	Reinspection Photo	O Load JPI	anna.
51	10/08/18 17:17	Reinspection Photo	D Load JPG	
52	10/08/18 17:17	Reinspection Photo	Load JP	_
53	10/08/18 17:17	Reinspection Photo	Load 3PG	
54	10/08/18 17:17	Reinspection Photo	Load 3P6	-
55	10/08/18 17:17	Reinspection Photo	Load 3Pt	
56	10/08/18 17:17	Reinspection Photo	■ Load 3PG	
57	10/08/18 17:17	Reinspection Photo	0 Load 3PG	anne.
58	10/08/18 17:17	Reinspection Photo	O Load JPC	-
59	10/08/18 17:17	Reinspection Photo		
70	10/08/18 17:17	Reinspection Photo	Load JPC Load JPC	
71	10/08/18 17:17	Reinspection Photo		4000
12	10/08/18 17:17	Reinspection Photo	77000	-
13	10/08/18 17:17	Reinspection Photo	€ Load JPC	1000
14	10/08/18 17:17	Reinspection Photo	1 Load JPC	
15	10/08/18 17:17	brigge Harrison control (1900)	O Load JPC	-
6		Reinspection Photo	1 Load 3PC	-
	10/08/18 17:17	Reinspection Photo	1 Load JPC	1000
7	10/08/18 17:17	Reinspection Photo	0 Load JPC	-
8	10/08/18 17:17	Reinspection Photo	O Load 3PC	
9	10/08/18 17:17	Reinspection Photo	1 Load 3PC	-
0	10/08/18 17:17	Reinspection Photo	1 Load JPC	-
1	10/08/18 17:17	Reinspection Photo	OPt bead 10	_
2	10/08/18 17:17	Reinspection Photo	1 Load 3PC	-
3	10/08/18 17:17	Reinspection Photo	Load JPC	8

	ters/Corresponde	nces	1 per	page 💟	×
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	-
84	10/08/18 17:17	Reinspection Photo	0	Load JPG	V
85	10/08/18 17:17	Reinspection Photo	0	Load JPG	V
86	10/08/18 17:17	Reinspection Photo	0	Load JPG	V
87	10/08/18 17:17	Reinspection Photo	0	Load JPG	V
88	10/08/18 17:17	Reinspection Photo	0	Load JPG	V
89	10/08/18 17:17	Reinspection Photo	0	Load JPG	V
90	10/08/18 17:17	Reinspection Photo	0	Load JPG	V
91	10/08/18 17:17	Reinspection Photo	0	Load JPG	V
92	10/08/18 17:17	Reinspection Photo	0	Load JPG	V
93	10/08/18 17:17	Reinspection Photo	0	Load JPG	V
94	10/08/18 17:17	Reinspection Photo	0	Load JPG	V
95	10/08/18 17:17	Reinspection Photo	0	Load 3PG	Z
96	10/08/18 17:17	Reinspection Photo	0	Load JPG	Z
97	10/08/18 17:17	Reinspection Photo			
98	10/08/18 17:17		0	Load JPG	V
99	0.0000000000000000000000000000000000000	Reinspection Photo	0	Load JPG	Z
	10/08/18 17:17	Reinspection Photo	0	Load JPG	N
100	10/08/18 17:17	Reinspection Photo	0	Load JPG	V
101	10/08/18 17:17	Reinspection Photo	0	Load JPG	V
102	10/08/18 17:17	Reinspection Photo	0	Load JPG	V
103	10/08/18 17:17	Reinspection Photo	0	Load JPG	Z
104	10/08/18 17:17	Reinspection Photo	0	Load JPG	1
105	10/08/18 17:17	Reinspection Photo	0	Load JPG	V
106	10/08/18 17:17	Reinspection Photo	0	Load JPG	⊻
107	10/08/18 17:17	Reinspection Photo	0	Load JPG	1
108	10/08/18 17:17	Reinspection Photo	0	Load JPG	V
109	10/08/18 17:17	Reinspection Photo	0	Load JPG	2
110	10/08/18 17:17	Reinspection Photo	0	Load JPG	7
111	10/08/18 17:17	Reinspection Photo	0	Load JPG	V
112	10/08/18 17:17	Reinspection Photo	0	Load JPG	2
113	10/08/18 17:17	Reinspection Photo	0	Load JPG	V
114	10/08/18 17:17	Reinspection Photo	0	Load 3PG	V
115	10/08/18 17:17	Reinspection Photo	0	Load JPG	V
116	10/08/18 17:17	Reinspection Photo	0	Load JPG	12
117	10/08/18 17:17	Reinspection Photo	0	Load JPG	W
118	10/08/18 17:17	Reinspection Photo	0	Load JPG	~
119	10/08/18 17:17	Reinspection Photo	0	Load JPG	V
20	10/08/18 17:17	Reinspection Photo	0	Load JPG	V
21	10/08/18 17:17	Reinspection Photo	0	Load JPG	M
22	10/08/18 17:17	Reinspection Photo	0	Load JPG	V
				10000.0	-
ocu	umentation		1 per p	age 🔽	V
¥0	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnall	Print
	13/08/18 15:05	TP GIA REPORT	0	Load PDF	
	15/09/18 14:03 15/09/18 14:04	TP ESTIMATE_MARKED PARF_COE REBATE	0	Load PDF	
	14/11/18 14:34	RENTAL RECEIPT	0	Load PDF	
	14/11/18 14:34	LTA SEARCH	ŏ	Load PDF	
,	14/11/18 14:34	LETTER TO OI	Ŏ	Load PDF	
	14/12/18 11:52	WORKSHOP INVOICE	0	Load PDF	
3	14/12/18 11:52	AUTHORISATION TO ACT FORM	0	Load PDF	
)	14/12/18 11:52	Release Voucher	0	Load PDF	

Let	ters/Corresponde	nces	1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbru	il Print
1	13/08/18 10:27	OI GIA REPORT	■ Load PDI	CC1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM	
$I \leftarrow \Delta BA$	

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vet	nicle No:	SLM94	50P (Insd veh	1)	٨	Model:		BMW 5	523I 2.5 (A)	
		SLC93	30E (TP veh)							
Date of Accident:		10/08/2018								
-			2003 110				$\overline{}$			
_	bal Sum Settlerr	ent :	[X] Yes] No	-32.00			
	pair Estimate			: \$		28,276	_			
_	al Repair Cost			: \$		12,59	00.00			
31112000	s of Use			: \$					sys at \$0.00 per da	ву
_	ntal (if any)			: \$				4 da	sys	
LTA	A / GIA Search F	ee		: \$						
Oth	ers:			: \$						
				: \$						
_	al Settlement Su	The second second	COSSESSION FOR PROPERTY.	: \$		12,59	00.00			
Is T belo	hird Party Worl	kshop G	A Registered	7	[]	YES	[X] NO	(Kindly indicate	e
A)	For Non GIA R	egistere	d Workshop:		Ag	greed Lia	bility	100	(%)	
B)	For GIA Regist	ered Wo	rkshop:		В	OLA App	licable:	Yes/No	BOLA Scenario N	0;
	BOLA Liability: * Assessed Liab		C1011F.	chair				A CONTRACTOR OF THE PARTY OF TH	(%) BOLA does not app	olv.
Ren	marks									
Pay	ment Instruction	n: Paye	e's Breakdow	n						
1)	Kim Chwee Au	to Pte Lt	d			: \$			12,	590.0
2)						: S			- 1944	
3)						s				
4)						: \$				
	JOANNE I	EE KHA	NG MIN			14 Dec				
	LKK Auto C				_	2018				

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (If any)

LKK Auto Consultants Pte Ltd (Co.Reg. No: 199607198R)

51 Ubi Ave 1 #01-25. Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC6/LCR18014507/UPA3Q2

Date:

14/12/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999994787

Claimant Vehicle No:

SLC9330E

Insured Vehicle No:

SLM9450P

Date of Loss:

10/08/2018

Nature of Claim:

TP

Claim No: 2498689745SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLC9330E

Make & Model:

BMW 5231, 2.5 (A)

Engine No:

05787379N52B25AF

Reg. Date: Colour:

24/06/2010 (Man. Year: 2010)

Chassis No: Odometer

WBAFP32070C257835 161665 km

Engine Capacity:

2497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

245/45 R18

Rear Tyre Size:

245/45 R18

Front Left Side:

Continental 6 mm

Rear Left Side:

Continental 6 mm

Front Right Side:

Continental 6 mm

Rear Right Side:

Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,096.34	10,958.54	10,137.80	48.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,330.00	3,060.00	2,270.00	42.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,426.34	14,018.54	12,407.80	46.95
Approved Total (Overridden) (S\$)		11,200.00		
(S\$)	26,426.34	11,200.00	15,226.34	57.62
+ GST 7.00/7.00% (S\$)	1,849.84	784.00	1,065.84	57.62
Nett Amount (S\$)	28,276.18	11,984.00	16,292.18	57.62
+ Car Rental (4.0 x S\$15	50.00/day) (S\$)	600.00		
+ Doc/Se	+ Doc/Search Fee (S\$)			
Net	Nett Liability (S\$)			
Global Sum S	ettlement (S\$)	12,590.00		

INSPECTION

Date of Assignment:

10/08/2018

Date inspected:

10/08/2018 Inspected At:

Kim Chwee Auto Pte Ltd (HQ) 1 Kaki Bukit Avenue 6 #01-48, AutoBay@Kaki Bukit Singapore 417883

Estimated Period of Repair:

7.0 days

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report

REPAIR DETAILS

Rec	omn	nen	ded	Par	ts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent / Warped	1,866.20 F	*1,766.10 FL
2	1		*BOOTLID REAR LOGO	Necessary	68.50 F	*68.50 FL
3	1		*BOOTLID 520I EMBLEM	Necessary	66.80 F	*66.80 FL
4	1		*BOOTLID REFLECTORS	N/S Cracked	970.60 F	*466.20 FL
5	1.		*BOOTLID INNER LOCK	Not Necessary	299.08 F	*-FL
6	1		*BOOTLID WEATHERSTRIP	Twisted	275.00 F	*266.05 FL
7	1		*TAILLAMPS	N/S Cracked	1,377.00 F	*585.00 FL
8	1		*REAR BUMPER	Distorted	1,866.20 F	*1,545.00 FL
9	1		*REAR BUMPER LOWER SKIRTING	Not fitted	650.00 F	*-FL
10	1		*REAR BUMPER REFLECTORS	N/S Broken	1,550.00 F	*75.00 FL
11	1		*REAR BUMPER PDC SENSORS	N/S Shorted (1 PCS ONLY)	1,220.00 F	*266.00 FL
12	1		*REAR BUMPER PDC SENSORS WIRE	Not Necessary	313.54 F	*-FL
13	1		*REAR BUMPER TOP GUIDE	Cracked	199.02 F	*199.02 FL
14	1		*REAR BUMPER REINFORCEMENT	Bent	755.01 F	*640.92 FL
15	1		*REAR BUMPER LOWER GUIDE	Cracked	185.13 F	*185.13 FL
16	1		*REAR BUMPER SIDE RETAINERS	N/S Cracked	230.00 F	*115.00 FL
17	1		*REAR BUMPER INNER ADAPTER	Not Necessary	185.00 F	*-FL
18	1		*REAR END PANEL	Badly Dented	1,122.10F	*1,018.57 FL
19	1		*REAR END PANEL TOP GARNISH	Twisted	311.20 F	*288.01 FL
20	1		*REAR FENDER N/S	Repair	1,412.30 F	*-FL
21	1		*REAR FENDER INNER TRIM N/S	Deformed / Warped	366.05 F	*366.05 FL
22	1		*REAR FENDER INNER SIDE MEMBER N/S	Badly Dented	699.01 F	*699.01 FL
23	1		*TAILLAMP SIDE GARNISH N/S	Cut	18.50 F	*18.50 FL
24	1		*REAR AIR VENT N/S	Distorted	66.50 F	*66.50 FL
25	1		*REAR EXHAUST ASSY	Bent / Twisted	1,880.10 F	*1,850.00 FL
26	1		*REAR EXHAUST HEAT SHIELD N/S	Distorted	299.20 F	*185.30 FL
27	1		*REAR FENDER UNDER COVER N/S	Distorted	322.20 F	*295.50 FL
28	1		*REAR TAILLAMP HOUSING PANEL N/S	Bent	366.20 F	*166.30 FL
29	1		*REAR WINDSCREEN MOULDING	Not Necessary	148.50 F	*-FL
30	1		*REAR SHOCK ABSORBER N/S	Not Necessary	522.30 F	*-FL
31	1		*REAR WHEEL HUB BEARING N/S	Not Necessary	645.10 F	*-FL
32	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00FS	*-FS
33	1		*REAR END PANEL SEALANT	Necessary	80.00FS	*50.00 FS
34	1		*REAR FLOOR PANEL INSULATOR	Necessary	380,00 FS	*150.00 FS
35	1		*SET REAR EXHAUST CHROME PIPE	Dented	300.00 FS	*120.00 FS
F=Fra	nchise	part. S=Spc	Nett. L=ListItemDisc.			
				Sub Total (S\$)		11,518.46
			- List Item Discoun	t on L Items 0.00/5.00% (S\$)	0.00	559.92

- List Item Discount on L Items 0.00/5.00% (S\$)

Total Parts (S\$) 21,096.34 10,958.54

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REAR PDC SENSOR	New	100.00	50.00
3	TO DISMANTLE & REFIX BOOTLID MECHANISM	New	100.00	80.00
4	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
5	TO DISMANTLE & REFIX SEAT , CUSHION , UPHOLSTERY	New	150.00	100.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	150.00	100.00
7	TO DISMANTLE & REFIX REAR UNDERCARRIAGE	New	180.00	0.00
3	TO DISMANTLE & REFIX PETROL TANK	New	100.00	0.00
9	TO REPROGRAMME & RESET FAULT CODE	New	200.00	0.00
10	TO SPRAY RUST PROOFING	New	120.00	100.00
11	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTENED & REPLACING PARTS	New	2,200.00	1,400.00
12	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,200.00
	Gross Labour	Cost (S\$)	5,330.00	3,060.00

< END OF ESTIMATES >