

## Shirley Hiew (LKK Auto)

---

**From:** Chin <chin@modernautomotive.com.sg>  
**Sent:** Friday, 17 August 2018 4:13 PM  
**To:** 'Shirley Hiew (LKK Auto)'  
**Cc:** 'SUR'  
**Subject:** RE: GBC 1163S OD (LPC)

Dear Shirley

We accept the amount of not exceeding \$15,000.00 for this repair.

Regret that our client is unable to provide the purchase agreement.

Regards,  
Grace Chin  
Modern Automotive Pte Ltd  
Blk 3023-A, Ubi Road 1 #01-61  
Singapore 408717

Tel: 6748 4422  
Fax: 6747 6720

---

**From:** Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]  
**Sent:** Friday, 17 August, 2018 4:08 PM  
**To:** 'Chin' <chin@modernautomotive.com.sg>  
**Cc:** 'SUR' <sur@lkkauto.com>  
**Subject:** RE: GBC 1163S OD (LPC)

Dear Chin,

As instructed by our client, please proceed at repair cost not exceeding \$15,000.00 (inclusive supplementary) to repair the insured vehicle

**GBC 1163S (Excess \$ 700/-)** on lump sum basis.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

\*Kindly update us whether your client has been forward the purchasing agreements documents to you for the 2 items as below?

- 1) Aluminium Cabin (Interior)
- 2) Aluminium Wheel Arch Box (Interior)

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chin [<mailto:chin@modernautomotive.com.sg>]

**Sent:** Tuesday, 14 August 2018 2:19 PM

**To:** 'Shirley Hiew (LKK Auto)' <[ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com)>

**Subject:** RE: GBC 1163S OD (LPC)

Dear Shirley

We are able to undertake this repair not exceeding \$15,000/- on lumpsum basis..

Please send your authorisation letter to repair this vehicle.

Thank you

Regards,

Grace Chin

Modern Automotive Pte Ltd

Blk 3023-A, Ubi Road 1 #01-61

Singapore 408717

Tel: 6748 4422

Fax: 6747 6720

---

**From:** Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]

**Sent:** Tuesday, 14 August, 2018 11:50 AM

**To:** [chin@modernautomotive.com.sg](mailto:chin@modernautomotive.com.sg)

**Cc:** [sur@lkkauto.com](mailto:sur@lkkauto.com)

**Subject:** GBC 1163S OD (LPC)

Hi Chin,

As spoken, Kindly check the repair cost limit whether you are able to repair the vehicle not exceeding \$ 15,000.00 on lump sum basis?

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)