



**KAH MOTOR CO. SDN. BHD.**  
 (A Member of the Oriental Holdings Berhad)  
 Service and Body Repair  
 Tel: +65 6841 3838 Website: www.honda.com.sg  
 For 24-hours Roadside Assistance, Call 98203838

Kindly Help to arrange  
 Surveyor to survey this  
 Vehicle thanks

# QUOTATION

GST Reg No.: M200050223  
 Company Ref. No.: S60FC1380G

<b>Customer</b> : FWD INSURANCE (S) PTE LTD 6 TEMASEK AVENUE #18-01 #18-01 SINGAPORE 038986	<b>Document No.</b> : SQT18003292	<b>Page</b> 1
<b>Registration No</b> : SLW3342E	<b>Date</b> : 7. Aug 2018	
<b>Chassis No</b> : MRHFC5650HT000878	<b>Customer No.</b> : WZF001	
<b>Model</b> : CIVIC 1.6 VTI YM2017	<b>Svc Advisor</b> : LIM CHOU SIONG	
<b>Owner's Name</b> : TEO CHUN CHENG	<b>Engine No</b> : R16B22001335	
<b>Ins Policy No.</b> :	<b>Date   Time</b> : 7. Aug 2018 10:42:08 AM	
<b>Date of Accident</b> : 4/8/2018	<b>Surveyor Name</b> :	
	<b>Survey Date</b> :	
	<b>Authorisation Date</b> :	

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TEO CHUN CHENG OWNER INSURER: AVIVA LTD ACC DATE: 4/8/2018 SURVEYED BY: DATE: REF NO: TP INSURER: FWD INSURANCE (S) PTE LTD TP VEH: SJQ4608M						
67010-TEA-T00ZZ	PANEL COMPR.FR.DOOR <i>Painted</i>	1	761.40	25	571.05	39.97	✓ 611.02
72425-TBA-A01	MOLDING ASSYR.FR.DOOR SASH <i>new</i>	1	25.80	25	19.35	1.35	✓ 20.70
72828-TEA-T01	SEALRR.DOOR LOWER <i>new</i>	1	6.10	25	4.57	0.32	✗ 4.89
	<b>Sum Item</b>				<u>594.97</u>	<u>41.64</u>	<u>636.61</u>
BOMISC1	REPLACE FR R DOOR, REPAIR RR R DOOR & OTHER DAMAGE	1	1200.00		<del>1200.00</del> <i>560</i>	84.00	<del>1284.00</del> <i>100</i>
BP02R	SPRAY PAINTING ON FR R DOOR & RR R DOOR	1	1000.00		<del>1000.00</del> <i>900</i>	70.00	1070.00
	<b>Sum Labor</b>				<u>2200.00</u>	<u>154.00</u>	<u>2,354.00</u>

Survey By	<u>Adrian King</u>	C S Lim	<b>Total Amount</b>	2,794.97	195.64	2,990.61
Date & Time	<u>28/08/18</u>	81006303 (HP)	<b>Total (Inclusive of GST)</b>			<u>2,990.61</u>
Excess						
Status	<u>Not Authorized</u>					
Signature	<u>[Signature]</u>	<u>03 days.</u>				

Printed on 7/8/2018 7:04:28 PM  
 This is a computer generated invoice. No signature is required.  
 Part prices are subjected to change without notice.  
 The above estimated cost of repair do not include any unforeseen damages.  
 GST Amount is calculated from individual line(s)