

22/03/2003

ASS. REC. BY:

REF:

CS/ICS18614589/Aad3

Special Instruction:

Survivor:

Adrian

ASSIGNMENT (Office)

From (Person):

Janice Goh

of

ICS

Date/Time:

13/8/18 @ 9:10am

Estimated Cost:

Bill to:

☒ OD

TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLG 4852C

Insured:

at Workshop m/s

First Autowork

Tel:

82925595

of

23 Keki Bkt Ave 4 #04-01

Policy No:

MPC/17A/449401

Claim No:

MPC/18W3214

Sum Insured:

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A.

03/08/2018

CA / ☒ REV

/ REP.

/ REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:01am @ 13/8/18

Person Contacted:

Kenny

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SLG 4852C-X
	kelnn.chu@alphine-motors.com.sg
13/8-	Revert manimen pending repair cost
13/8-	Email Kelnn offer 2ok 4/5
15/8/18 @ 12:04pm	revert to Janice Goh via Manimen. (repairer asking 45 to 22k)
21/8/18 @ 4:03pm	Janice Goh informed o/a at 45 to 21900 via Manimen.



(02/11/13) wef

REF: JCS

ASS. REC. BY:

## ASSIGNMENT

From: Date: 13/8/18

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLG 4852C

at Workshop m/s First Autoworks

of 23 Kaki Blk Ave 4 #04-01

Insured:

Policy No.

Claims No.

Sum Insured: Excess: \$500.00

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLG4852C Yr Regn: 2016 / Sept

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Opel Insignia c.c 1598

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 64299 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WOL6S5E3861002042

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil ☒ S/Rim STD A/Rim or

Tyre Size: F: 245/45R18

R: 245/45R18

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 13/08/18

Survey held at First Autoworks

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

OD ECICS.

21/8/18 @ 4.10pm Informed Kelvin CA not more than US \$21900 &amp; EX: \$500 by email

MV: 87K

PV: 65.1K.

RECEIVED 25 MAR 2019

Nett: 21.915.

22/3/19 Repairer informed Astan that they has not repair the vehicle.

22/3/19 Submit Preli - report.

Date/Time, File Pass to?

☒ Preli. Report

Days Of Repair:

11/1/13 Initial

☐ Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ Site Insp (\$ )☐ Interview (\$ )☐ Tech. Invs (\$ )☐ Weekend (\$ )

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ )

490

10

490





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

Ref : CS/ICS18014589/Aqd3

10 EUNOS ROAD 8

SINGAPORE POST CENTRE #09-04A SINGAPORE  
&nbsp; 408600

Date : 13-08-2018



Code : ICS

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SLG 4852C
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From JANICE GOH	Assign Date	13/08/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	03/08/2018	Inspection Date	13/08/2018
Survey held at	1ST AUTOWORKS PTE LTD 23 KAKI BUKIT AVE 4 #04-01 (SOUTH WING) SINGAPORE 415933		

## 5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.



## Nivitha (LKK Auto)

---

**From:** ECICS Claims <claims@ecics.com.sg>  
**Sent:** Monday, 13 August 2018 9:10 AM  
**To:** vincent.sim@alpinemotors.sg; 'assignments'  
**Cc:** Kelvin Chew; suhaimi@alpinemotors.sg; ECICS Claims  
**Subject:** RE: SLG4852C - OPEL INSIGNIA - OWN DAMAGED CLAIM - DOA 3-8-2018  
**Attachments:** SLG4852C -OWN DAMAGED OPEL.PDF; SLG4852C\_ESTIMATE 2.jpg;  
SLG4852C\_ESTIMATE 3 (2).jpg; SLG4852C\_ESTIMATE 3 (1).jpg

Hi Vincent

Sorry for the late reply.

We will appoint LKK for the OD survey.

Aside to LKK

Please assist to arrange for OD survey on urgent basis.  
Policy excess \$500.00

Thank you.

Regards,  
Janice Goh  
**Claims Division**  
DID: +65 6303 0182  
FAX: +65 6338 9267

**ECICS Limited**  
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

**WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY**, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.

*\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.\*\**

**From:** Vincent Sim [mailto:vincent.sim@alpinemotors.sg]  
**Sent:** Friday, 10 August, 2018 3:45 PM  
**To:** Janice Goh Siew Geok (ECICS, Claims); ECICS Claims  
**Cc:** Kelvin Chew; suhaimi@alpinemotors.sg  
**Subject:** re: SLG4852C - OPEL INSIGNIA - OWN DAMAGED CLAIM - DOA 3-8-2018

Janice,  
Any reply for this on Monday ?

Regards,  
Vincent Sim- Claims Dept

[vincent.sim@alpinemotors.sg](mailto:vincent.sim@alpinemotors.sg)

65113022 ext 343



---

**From:** "Vincent Sim" <vincent.sim@alpinemotors.sg>

**Sent:** Friday, August 10, 2018 12:35 PM

**To:** "Janice Goh Siew Geok (ECICS, Operations / Claims)" <Janice\_Goh@ecics.com.sg>, "ecics" <claims@ecics.com.sg>

**Cc:** "Kelvin Chew" <Kelvin.chew@alpinemotors.sg>, "suhaimi@alpinemotors.sg" <suhaimi@alpinemotors.sg>

**Subject:** SLG4852C - OPEL INSIGNIA - OWN DAMAGED CLAIM - DOA 3-8-2018

Good Morning Janice,  
kindly arranged for survey on coming Monday ( 13-8-2018 ) as the owner is still driving the vehicle  
survey will be done at add below :  
Person in charge :-  
Suhaimi , Kelvin – 82925595 H/P.  
68441985 – office phone  
E-mail ;  
[suhaimi@alpinemotors.sg](mailto:suhaimi@alpinemotors.sg)  
[kelvin.chew@alpinemotors.sg](mailto:kelvin.chew@alpinemotors.sg)

Add;  
First Autoworks Pte Ltd  
23, Kaki Bukit Ave 4  
#04-01 ( South Wing )  
singapore 415933  
( Vicom Building )  
tel; 6844-1985

Regards,  
Vincent Sim- Claims Dept

[vincent.sim@alpinemotors.sg](mailto:vincent.sim@alpinemotors.sg)

65113022 ext 343

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

follow us on  facebook  follow us on twitter  visit our website [ecics.com.sg](http://ecics.com.sg) 

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.



## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Tuesday, 21 August 2018 4:18 PM  
**To:** 'Kelvin.chew@alpinemotors.sg'; Denise Tay (LKKAuto)  
**Cc:** suhaimi@firstautoworks.com.sg  
**Subject:** RE: SLG 4852C / OD / ECICS

Dear Kelvin,

As instructed by our client ECICS Insurance, please proceed to repair the insured vehicle **SLG 4852C** at repair cost **not more than \$21,900.00 on Lump Sum basis (excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Kelvin Chew <Kelvin.chew@alpinemotors.sg>  
**Sent:** Wednesday, 15 August 2018 10:17 AM  
**To:** Denise Tay (LKKAuto) <denisetay@lkkauto.com>  
**Cc:** suhaimi@firstautoworks.com.sg; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>  
**Subject:** re: SLG 4852C / OD / ECICS

Hi Denise,

workshop request \$22K lump sum repair for this case.  
thanks.

from,  
kelvin chew  
8292 5595

---

**From:** "Denise Tay (LKKAuto)" <denisetay@lkkauto.com>  
**Sent:** 13 August 2018 17:22  
**To:** "Kelvin.chew@alpinemotors.sg" <Kelvin.chew@alpinemotors.sg>  
**Cc:** "Shiau Chan (LKKAuto)" <siewsc@lkkauto.com>  
**Subject:** SLG 4852C / OD / ECICS

Dear Kelvin,

As spoken to Adrian, we would check if you can repair the vehicle within \$20K lump sum



## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	13 Aug 2018 13:12	<b>Clm Dtl Modified</b>	Insured Name: -> LIM HIAP SENG.	[A] Nivitha Govindasamy
2	13 Aug 2018 13:12	<b>Clm Dtl Modified</b>	Claimant's Name: -> LIM HIAP SENG. Claimant's ID: -> S7249848H.	[A] Nivitha Govindasamy
3	13 Aug 2018 13:12	<b>Clm Veh Model Changed</b>	(204270) OPEL INSIGNIA 1.6 Turbo (A).	[A] Nivitha Govindasamy
4	13 Aug 2018 13:12	<b>Clm Created</b>	Reg No: SLG4852C. Policy No: MPC17A00449401. Acct Date: 2018/08/03. Claim Type: OD. Insurer: ECICS Limited (HQ). Workshop: 1st Autoworks Pte Ltd (HQ)	[A] Nivitha Govindasamy
5	13 Aug 2018 13:12	<b>Adj Co Assigned</b>	LKK Auto Consultants Pte Ltd (HQ); RR Region: ECICS EXT ADJ - OD/TP. Suggested Adj.: AutoProbe Consultants.	[A] Nivitha Govindasamy
6	13 Aug 2018 13:12	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2018/08/23	[A] Nivitha Govindasamy
7	13 Aug 2018 13:12	<b>Adj Mandate Set</b>	Approved:0.00.Reinsp:Adj decides.	[A] Nivitha Govindasamy
8	13 Aug 2018 13:13	<b>Adj Adjuster Assigned</b>	[None] -> ADRIAN LING	[A] Nivitha Govindasamy
9	13 Aug 2018 16:00	<b>Adj Rpt Initiated</b>		[A] DENISE TAY KWEE CHENG
10	13 Aug 2018 16:00	<b>Ins Email Updated</b>	[None] -> [YNKNOW@EMAIL.COM]	[A] DENISE TAY KWEE CHENG
11	13 Aug 2018 16:00	<b>Clm Dtl Modified</b>	JPJ Reg. Date: -> 2016/09/30.	[A] DENISE TAY KWEE CHENG
12	13 Aug 2018 16:00	<b>Clm Details Notified</b>		[A] DENISE TAY KWEE CHENG
13	13 Aug 2018 17:20	<b>Adj Mandate Request</b>	Cur.Req:0.00:PENDING REPAIR COST FROM REPAIRER	[A] DENISE TAY KWEE CHENG
14	13 Aug 2018 17:21	<b>Adj Mandate Request Cancelled</b>		[A] DENISE TAY KWEE CHENG
15	13 Aug 2018 17:21	<b>Adj Im. Advice Submitted</b>	Next Rpt:Final Rpt.Due Date:2018/08/23	[A] DENISE TAY KWEE CHENG
16	13 Aug 2018 17:21	<b>Adj Mandate Request</b>	Cur.Req:0.00:PENDING REPAIR COST FROM REPAIRER	[A] DENISE TAY KWEE CHENG
17	15 Aug 2018 11:59	<b>Adj Mandate Request Cancelled</b>		[A] SHIAU CHAN
18	15 Aug 2018 12:02	<b>Adj Im. Advice Submitted</b>	Next Rpt:Final Rpt.Due Date:2018/08/23	[A] SHIAU CHAN
19	15 Aug 2018 12:03	<b>Adj Mandate Request</b>	Cur.Req:28881.50:DAMAGES CONSISTENT. REPAIRER ASKING FOR REPAIR COST NOT MORE THAN \$22,000.00 ON LUMP SUM BASIS. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
20	21 Aug 2018 15:44	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2018/08/23	[I] Jeffrey Chew
21	21 Aug 2018 15:44	<b>Adj Mandate Set</b>	Approved:21900.00.	[I] Jeffrey Chew
22	21 Aug 2018 16:03	<b>Clm Registration Modified</b>	Excess: -> 500.00.	[I] Janice Goh

Date From



Date To



Audit Type None

Go

### ACTIVITY

No record

### Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1885727	13/08/2018 16:00	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLG4852C		10.70



**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited  
7 Temasek Boulevard  
#10-01 Suntec Tower One  
Singapore 038987

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 15 Aug 2018

**Preliminary Advice**

Vehicle No	: SLG4852C	Accident Date	: 03/08/2018
Make	: OPEL INSIGNIA	Policy No.	: MPC17A00449401
Assignment Date	: 13/08/2018	Excess	: S\$0.00
Date of Inspection	: 13/08/2018	Est. Duration of Repair	: 7.00
Inspection At	: 1ST AUTOWORKS PTE LTD (HQ) 23 KAKI BUKIT AVE 4, #04-01 SINGAPORE 415933		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	37,265.00
Revised Amount	:S\$	19,040.00
Check Items (Estimated)	:S\$	9,841.50
Total	:S\$	28,881.50
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	87,000.00
COE / PARF Rebate	:S\$	65,094.00
Salvage Value	:S\$	
Margin for Repair	:S\$	21,906.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : REPAIRER ASKING FOR REPAIR COST NOT MORE THAN \$22,000.00 ON LUMP SUM BASIS.



## Shiau Chan (LKKAUTO)

---

**From:** Kelvin Chew <Kelvin.chew@alpinemotors.sg>  
**Sent:** Wednesday, 15 August 2018 10:17 AM  
**To:** Denise Tay (LKKAUTO)  
**Cc:** suhaimi@firstautoworks.com.sg; Shiau Chan (LKKAUTO)  
**Subject:** re: SLG 4852C / OD / ECICS

Hi Denise,

workshop request \$22K lump sum repair for this case.  
thanks.

from,  
kelvin chew  
8292 5595

---

**From:** "Denise Tay (LKKAUTO)" <denisetay@lkkauto.com>  
**Sent:** 13 August 2018 17:22  
**To:** "Kelvin.chew@alpinemotors.sg" <Kelvin.chew@alpinemotors.sg>  
**Cc:** "Shiau Chan (LKKAUTO)" <siewsc@lkkauto.com>  
**Subject:** SLG 4852C / OD / ECICS

Dear Kelvin,

As spoken to Adrian, we would check if you can repair the vehicle within \$20K lump sum

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.



## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Monday, 13 August 2018 5:21 PM  
**To:** 'Kelvin.chew@alpinemotors.sg'  
**Cc:** Shiau Chan (LKKAuto)  
**Subject:** SLG 4852C / OD / ECICS

Dear Kelvin,

As spoken to Adrian, we would check if you can repair the vehicle within \$20K lump sum

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited  
7 Temasek Boulevard  
#10-01 Suntec Tower One  
Singapore 038987

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 13 Aug 2018

**Preliminary Advice**

Vehicle No	: SLG4852C	Accident Date	: 03/08/2018
Make	: OPEL INSIGNIA	Policy No.	: MPC17A00449401
Assignment Date	: 13/08/2018	Excess	: S\$0.00
Date of Inspection	: 13/08/2018	Est. Duration of Repair	: 7.00
Inspection At	: 1ST AUTOWORKS PTE LTD (HQ) 23 KAKI BUKIT AVE 4, #04-01 SINGAPORE 415933		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	37,265.80
Revised Amount	:S\$	19,040.00
Check Items (Estimated)	:S\$	9,841.50
Total	:S\$	28,881.50

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	87,000.00
COE / PARF Rebate	:S\$	65,094.00
Salvage Value	:S\$	
Margin for Repair	:S\$	21,906.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : Pending repair cost from repairer



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	9848H
<b>Vehicle Details</b>	
Vehicle No.:	SLG4852C
Vehicle to be Exported:	Yes
Intended De-registration Date:	03 Aug 2018
Vehicle Make:	OPEL
Vehicle Model:	INSIGNIA NB4 1.6 CDTI AT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	A1152036GZJX0082
Chassis No.:	W0LG55E38G1002042
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$27,936.00
Original Registration Date:	30 Sep 2016
First Registration Date:	30 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$26,111.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2026
PARF Rebate Amount:	\$19,583.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	29 Sep 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$56,889.00
COE Rebate Amount:	\$45,511.00
<b>Total Rebate Amount:</b>	<b>\$65,094.00</b>

The information contained herein is correct as at 03 Aug 2018

OK



**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Cbe Renewal Toyota Vios 1.5A



**\$3000** downpayment Monthly  
From \$450! Over 1000+ Loans  
3.68% P.A. 90% Car Financing  
GV Credit Pte Ltd [Start Ad](#)



Browse by Category ▾

Sort by Date Posted ▾

20 results/page ▾

4 vehicles

Opel Insignia

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	Opel Insignia	Any	Any	Any	Any	Any	Any	Available
	<b>Opel Insignia 2.0A</b>	<b>\$59,000</b>	<b>\$10,930 /yr</b>	<b>25-Oct-2012</b>	<b>1,998 cc</b>	<b>84,285 km</b>	<b>Luxury</b>	<b>Available</b>
Premium Aspiration And Dynamics Insignia. Pretty Impressive Improved Design, Class And Sophistication Interior. Luxurious Interior And Spacious Boot Space. Regularly Serviced And Well Taken Care By Pr...								
Posted: 31-Jul-2018 Tags: 2012 Opel Insignia, Opel Insignia, Opel, Insignia, Used Opel								
	<b>Opel Insignia Diesel 1.6A Turbo</b>	<b>\$89,000</b>	<b>\$9,730 /yr</b>	<b>29-Jul-2016</b>	<b>1,598 cc</b>	<b>40,000 km</b>	<b>Luxury</b>	<b>Available</b>
<b>Fuel Type:</b> Diesel (Euro 5 Engine and Above) Price Negotiable. Loan/Admin Services Provided. Maintained/Serviced By Agent. Left 1 Year Free Servicing With Agent. Still Under Agent Warranty. 1 Owner Only. Still Brand New Condition. Electrical Ret...								
Posted: 24-Jul-2018 Tags: 2016 Opel Insignia, Opel Insignia, Opel, Insignia, Used Opel								
	<b>Opel Insignia Sport Tourer 2.0A</b>	<b>\$158,800</b>	<b>\$14,010 /yr</b>	<b>12-Feb-2018</b>	<b>1,998 cc</b>	<b>6,500 km</b>	<b>Stationwagon</b>	<b>Available</b>
Management Unit, One And Only Opel Sports Tourer For Sale In Market, Great Offer, Save \$30K, Best Deal Available. Adaptive Cruise Control, All Round 360 View Camera, Blind Spot Alert, Lane Departure W...								
Posted: 23-Jul-2018 Tags: 2018 Opel Insignia, Opel Insignia, Opel, Insignia, Used Opel								
	<b>Opel Insignia 2.0A</b>	<b>\$38,000</b>	<b>\$9,930 /yr</b>	<b>28-Sep-2010</b>	<b>1,998 cc</b>	<b>-</b>	<b>Luxury</b>	<b>Available</b>
One And Only Opel Insignia 2.0a Turbo In The Market, Careful Owner, 6 Months Free Servicing By Reputable Workshop With 40 Years Experience In The Market For A Peace Of Mind, Car Look Brand New With No...								
Posted: 12-Jul-2018 Tags: 2010 Opel Insignia, Opel Insignia, Opel, Insignia, Used Opel								

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 ▾ results/page

[Home](#)
[New Cars](#)
[Used Cars](#)
[Sell My Car](#)
[Directory](#)
[Products](#)
[Insurance](#)
[Article](#)
[Forum](#)
[Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Opel Insignia, Opel Insignia Singapore, used Opel Insignia Singapore, used Opel Insignia, used vehicles Singapore or even buy used Opel Insignia Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#)
[Careers](#)
[Contact Us](#)
[Sitemap](#)
[Terms of Service](#)
[Privacy Policy](#)
[Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

[Compare](#)



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	03/08/2018 14:58
Date Of Accident	03/08/2018 09:50
Exact Location Of Accident	WOODLAND AVE 12
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLG4852C
Insured/Policyholder	
Name Of Registered Owner	LIM HIAP SENG
Passport No/FIN	S7249848H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97514351
Alternative Phone No	OFFICE-97514351
Vehicle Particulars	
Manufacturer	OPEL
Model	INSIGNIA-1.6 TURBO (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC17A00449401
Cover Note Number	
Driver	
Name of Driver	LIM HIAP SENG
Passport No/FIN	S7249848H
Date Of Birth	30/10/1972
Occupation	INDOOR
Date Of Driving Pass	07/04/2003
Driving Experience	15 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97514351
Fax Number	
Contact Number	OFFICE-97514351
Email Address	NOEMAIL



Address	416 CANBERRA ROAD
Postcode	750416
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO REPORT ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP6531P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



# Sketch Plan

SKETCH PLAN

Woodlands Ave 12

A B

A: SLG4852C  
B: YP6531P

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 03/08/18, 9.50am while travelling on Woodlands Ave 12, Vehicle B (YP6531P) stopped suddenly which I did not see any brake light I applied brake too but unable to stop in time.

## DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature  
Date & Time

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

Reporting Centre Personnel's Signature  
Name  
NRIC/EPN No.



## Sketch Plan #2

### SKETCH PLAN

#### IMPORTANT NOTICE

- 1 - Please report correctly the details of the accident to speed up the claims process.
- 2 - This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3 - Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 - The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 - Any false reporting may be referred to the Police for investigation.
- 6 - The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 - By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 - **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers", the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me; which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# INSURANCE CERT



## CERTIFICATE OF INSURANCE

Motor Vehicle Third Party Risks Compulsory Act (Chapter 183)  
Motor Vehicle Third Party Risks and Compensation Rules 1993  
Road Traffic Act, 1987 (Chapter 183)  
Motor Vehicle Third Party Risks Rules 1993 (Chapter 183)

OPTEL WORKSHOPS

SEVERE  
COMPREHENSIVE  
ORIGINAL

CERTIFICATE NO: MPTSA001640	Class No: MPTSA001640										
Agency Name: ALLIANCE INSURANCE AGENCY PTE LTD	Policy No: A114200602100007										
Agency Code: A000003											
1. Policy Number and Registered Number of Vehicle: SLG4851C											
2. Name of Policyholder: LIM HUI SHEN											
3. Period of Insurance (both as is subject): 28 September 2017 to 28 September 2018											
4. Principal Class of Permissible Use: <ul style="list-style-type: none"> <li>a. The policyholder and all named drivers declared herein in policy.</li> <li>b. Any other person who is in the car at the time of the accident is covered as with the policyholder.</li> </ul> <p>Provided that the person who is permitted to drive the vehicle with the license of a driver (as per regulations) to drive the motor vehicle has been so permitted and is not disqualified by virtue of a Court of Law or by virtue of any enactment or regulation in that respect from driving the motor vehicle.</p>											
5. Insured Vehicle: <p>Use for service, domestic and pleasure purposes and for the policyholder's business. The policy does not cover the use of the vehicle for racing, motor racing, stunt driving, performance, off-road driving, speedway racing, the carriage of goods or for the purpose of transportation and any other use of the vehicle for any purpose in connection with the above.</p>											
6. PREMIUMS APPLICABLE: <table border="1"> <tr> <td>PREMIUM</td> <td>2017 - 195.00</td> </tr> <tr> <td>SECTION 1 - UNINSURED DRIVER</td> <td>110.00</td> </tr> <tr> <td>SECTION 2 - UNINSURED DRIVER</td> <td>110.00</td> </tr> <tr> <td>SECTION 3 - UNINSURED DRIVER</td> <td>110.00</td> </tr> <tr> <td>SECTION 4 - UNINSURED DRIVER</td> <td>110.00</td> </tr> </table>		PREMIUM	2017 - 195.00	SECTION 1 - UNINSURED DRIVER	110.00	SECTION 2 - UNINSURED DRIVER	110.00	SECTION 3 - UNINSURED DRIVER	110.00	SECTION 4 - UNINSURED DRIVER	110.00
PREMIUM	2017 - 195.00										
SECTION 1 - UNINSURED DRIVER	110.00										
SECTION 2 - UNINSURED DRIVER	110.00										
SECTION 3 - UNINSURED DRIVER	110.00										
SECTION 4 - UNINSURED DRIVER	110.00										
7. Excess/Retention: MAYANK											
<p>Signed and sealed by the Officer in Charge</p>  <p>Chief Executive Officer</p>											

### Important Notice:

1. Policyholder hereby warrants that it shall be entitled to the policy as a result of providing information that is true and correct and that it is valid under the Act.
2. On the sale of a motor vehicle, Policyholder must provide all necessary papers and documents to the Certificate of Insurance and the Policy to the new owner. If the Certificate of Insurance is not provided, the Certificate of Insurance is void and the Policy is void.
3. The Certificate of Insurance and the Policy must be provided to the new owner of the vehicle. If the Certificate of Insurance is not provided, the Certificate of Insurance is void and the Policy is void.
4. The Certificate of Insurance and the Policy must be provided to the new owner of the vehicle. If the Certificate of Insurance is not provided, the Certificate of Insurance is void and the Policy is void.
5. The Certificate of Insurance and the Policy must be provided to the new owner of the vehicle. If the Certificate of Insurance is not provided, the Certificate of Insurance is void and the Policy is void.



---





Driving License





## Repair Estimate



Wir leben Autos.

Date :08/08/2018

Reference: OPEL  
Make: INSIGNIA

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SLG4852C  
CHASSIS NO.: W0LGS5E38G1002042  
ENGINE NO.: A1152036GZJX0082

Name of insured : LIM HIAP SENG  
Date of accident.: 03/08/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

### Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BONNET <i>Distorted</i>	\$ 2,866.00 ✓
2	1	FRT BONNET INSULATOR ?	\$ 483.00 ?
3	10	FRT BONNET INSULATOR CLIP ?	\$ 65.00 ?
4	1	FRT BONNET LOCK <i>Damaged</i>	\$ 220.00 ✓
5	1	FRT BONNET LOCK CABLE ?	\$ 126.00 ?
6	1	FRT BONNET HINGE LH ?	\$ 216.00 ?
7	1	FRT BONNET HINGE RH ?	\$ 216.00 ?
8	1	FRT FENDER RH <i>Repair</i>	\$ 902.00 x
9	1	FRT FENDER BRACKET RH ?	\$ 182.00 +
10	1	FRT FENDER INNERSHIELD RH <i>new</i>	\$ 154.00 +
11	10	FRT FENDER INNERSHIELD CLIP	\$ 65.00 +
12	1	FRT FENDER LH <i>new</i>	\$ 902.00 +
13	1	FRT FENDER BRACKET LH ?	\$ 182.00 +
14	1	FRT FENDER INNERSHIELD LH <i>new</i>	\$ 154.00 +
15	1	FRT BUMPER <i>Distorted</i>	\$ 2,364.00 ✓
16	1	FRT BUMPER TOW COVER <i>new</i>	\$ 156.00 +
17	1	FRT BUMPER LOWER CENTRE GRILLE <i>cracked</i>	\$ 194.00 ✓
18	10	FRT BUMPER CLIP <i>new</i>	\$ 65.00 ✓
19	1	FRT BUMPER TOP CENTRE RETAINER	\$ 172.00 ✓
20	1	FRT BUMPER SIDE RETAINER LH, SUPPORT ?	\$ 134.00 ✓
21	1	FRT BUMPER SIDE RETAINER RH, SUPPORT ?	\$ 134.00 ✓
22	1	FRT BUMPER BRACKET LH, GUIDE ?	\$ 120.00 ?
23	1	FRT BUMPER BRACKET RH, GUIDE ?	\$ 120.00 ?
24	1	FRT BUMPER SPONGE UPP ?	\$ 282.00 ?
25	1	FRT BUMPER REINFORCEMENT, IMPACT BAR UPP <i>Bent</i>	\$ 646.00 ✓
26	1	FRT BUMPER LOW LIP, RH ?	\$ 246.00 +
27	1	FRT BUMPER LOW LIP, LH ?	\$ 246.00 +
28	1	FRT BUMPER FOG LAMP COVER RH ?	\$ 380.00 ?
29	1	FRT BUMPER FOG LAMP RH <i>new</i>	\$ 366.00 +
30	1	FRT BUMPER FOG LAMP COVER LH ?	\$ 380.00 ?
31	1	FRT BUMPER FOG LAMP LH <i>new</i>	\$ 366.00 x



32	2	FRT BUMPER PARKING SENSOR ?		\$	492.00	?
33	2	FRT BUMPER PARKING SENSOR SEAL ?		\$	13.00	?
34	1	FRT BUMPER PARKING SENSOR WIRE HARNESS <i>MAN</i>		\$	256.00	?
35	1	FRT GRILLE ASSY <i>crushed</i>		\$	1,141.00	✓
36	1	RH HEADLAMP <i>3 crushed</i>		\$	1,528.00	✓
37	1	LH HEADLAMP		\$	1,528.00	✓
38	1	FRT SUPORT PANEL TOP CENTRE ?		\$	646.00	?
39	1	A/C CONDENSER <i>Best</i>		\$	1,498.00	✓
40	1	A/C CONDENSER TOP AIR GUIDE ?		\$	130.00	?
41	1	A/C CONDENSER AIR GUIDE RH ?		\$	102.00	?
42	1	A/C CONDENSER AIR GUIDE LH ?		\$	154.00	?
43	1	A/C PIPE (condenser to compressor) ?		\$	675.00	?
44	1	A/C PIPE (cooling coil to condenser) ?		\$	504.00	?
45	1	TURBO INTAKECOOLER ?		\$	1,047.00	?
46	1	AIR HOSE(intakecooler to throttle body) ?		\$	669.00	?
47	1	AIR HOSE(turbo to intakecooler) ?		\$	555.00	?
48	1	FRT INTAKE AIR DUCT(to resonator box) <i>del</i>		\$	415.00	✓
49	1	FRT INTAKE RESONATOR BOX ?		\$	373.00	?
50	1	RADIATOR <i>Best</i>		\$	1,495.00	✓
51	1	RADIATOR TOP MOUNTING, INSULATOR ?		\$	16.00	?
52	1	RADIATOR TOP BRACKET ?		\$	10.00	?
53	1	RADIATOR LOW BRACKET ?		\$	34.00	?
54	1	RADIATOR TOP HOSE, INLET ?		\$	214.00	?
55	1	RADIATOR LOW HOSE, OUTLET ?		\$	254.00	?
56	1	RADIATOR FAN ASSY - RH ?		\$	912.00	?
57	1	RADIATOR FAN ASSY - LH ?		\$	912.00	?
58	1	RADIATOR FAN COWLING ?		\$	835.00	?

Parts Total: \$ 29,512.00  
Less 10%: \$ 2,951.20  
Total : \$ 26,560.80

### Labour

No.	Labour Description	Price (SGD)	
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ <del>3,900.00</del>	2600
2	Carry out spray painting on affected area, FRT BUMPER, FRT BONNET, FRT FENDER RH, FRT FENDER LH, FRT SUPORT PANEL, FRT DOOR RH, FRT DOOR LH	\$ <del>3,850.00</del>	2475
3	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ <del>280.00</del>	120
4	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 600.00	✓
5	To remove and refix radiator and conduct pressure test	\$ <del>220.00</del>	80
6	To conduct chasis alignment of vehicle	\$ 1,300.00	X
7	To conduct reset of engine light on	\$ 350.00	X



Labour Total : \$ 10,500.00

Others

Other Description

<u>No.</u>			<u>Price (SGD)</u>	
<u>1</u>		FRT NUMBER PLATE <i>included.</i>	\$	65.00 ✓
<u>2</u>		RADIATOR COOLANT <i>Nec</i>	\$	80.00 ✓
<u>3</u>		A.T.F <i>Nec</i>	\$	60.00 ✓

Other Total: 205.00

TOTAL: 37,265.80

GST ( 7%): 2,608.61

GRAND TOTAL : 39,874.41

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

\_\_\_\_\_  
Service Advisor

*Adrian King*  
*P/P 13/08/18*

*07 Days*  
*Not Authorised*  
*Excess \$500.*



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Aug 2018 16:00 <a href="#">Edit Reg</a>		13 Aug 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$19,040.00</b> <a href="#">Edit Estimates</a>	<b>S\$19,040.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>LIM HIAP SENG</b> , ID: S7249848H, Email: YNKNOW@EMAIL.COM									
Vehicle Reg. No.: <b>SLG4852C</b>		Date of Loss: 03/08/2018 09:00 - :59 [22 Months and 4 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>OD / DMPC1800321H</b>		Policy/Cover Note No.: MPC17A00449401 (Comprehensive)							
		Excess: S\$500.00							
Repairer: <b>1st Autoworks Pte Ltd (HQ)</b> 23 Kaki Bukit Ave 4, #04-01, 415933 Kaki Bukit - Tel: 68441985									
Handling Insurer: <b>ECICS Limited (HQ)</b> - Tel: 63374779 /6303 0178 ... [Handled by <b>Janice Goh</b> - 6303 0182]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... <b>[Final Rpt due 23/08/2018]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>ECICS (21/08/2018): <b>Alert - Adj Mandate Approved (S\$21900.00) - SLG4852C</b></li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*SLG4852C (DMPC1800321H)  
 OD  
 Aug 3 2018 9:00AM  
 [LIM HIAP SENG]  
 1st Autoworks Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

**View** View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/08/18 17:21	Adjuster Immediate Advice	1	Load HTM	
2	15/08/18 12:02	Adjuster Immediate Advice	1	Load HTM	


  

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
29	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
32	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	13/08/18 17:22	General View	1	Load JPG	<input checked="" type="checkbox"/>

Documentation			



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ECICS Limited (HQ)	Thumbnail	Print
1	21/08/18 15:22	Singapore Accident Statement	 Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited  
10 Eunus Road 8, #09-04A Singapore Post Centre  
Singapore 408600

Our File No: CS/ICS18014589/AQD3E2

Date: 25/03/2019

## REFERENCE

Insured/Claimant: LIM HIAP SENG Policy No: MPC17A00449401  
Date of Loss: 03/08/2018 Nature of Claim: OD Claim No: DMPC1800321H

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SLG4852C**  
Make & Model: OPEL INSIGNIA, 1.6 Turbo (A) Engine No: A1152036GZJX0082  
Reg. Date: 30/09/2016 (Man. Year: 2016) Chassis No: W0LGS5E38G1002042  
Colour: Black Odometer: 64299 km  
Engine Capacity: 1598 cc  
Market Value/New Car Price: S\$87,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 245/45 R18 Rear Tyre Size: 245/45 R18  
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,765.80	13,165.00	13,600.80	50.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,500.00	5,875.00	4,625.00	44.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>37,265.80</b>	<b>19,040.00</b>	<b>18,225.80</b>	<b>48.91</b>
<b>- Excess (S\$)</b>	<b>500.00</b>	<b>500.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>36,765.80</b>	<b>18,540.00</b>	<b>18,225.80</b>	<b>49.57</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,573.61</b>	<b>1,297.80</b>	<b>1,275.81</b>	<b>49.57</b>
<b>Nett Amount (S\$)</b>	<b>39,339.41</b>	<b>19,837.80</b>	<b>19,501.61</b>	<b>49.57</b>

## INSPECTION

Date of Assignment: 13/08/2018  
Date Inspected: 13/08/2018 Inspected At: 1st Autoworks Pte Ltd (HQ)  
23 Kaki Bukit Ave 4, #04-01  
Singapore 415933  
Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN



*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$9,841.50 NETT)



## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 25 Mar 2019)
<b>Parts:</b> 143	OPEL INSIGNIA 1.6 Turbo (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLG4852C)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET	Distorted	2,866.00 FL	*2,866.00 FL
2	1		*FRT BONNET INSULATOR	* Check	483.00 FL	*- FL
3	10		*FRT BONNET INSULATOR CLIP	* Check	65.00 FL	*- FL
4	1		*FRT BONNET LOCK	Damaged	220.00 FL	*220.00 FL
5	1		*FRT BONNET LOCK CABLE	* Check	126.00 FL	*- FL
6	1		*FRT BONNET HINGE LH	* Check	216.00 FL	*- FL
7	1		*FRT BONNET HINGE RH	* Check	216.00 FL	*- FL
8	1		*FRT FENDER RH	Repair	902.00 FL	*- FL
9	1		*FRT FENDER BRACKET RH	Not Necessary	182.00 FL	*- FL
10	1		*FRT FENDER INNERSHIELD RH	Not Necessary	154.00 FL	*- FL
11	10		*FRT FENDER INNERSHIELD CLIP	Not Necessary	65.00 FL	*- FL
12	1		*FRT FENDER LH	Not Necessary	902.00 FL	*- FL
13	1		*FRT FENDER BRACKET LH	Not Necessary	182.00 FL	*- FL
14	1		*FRT FENDER INNERSHIELD LH	Not Necessary	154.00 FL	*- FL
15	1		*FRT BUMPER	Distorted	2,364.00 FL	*2,364.00 FL
16	1		*FRT BUMPER TOW COVER	Not Necessary	156.00 FL	*- FL
17	1		*FRT BUMPER LOWER CENTRE GRILLE	Cracked	194.00 FL	*194.00 FL
18	10		*FRT BUMPER CLIP	Necessary	65.00 FL	*65.00 FL
19	1		*FRT BUMPER TOP CENTRE RETAINER	Necessary	172.00 FL	*172.00 FL
20	1		*FRT BUMPER SIDE RETAINER LH, SUPPORT	Necessary	134.00 FL	*134.00 FL
21	1		*FRT BUMPER SIDE RETAINER RH, SUPPORT	Necessary	134.00 FL	*134.00 FL
22	1		*FRT BUMPER BRACKET LH, GUIDE	* Check	120.00 FL	*- FL
23	1		*FRT BUMPER BRACKET RH, GUIDE	* Check	120.00 FL	*- FL
24	1		*FRT BUMPER SPONGE UPP	* Check	282.00 FL	*- FL
25	1		*FRT BUMPER REINFORCEMENT, IMPACT BAR UPP	Bent	646.00 FL	*646.00 FL
26	1		*FRT BUMPER LOW LIP, RH	Not Necessary	246.00 FL	*- FL
27	1		*FRT BUMPER LOW LIP, LH	Not Necessary	246.00 FL	*- FL
28	1		*FRT BUMPER FOG LAMP COVER RH	* Check	380.00 FL	*- FL
29	1		*FRT BUMPER FOG LAMP RH	Not Necessary	366.00 FL	*- FL
30	1		*FRT BUMPER FOG LAMP COVER LH	* Check	380.00 FL	*- FL
31	1		*FRT BUMPER FOG LAMP LH	Not Necessary	366.00 FL	*- FL
32	2		*FRT BUMPER PARKING SENSOR	* Check	492.00 FL	*- FL
33	2		*FRT BUMPER PARKING SENSOR SEAL	* Check	13.00 FL	*- FL
34	1		*FRT BUMPER PARKING SENSOR WIRE HARNESS	Not Necessary	256.00 FL	*- FL
35	1		*FRT GRILLE ASSY	Cracked	1,141.00 FL	*1,141.00 FL
36	1		*RH HEADLAMP	Cracked	1,528.00 FL	*1,528.00 FL
37	1		*LH HEADLAMP	Cracked	1,528.00 FL	*1,528.00 FL
38	1		*FRT SUPPORT PANEL TOP CENTRE	* Check	646.00 FL	*- FL
39	1		*A/C CONDENSER	Bent	1,498.00 FL	*1,498.00 FL

Report was unsubmitted during this print-out.



No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*A/C CONDENSER TOP AIR GUIDE	* Check	130.00 FL	*- FL
41	1		*A/C CONDENSER AIR GUIDE RH	* Check	102.00 FL	*- FL
42	1		*A/C CONDENSER AIR GUIDE LH	* Check	154.00 FL	*- FL
43	1		*A/C PIPE (CONDENSER TO COMPRESSOR)	* Check	675.00 FL	*- FL
44	1		*A/C PIPE (COOLING COIL TO CONDENSER)	* Check	504.00 FL	*- FL
45	1		*TURBO INTAKECOOLER	* Check	1,047.00 FL	*- FL
46	1		*AIR HOSE (INTAKECOOLER TO THROTTLE BODY)	* Check	669.00 FL	*- FL
47	1		*AIR HOSE (TURBO TO INTAKECOOLER)	* Check	555.00 FL	*- FL
48	1		*FRT INTAKE AIR DUCT (TO RESONATOR BOX)	Deformed	415.00 FL	*415.00 FL
49	1		*FRT INTAKE RESONATOR BOX	* Check	373.00 FL	*- FL
50	1		*RADIATOR	Bent	1,495.00 FL	*1,495.00 FL
51	1		*RADIATOR TOP MOUNTING, INSULATOR	* Check	16.00 FL	*- FL
52	1		*RADIATOR TOP BRACKET	* Check	10.00 FL	*- FL
53	1		*RADIATOR LOW BRACKET	* Check	34.00 FL	*- FL
54	1		*RADIATOR TOP HOSE,INLET	* Check	214.00 FL	*- FL
55	1		*RADIATOR LOW HOSE, OUTLET	* Check	254.00 FL	*- FL
56	1		*RADIATOR FAN ASSY - RH	* Check	912.00 FL	*- FL
57	1		*RADIATOR FAN ASSY - LH	* Check	912.00 FL	*- FL
58	1		*RADIATOR FAN COWLING	* Check	835.00 FL	*- FL
59	1		*FRT NUMBER PLATE	Cracked	65.00 FS	*65.00 FS
60	1		*RADIATOR COOLANT	Necessary	80.00 FS	*80.00 FS
61	1		*A.T.F	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **29,717.00**    **14,605.00**  
 - List Item Discount on L Items 10.00/10.00% (S\$)    2,951.20    1,440.00

Total Parts (S\$) **26,765.80**    **13,165.00**

Report was unsubmitted during this print-out.
---



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	3,900.00	2,600.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA, FRT BUMPER, FRT BONNET, FRT FENDER RH, FRT FENDER LH, FRT SUPORT PANEL, FRT DOOR RH, FRT DOOR LH	New	3,850.00	2,475.00
3	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	280.00	120.00
4	TO REMOVE AND REFIT AIRCON CONDENSOR, VACUUM, REFILL AND CHECK AIR CON GAS SYSTEM	New	600.00	600.00
5	TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	220.00	80.00
6	TO CONDUCT CHASIS ALIGNMENT OF VEHICLE	New	1,300.00	0.00
7	TO CONDUCT RESET OF ENGINE LIGHT ON	New	350.00	0.00
Gross Labour Cost (\$\$)			10,500.00	5,875.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >