

FINALIZATION		Date/Time:	Confirm with:	Confirm by:
Repair Cost:	\$5	days) Reduction:	%	Email ☐ Call ☐
FINAL SETTLEMENT		Date/Time: 2/13/11	Confirm with: Yushuy	Email ☒ Call ☐
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.: 73		If NO or B 28, Ass. Lia:
Repair Cost:	\$5 2300.00			
Loss of Rental (LOR):	\$5 500.00	(5 days)	X 1W	
Loss of Use (LOU):	\$5 =	(5 x days)		
Loss of Income (LOI):	\$5 =	(5 x days)		
LOR only ☐ LOU only ☐	LOR + LOU ☐	LOR + LO ☐	(Tick only one)	
GIA/LTA Search	\$5 7.45			
Medical:	\$5 =			
Disbursement:	\$5 =	(e.g. Tow/Independent)		
Legal Cost	\$5 =			
Total:	\$5 2807.45	Global Sum \$5:		
FINAL PAYMENT		Date/Time:	Confirm with:	Email ☒ Call ☐
Payee 1:	\$5 2807.45	Name 1:	Platinum Werkz Pte Ltd	
Payee 2: (Strike if N.A.)	\$5	Name 2:		
Payee 3: (Strike if N.A.)	\$5	Name 3:		

REF:

REQ. REQ. BY: Adrian King

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lump Sum:

2

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJ86323A.

Yr Regn: 2008 / Jan.

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mit Lances

C.C. 1584

Colour:

Yellow

A/C: Insured / Std / NI / NA

Sp. Reading

342574

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JMYSNCS3A84002665

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ STD A/Rim or

Tyre Size:

F: 215/40R17.

R: 215/40R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front:

Rear:

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A

D.O.I.

13/08/18.

Survey held at

Platinum.

Des. of Damages: Frt / ☒ Lea / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TR 111

COE Expiry: 17/01/08.

2/5 # 23w (Cool \$ 5678.10/ 717.2

MV: 53K
 PV: 40.5K
 Nett: 12.5K

Date/Time, File Pass to?

☐

Prel. Report

if

☐

Final Report

Date/Time, File Return to?

if

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

B + RD. \$

Photo:

Other:

TOTAL

Report Format:

Lump Sum / U.C. /



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18014593/Aub3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 13-08-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7852U	Veh. Inspected	SJB 6323A	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	13/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	09/08/2018	Inspection Date	13/08/2018	
Survey held at	PLATINUM WERKZ PTE. LTD. 53 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

PLATINUM WERKZ PTE LTD

Look Auto Consultants notice hereby

the Repair 53, UBI AVENUE 1, #01-25, PAYA UBI INDUSTRIAL PARK, SINGAPORE 408934

Contact: +65 6741 0610

Email: platinumwerkz@gmail.com FAX: 67410892

To resurvey before/after spray painting

To display (to repair parts) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "No Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and

subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Particular

Qty

Amount (\$)

Vehicle:

SJB 6323A

Make & Model: MITSUBISHI LANCER

Acknowledged by Repairer

No	Particular	Qty	Amount (\$)
	<u>List Price</u>		
1	REAR BOOT LID <i>Repair</i>	1PC	595.00
2	REAR BOOT LOGO <i>new</i>	1PC	42.00
3	REAR BOOT EMBLEM 'LANCER' <i>new</i>	1PC	35.00
4	REAR BOOT LICENCE PLATE GARNISH <i>new</i>	1PC	197.00
5	REAR BOOT INNER LOCK <i>2</i>	1PC	135.00
6	REAR BOOT LOCK STRICKER <i>new</i>	1PC	45.00
7	REAR BOOT WEATHERSTRIP <i>new</i>	1PC	146.00
8	REAR BOOT HINGE @ \$ 98.00 <i>1718</i>	2PCS	196.00
9	REAR TAILALMP @\$424.00 <i>Cracked.</i>	2PCS	848.00 668
10	REAR TAILALMP PANEL @\$165.00 <i>Repair</i>	2PCS	330.00
11	REAR BUMPER <i>Deland</i>	1PC	743.00
12	REAR BUMPER SIDE RETAINER @ \$48.00 <i>new</i>	2PCS	96.00
13	REAR END PANEL <i>Repair</i>	1PC	485.00
14	REAR END PANEL GARNISH <i>Deland</i>	1PC	169.00
15	REAR SAPER TYRE TANK <i>new</i>	1PC	910.00
	Total		4,972.00
	Less 20% (10%)		(994.40)
	Sub-Total cost for parts		3,977.60
	<u>Part Replacement - Special</u>		
	<u>Nett Item</u>		
1	REAR END PANEL GARNISH CLIP <i>new</i>	1 SET	22.50
2	REAR TAILLAMP CLIP @ \$12.50 <i>new</i>	2PCS	25.00
3	REAR TAILLAMP CLIP HOLDER @ \$11.50 <i>new</i>	2PCS	23.00
4	REAR REVERSE SENSOR <i>Damaged</i>	1 SET	280.00
5	REAR BUMPER LOWER SPOILER <i>Repair</i>	1PC	760.00
	Sub-Total cost for parts		1,110.50
	<u>Labour & MISC Charges</u>		
1	TO CHECK UP REAR ELECTRICAL WIRING & TEST FOR ANY LEAKAGE <i>1130</i>		80.00
2	TO REMOVE & REFIX REVERSE SENSOR		80.00
3	TO REMOVE & REFIX REAR INTERIOR TRIM TO ASSIT REAPIR		150.00
4	TO RESPRAY UNDERCOATING <i>total 2906.20</i>		180.00
5	TO RESPRAY & etc		1,200.00
6	PANEL BEATING, REMOVE & REPLACING ABOVE PARTS <i>2.3K</i>		1,200.00
	Sub-Total Labour		2,890.00

TP 111

Thin Thin

1718

1546.20

230

total 2906.20

2.3K

042m

2988.10

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8695G
Vehicle Details	
Vehicle No.:	SJB6323A
Vehicle to be Exported:	Yes
Intended De-registration Date:	13 Aug 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 M
Primary Colour:	Black
Manufacturing Year:	2007
Engine No.:	4G18JN0791
Chassis No.:	JMYSNCS3A8U002665
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$11,257.00
Original Registration Date:	18 Jan 2008
First Registration Date:	18 Jan 2008
Transfer Count:	2
Actual ARF Paid:	\$12,383.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	17 Jan 2028
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$42,970.00
COE Rebate Amount:	\$40,509.00
Total Rebate Amount:	\$40,509.00

The information contained herein is correct as at 13 Aug 2018

OK

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	13 Aug 2018 13:57	Cim Veh Model Changed	(202021) ADIVA AD200A 200cc (M).	[A] Lau Shu Pei
2	13 Aug 2018 13:57	Cim Created	Reg No: SJB6323A, Acct Date: 2018/08/09, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), Workshop: Platinum Werkz Pte Ltd (HQ)	[A] Lau Shu Pei
3	13 Aug 2018 13:57	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
4	13 Aug 2018 13:57	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/08/23	[A] Lau Shu Pei
5	13 Aug 2018 13:57	Adj Mandate Set	Approved:0.00,Reinsp:Adj decides.	[A] Lau Shu Pei
6	13 Aug 2018 13:58	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pei
7	13 Aug 2018 13:58	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] Lau Shu Pei
8	14 Aug 2018 14:39	Cim Veh Model Changed	(202021) -> (204472) MITSUBISHI LANCER 1.6 EX GLX GAS (M).	[A] Lau Shu Pei
9	13 Sep 2018 11:20	Adj Mandate Request	Cur.Req:0.00:PODS - Express Settlements Dear Sir / Madam, We advise liability as follows for Direct Settlement: Liability : 100% Remarks : BOLA - 27 (OI rear-ended to T P)	[A] THIN HLAING
10	13 Sep 2018 17:07	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/08/23	[I] Zuhaidah Bte Samsuri
11	13 Sep 2018 17:07	Adj Mandate Set	Approved:0.00.	[I] Zuhaidah Bte Samsuri
12	11 Feb 2019 09:24	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
13	11 Feb 2019 09:24	Cim Dtl Modified	Insured Name: -> -.	[A] JOANNE LEE KHANG MIN
14	11 Feb 2019 09:24	Cim Dtl Modified	Claimant's Name: -> -. Claimant's ID: -> -.	[A] JOANNE LEE KHANG MIN
15	11 Feb 2019 09:24	Cim Dtl Modified	JPJ Reg. Date: -> 2008/01/18.	[A] JOANNE LEE KHANG MIN
16	11 Feb 2019 09:24	Cim Details Notified		[A] JOANNE LEE KHANG MIN
17	10 Mar 2019 12:04	Adj Mandate Request	Cur.Req:2807.45:PODS Liability: 100% Quantum: (a)COR: \$2,300.00 + (b)LOR(5days x \$100.00): \$500.00 + (c)LTA/GIA search fee: \$7.45 = Total: \$2,807.45 Vehicle Model: Mitsubishi Lancer (1584cc) 4 recommendation repair days +1PRS = 5days For your ap	[A] CHEW HSIAO TONG

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2051764	11/02/2019 09:24	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SJB6323A	SH7852U	10.70

Print Received Message

This mail is associated with :

***SJB6323A (MCT18080301)**
[SH7852U]
TP
RAHIMAN BIN RAHIM
Aug 9 2018 12:00AM
[-]
Platinum Werkz Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 11/03/2019 11:55 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2807.45) - SJB6323A - Claim Handler: Sherini Pillai

Approved:2807.45.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 29 March 2019 9:20 AM
To: platinumwerkz@gmail.com
Subject: Your Ref: SJB6323A *Our Ref: CC4/III18014593/Apb3 [ACCIDENT INVOLVING SH 7852U(III) AND SJB 6323A ON 09/08/2018]
Attachments: DV_SJB6323A.pdf

Your Ref: **SJB6323A** Without Prejudice
Our Ref: CC4/III18014593/Apb3

Dear Sirs/Mdm,

ACCIDENT INVOLVING SH 7852U(III) AND SJB 6323A ON 09/08/2018

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair	\$ 2,300.00
2. Loss of Rental (5days x \$100.00)	\$ 500.00
3. LTA/ GIA Search Fee	\$ 7.45
TOTAL	\$ 2,807.45

If our offer is acceptable by your client, please duly sign the **document** enclosed and return the original copy to us(LKK) for our necessary action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Our Ref SJB6323A

LETTER OF DEMAND

Your Ref SH7852U

Date 29-Nov-2018

FAX: 67410892

LKK AUTO CONSULTANTS PTE LTD
51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park
Singapore 408933

Attn: Motor Claims Department

Dear Sir / Madam ,

**ACCIDENT INVOLVING SJB6323A AND SH7852U ON 09 AUGUST 18
ALONG ROCHOR RD BESIDE OG BULIDING**

We act for owner of motor vehicle no.SJB6323A ,who was involver in the above accident.
Our client has suffered loss and damage as a result of your insured's negligence in the driving of
motor vehicle no. SH7852U

We quantify our client's claim as follow

Cost of Repair	\$ 2,300.00
Loss of Rental for 05 Days	\$ 600.00
LTA SEARCH	\$ 7.45
Total	<u>\$ 2,907.45</u>

Yours Truly ,



PLATINUM WERKZ PTE LTD
MAX OH
97659745

PLATINUM WERKZ
UEN 2017351680
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park, S(408934)
Tel: 6741 0810
E: platinumwerkz@gmail.com

LETTER OF AUTHORITY TO PLATINUM WERKZ

CLAIMANT: Rahiman Bin Rahim

ACCIDENT INVOLVING STB 6323A AND SH7852U ON 09.08.18
AT Rochor Rd Beade OG Building

1. I hereby irrevocably appoint PLATINUM WERKZ to be my workshop in respect of my claim.

2. My workshop is authorized to conduct the following:

(a) To receive and keep records of all correspondences including Letter of Demand between my lawyers and 3rd party insurers pertaining to the conduct of my workshop until my claim is settled. I will liaise with my workshop and/or contact my lawyers directly if I require to have sight and/or record of any of the correspondences.

(b) To give instructions to commence legal proceedings in court in my name against the third-party driver and/or his employers, if applicable.

(c) My said agent also has my authority to decide on my behalf whether to accept any offer of settlement from the third party and/or his insurers.

3. I understand and accept that until I revoke my said workshop's authority in writing to you, I am bound by all instructions given by my said workshop to you.



SIGNATURE
NAME OF AUTHORISED SIGNATORY

13/08/18

DATE

COMPANY STAMP

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT18080301
Claimant Ref: SJB6323A

We/I, Platinum Werkz Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 2,300.00 (repair cost), S\$ 500.00 (loss of ~~use~~/rental), S\$ 7.45 (search fee), vehicle no. SJB 6323A that was damaged pursuant to the accident which occurred on 09/08/2018 (date) at Rochor Rd Beside OG Building (location) involving vehicle no. SH 7852U (insured vehicle). This is pursuant to the inspection conducted on 13/08/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner RAHIMAN BIN RAHIM ("the third party claimant") of vehicle no. SJB 6323A to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SJB 6323A (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 2,807.45 to Platinum Werkz Pte Ltd.

Dated this 29 day of March 2019

CLAIMANT:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:


Signed by "the workshop" (with chop)



WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:



Signed by appointed Surveyor

LKK Auto Consultants Pte Ltd

199607198R

51 Ubi Avenue 1

#01-25 Paya Ubi Ind. Park S(408933)

Date 29-Nov-2018

Our Ref: SJB6323A

53 Ubi Avenue 1,
#01-25 , Paya Ubi Industrial Park ,
Singapore 408934.

THE MOTOR CLAIMS DEPARTMENT

OMIA INTERNATIONAL INSURANCE PTE LTD
84 CECIL STREET #03-02
IOB BUILDING
SINGAPORE 0108

FINAL BILL FOR VEHICLE NO: SJB6323A

MODEL:MITSUBISHI LANCER EX

LUMP SUM REPAIR \$ 2,300.00

INCLUDING SUPPLY OF PART & LABOUR ,
PANEL BEATING & SPRAY PAINTING

GRAND TOTAL \$ 2,300.00

PATINUM WERKZ PTE LTD



MAX OH
97659745

PLATINUM WERKZ
SINCE 2017 SINGAPORE
53 Ubi Ave 1, #01-25
Paya Ubi Industrial Park, Singapore 408934
Tel: 8741 8618
E: platinumwerkz.sg@gmail.com



WIN WIN RENT-A-CAR PTE LTD

Invoice

RAHIMAN BIN RAHIM
BLK 704 WEST COAST RD
#03-429
S(120704)

Invoice No : WPLIN0002212
Invoice Date : 16/8/2018
Due Date : 16/8/2018
VHA No : 2575
Referral ID : P024

Description :	Amount
Rental for 5 Day/s @ \$120 per Day	\$600

Vehicle No : SKD 9039 D

Vehicle Description : Mitsubishi Lancer 1.5 EX

Rental Period : 10/08/2018 to 15/08/2018

Total Amount Payable : \$600

WIN WIN RENT-A-CAR PTE LTD

8 Kaki Bukit Ave 4 #06-04 Premier@Kaki Bukit Singapore 415875
Tel: 6315 8479 H/P: 9833 0807


VHA No: 2575

Invoice No: WPLIN 001

Hirer's Vehicle No:

UEN: 201505115E

VEHICLE RENTAL AGREEMENT

HIRER'S PARTICULARS		Vehicle No: 201505115E		Replace Veh No:	
Name: (as in I/C) RAHMAN BIN RAHMAN		Mileage Out: 21155		Mileage Out:	
NRIC / FIN No: S9018695 C		Make & Model: HILUX 2.0 4X4		Auto / Manual	
Address (Res): 103-429 2 (120704)		Out : Date: 15/11/2018		Time: 11:33	
Name & Address of Employer:		HIRE / PERIOD EXPIRY: 2000		Time:	
Occupation: Driving Exp:		NON-WAIVER EXCESS=\$			
Singapore Driving Licence No:		CHARGES			
Issue Date: Date of Birth: 19/5/1980		Daily 5 @ \$ 120 per day 11600 -			
Tel: (O) (R) HP :		Weekly @ \$ per week			
ADDITIONAL DRIVER'S PARTICULARS		Monthly @ \$ per month			
Name: (as in I/C)		Hours @ \$ per hour			
NRIC / FIN No:		Extension @ \$			
Address (Res):		Delivery/Collection Service			
Occupation: Driving Exp:		SUB-TOTAL \$			
Singapore Driving Licence No:		PETROL LEVEL			
Issue Date: Date of Birth:		Out E 1/8 1/4 3/8 1/2 5/8 3/4 7/8 F			
Tel: (O) (R) H/P:		In E 1/8 1/4 3/8 1/2 5/8 3/4 7/8 F			
VEHICLE CHECK LIST		Fuel			
INDICATE: D - DENTS A - ACCIDENTS S - SCRATCHES		Traffic / Parking Fines			
		TOTAL CHARGES \$			
MISSING / FAULTY ACCESSORIES / PARTS		Hirer's Signature 			
REMARKS:		Additional Driver's Signature			

I have read and agree to the terms and condition on both sides of the agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given WIN WIN RENT-A-CAR PTE LTD in connection with this agreement is true.

*IMPORTANT

1. VEHICLE IS STRICTLY PROHIBITED FOR "HIRE FOR REWARDS" USAGE SUCH AS UBER / GRABCAR / GRABSHARE ETC.
2. ONLY PERSON ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORIZED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
3. ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
4. THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
5. IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
6. VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY WIN WIN RENT-A-CAR PTE LTD.

RETURN OF VEHICLE. THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO WIN WIN RENT-A-CAR PTE LTD AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	SIGNATURE OF HIRER/DRIVER
15/11	11:35	202312			

Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 10 Aug 2018 / 12:00:10

Receipt Date/Time : 10 Aug 2018 / 12:00:10

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180810-000861

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	Result of Insurance Enquiry - SH7852U As at 09 Aug 2018/15:10:00 Insurance Co: INDIA INT'L INS PTE LTD			
1	Insurance Enquiry - SH7852U Enquiry Fee 20180810115903401461	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	20180810115918619 Direct Debit: eNETS Debit (Internet Banking)			7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Aug 2018 Edit Reg		10 Aug 2018 00:00 Edit Adj Rpt	S\$2,300.00 Edit Estimates	S\$2,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: -								
Main Claimant:	RAHIMAN BIN RAHIM , ID: S901869SG								
Vehicle Reg. No.:	SJB6323A	Date of Loss:	09/08/2018 00:00 - :59 [126 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18080301	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SH7852U	Policy No. (Claimant):	5097157942						
		Excess:							
Repairer:	Platinum Werkz Pte Ltd (HQ) 53 Ubi Ave 1 01-25 Paya Ubi Industrial Park, 408934 Ubi - Tel: 6741 610								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 23/08/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (11/03/2019): Alert - Adj Mandate Approved (S\$2807.45) - SJB6323A - Claim Handler: Sherini Pillai - III_SG (13/09/2018): Alert - Adj Mandate Approved (S\$0.00) - SJB6323A - Claim Handler: Sherini Pillai									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJB6323A (MCT18080301)
[SH7852U]
TP
RAHIMAN BIN RAHIM
Aug 9 2018 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Platinum Werkz Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View View in Browser	
Photos/Images							3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print
1	29/11/18 16:59	General View					 Load JPG	☒
2	29/11/18 16:59	General View					 Load JPG	☒
3	29/11/18 16:59	General View					 Load JPG	☒
4	29/11/18 16:59	General View					 Load JPG	☒
5	29/11/18 16:59	General View					 Load JPG	☒
6	29/11/18 16:59	General View					 Load JPG	☒
7	29/11/18 16:59	General View					 Load JPG	☒
8	29/11/18 16:59	General View					 Load JPG	☒
9	29/11/18 16:59	General View					 Load JPG	☒
10	29/11/18 16:59	General View					 Load JPG	☒
11	29/11/18 16:59	General View					 Load JPG	☒
12	29/11/18 16:59	General View					 Load JPG	☒
13	29/11/18 16:59	General View					 Load JPG	☒
14	29/11/18 16:59	General View					 Load JPG	☒
15	29/11/18 16:59	General View					 Load JPG	☒
16	29/11/18 16:59	Reinspection Photo					 Load JPG	☒
17	29/11/18 16:59	Reinspection Photo					 Load JPG	☒
18	29/11/18 16:59	Reinspection Photo					 Load JPG	☒
19	29/11/18 16:59	Reinspection Photo					 Load JPG	☒
20	29/11/18 16:59	Reinspection Photo					 Load JPG	☒
21	29/11/18 16:59	Reinspection Photo					 Load JPG	☒
22	29/11/18 16:59	Reinspection Photo					 Load JPG	☒
23	29/11/18 16:59	Reinspection Photo					 Load JPG	☒
24	29/11/18 16:59	Reinspection Photo					 Load JPG	☒
25	29/11/18 16:59	Reinspection Photo					 Load JPG	☒
26	29/11/18 16:59	Reinspection Photo					 Load JPG	☒
27	29/11/18 16:59	Reinspection Photo					 Load JPG	☒
28	29/11/18 16:59	Reinspection Photo					 Load JPG	☒
29	29/11/18 16:59	Reinspection Photo					 Load JPG	☒
30	29/11/18 16:59	Reinspection Photo					 Load JPG	☒
31	29/11/18 16:59	Reinspection Photo					 Load JPG	☒
32	29/11/18 16:59	Reinspection Photo					 Load JPG	☒
33	29/11/18 16:59	Reinspection Photo					 Load JPG	☒
34	29/11/18 16:59	Reinspection Photo					 Load JPG	☒
35	29/11/18 16:59	Reinspection Photo					 Load JPG	☒
36	29/11/18 16:59	Reinspection Photo					Load JPG	☒
37	29/11/18 16:59	Reinspection Photo					Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	29/11/18 16:59	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/08/18 13:58	EMAIL FROM III DD 13082018	 Load PDF	
2	13/08/18 13:58	WKSP NOTICE	 Load PDF	
3	07/02/19 13:17	TP ESTIMATE_MARKED	 Load PDF	
4	11/02/19 09:31	RENTAL RECEIPT	 Load PDF	
5	11/02/19 09:31	LTA SEARCH	 Load PDF	
6	11/02/19 09:31	LOD	 Load PDF	
7	09/04/19 14:41	WORKSHOP INVOICE	 Load PDF	
8	09/04/19 14:41	AUTHORISATION TO ACT FORM	 Load PDF	
9	09/04/19 14:41	DISCHARGE VOUCHER	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	14/08/18 08:47	Singapore Accident Statement	 Load PDF	
2	12/12/18 10:32	Letter of Demand from Third Party PLATINUM WERKZ	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18014593/APB3Q2

Date: 09/04/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle
No : SJB6323A

Insured Vehicle No : SH7852U

Date of Loss: 09/08/2018

Nature of Claim:

TP

Claim No: MCT18080301

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJB6323A

Make & Model: MITSUBISHI LANCER, 1.6 EX GLX GAS (M)

Engine No: 4G18JN0791

Reg. Date: 18/01/2008 (Man. Year: 2007)

Chassis No: JMYSNCS3A8U002665

Colour: Yellow

Odometer: 342574 km

Engine Capacity: 1584 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/40 R17

Rear Tyre Size: 215/40 R17

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,585.30	1,776.20	3,809.10	68.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,890.00	1,130.00	1,760.00	60.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,475.30	2,906.20	5,569.10	65.71
Approved Total (Overridden) (S\$)		2,300.00		
Nett Amount (S\$)	8,475.30	2,300.00	6,175.30	72.86
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,807.45		

INSPECTION

Date of Assignment: 10/08/2018

Date Inspected: 13/08/2018 Inspected At:

Platinum Werkz Pte Ltd (HQ)

53 Ubi Ave 1 01-25 Paya Ubi Industrial Park

Singapore 408934

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Feb 2019)
Parts:	143	MITSUBISHI LANCER 1.6 EX GLX GAS (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJB6323A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	595.00 FL	*- FL
2	1		*REAR BOOT LOGO	Necessary	42.00 FL	*42.00 FL
3	1		*REAR BOOT EMBLEM LANCER	Not Necessary	35.00 FL	*- FL
4	1		*REAR BOOT LICENCE PLATE GARNISH	Not Necessary	197.00 FL	*- FL
5	1		*REAR BOOT INNER LOCK	Not Necessary	135.00 FL	*- FL
6	1		*REAR BOOT LOCK STRICKER	Not Necessary	45.00 FL	*- FL
7	1		*REAR BOOT WEATHERSTRIP	Not Necessary	146.00 FL	*- FL
8	2		*REAR BOOT HINGE	Not Necessary	196.00 FL	*- FL
9	2		*REAR TAILLAMP	Cracked	848.00 FL	*668.00 FL
10	2		*REAR TAILLAMP PANEL	Repair	330.00 FL	*- FL
11	1		*REAR BUMPER	Deformed	743.00 FL	*743.00 FL
12	2		*REAR BUMPER SIDE RETAINER	Necessary	96.00 FL	*96.00 FL
13	1		*REAR END PANEL	Repair	485.00 FL	*- FL
14	1		*REAR END PANEL GARNISH	Deformed	169.00 FL	*169.00 FL
15	1		*REAR SPARE TYRE TANK	Not Necessary	910.00 FL	*- FL
16	1		*SET REAR END PANEL GARNISH CLIP	Necessary	22.50 FS	*10.00 FS
17	2		*REAR TAILLAMP CLIP	Necessary	25.00 FS	*20.00 FS
18	2		*REAR TAILLAMP CLIP HOLDER	Not Necessary	23.00 FS	*- FS
19	1		*SET REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
20	1		*REAR BUMPER LOWER SPOILER	Repair	760.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,082.50	1,948.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	497.20	171.80
Total Parts (\$\$)	5,585.30	1,776.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK UP REAR ELECTRICAL WIRING & TEST FOR ANY LEAKAGE	New	80.00	30.00
2	TO REMOVE & REFIX REVERSE SENSOR	New	80.00	50.00
3	TO REMOVE & REFIX REAR INTERIOR TRIM TO ASSIST REPAIR	New	150.00	50.00
4	TO RESPAY UNDERCOATING	New	180.00	0.00
5	TO RESPRAY & ETC	New	1,200.00	600.00
6	PANEL BEATING ,REMOVE & REPLACING ABOVE PARTS	New	1,200.00	400.00
Gross Labour Cost (S\$)			2,890.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >