

KIM CHWEE AUTO PTE LTD

1 Kakit Bukit Ave 6

#01-46,48,50 Autobay

SINGAPORE 417883

not Authorised
Make
9/12 \$ 4138.27
3 dy.

VEHICLE NO:SFM 9363D

QTY	PARTICULAR		
1 PCS	TAILGATE	12	\$1,280.30 X
1 PCS	TAILGATE REAR LOGO	11	\$86.50 X
1 PCS	TAILGATE C&C LOGO	11	\$82.00 X
1 PCS	TAILGATE CITROEN EMBLEM	11	\$105.00 X
1 PCS	TAILGATE 'C4' EMBLEM	11	\$80.50 X
1 PCS	TAILGATE INNER LOCK	11	\$299.00 X
1 PCS	TAILGATE WEATHERSTRIPS	11	\$312.00 X
1 PCS	REAR BUMPER	10/312	\$1,150.00
1 PCS	REAR BUMPER TOW COVER	11	\$30.00 X
2 PCS	REAR BUMPER SIDE RETAINERS @\$45.00	rec	\$90.00
1 PCS	REAR BUMPER REINFORCEMENT	Bel	\$688.00
1 PCS	REAR BUMPER LOWER GARNISH	De	\$650.00
1 PCS	REAR BUMPER LOWER GARNISH CHROME	cm	\$390.00
4 PCS	REAR BUMPER PDC SENSORS @\$185.00	shut	\$740.00 1pc
1 PCS	REAR END PANEL	12	\$650.00 X
1 PCS	REAR END PANEL TOP GARNISH	11	\$315.00 X
2 PCS	TAILLAMPS @\$625.00	o/sone	\$1,250.00 1pc
			\$8,198.30

LABOUR CHARGES:

TO CHECK WIRING	\$80.00	20
TO DISMENTLE & REPLACING PDC SENSOR	\$80.00	50
TO DISMENTLE & REFIX SEAT,CUSHION UPHOLSTREY	\$120.00	80
TO DISMENTLE & REFIX REAR WINDSCREEN	11	\$150.00 X
TO SPRAY RUST PROOFING	11	\$80.00 X
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$800.00	520
TO PUTTY & SPRAY PAINTING	\$1,080.00	600
TOTAL	\$10,588.30	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-318687
28827