

ASS. REC. BY:

REF: CS/FCI/8014631/Gsd3

Special Instruction: n2

Surveyor: GQ  
aws

ASSIGNMENT (Office)

From (Person): Karen Tan

of FCI

Date/Time: 13/8/18 @ 11:58am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FE 3333 Y

Insured: SHA 7316T

at Workshop m/s: Pan Euro Bikes

Tel: 97317133

of 21 Moonstone Lane # 01-01

Policy No:

Claim No: D18005906MFSH

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A. 2/8/18

CA / REV / REP. / REV 24 HRS (CDS)

H.O.D. Endorsement:

Date/Time: 12:38pm @ 13/8/18

Person Contacted: Kin Wah

Vehicle: IN/OUT

| Date/Time          | Action/Instruction (✓) Estimate                      |
|--------------------|--|
|                    | FE 3333 Y - X  |
|                    | SHA 7316T - CC3/CAI/14022691/H/rev 3q 2 DVA: 3/12/14 |
| 20/08/18 @ 9:09 am | revised AA to Karen via email.                       |
|                    |  |
|                    |  |
|                    |  |





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18014631/Gsd3

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 13-08-2018



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                 |                |            |
|--------------|-----------------|----------------|------------|
| Insured Veh. | SHA 7316T       | Veh. Inspected | FE 3333Y   |
| Policy No.   |                 | Coverage (\$)  | 0.00       |
| Claim No.    | D18005906MFSH   | Excess (\$)    | 0.00       |
| Assign From  | CWS (KAREN TAN) | Assign Date    | 13/08/2018 |

### 2. Vehicle Particulars & Condition

|              |        |              |   |
|--------------|--------|--------------|---|
| Make & Model |        | c.c          | 0 |
| Engine No.   | HIDDEN | Year of Reg. |   |
| Chassis No.  |        | Colour       |   |
| Odometer     | -      | Steering     |   |
| Brakes       |        | Modification |   |
| General      |        |              |   |

### 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

### 4. Description of Damages

|  |  |
|--|--|
|  |  |
|--|--|

### 5. General Information

|                |  |                 |            |
|----------------|--|-----------------|------------|
| Accident Date  | 02/08/2018   | Inspection Date | 13/08/2018 |
| Survey held at | PAN EURO BIKES PTE LTD<br>21 MOONSTONE LANE #01-01<br>POH LENG BUILDING<br>SINGAPORE 328462. |                 |            |

### 5a. Remarks

|  |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005906MFSH

Date: 20 August 2018

Our Ref: CS/FCI18014631/Gsd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. FE 3333Y**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 13/08/2018 at the premises of M/s Pan Euro Bikes Pte Ltd and have the following to report:-

|                          |                      |
|--------------------------|----------------------|
| Workshop Estimate Amount | : <u>SS 5,108.50</u> |
| Revised Estimate Amount  | : <u>SS 3,420.80</u> |
| "Check" Items Amount     | : <u>SS 1,420.00</u> |
| Market Value             | : <u>SS</u>          |
| LTA Reimbursement Value  | : <u>SS</u>          |
| Nett Value               | : <u>SS</u>          |

**Description of Damage:**

The vehicle sustained damages at the n/s body.



**Comments/ Present Status:**

Damages Consistent.  
Repair days: 2 Days

Yours faithfully,  
Xing Guo Qiang  
Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

|                           |  |                                     |
|---------------------------|--|-------------------------------------|
| <b>Date</b>               | 06-08-2018                                 | <b>Our Ref No.</b> D18005906MFSH    |
| <b>Accident Date</b>      | 02-08-2018                                 | <b>Claim Type.</b> Third Party      |
| <b>Insured Vehicle</b>    | SHA7316T                                   | <b>Third Party Vehicle.</b> FE3333Y |
| <b>Survey Location</b>    | 21 MOONSTONE LANE #01-01 POH LENG BUILDING |                                     |
| <b>Contact Person.</b>    | KIN WAH                                    |                                     |
| <b>Contact No.</b>        | 62994929/ 97317133                         | <b>Fax No.</b> 62994430             |
| <b>Survey Type</b>        | DIRECT SETTLEMENT:                         |                                     |
| <b>Appointed Surveyor</b> | LKK AUTO CONSULTANTS PTE LTD               |                                     |
| <b>Contact Person</b>     | NA   | <b>Fax No.</b> 68416315             |
| <b>Contact Number.</b>    | NA   |                                     |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                          |                        |                                |
|--------------------------|------------------------|--------------------------------|
| <b>Cc : Workshop</b>     | PAN EURO BIKES PTE LTD | <b>Attention.</b> NIL          |
| <b>Cc : TP Solicitor</b> | NA                     | <b>TP Solicitor Fax No.</b> NA |
| <b>Officer Incharge</b>  | KARENT                 |                                |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Monday, 20 August 2018 9:09 AM  
**To:** 'KARENTAN@MSFIRSTCAPITAL.COM.SG'; 'Claim Workflow System'  
**Cc:** 'sur@lkkauto.com'; 'Nivitha (LKK Auto)'; 'ASSIGNMENTS@LKKAUTO.COM'  
**Subject:** RE: SURVEY ASSESSMENT - D18005906MFSH/1  
**Attachments:** FE 3333Y - Preli Advise.pdf

Dear Karen,

Enclosed herewith preliminary advice of FE 3333Y.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]  
**Sent:** Monday, 13 August 2018 1:16 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM  
**Cc:** KARENTAN@MSFIRSTCAPITAL.COM.SG; sur@lkkauto.com  
**Subject:** RE: SURVEY ASSESSMENT - D18005906MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]  
**Sent:** Monday, 13 August 2018 11:57 AM  
**To:** ASSIGNMENTS@LKKAUTO.COM  
**Cc:** CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG  
**Subject:** PRI: SURVEY ASSESSMENT - D18005906MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,

Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars      |                   |
|--------------------------------|-------------------|
| Owner ID Type:                 | Singapore NRIC    |
| Owner ID:                      | 3171D             |
| Vehicle Details                |                   |
| Vehicle No.:                   | FE3333Y           |
| Vehicle to be Exported:        | No                |
| Intended De-registration Date: | 17 Aug 2018       |
| Vehicle Make:                  | TRIUMPH           |
| Vehicle Model:                 | TIGER EXPLORER XC |
| Primary Colour:                | Green             |
| Manufacturing Year:            | 2013              |
| Engine No.:                    | E587923           |
| Chassis No.:                   | SMTV1F12E9D586598 |
| Maximum Power Output:          | -                 |
| Open Market Value:             | \$20,493.00       |
| Original Registration Date:    | 25 Jul 2013       |
| First Registration Date:       | 25 Jul 2013       |
| Transfer Count:                | 2                 |
| Actual ARF Paid:               | \$3,074.00        |
| Intended PARF Rebate Details   |                   |
| PARF Eligibility:              | No                |
| PARF Eligibility Expiry Date:  | -                 |
| PARF Rebate Amount:            | \$0.00            |
| Intended COE Rebate Details    |                   |
| COE Expiry Date:               | 24 Jul 2023       |
| COE Category:                  | D - Motorcycle    |
| COE Period(Years):             | 10                |
| QP Paid:                       | \$1,712.00        |
| COE Rebate Amount:             | \$844.00          |
| <b>Total Rebate Amount:</b>    | <b>\$844.00</b>   |

The information contained herein is correct as at 17 Aug 2018

OK

## Contact us at

Hotline: (65) 6532 2888

E-mail: CustomerService@DirectAsia.com

## CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) (Singapore) (the "Act")

Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 (Singapore)

Road Transport Act, 1987 (Malaysia)

Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

This document forms part of your contract with us and should be read together with your Policy Schedule and your Policy Details. Do let us know if any of the details shown here need to be amended or updated.

|  |                                 |
|--|---------------------------------|
| Certificate No.  | MC/0024471/03                   |
| Type of Coverage   | Comprehensive Cover             |
| 1) Vehicle Registration No.  | FE3332F                         |
| Chassis No.  | 58FVVF128F0586398               |
| 2) Name of Policy Holder   | MURUGANARAJAN, RAJENDRAN        |
| 3) Effective Date of Commencement of Insurance for the Purpose of the Act  | 25/01/2018                      |
| 4) Date of Expiry of Insurance   | 24/01/2019                      |
| 5) Persons or Classes of Persons Entitled to Drive   |                                 |
| (a) The Insured  |                                 |
| (b) A named driver who is driving on the Insured's order or with his permission.   |                                 |
| Provided that the person driving has a valid Motorcycle driving licence to drive in Singapore and is not under suspension or disqualification from driving.  |                                 |
| 6) Limitations as to use <sup>1</sup>  |                                 |
| Use only for private purposes, in accordance with the declared motorcycle usage stated on your Policy Schedule. The policy does not cover use for hire or reward, tuition, driving test, racing, pace making, reliability trials, speed tests, the carriage of goods for payment or for any purpose in connection with the motor trade business. |                                 |
| <sup>1</sup> Limitations rendered inoperative by Section 8 of the Act and Section 85 of the Road Transport Act, 1987 (Malaysia), are not to be included under this heading.  |                                 |
| Sum Insured  | Market Value                    |
| Policy Excess  | S\$ 400.00                      |
| Main driver  | S/O P. J. UTHARAPATH, RAJENDRAN |
| <b>Important Note:</b> The policy only cover the main driver and the following named driver.<br>No named driver declared.  |                                 |
| Finance Company / Hire Purchase  |                                 |

<sup>1</sup>We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and the Road Transport Act, 1987 (Malaysia)

Issued on: 26/12/2017

Direct Asia Insurance (Singapore) Pte. Ltd.



 Edip Okur  
 Chief Underwriting Officer

DRIVER IC/DL Pg. 1

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S1743171D



NAME  
RAVINDREN S/O P T  
UTHIRAPATHI

RACE  
INDIAN

Date of Birth  
11-12-1966

Sex  
M

Country of Birth  
SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S1743171D

NAME  
RAVINDREN S/O P T  
UTHIRAPATHI

Birth Date 11 Dec 1966

Issue Date 01 Sep 2003




096000



NRIC No. S1743171D



Blood Group  
g+

Date of issue  
15-05-1993

APT BLK 6 HANG ROAD #11-453  
SINGAPORE 430086

NRIC No. S1743171D Date: 08/09/2007 No. 5505928

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

|          |  | PASS DATE   |
|----------|--|-------------|
| Class 2B | Motorcycles not exceeding 250 cc   | 26 Nov 1980 |
| Class 2A | Motorcycles between 251 cc and 400 cc  | 04 Jan 1995 |
| Class 2  | Motorcycles exceeding 400 cc   | 21 Oct 1997 |
| Class 3  | Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms | 04 Apr 2001 |

Licence No. S1743171D



NP 429A

# PAN EURO BIKES PTE LTD

21 Moonstone Lane #01-01 Poh Leng Building Singapore 328462  
Tel: 62994929 Fax: 62994430 Email: paneurobikes@singnet.com.sg

Biz/GST Reg: 200916151R

PAGE 1

TO: MOTOR CLAIMS DEPARTMENT  
FIRST CAPITAL INS. LTD

DATE: 10.08.2018

## ESTIMATED COST OF REPAIRS TO TRIUMPH EXPLORER XC 1200

ENGINE NO : CHASSIS NO :  
VEHICLE NO : FE 3333Y ACCIDENT ON : 02.08.2018  
INSURED : RAVINDREN S/O PT UTHIRAPATHI

|      |  |          |                 |
|------|--|----------|-----------------|
| 1 PC | LH MIRROR / CRA                        | S        | 116.00          |
| 1 PC | LH BAR END, SILVER - cut               | S        | 36.00           |
| 1 PC | LH HANDGUARD, MATT - cut               | S        | 75.00           |
| 1 PC | HANDLEBAR, SILVER - BT                 | S        | 328.00          |
| 1 PC | CLUTCH LEVER - cut                     | S        | 75.00           |
| 1 PC | LH GARNISH, MATT GREEN, HEADLAMP - cut | S        | 222.00          |
| 1 PC | LH FRONT SIGNAL ASSY - CRA             | S        | 150.00          |
| 1 PC | LH FOG LAMP GUARD, BRUSHED - cut       | S        | 62.00           |
| 1 PC | LH FRONT FORK ASSY - cut               | S        | 1,208.00        |
| 1 PC | LH FRONT FOOTREST X MN                 | S        | 95.00           |
|      | <b>TOTAL</b>                           | <b>S</b> | <b>2,367.00</b> |

LESS 10% S 236.70

**SUB TOTAL** S 2,130.30

### NETT ITEMS:

|       |   |          |                 |
|-------|---|----------|-----------------|
| 1 SET | WINDSHIELD, AFTERMARKET, LIGHT TINT - CRA                       | S        | 325             |
|       | FRONT NO. PLATE - ec  | S        | 10.00           |
| 1 PC  | CRASHBAR, TRIUMPH ACCESSORY <del>X repair</del> BT local repair | S        | 488.00          |
| 1 SET | SIDE PANNIERS, GIVI OUTBACK BLACK                               | S        | 1,420.00        |
| 1 SET | SIDE PANNIER BRACKETS, GIVI <del>BR</del> - BR                  | S        | 396.00          |
|       | TOWING S40 x 2  | S        | 80.00           |
|       | LABOUR CHARGE   | S        | 250.00          |
|       | <b>TOTAL</b>  | <b>S</b> | <b>4,774.30</b> |

ADD 7% GST S 334.20

**GRAND TOTAL** S 5,108.50

### REMARKS:

Kindly send a surveyor down for 3rd Party claim against your insured SHA 7316T.

Thank You.

Kin Wah: 9731-7133

4795.6

Gmo Qianp.  
13/8/18  
2 Days.  
part by mt.  
After part photos.

*[Handwritten Signature]*  
20/8/18

### LPK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# PAN EURO BIKES PTE LTD

21 Moonstone Lane #01-01 Poh Leng Building Singapore 328462  
Tel: 62994929 Fax: 62994430 Email: paneurobikes@singnet.com.sg  
Biz/GST Reg: 200916151R

PAGE 1

TO: MOTOR CLAIMS DEPARTMENT  
FIRST CAPITAL INS. LTD

DATE: 10.08.2018

## ESTIMATED COST OF REPAIRS TO TRIUMPH EXPLORER XC 1200

ENGINE NO : CHASSIS NO :  
VEHICLE NO : FE 3333Y ACCIDENT ON : 02.08.2018  
INSURED : RAVINDREN S/O PT UTHIRAPATHI

|             |                                     |          |   |          |
|-------------|-------------------------------------|----------|---|----------|
| 1 PC        | LH MIRROR                           |          | S | 116.00   |
| 1 PC        | LH BAR END, SILVER                  |          | S | 36.00    |
| 1 PC        | LH HANDGUARD, MATT                  |          | S | 75.00    |
| 1 PC        | HANDLEBAR, SILVER                   |          | S | 328.00   |
| 1 PC        | CLUTCH LEVER                        |          | S | 75.00    |
| 1 PC        | LH GARNISH, MATT GREEN, HEADLAMP    |          | S | 222.00   |
| 1 PC        | LH FRONT SIGNAL ASSY                |          | S | 150.00   |
| 1 PC        | LH FOG LAMP GUARD, BRUSHED          |          | S | 62.00    |
| 1 PC        | LH FRONT FORK ASSY                  |          | S | 1,208.00 |
| 1 PC        | LH FRONT FOOTREST                   |          | S | 322.00   |
| 1 PC        | SUBFRAME, HEADLAMP/COCKPIT CLUSTER  | (A) / BR | S | 322.00   |
|             | TOTAL                               |          | S | 2,594.00 |
|             | LESS 10%                            |          | S | 259.40   |
|             | SUB TOTAL                           |          | S | 2,334.60 |
| NETT ITEMS: |                                     |          |   |          |
| 1 SET       | WINDSHIELD, AFTERMARKET, LIGHT TINT |          | S | 325.00   |
|             | FRONT NO. PLATE                     |          | S | 10.00    |
|             | CRASHBAR REPAIR/PAINTING            |          | S | 50.00    |
| 1 SET       | SIDE PANNIERS, GIVI OUTBACK BLACK   |          | S | 1,420.00 |
| 1 SET       | SIDE PANNIER BRACKETS, GIVI         |          | S | 396.00   |
|             | TOWING                              | \$40 x 2 | S | 80.00    |
|             | LABOUR CHARGE                       |          | S | 180.00   |
|             | TOTAL                               |          | S | 4,795.60 |
|             | ADD 7% GST                          |          | S | 335.69   |
|             | GRAND TOTAL                         |          | S | 5,131.29 |

### REMARKS:

For 3rd Party claim against your insured SHA 7316T.

Thank You.

Kin Wah: 9731-7133



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |                             |   |
|--|--|-----------------------------|---|
| MS FIRST CAPITAL INSURANCE LTD   |  | Ref : CS/FCI18014631/Gsd3n2 |   |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877  |  | Date : 19-02-2019           |  |
|  |  | Code : FCI2                 |   |
| 1. Policy Particulars :- THIRD PARTY CLAIM   |  |                             |   |
| Insured Veh.   | SHA 7316T  | Veh. Inspected              | FE 3333Y  |
| Policy No.   |  | Coverage (\$)               | 0.00  |
| Claim No.  | D18005906MFSH  | Excess (\$)                 | 0.00  |
| Assign From  | KARENT   | Assign Date                 | 13/08/2018  |
| 2. Vehicle Particulars & Condition   |  |                             |   |
| Make & Model   | TRIUMPH TIGER EXPLORER XC  | c.c                         | 1215  |
| Engine No.   | HIDDEN   | Year of Reg.                | 2013  |
| Chassis No.  | SMTV1F12E9D586598  | Colour                      | GREEN   |
| Odometer   | -  | Steering                    | IN ORDER  |
| Brakes   | IN ORDER   | Modification                | NIL   |
| General  | GOOD   |                             |   |
| 3. Conditions of Tyres   |  |                             |   |
|  | Size   | Make                        | Balance   |
| R/H Front Tyre   | 110/80 R19   | MICHELIN                    | 5 mm  |
| L/H Front Tyre   |  |                             | mm  |
| R/H Rear Tyre  | 150/70 R17   | MICHELIN                    | 5 mm  |
| L/H Rear Tyre  |  |                             | mm  |
| 4. Description of Damages  |  |                             |   |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.<br>DAMAGES SEE DETAILS.   |  |                             |   |
| 5. General Information   |  |                             |   |
| Accident Date  | 02/08/2018   | Inspection Date             | 13/08/2018  |
| Survey held at   | PAN EURO BIKES PTE LTD<br>21 MOONSTONE LANE #01-01<br>POH LENG BUILDING<br>SINGAPORE 328462. |                             |   |
| 5a. Remarks  |  |                             |   |
| A)DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                             |   |
| 5b. Estimate Days of Repair  |  |                             |   |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |  | 2 Working Days              |   |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FE 3333Y

| Qty                                | Description of Parts                           | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|---------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |  |               |                           |                   |
| 1                                  | LH MIRROR                                      | CRACKED       | 116.00                    | 116.00            |
| 1                                  | LH BAR END,SILVER                              | CUT           | 36.00                     | 36.00             |
| 1                                  | LH HANDGUARD,MATT                              | CUT           | 75.00                     | 75.00             |
| 1                                  | HANDLEBAR,SILVER                               | BENT          | 328.00                    | 328.00            |
| 1                                  | CLUTCH LEVER                                   | CUT           | 75.00                     | 75.00             |
| 1                                  | LH GARNISH,MATT GREEN,HEADLAMP                 | CUT           | 222.00                    | 222.00            |
| 1                                  | LH FRONT SIGNAL ASSY                           | CRACKED       | 150.00                    | 150.00            |
| 1                                  | LH FOG LAMP GUARD,BRUSHED                      | CUT           | 62.00                     | 62.00             |
| 1                                  | LH FRONT FORK ASSY                             | CUT           | 1,208.00                  | 1,208.00          |
| 1                                  | LH FRONT FOOTREST                              | NOT NECESSARY | 95.00                     | -                 |
| 1                                  | SUBFRAME,HEADLAMP/COCKPIT CLUSTER (ADDITIONAL) | BROKEN        | 322.00                    | 322.00            |
|                                    | LESS 10% DISCOUNT                              |               | -268.90                   | -259.40           |
|                                    |  |               | <b>2,420.10</b>           | <b>2,334.60</b>   |
| <b><u>SPECIAL NETT ITEMS</u></b>   |  |               |                           |                   |
| 1                                  | SET WINDSHIELD AFTERMARKET LIGHT TINT (SN)     | CRACKED       | 325.00                    | 325.00            |
| 1                                  | FRONT NO PLATE (SN)                            | NECESSARY     | 10.00                     | 10.00             |
| 1                                  | CRASHBAR TRIUMPH ACCESSORY (LOCAL REPAIR)(SN)  | BENT          | 488.00                    | 50.00             |
| 1                                  | SET SIDE PANNIERS,GIVI OUTBACK BLACK (SN)      | DENTED        | 1,420.00                  | 1,420.00          |
| 1                                  | SET SIDE PANNIER BRACKETS,GIVI (SN)            | BROKEN        | 396.00                    | 396.00            |
|                                    |  |               | <b>2,639.00</b>           | <b>2,201.00</b>   |
| <b><u>LABOUR</u></b>               |  |               |                           |                   |
|                                    | TOWING.  |               | 80.00                     | 80.00             |
|                                    | LABOUR CHARGE.                                 |               | 250.00                    | 180.00            |
|                                    | -  |               | -                         | -                 |
|                                    | -  |               | -                         | -                 |
|                                    | -  |               | -                         | -                 |
|                                    |  |               | <b>330.00</b>             | <b>260.00</b>     |
| <b>GRAND TOTAL</b>                 |  |               | <b>5,389.10</b>           | <b>4,795.60</b>   |



|                             |  |  |          |
|-----------------------------|--|--|----------|
| RECOMMENDED COST OF REPAIRS |  |  | 4,795.60 |
|-----------------------------|--|--|----------|

Report Ref No. CS/FCI18014631/Gsd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.