

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

M/S : YEO PING

Singapore

ATTN:

Your Ref No: 18/FC/TP-155 (08)

Claim Type: Third Party

Accident Date: 06/08/2018

TP Veh Reg No: SHB4087T

Estimate No: EST0004322

Date: 27 Sep 2018

Policy No: 1700078035

Veh Reg No: SLV567Z

Make/Model: M.BENZ C180

Chasis No: WDD2040312A774684

Engine No: 27491030016616

Reg. Date: 01/11/2012

Estimate Repair Cost to Vehicle No :SLV567Z

Description	Quantity	List Price SS	Amount SS
Supplementary Parts to Repair			
Special Net			
1 REVERSE SENSOR (4PCS)	1 PC	350.00	250
		350.00	350.00
		Total	SS 350.00
		GST Amount	SS 24.50
		Total Amount Payable	SS 374.50

For SME Motor Pte Ltd

AUTHORISED SIGNATURE