

# WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03  
 Halcyon 2, S'pore 577200  
 Tel No. : 6451 3933 Fax No. : 6455 7576  
 E-Mail : worldaut@singnet.com.sg  
 Website : www.worldauto.com.sg  
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD  
 143 Cecil Street #01-01 GB Building  
 069542

Attention : Motor Claim Department  
 Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000279

Date : 11/08/2018  
 Vehicle Num. : SLR 2423M (LCR)  
 Make/Model : HONDA VEZEL HYBRID  
 Chassis/Eng# :  
 Accident Date : 21/07/2018  
 Claim No. :  
 Reference :  
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS : REAR BUMPER		900.00 <i>✓R</i>
		List TotalS\$ :		900.00
		20.00% Discount S\$ :		180.00
				720.00
1.	1	SPECIAL NETT ITEMS : REAR BUMPER CLIP		40.00 ?
		Special Nett Total S\$ :		40.00
		LABOUR : LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.		<del>380.00</del> <i>200</i>
		PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER)		<del>380.00</del> <i>200</i>
		Labour Total S\$ :		760.00

E. & O.E.

Total S\$ : 1,520.00

=====

for WORLD AUTO PTE LTD Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

NAZ LCR  
 14/8/18 1415  
 P/P  
 2 DAYS  
 AFTER REPAIR PHOTO