

<< Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
General Details						
Involving	1 2009 VOLKSWAGEN GOLF 1.4 TSI (SJU6831A)					
Date of Loss	August 11, 2018					
Time of Loss	22:30					
Loss Description	SJU6831A (OI) CAUGHT FIRE					
Comment						
Workshop Details						
Total Rebate Amount	11602					
Nett Loss Amount	\$8,398.00					
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)					
Days of work completion	7					

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Vehicle & Driver Details

Vehicle Registration#	SJU6831A	Purchase Date	mm/dd/yyyy
Registration State	SINGAPORE	Registration Date *	12/22/2009
Mileage		Age of Vehicle	8

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	POST SURVEY INFORMATION
Manufacturing Year	2009	2009	
Make	VOLKSWAGEN	VOLKSWAGEN	Driver Name LEE YONG FONG
Model	GOLF 1.4 TSI	NEW GOLF 1.4 AT 5K	Date of Birth January 10, 1974
Type			Age 44
Type of Paint			Occupation Unknown
Chassis No	WWWZZZ1KZ9W584747	WWWZZZ1KZ9W584	Education Qualification Other
Engine No	CAX238245	CAX238245	Driving Experience 19
Engine Capacity		1390 cc	Driver License #

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Detailed Assessment

Condition of Vehicle at time of survey

Inspection Date *	08/15/2018	General condition	Good
Total Loss	Yes No	Steering (Serviceable)	Yes No
Towing Charges	0	Footbrake (Serviceable)	Yes No
Voluntary Excess	0	Handbrake (Serviceable)	Yes No
Compulsory Excess	0	Engine Modification	Yes No
Young/Inexperienced/Unlicensed Driver Excess	0	Pre-accident condition	Good
Other Excess			

Tyre Condition

Age of Tyres		Spare wheel	
Front Tyre Size	225/40R18	Rear Tyre Size	225/40R18
Front left side	PIRELLI 5mm	Rear left side	PIRELLI 5mm
Front right side	PIRELLI 5mm	Rear right side	PIRELLI 5mm