

## FIRE REPORT

1. GENERAL INFORMATION		
INCIDENT NO. : /20180811/0967	LOCATION OF FIRE: Block 196, Boon Lay Drive	
FIRE REPORTED ON: 11 August 2018		
TIME OF CALL: 22:29:48 hrs	Multi storey car park (Deck 3A) Singapore 640196	
STATION COVERAGE : Jurong Fire Station		
2. INCIDENT INFORMATION		
FIRE INVOLVED: The engine of a Volkswagen car (SJU6831A).		
METHOD OF EXTINGUISHMENT: By a member of public using an internal hose reel jet before the arrival of SCDF crew.		
PROBABLE CAUSE OF FIRE: Accidental (Overheating at engine compartment)		
DAMAGE SUSTAINED: As a result of the fire, the engine of the car was damaged.		
3. FATALITY/INJURY INFORMATION		
NAME PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL NIL	NIL	NIL
REPORT CERTIFIED TRUE AND CORRECT BY:		
BASIR BIN MD YUSOF for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE		

This is a computer generated Fire Report. No signature is required.