

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

LONPAC INSURANCE BHD

100 BEACH RD #19-00 SHAW TOWER

S'PORE 189702

Attention : Motor Claim Department

Contact : 62507388 Fax No. : 62963767

Estimate : ES000283

Date : 14/08/2018

Vehicle Num. : SLH 7379C (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 14/08/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	REAR BOOT LID	1,350.00	✓BUL
2.	1	REAR BOOT HYBRID EMBLEM (SHUTTLE)	89.00	✓ACC
3.	1	REAR BOOT SHUTTLE EMBLEM (SHUTTLE)	89.00	✓ACC
4.	1	REAR BOOT REFLECTOR LAMP RH	580.00	✓MISsing
5.	1	REAR NUMBER PLATE LAMP GARNISH	460.00	✓X SVC
6.	1	REAR BOOT INNER TRIM BOARD	345.00	?
7.	1	REAR WINDSCREEN GLASS MOULDING	250.00	✓ACC
8.	1	REAR BOOT WEATHER STRIP	180.00	✓X SVC
9.	1	REAR BUMPER	1,150.00	✓CRA
10.	1	REAR BUMPER TAIL LAMP RH	580.00	✓CRA
11.	1	REAR END PANEL	950.00	✓X SVC
12.	1	REAR END PANEL TOP GARNISH	260.00	✓X SVC
13.	1	REAR BUMPER TOW COVER	89.00	✓CRA
14.	1	REAR BOOT COMPARTMENT BOX	420.00	✓CRA
15.	1	REAR BOOT COMPARTMENT BOX BACK COVER	160.00	✓X SVC
16.	1	REAR FLOOR BOARD	350.00	✓X SVC
17.	1/RH	REAR FENDER	1,100.00	✓BUCKLED
18.	1	REAR FENDER GLASS MOULDING	200.00	✓ACC
19.	1	REAR FENDER INNER TRIM BOARD RH	340.00	✓BT
20.	1/RH	REAR SIDE COMPARTMENT BOX	280.00	✓CRA
21.	1/RH	REAR COMPARTMENT SIDE FLOOR BOARD	280.00	✓BT
22.	1/RH	REAR TAILLAMP UPPER PANEL	350.00	✓BT
23.	1/RH	REAR TAILLAMP LOWER PANEL	250.00	✓BT
24.	1	REAR WHEELHOUSE INNER PANEL RH	980.00	✓X SVC
25.	1	REAR WHEELHOUSE OUTER PANEL RH	490.00	✓X ?
26.	1/RH	REAR WHEELHOUSE	900.00	✓XR
27.	1	REAR FRAME STIFFENER RH	320.00	✓BT
28.	1/RH	REAR BUMPER UNDERDUST COVER	210.00	✓X SVC
29.	1	REAR BUMPER RETAINER RH	90.00	✓CRA

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

LONPAC INSURANCE BHD
 100 BEACH RD #19-00 SHAW TOWER
 S'PORE 189702

Attention : Motor Claim Department
 Contact : 62507388 Fax No. : 62963767

Estimate : ES000283

Date : 14/08/2018
 Vehicle Num. : SLH 7379C (LCR)
 Make/Model : HONDA SHUTTLE HYBRID
 Chassis/Eng# :
 Accident Date : 14/08/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
30.	1	REAR BUMPER RETAINER RH		90.00
31.	1	REAR BUMPER INNER FOAM - RH		138.00
32.	1	REAR FENDER AIR GRILLE - RH		150.00
33.	1/RH	REAR FENDER BRACKET STAY		140.00
34.	1	REAR FENDER UNDERDUST COVER RH		250.00
35.	1	REAR AXLE CROSSMEMBER		980.00
36.	1	REAR SHOCK ABSORBER		320.00
37.	1	REAR WHEEL HUB ASSY		280.00
38.	1/RH	REAR ABS SENSOR		252.00
39.	1	FRONT BONNET		1,080.00
40.	2	HEADLAMP ASSY RH/LH	850.00	1,700.00
41.	1	FRONT RADIATOR GRILLE CHROME		230.00
42.	1	FRONT RADIATOR GRILLE BASE		250.00
43.	1	FRONT RADIATOR GRILLE CHROME STRIP		180.00
44.	1	FRONT 'H' LOGO		100.00
45.	2	FRONT HEADLAMP LOWER BRACKET	120.00	240.00
46.	1	FRONT BUMPER		1,100.00
47.	1	FRONT LOWER GRILLE		152.00
48.	2	FRONT BUMPER FOGLAMP GARNISH LOWER	80.00	160.00
49.	2	FRONT BUMPER FOGLAMP GARNISH UPPER	88.00	176.00
50.	2	FRONT FENDER	650.00	1,300.00
51.	2	FRONT FENDER HYBRID EMBLEM	89.00	178.00
52.	2	FRONT BUMPER RETAINER	110.00	220.00
53.	1	FRONT BUMPER REINFORCEMENT		550.00
54.	1	FRONT BUMPER TOW COVER		89.00
55.	1	RADIATOR		1,400.00
56.	1	RADIATOR FAN BLADE		180.00
57.	1	RADIATOR FAN MOTOR		360.00
58.	1	RADIATOR FAN COWLING		190.00
59.	1	AIRCON CONDENSER		1,160.00
60.	1	AIR CON FAN MOTOR		350.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

LONPAC INSURANCE BHD
 100 BEACH RD #19-00 SHAW TOWER
 S'PORE 189702

Attention : Motor Claim Department
 Contact : 62507388 Fax No. : 62963767

Estimate : ES000283

Date : 14/08/2018
 Vehicle Num. : SLH 7379C (LCR)
 Make/Model : HONDA SHUTTLE HYBRID
 Chassis/Eng# :
 Accident Date : 14/08/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

61.	1	AIRCON FAN BLADE		180.00 ?
62.	1	SUPPORT PANEL		1,180.00 ?
63.	1	FRONT SUPPORT PANEL TOP GARNISH		160.00 X SUC
64.	1	FRONT GRILLE CENTRE LOCK BRACKET		230.00 CEA
65.	1	REAR DOOR - RH		1,200.00 XR

List Total S\$:	30,087.00
20.00% Discount S\$:	6,017.40
	24,069.60

SPECIAL NETT ITEMS :				
1.	1	REAR BOOT INNER TRIM BOARD CLIP		40.00 ?
2.	1	REVERSE SENSOR		280.00 missing
3.	1	REAR WINDSCREEN SEALANT		100.00 n/c
4.	1	REAR BUMPER CLIP		40.00 n/c
5.	1	REAR END PANEL TOP GARNISH CLIPS		40.00 P n/c
6.	1/RH	REAR FENDER GLASS SEALANT		100.00 n/c
7.	1	REAR FENDER INNER TRIM BOARD CLIPS		40.00 n/c
8.	1	REAR BUMPER UNDERDUST COVER CLIP		40.00 n/c
9.	1	REAR FENDER UNDERDUST COVER CLIPS		40.00 n/c
10.	1/RH	REAR WHEEL RIM		188.00 ?
11.	1/RH	REAR WHEEL RIM COVER		90.00 X SUC
12.	1/RH	REAR TYRE		188.00 n/c
13.	1	FRONT BUMPER CLIP		40.00 n/c
14.	1	FRONT NUMBER PLATE WITH CASING		40.00 missing
15.	1	FRONT SUPPORT PANEL TOP GARNISH CLIPS		40.00 n/c
16.	1	TOWING CHARGE		120.00 n/c

Special Nett Total S\$:	1,426.00
--------------------------	----------

LABOUR :	
TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES	180.00 60

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

LONPAC INSURANCE BHD
 100 BEACH RD #19-00 SHAW TOWER
 S'PORE 189702

Attention : Motor Claim Department
 Contact : 62507388 Fax No. : 62963767

Estimate : ES000283

Date : 14/08/2018
 Vehicle Num. : SLH 7379C (LCR)
 Make/Model : HONDA SHUTTLE HYBRID
 Chassis/Eng# :
 Accident Date : 14/08/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

REMOVE & REFIT REAR WINDSCREEN GLASS
 REMOVE & REPLACE FENDER 1/4 GLASS

360.00 200

TO DISMANTLE REAR DAMAGE PARTS, CUT AND WELD REAR
 SUPPORT PANEL, KNOCK, STRAIGHTEN AND RESHAPE O/S REAR
 CHASSIS FRAME AND REPLACE RECOMMENDED PARTS.

2,200.00 1,600

TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS

1,800.00 1,200

TO REMOVE AND REFIT HIGH VOLTAGE HYBRID BATTERY IN
 ORDER TO FACILITATE REPAIRS.

380.00 240

TRANSFER DOOR MECHANISM

180.00 90

TO CONDUCT A STANDARD OF OPEARTING PROCEDURE POST
 REPAIRS DIAGNOSTIC SCAN TEST A REQUIREMENT FOR HYBRID
 CARS UPON COMPLETION OF COLLISION REPAIRS.

380.00 150

TO CHECK WIRES, CONNECTORS, REPLACE DAMAGED LAMPS
 AND REVERSE SENSORS.

180.00 50

REMOVE FRT/RR UPHOLSTERY IN ORDER TO FACILITATE REPAIRS
 AND REFIT BACK SAME

300.00 100

TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO
 REPLACED PARTS.

180.00 80

REMOVE REAR UNDERCARRIAGE COMPANENTS IN ORDER TO
 FACILITATE REPAIRS AND REPLACE REAR UNDERCARRIAGE
 PARTS, INCLUDING COMPUTERISED ALIGNMENT.

380.00 150

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

LONPAC INSURANCE BHD
 100 BEACH RD #19-00 SHAW TOWER
 S'PORE 189702

Attention : Motor Claim Department
 Contact : 62507388 Fax No. : 62963767

Estimate : ES000283

Date : 14/08/2018
 Vehicle Num. : SLH 7379C (LCR)
 Make/Model : HONDA SHUTTLE HYBRID
 Chassis/Eng# :
 Accident Date : 14/08/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO REMOVE, REARRANGE ELECTRICAL WIRING, CHECK LIGHTINGS & RESET HEADLAMP FOCUSING.	280.00	100
		TO DISMANTLE FRONT DAMAGE PARTS, CUT AND WELD FRONT SUPPORT PANEL, KNOCK, STRAIGHTEN AND RESHAPE O/S FRONT CHASSIS FRAME AND REPLACE RECOMMENDED PARTS.	1,600.00	800
		TO PUTTY & SPRAY PAINTING ON FRONT AFFECTED AREAS.	1,400.00	1,000
		ENGINE COOLING SYSTEM CHECK & RECTIFY WHERE NECESSARY INCLUDING REPLACING ABOVE PARTS AND REFILLING ENGINE COOLANT	180.00	50
		TO REMOVE AND REFIX AIR CON TO FACILITATE REPAIRS & REFILL AIRCON GAS.	280.00	?
		Labour Total S\$:		10,260.00

E. & O.E.

Total S\$: 35,735.60

for WORLD AUTO PTE LTD

NAZ LKK

14/8/18 1500

PIP

13 days

BEFORE PAINT P 140 TO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: