

JAS Auto Services

6D Mandai Estate #03-02 M-Space, Singapore 729938
Tel: 6453 1967 (5 lines). Fax: 6457 3091
53255447K

M/s Lonpac Insurance
300 Beach Rd #17-04/07 The Concourse
Singapore 199555

Date : 15-Aug-18

Fax: 62963767

Attn: Motor Claim Dept

Re: **Accident on 12/08/2018. Between SJD1000D. AND SMC2611D. (Your Insured)**

Dear Sir;

We are pleased to submit herewith the estimate for repairs to the above mentioned accident damaged vehicle **Third Party Claim.**

Parts	Price
1pc Rear bumper	\$601.20 CR
1pc Rear bumper retainer LH/RH @\$40.00	\$80.00 CR
1pc Rear bumper clips S/N	\$50.00 CR
1pc Rear end panel	\$854.20 CR
1pc Number plate with holder S/N	\$50.00 CR
1pc Reverse sensor S/N	\$120.00 CR
Rear Fender (RH)	

Total: **\$1,755.40**
Less: 20% **\$351.08**
\$1,404.32

Labour

To remove the affected parts, all relevant attachments, fittings to commence repairs, replace the damaged parts, reinstall & realign all necessary parts.
To putty & respray paint on the relevant repaired areas.
To rust proof affected areas where necessary.

\$800.00 ~~400~~
\$600.00 ~~400~~
\$90.00 ~~50~~

Parts & Labour Total: \$2,894.32

Your Faithfully,

LKK Auto Services hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To disassemble part(s) during resurvey

Prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

NA2 LKK
15/8/18 1620
LIS
3 Days
AFTER REPAIR PHOTO