

**MOTORWAY**

1094 Lower Delta Road Motorway Building Singapore 169205

Main +65.6468 2200 | Fax +65.6273 5535

AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 Shenton Way

#07-16

Singapore 079120

Attn : MOTOR CLAIMS DEPT

ESTIMATEVEHICLE NO. : **GBD6430H**

CHASSIS NO : KPADA1ETSFP230230

ENGINE NO. : 67196022638154

MAKE / MODEL : SSANGYONG ACTYON SPORTS D/CAB 2.0 5AT ABS D/AB 2WD

DATE OF ACCIDENT : 20th JULY 2048

<u>PARTS DISCRIPTION</u>	<u>QTY</u>	<u>COST PRICE</u>	<u>TOTAL COST PRICE</u>
REAR BUMPER	1	\$ 1,890.00	\$ 1,890.00 <i>see</i>
REAR BUMPER CLIPS	1SET	\$ 50.00	\$ 50.00 <i>see</i>
REAR BUMPER REINFORCEMENT	1	\$ 750.00	\$ 750.00 <i>see</i>
REAR RIGHT TAIL LAMP ASSY	1	\$ 1,380.00	\$ 1,380.00 <i>Bro - price?</i>
REAR RIGHT SIDE PANEL	1	\$ 1,850.00	\$ 1,850.00 <i>repair</i>
REAR RH BUMPER REFLECTOR	1	\$ 95.00	\$ 95.00 <i>see</i>
REVERSE SENSOR	1SET	\$ 280.00	\$ 280.00 <i>X</i>
<i>RASUL</i> <i>HP 90010068</i> <i>6 days</i> <i>4/5</i> <i>14/08/18 @ 1130</i> <i>Resurvey after repair</i>			
Total			\$ 6,295.00
ADD 10%			\$ 629.50
Total Parts			\$ 6,924.50

LABOUR CHARGES

TO REMOVE & REPLACE ALL DAMAGED BODY PART ITEMS DUE TO ACCIDENT	\$ 1,400.00	<i>700</i>
TO REALIGN REAR RH SIDE CABIN & REAR RH DOOR	\$ 350.00	<i>X</i>
TO RUSTPROOF ON ACCIDENT & AFFECTED AREA	(nett) \$ 60.00	<i>40</i>
TO SPRAY PAINT ON THE DAMAGES ITEMS & AFFECTED AREA DUE TO ACCIDENT	\$ 600.00	<i>550</i>
Total Labour	\$ 2,410.00	

Sub Total

\$ 9,334.50

* SSANGYONG VEHICLES LABOUR & SPRAY PAINT RATES :

Spray Painting \$300 per panel
Labour \$350 per day

Prepared By :

Lynn Ahmad

Motorway Car Care Centre Pte Ltd

TEL: 6571 9635 FAX : 6278 5535

EMAIL: lynn@motorway.com.sg

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: