

INFORM

INS. CASE OWNER:

CG 6 / CTI1801

4806, U 1/2

LKK:

IDAC:

Surveyor:

marins

DOE:

ASSIGNMENT

7/8/18

Date / Time:

11/8/18

Registered in Merimen:

Pre-assign / CCU / FTE

VN R274L



Insured Vehicle No.:

Name of Insured:

HAPE LOGISTICS PTE

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

11/8/18

Is driver the owner?

(YES / ☒)

Nature of Accident:

If NO. Driver Name / Age:

BRAND BR01

Driver Tel No.:

(V/L: ☒ YES / NO)

Claim No.:

SNM1800791820Y

Policy No.:

PmLVSNI66671301

Make / Model:

MITSUBISHI

Place of Accident:

TOR PAVON SUP RD TMS PIE

OI GIA REPORT: YES / NO

☒ YES / ☐ NO

TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SKL 3845m



INSRS:

WSP:

Tel:

Liability:

RMKS:

fix



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

5/9/18

gdy

SKL 3845m

VN R274L-X

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI: - email only - THY

Documentation Check List: Handler Type

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

45

S\$ 6,550

(4

days) Reduction:

65 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Confirm by:

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

Repair Cost:

(4/650)

S\$ 7,008.50

Loss of Rental (LOR):

S\$

600.00

(5

days) X \$120

Loss of Use (LOU):

S\$ -

(5

days)

Loss of Income (LOI):

S\$ -

(5

days)

LOR only

LOU only

☒

LOR + LOU

☐

LOR + LO ☐ [Tick only one]

GIA/LTA Search:

S\$

2.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow / Independent)

Legal Cost:

S\$ -

Total:

S\$

7,610.50

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Confirm by:

Payee 1:

S\$

7,610.50

Name 1:

VFIX AUTO SERVICE PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

Email

Call

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$320

COPY SENT 20/1/2020

(02/11/13) wef

ASS. REC. BY:

REF: CTL

ASSIGNMENT

From: Date: 21082018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKC 3845M

at Workshop m/s Vix Auto

of 60 Kaki Bukit Ave 6

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA LPR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKC 3845M Yr Regn: 8.11

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: VOLVO XC60 c.c. 1999

Colour: Brown A/C: Insured / Std / NI / NA

Sp. Reading: 180558 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: 1V1D7475B32181924

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R: 235/60R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 11/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Tailg. 3/22/20

(L/S \$ 6,550 / Red \$ 11,921.50 / 65%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$))

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18014806/Ujb3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 14-08-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 9474L	Veh. Inspected	SKC 3845M	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	14/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/08/2018	Inspection Date	21/08/2018	
Survey held at	VFIX AUTO SERVICE PTE LTD 60 KAKI BUKIT AVE 6, ARK@KB, 417892 KAKI BUKIT SINGAPORE 417892			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

511 BLAIVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC6/CTH18014806/Ujb3

Date: 23.08.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SKC3845M

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21.08.2018 at the premises of M/s Vfix Auto Service Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	14,550.70
Revised Estimate Amount	: S\$	6,059.09
"Check" Items Amount	: S\$	2,413.50
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

onefm
913
GOOD TIMES, GREAT HIT

• THE COURTS ONE FM 913 •
TOP 913 GREATEST HITS
OF ALL TIME COUNTDOWN

WHAT'S YOUR NO
OF ALL TIME?

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Maserati GTS.



Rare.
Direct Owner StarAd



Post an Ad

Advertiser Login

Ways of Selling

Browse by Category ▼

Sort by

9 vehicles

Volvo XC60

Advanced

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mile

Search Selection

Volvo XC60

Any

Any

2011

Any

**Volvo XC60 T5 2.0A****\$59,800****\$12,540 /yr****27-Sep-2011****1,999 cc****11**

New Arrival! Single Owner. Beautiful Grey On Black, Low Mileage Done, Very Well Maintained! Servicing History With Rec Mileage. Flexible Loan Packages Available At 1.99% Or Up To ...

Receipts Proven For Past Servicing Records. Low Mileage Done. Call Now!
SKL Automobile Pte Ltd

Posted: 23-Aug-2018 Tags: 2011 Volvo XC60, Volvo XC60, Volvo, XC60, Used Volvo

**Volvo XC60 T5 2.0A R-Design****\$69,800****\$13,940 /yr****30-Dec-2011****1,999 cc**

R-Design Model. In House Loan And Balloon Scheme Available, No Gimmicks! Down Payment \$6980 With Monthly \$1377 Mileage Done 18500Km Yearly, Full Wearnes Service Record, City Safet...

Posted: 20-Aug-2018 Tags: 2011 Volvo XC60, Volvo XC60, Volvo, XC60, Used Volvo

**Volvo XC60 T5 2.0A****\$52,166****\$11,810 /yr****14-Apr-2011****1,999 cc****13**

Volvo's Mid-Size SUV Where Style, Practicality, Safety And Performance Gels Perfectly! Powered By A 2L Turbo Engine M Gearbox Ensuring You An Exhilarating Drive! Spacious C...

Creative Auto

Posted: 17-Aug-2018 Tags: 2011 Volvo XC60, Volvo XC60, Volvo, XC60, Used Volvo

**Volvo XC60 T5 2.0A****\$52,800****\$12,640 /yr****28-Feb-2011****1,999 cc****11**

One Of The Lowest Depreciation Continental SUV, Mint Condition. Well Maintained By Owner. No Repairs Needed. Many Replaced! Original Condition. Please Call For Viewing Now.

Posted: 16-Aug-2018 Tags: 2011 Volvo XC60, Volvo XC60, Volvo, XC60, Used Volvo

Car Buying

Car Selling

Car Ownership

Compare

On The Move

Lifestyle

Buy
Later

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0801B
Vehicle Details	
Vehicle No.:	SKC3845M
Vehicle to be Exported:	No
Intended De-registration Date:	23 Aug 2018
Vehicle Make:	VOLVO
Vehicle Model:	XC60 T5 2.0 AT ABS D/AB 2WD 5DR TURBO
Primary Colour:	Brown
Manufacturing Year:	2010
Engine No.:	B4204T71002329
Chassis No.:	YV1DZ475BB2181924
Maximum Power Output:	177.0 kW (237 bhp)
Open Market Value:	\$41,951.00
Original Registration Date:	22 Aug 2011
First Registration Date:	22 Aug 2011
Transfer Count:	0
Actual ARF Paid:	\$41,951.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Aug 2021
PARF Rebate Amount:	\$25,170.00
Intended COE Rebate Details	
COE Expiry Date:	21 Aug 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$65,521.00
COE Rebate Amount:	\$19,621.00
Total Rebate Amount:	\$44,791.00

The information contained herein is correct as at 23 Aug 2018

OK



Not Authorized
21/8/18
407

Vfix Auto Service Pte Ltd
 60 Kaki Bukit Ave 6 Ark@KB
 Singapore 417892
 Email : contact@vfixauto.com.sg
 Tel : 6448 9268 Fax: 6445 2368
 UEN / GST Reg No. : 201602964H

M/S CHINA TAIPING INS (S'PORE) PTE LTD
 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

ESTIMATE

DATE : 14/08/2018
 ACC DATE : 11/08/2018
 REF NO : VFIX - TP20180513
 POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO.SKC3845M VOLVO XC60 T5

DESCRIPTION	AMOUNT S\$
1 1 REAR WINDSCREEN GLASS	17 1,343.70 X
2 1 REAR WINDSCREEN GLASS SEALANT	RM 90.00 —
3 1 REAR WINDSCREEN GLASS MOULDING	RM 265.00 —
4 1 TAIL GATE	20/11 2,486.00 —
5 1 TAIL GATE EMBLEM XC60	RM 75.00 —
6 1 TAIL GATE EMBLEM T5	RM 75.00 —
7 1 TAIL GATE EMBLEM VOLVO 105	RM 205.00 —
8 1 TAIL GATE MOULDING	17 165.00 X
9 1 TAIL GATE LOCK	17 370.00 X
10 2 TAIL GATE LOCK CATCH	167.40 17 334.80 X
11 1 REAR WIPER MOTOR	1,105.00 ?
12 1 REAR WIPER ARM	CU 325.00 —
13 1 REAR WIPER BLADE	17 115.00 X
14 1 TAIL LAMP LH	17 287.00 X
15 1 REAR END PANEL	910.00 ?
16 1 REAR BUMPER TOP GARNISH	17 322.00 X
17 1 REAR BUMPER	20 1,454.80 —
18 1 REAR BUMPER LOWER SPOILER 434.30	70.7 486.40 —
19 1 REAR BUMPER REFLECTOR LH	17 164.00 X
20 2 REAR BUMPER SIDE RETAINER	74.00 17 148.00 X
21 1 REVERSE SENSOR 194 x 2 = 388	500.00 —
22 1 REAR EXHUAST MUFFLER 102	924.00 X
	S 12,150.70

LABOUR & MISCELLANEOUS:

AMOUNT S\$

1	To remove damaged parts with all necessary components/attachments apply hot-works where necessary replace new parts align into position	600	1,200.00?
2	To spray paint replaced/repared body panels inclusive of preparatory works and painting materials	800	800.00
3	To transfer tail gate components with all necessary attachments	20	150.00
4	To remove,replace rear windscreen glass and water test	120	150.00
5	To install reverse sensor and check funtion	30	100.00
		\$	2,400.00

GRAND TOTAL : \$ 14,550.70

**SINGAPORE DOLLARS : FOURTEEN THOUSAND FIVE HUNDRED FIFTY
& CENTS SEVENTY ONLY**

Vfix Auto Service Pte Ltd



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey & return after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Not Authorized
LWR

the photo attached

21/8/18

4 day

1/5 6550

Vfix Auto Service Pte Ltd
60 Kaki Bukit Ave 6 Ark@KB
Singapore 417892
Email : contact@vfixauto.com.sg
Tel : 6448 9268 Fax: 6445 2368
UEN / GST Reg No. : 201602964H

M/S CHINA TAIPING INS (S'PORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Attention: Motor Claim Department

ESTIMATE

DATE : 14/08/2018
ACC DATE : 11/08/2018
REF NO : VFIX - TP20180513
POLICY NO :

YV102

RE : VEHICLE NO.SKC3845M VOLVO XC60 T5

DESCRIPTION	AMOUNT S\$
1 1 REAR WINDSCREEN GLASS	17 1,343.70 X
2 1 REAR WINDSCREEN GLASS SEALANT	neu 90.00 405.0
3 1 REAR WINDSCREEN GLASS MOULDING 166	neu 265.00 ✓
4 1 TAIL GATE 3123.30	no/cue 5,157.00 ✓
5 1 TAIL GATE EMBLEM XC60 125	neu 135.00 ✓
6 1 TAIL GATE EMBLEM T5 115	neu 135.00 ✓
7 1 TAIL GATE EMBLEM VOLVO 105	neu 369.00 ✓
8 1 TAIL GATE MOULDING	17 165.00 X
9 1 TAIL GATE LOCK	17 370.00 X
10 2 TAIL GATE LOCK CATCH	167.40 17 334.80 X
11 1 REAR WIPER MOTOR 980	best/you 1,105.00 ✓
12 1 REAR WIPER ARM 180	cut 325.00 ✓
13 1 REAR WIPER BLADE	17 115.00 X
14 1 TAIL LAMP LH	17 287.00 X
15 1 REAR END PANEL	neu 910.00 X
16 1 REAR BUMPER TOP GARNISH	de/cue 322.00 ✓
17 1 REAR BUMPER 1528.31	no 2,160.00 ✓
18 1 REAR BUMPER LOWER SPOILER 434.30	to-in 747.00 ✓
19 1 REAR BUMPER REFLECTOR LH	17 164.00 X
20 2 REAR BUMPER SIDE RETAINER	74.00 17 148.00 X
21 2 REVERSE SENSOR 194X2=388	should 500.00 ✓
22 1 REAR EXHUAUST MUFFLER	neu 924.00 X
	S 16,071.50

10%

LABOUR & MISCELLANEOUS:

AMOUNT S\$

1	To remove damaged parts with all necessary components/attachments apply hot-works where necessary replace new parts align into position	600	1,200.00
2	To spray paint replaced/repared body panels inclusive of preparatory works and painting materials	600	800.00
3	To transfer tail gate components with all necessary attachments	80	150.00
4	To remove,replace rear windscreen glass and water test	120	150.00
5	To install reverse sensor and check funtion	30	100.00
			<u>2,400.00</u>
			\$ 2,400.00

GRAND TOTAL : \$ 18,471.50

**SINGAPORE DOLLARS : EIGHTEEN THOUSAND FOUR HUNDRED
SEVENTY ONE & CENTS FIFTY ONLY**

P-746681

102
6720.21

S.N-40

1040-1430

8190.21

6522.16

Insurance Company will advise notify
insured party of following:
 • To provide cost of temporary painting
 • To provide temporary part(s) during resurvey
 • To provide subject to confirmation
 • To provide survey is on a "Without Prejudice" basis
 • To provide modification is allowed
 • To provide items must be resurveyed and
 at Insured's Total approval from Insurance Company

Authorised by Reparer
 Signature:
 Date:

Vfix Auto Service Pte Ltd



Shu Pei (LKKAuto)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Thursday, 30 August 2018 3:59 PM
To: Shu Pei (LKKAuto)
Subject: RE: Direct Settlement - Accident Involving YN9474L (OI : CTI - SNM18D03918C02) AND SKC3845M (TP : LKK REF - CC6/CTI18014806/Ujb3) on 11.08.2018
Attachments: leeSZ_SNM18D03918C01-YN9474L-LKKDirectSettlementAccidentLtr_CLCR95.099.pdf; MCHM18104428-YN9474L.pdf

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Chong Boon Sen

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175/6224 7478
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Thursday, 23 August, 2018 5:25 PM
To: Claims Dept of CTI
Cc: Chong Boon Sen; Lucas Lee; Joy Irene (LKKAuto); Admin A
Subject: Direct Settlement - Accident Involving YN9474L (OI : CTI - TBA) AND SKC3845M (TP : LKK REF - CC6/CTI18014806/Ujb3) on 11.08.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SKC 3845M at M/s Vfix Auto Service Pte Ltd.

Enclosed for your perusal is:

- TP GIA report
- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action

Kindly take note that the case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springvale Tower Singapore 079908
Tel: 6289 6111 Fax: 6222 1033
Website: www.ctaiping.com
Co. Reg. No. 30008384E

Our Reference: **SNM18D03918/C01/4**

Date: **30 AUGUST 2018**

via Ordinary & Registered Mail

**AGAPE LOGISTICS PTE LTD
30 SENOKO SOUTH ROAD**

SINGAPORE 758088

Dear Sir / Madam

**ACCIDENT INVOLVING YN9474L AND SKC3845M ON 11 AUGUST 2018
ALONG TOA PAYOH SLIP ROAD TOWARDS PIE**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SKC3845M**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,

Claims Department

(This is a computer generated letter and no signature is required.)

CC: LKK Auto Consultants Pte Ltd

Attn: JOY

Ref: CC6/CTI18014806/UJB3

Contact No: 68412409

via Email: JOY@LKKAUTO.COM

CC: Agent - (AN0365A) - HIGH POWER ENTERPRISE

F01/LKKDS-2013

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Monday, 8 July 2019 4:28 PM
To: 'SAM@AGAPELOGISTICS.SG'
Cc: Admin A
Subject: ACCIDENT INVOLVING YN 9474L AND SKC 3845M ON 11/08/2018

OUR REF: CC6/CTI18014806/Ukb3
YOUR REF: YN 9474L [DRIVER: ZHANG BAOLEI]

AGAPE LOGISTICS PTE LTD
[ATTN: THE MANAGEMENT]

Dear Sir/Madam,

ACCIDENT INVOLVING YN 9474L [CTI] AND SKC 3845M ON 11/08/2018

We refer to the above accident where we are acting for **China Taiping Insurance (Singapore) Pte Ltd** to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Tuesday, 17 December 2019 11:06 AM
To: wskoh@vfixauto.com.sg
Cc: ybsim@vfixauto.com.sg; jessicassy@vfixauto.com.sg; jeffbz@vfixauto.com.sg; alanclk@vfixauto.com.sg; kentsh@vfixauto.com.sg; Admin A
Subject: RE: ACCIDENT INVOLVING SKC3845M & YN9474L ON 11/08/2018
Attachments: CTI DV.pdf

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

Thank you for the acceptance.

We attach herewith a copy of the DV.

Kindly send us (LKK) all the documents below for our necessary action: -

- **Original LOD**
- **Original Final Repair Tax Invoice, Rental Agreement and Invoice**
- **Original Letter of Authorisation & hardcopy of the DV**

Thank you.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: wskoh@vfixauto.com.sg <wskoh@vfixauto.com.sg>
Sent: Wednesday, 11 December 2019 11:49 AM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Cc: ybsim@vfixauto.com.sg; jessicassy@vfixauto.com.sg; jeffbz@vfixauto.com.sg; alanclk@vfixauto.com.sg; kentsh@vfixauto.com.sg; Admin A <admin-a@lkkauto.com>

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: wskoh@vfixauto.com.sg <wskoh@vfixauto.com.sg>

Sent: Wednesday, 11 December 2019 10:36 AM

To: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Cc: ybsim@vfixauto.com.sg; jessicassy@vfixauto.com.sg; jeffbz@vfixauto.com.sg; alanclk@vfixauto.com.sg; kentsh@vfixauto.com.sg; Admin A <admin-a@lkkauto.com>

Subject: RE: ACCIDENT INVOLVING SKC3845M & YN9474L ON 11/08/2018

Dear Khanchna,

Noted with thanks!



Remark: W.e.f 22nd April 2019, our office has been relocated to 26, Chia Ping Road, Singapore 619977. Please update your record with the following: Company contact number - 6455 2957 ; Company general email - contact@vfixauto.com.sg

Thanks & Regards,

Weng Sheng

Motor Claim Operation Admin

Vfix Auto Pte Ltd | Vfix Auto Service Pte Ltd | Vfix Leasing Pte Ltd

26 Chia Ping Road Singapore 619977

Contact: 6455 2957 | E: wskoh@vfixauto.com.sg

From: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Sent: Wednesday, 11 December 2019 10:27 AM

To: wskoh@vfixauto.com.sg

Cc: ybsim@vfixauto.com.sg; jessicassy@vfixauto.com.sg; jeffbz@vfixauto.com.sg; alanclk@vfixauto.com.sg; kentsh@vfixauto.com.sg; Admin A <admin-a@lkkauto.com>

Subject: RE: ACCIDENT INVOLVING SKC3845M & YN9474L ON 11/08/2018

WITHOUT PREJUDICE

VFIX AUTO SERVICE PTE LTD

26 CHIA PING RD
SINGAPORE 619977
UEN / GST REG NO.: 201602964H
TEL: +65 6455 2957 FAX: +65 6862 8669
E-MAIL: CONTACT@VFIXAUTO.COM.SG

**TAX INVOICE**

Co. Name : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
Address : 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Account No. : 300-C025
Invoice No. : **VS2001003**
Date : 15/01/2020
Due Date : 15/01/2020
Terms : C.O.D.
Page : 1 of 1

Attn :
Tel : 63896111 FAX :

VEHICLE NO. : SKC3845M MODEL : VOLVO XC60

Item	Description	Tax Code	Qty	U/ Price S\$	Total S\$
1.	INSURANCE CLAIMS (TP) TP CLAIMS AGAINST YN9474L DOA : 11/08/2018 COR : \$7,008.50 LOU : \$600.00 LTA SEARCH FEE : \$2.00 REFER TO TP20180513	SR	1	7,112.62	7,112.62

SUB TOTAL **7,112.62**

GST TOTAL 7% **497.88**

TOTAL WITH GST **7,610.50**

1. Payment can be made by Cash, Cheque, Credit Card, Nets, GIRO or bank Transfer.
2. Cheque should make crossed "A/C PAYEE" to **VFIX AUTO SERVICE PTE LTD** Bank Tranfer or GIRO, please make your payment to:
Account Name : VFIX AUTO SERVICE PTE LTD
Bank Name : DBS
Bank Account No : 003-940722-0
3. Credit Card Instalment is available upon request. Only available for DBS Credit Card Holder.
4. Please quote the invoice No. when making payment.
5. Any errors or discrepancies on this invoice discovered should be made known to us within 7 days from the date of invoice.

YEEBING

Prepare By

Verified By

Approved By





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18014806/Uka3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 22-01-2020	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	YV 9474L	Veh. Inspected
			SKC 3845M
	Policy No.	DMCVSN1663671701	Coverage (\$)
			0.00
	Claim No.	SNM18D03918C02	Excess (\$)
			0.00
	Assign From		Assign Date
			21/08/2018
2. Vehicle Particulars & Condition			
	Make & Model	VOLVO XC60 (A)	c.c
			1999
	Engine No.	HIDDEN	Year of Reg.
			2011
	Chassis No.	YV1DZ475BB2181924	Colour
			BROWN
	Odometer	180558	Steering
			IN ORDER
	Brakes	IN ORDER	Modification
			SPORTS RIM
	General	GOOD	
3. Conditions of Tyres			
		Size	Make
			Balance
	R/H Front Tyre	235/60 R18	NEXEN
			6 mm
	L/H Front Tyre	235/60 R18	NEXEN
			6 mm
	R/H Rear Tyre	235/60 R18	NEXEN
			6 mm
	L/H Rear Tyre	235/60 R18	NEXEN
			6 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.		
	DAMAGES SEE DETAILS.		
5. General Information			
	Accident Date	11/08/2018	Inspection Date
			21/08/2018
	Survey held at	VFIX AUTO SERVICE PTE LTD	
		60 KAKI BUKIT AVE 6, ARK@KB, 417892 KAKI BUKIT	
		SINGAPORE 417892	
5a. Remarks			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.		
	B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 3845M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN GLASS	NOT NECESSARY	1,343.70	-
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	265.00	166.00
1	TAIL GATE	DENTED / CRACKED	5,157.00	3,123.30
1	TAIL GATE EMBLEM XC60	NECESSARY	135.00	125.00
1	TAIL GATE EMBLEM T5	NECESSARY	135.00	115.00
1	TAIL GATE EMBLEM VOLVO	NECESSARY	369.00	105.00
1	TAIL GATE MOULDING	NOT NECESSARY	165.00	-
1	TAIL GATE LOCK	NOT NECESSARY	370.00	-
2	TAIL GATE LOCK CATCH @\$167.40	NOT NECESSARY	334.80	-
1	REAR WIPER MOTOR	BENT / JAMMED	1,105.00	980.00
1	REAR WIPER ARM	CUT	325.00	180.00
1	REAR WIPER BLADE	NOT NECESSARY	115.00	-
1	TAIL LAMP LH	NOT NECESSARY	287.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	910.00	-
1	REAR BUMPER TOP GARNISH	DEFORMED / CRACKED	322.00	322.00
1	REAR BUMPER	DENTED	2,160.00	1,528.31
1	REAR BUMPER LOWER SPOILER	TORN	747.00	434.30
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	164.00	-
2	REAR BUMPER SIDE RETAINER @\$74.00	NOT NECESSARY	148.00	-
2	REVERSE SENSOR	SHORTED	500.00	388.00
1	REAR EXHAUST MUFFLER	TO REPAIR SEE LABOUR	924.00	-
	LESS 10% DISCOUNT		-	-746.69
			15,981.50	6,720.22
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	90.00	40.00
			90.00	40.00

Report Ref No. CC6/CT118014806/Uka3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE DAMAGED PARTS WITH ALL NECESSARY COMPONENTS /ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY REPLACE NEW PARTS ALIGN INTO POSITION.INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR EXHAUST MUFFLER .		1,200.00	600.00
	TO SPRAY PAINT REPLACED/ REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS.		800.00	600.00
	TO TRANSFER TAIL GATE COMPONENTS WITH ALL NECESSARY ATTACHMENTS.		150.00	80.00
	TO REMOVE,REPLACE REAR WINDSCREEN GLASS AND WATER TEST.		150.00	120.00
	TO INSTALL REVERSE SENSOR AND CHECK FUNCTION.		100.00	30.00
			2,400.00	1,430.00
	GRAND TOTAL		18,471.50	8,190.22
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,550.00

Report Ref No. CC6/CTI18014806/Uka3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.