



Not Authorized  
2/5/18  
the photo is not  
21/8/18  
407.

Vfix Auto Service Pte Ltd  
60 Kaki Bukit Ave 6 Ark@KB  
Singapore 417892

Email : contact@vfixauto.com.sg  
Tel : 6448 9268 Fax: 6445 2368  
UEN / GST Reg No. : 201602964H

M/S CHINA TAIPING INS (S'PORE) PTE LTD  
3 ANSON ROAD  
#16-00 SPRINGLEAF TOWER  
SINGAPORE 079909

**ESTIMATE**

DATE : 14/08/2018  
ACC DATE : 11/08/2018  
REF NO : VFIX - TP20180513  
POLICY NO :

**Attention: Motor Claim Department**

**RE : VEHICLE NO.SKC3845M VOLVO XC60 T5**

| DESCRIPTION                           | AMOUNT S\$         |
|---------------------------------------|--------------------|
| 1 1 REAR WINDSCREEN GLASS             | 17 1,343.70 X      |
| 2 1 REAR WINDSCREEN GLASS SEALANT     | 90.00 —            |
| 3 1 REAR WINDSCREEN GLASS MOULDING    | 265.00 —           |
| 4 1 TAIL GATE                         | 2,486.00 —         |
| 5 1 TAIL GATE EMBLEM XC60             | 75.00 —            |
| 6 1 TAIL GATE EMBLEM T5               | 75.00 —            |
| 7 1 TAIL GATE EMBLEM VOLVO 105        | 205.00 —           |
| 8 1 TAIL GATE MOULDING                | 17 165.00 X        |
| 9 1 TAIL GATE LOCK                    | 17 370.00 X        |
| 10 2 TAIL GATE LOCK CATCH             | 167.40 17 334.80 X |
| 11 1 REAR WIPER MOTOR                 | 1,105.00 ?         |
| 12 1 REAR WIPER ARM                   | CU 325.00 —        |
| 13 1 REAR WIPER BLADE                 | 17 115.00 X        |
| 14 1 TAIL LAMP LH                     | 17 287.00 X        |
| 15 1 REAR END PANEL                   | 910.00 ?           |
| 16 1 REAR BUMPER TOP GARNISH          | 17 322.00 X        |
| 17 1 REAR BUMPER                      | 1,454.80 —         |
| 18 1 REAR BUMPER LOWER SPOILER 434.30 | 71.7 486.40 —      |
| 19 1 REAR BUMPER REFLECTOR LH         | 17 164.00 X        |
| 20 2 REAR BUMPER SIDE RETAINER        | 74.00 17 148.00 X  |
| 21 1 REVERSE SENSOR 194 x 2 = 388     | 500.00 —           |
| 22 1 REAR EXHUAUST MUFFLER 107        | 924.00 X           |
|                                       | \$ 12,150.70       |

| LABOUR & MISCELLANEOUS: |                                                                                                                                            | AMOUNT S\$    |
|-------------------------|--------------------------------------------------------------------------------------------------------------------------------------------|---------------|
| 1                       | To remove damaged parts with all necessary components/attachments<br>apply hot-works where necessary replace new parts align into position | 600 1,200.00? |
| 2                       | To spray paint replaced/repaired body panels inclusive of preparatory<br>works and painting materials                                      | 600 800.00    |
| 3                       | To transfer tail gate components with all necessary attachments                                                                            | 20 150.00     |
| 4                       | To remove,replace rear windscreen glass and water test                                                                                     | 120 150.00    |
| 5                       | To install reverse sensor and check funtion                                                                                                | 30 100.00     |
|                         |                                                                                                                                            | \$ 2,400.00   |
| GRAND TOTAL :           |                                                                                                                                            | \$ 14,550.70  |

SINGAPORE DOLLARS : FOURTEEN THOUSAND FIVE HUNDRED FIFTY  
& CENTS SEVENTY ONLY

Vfix Auto Service Pte Ltd



LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: