

LKK AUTO CONSULTANTS PTE LTD

51 Ubi Ave1, #01-25 Paya Ubi Industrial Park, Singapore 408933.

TEL : 6256 3561

FAX : 6256 4315

Reg. No: 199607198R

GST Reg. No. 19-9607198-R

MINISTRY OF DEFENCE
HQ-TRANSPORT COMMAND
KRANJI CAMP 3
151 CHUA CHU KANG WAY
SINGAPORE 688248

REF No. CC2/MIDA18014816/Gpq2

REF Date 22/01/2019

Code MIDA

DISBURSEMENT FEE

Vehicle No. **MID 20599**
Insured
Claim No **FY 18/19/0022**
Policy No
Accident Date **7/8/2018**
Inspection Date **13/8/2018**

<u>LKK Cost of Claim paid to claimant on behalf of MINDEF</u>		
Repair Cost of FZ 356R	\$	4,100.00
GST paid to claimant on behalf of MINDEF	\$	287.00
Loss of Use (4 days x \$30.00)	\$	120.00
Towing Fee	\$	80.00
Total Fee	\$	4,587.00

We shall be glad if you could forward us the payment at your early convenience.

Cheque should be crossed and made payable to "**LKK AUTO CONSULTANTS PTE LTD**".

LKK AUTO CONSULTANTS PTE LTD

CHEW LIAN