

Addendum Sheet

**GENERAL
INSURANCE
ASSOCIATION**

GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel: 651 8228 0000 Fax: 651 6724 0000
Operating Hours: Monday to Friday, 09:00 - 17:00
UEN: S65106285 / GST Reg. No: M400817715

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MPA 118102339 Vehicle Registration No: SMB 1109 P
Name (as shown on NRIC) : Tan Anand Lee NRIC/FIN/Passport No : 574878384
(* Vehicle Driver / Vehicle Owner) (* Please delete as appropriate
Address : APT BLK 79D TOA PAYOH CENTRAL #17-47 31079
11/15a Belfry / Central / Toa Payoh / Singapore
Contact (Tel) : _____ Mobile No. : 97877551
Email Address : tanan@malacorp.com.sg
Date of Accident : 07/08/18 Time of Accident : 12:56
Place of Accident : Bedok Rd Corridor
Insurance Company : AGS AND PACIFIC INSURANCE PTE LTD

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Want reporting only to own Damage Claims

Policyholder / Driver's Signature
Date: 16/8/18

Reporting Centre Personnel's Signature
Name: Wendy KHEAH SEAH, Wendy
NRIC/FIN No: 62927432
Date: 16/8/18

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/08/2018 08:48
Date Of Accident	07/08/2018 07:55
Exact Location Of Accident	DUXTON ROAD CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD1109P
Insured/Policyholder	
Name Of Registered Owner	TAN SHEN LEK
NRIC No	S7487828H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97877551
Alternative Phone No	OFFICE-97877551

Vehicle Particulars

Manufacturer	AUDI
Model	A4 SEDAN 2.0 TFSI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800088788
Cover Note Number	


Driver

Name of Driver	TAN SHEN LEK
NRIC No	S7487828H
Date Of Birth	28/07/1974
Occupation	INDOOR
Date Of Driving Pass	20/02/2009
Driving Experience	9 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97877551
Fax Number	
Contact Number	OFFICE-97877551
Email Address	NOEMAIL

No. Of Passenger (Including Driver)

Sketch Plan #2

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car was parked and found damaged upon return.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Lyle Lee Soney
NIC/ID No: 6550360

Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Police Report



**SINGAPORE
POLICE FORCE**



1 05188070159

1 of 3

Police Station Of Origin
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

Report No: T3001902070159

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 07/08/2018 18:29	Video Report No.	Station Diary No. 192
---	------------------	--------------------------

Informant's Particulars

Name of Informant TAN SHEN LEE			Address APT BLK 79D TOA PAYOH CENTRAL #17-47 SINGAPORE 214079		
ID Type / ID No NRIC NO: S7487828H			Contact No Home/Office: Mobile: 97877651		
Nationality MALAYSIAN			Email		
Sex Male	Age 44	Date of Birth 28/07/1974	Type of Informant Driver		
Race Chinese			Language English		Institution / School Name
Occupation SALES DIRECTOR			Driving Licence Information Class: 3		Date of Expiry

General Information of the Accident

Type of Accident Non-Injury Hit and Run	Drink Drive No	Date/Time of Accident 07/08/2018 12:55	Type of Location Car Park
Location Along Road 1 DUXTON HILL			
Open space carpark, in front of No 2 Duxton Hill			
Weather Clear		Road Surface Dry	Road Speed Limit
Traffic Flow Two Way		Traffic Control Not Controlled	Traffic Volume No Traffic
Type of Collision Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SMD1109P	Car	AUDI	A4 SEDAN 2.0 TFSI 5 TRONIC (NAV)	Grey	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SMD1109P	AIG ASIA PACIFIC INSURANCE PTE LTD	1800088788	01/08/2018	31/07/2020

Accident Photo

 SINGAPORE POLICE FORCE		 T201808072186
Police Station Of Origin Tee Payoh N P C 93 Tee Payoh Central #01-02 Tee Payoh Community Building SINGAPORE 319194 Tel No. 1800-3519999		3 of 3 Report No. T201808072186
CONTINUATION OF REPORT		
Sketch Plan Informant is not able to provide sketch plan.		
IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474855 stating the <u>report number</u> as reference.		
Signature Of Officer Recording The Report E SI KAMAL BIN KAMIS	Signature Of Informant 	
Signature Of Interpreter Not applicable	Date/Time 07/08/2018 18:26	
Officer In Charge Of Case TP / HRT / SSI GOH GEOK LYE Contact No : 65476148	Classification Of Case 34 165	
Authentication Stamp SP1808	 RESISTANCE	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0914/2018/PH
Date : 10-Aug-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Tan Shen Lek
Address : Blk 79D Toa Payoh Central
#17-47
Singapore 314079
Telephone : HP +65 97877551
Type of Claim : Own Damage claims
Policy No. : 1800088788
Vehicle No : **SMD 1109 P**
Model Code : Audi A4 SEDAN 2.0 TFSI
Model / Year : Aug-18
Engine No : CVK 063736
Chassis No : WAUZZZF40JA186949
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 7-Aug-18
Place of Accident : Duxton Road carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMD 1109 P.

<u>S/N</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and transfer rear parking aid and rear lid kick sensor.	S/N \$ 360.00 ✓	✓
2	To dismantle and renew rear bumper.	\$ 900.00 500 ✓	
3	To respray rear bumper.	\$ 800.00 550 ✓	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 2,252.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SFC 13 B.**

SDM1109P

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
1	BUMPER COVER <i>rebad</i>	\$ 1,907.00 ✓	1525.60
2	FIXING PARTS FOR BUMPER	\$ 63.00 ✗	
3	SECURING STRIP	\$ 191.00 ✗	
4	SPOILER	\$ 216.00 ✗	
5	REAR LIGHT REFLECTOR - LH/RH	2 \$ 70.00 ✗	
6	BUMPER CARRIER	\$ 786.00 ✗	
7	SEAL	2 \$ 24.00 ✗	
8	GUIDE SECTION - LH/RH	2 \$ 76.00 ✗	
9	GUIDE SECTION - LH/RH	2 \$ 38.00 ✗	
10	SENSOR - REAR INNER/OUTER	2 \$ 421.00 ✗	
11	SUNDRIES ? <i>nn</i>	\$ 300.00 ? ✗	
TOTAL SPARE PARTS		: \$ 4,092.00	
TOTAL LABOUR CHARGES		: \$ 2,252.00	
GRAND TOTAL		: \$ 6,344.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Adrian King
15/08/18

: ~~Not~~ Authorised Repairs, 03 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 22 October 2018 10:29 AM
To: Boo seng yak; Carrine Leong; jiayee.yap@premiumauto.com.sg; Chang Chee Sing;
SUR
Subject: RE: FINAL REVISION - SMD1109P - OD AIG - SURVEYED 15 AUG 18

Dear Mr Boo,

Repair cost of \$3,127.60 before excess \$600 @ 3 days of repairs.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Friday, 19 October 2018 2:31 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong
<carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing
<claims@premiumauto.com.sg>
Subject: FINAL REVISION - SMD1109P - OD AIG - SURVEYED 15 AUG 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$3127.60 @ 3 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0914/2018/PH
Date	:	10-Aug-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

3 days - ok - jb - 19 Oct 18

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Tan Shen Lek
Address	:	Blk 79D Toa Payoh Central #17-47 Singapore 314079
Telephone	:	HP +65 97285342
Type of Claim	:	Own Damage Claims
Policy No.	:	1800088788
Vehicle No	:	SMD 1109 P
Model Code	:	Audi A4 Sedan 2.0 TFSI
Model / Year	:	Aug-18
Engine No	:	CVK 063736
Chassis No	:	WAUZZZF40JA186949
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	7-Aug-18
Place of Accident	:	Duxton Road carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMD 1109 P.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor.	S/N	\$ 360.00	\$ 360.00
2	To dismantle and renew rear bumper.		\$ 900.00	\$ 500.00
3	To respray rear bumper.		\$ 800.00	\$ 550.00
4	To carry out diagnostic check	S/N	\$ 192.00	\$ 192.00
	TOTAL LABOUR CHARGES	:	\$ 2,252.00	\$ 1,602.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMD 1109 P.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	BUMPER COVER	\$ 1,907.00	\$ 1,525.60
2	FIXING PARTS FOR BUMPER	\$ 63.00	
3	SECURING STRIP	\$ 191.00	
4	SPOILER	\$ 216.00	
5	REAR LIGHT REFLECTOR - LH/RH	2 \$ 70.00	
6	BUMPER CARRIER	\$ 786.00	
7	SEAL	2 \$ 24.00	
8	GUIDE SECTION - LH/RH	2 \$ 76.00	
9	GUIDE SECTION - LH/RH	2 \$ 38.00	
10	SENSOR - REAR INNER/OUTER	2 \$ 421.00	
11	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS CHARGES		\$ 4,092.00	\$ 1,525.60
TOTAL LABOUR CHARGES		\$ 2,252.00	\$ 1,602.00
GRAND TOTAL		\$ 6,344.00	\$ 3,127.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SMD 1109 P

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0914/2018/MAS

20 Nov 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SMD 1109 P, Audi A4 Sedan 2.0 TFSI

With reference to the above-mentioned vehicle, no **SMD 1109 P**, claimant,
Mr. Tan Shen Lek @Tan Sheng Lek, please find the related document per
attached.

1. A copy of the Original invoice no. 85013124 – S\$2,704.53
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the
payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at
6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SMD 1109 P

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6386 2223
Page 1 16:11

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6388 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408683
Telephone: 6388 2223
Telefax: 6341 1181

Customer Service
Service Appointment
Without Breakdown Service
Email: customer.care@premiumauto.com.sg

6366 2323
9828 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013124
Date: 12/11/2018
Order: SMD1109P
Term: 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SMD1109P (V 38793)

Regn Date: 01/08/2018

Mileage: 2380

WIP No.: 20643

Model: A4 SEDAN 2.0 TFSI 8W2ADG (NAV, Chassis: WAUZZZF40JA106949

Engine: CVK 063736

Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee

(33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888			
S	BODYWORK	Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW REAR BUMPER. REORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	500.00	1.00	500.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER	550.00	1.00	550.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8W5807067A GRU	COVER Less 020%	1.00	1907.00	1,525.60
Parts					1,525.60
Labour					0.00
Sublet					1,602.00
Menus					0.00
Lubricant					0.00
				Sub-Total	2,527.60
				7% GST	176.93
				Grand Total	2,704.53

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SMD 1109 P

Norah Khai
6768 9828
6841 1183

Body Repair
PA/OD/0914/2018/GW
06 September 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 SEDAN 2.0 TFSI
Vehicle Chassis No. : WAUZZZF40JA186949
Vehicle Regn No. : SMD 1109 P
Vehicle Mileage : 2380 KM
Vehicle Owner : Mr. Tan Shen Lek
Certificate No : 1800088788
Policy Excess : S\$642.00 (Inclusive GST)
Accident Date : 07 of August 2018
Place : Duxton Road Carpark
Repair Cost : \$ 2,704.53
WIP No. : 20643
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 

Time : 1900

Date : 6/9/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Aug 2018		15 Aug 2018 13:20 Edit Adj Rpt	S\$3,127.60 Edit Estimates	S\$3,127.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured: TAN SHEN LEK , ID: S7487828H, Tel: +6597877551, Email: NOEMAIL									
Vehicle Reg. No.: SMD1109P		Date of Loss: 07/08/2018 07:00 - :59 [6 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 5369147792SG		Policy/Cover Note No.: 1800088788 (Comprehensive)							
		Excess: S\$600.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 27/08/2018]									
Driver/Custodian: TAN SHEN LEK (44 / Male), NRIC: S7487828H, Tel: +6597877551									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
• AIG_SG (17/08/2018): SMD1109P / OD / 07/08/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMD1109P (5369147792SG)**
OD
Aug 7 2018 7:55AM
[TAN SHEN LEK]
Premium Automobiles Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#)

1 per page
☒

Video

No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	08/08/18 08:59	Video - Accident [Linked Accident Report Documents]	Load MP4	
2	08/08/18 08:59	Video - Accident [Linked Accident Report Documents]	Load MP4	

1 per page
☒

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/08/18 09:05	General View	Load JPG	☒
2	17/08/18 09:05	General View	Load JPG	☒
3	17/08/18 09:05	General View	Load JPG	☒
4	17/08/18 09:05	General View	Load JPG	☒
5	17/08/18 09:05	General View	Load JPG	☒
6	17/08/18 09:05	General View	Load JPG	☒
7	17/08/18 09:05	General View	Load JPG	☒
8	17/08/18 09:05	General View	Load JPG	☒
9	17/08/18 09:05	General View	Load JPG	☒
10	17/08/18 09:05	General View	Load JPG	☒

1 per page
☒

Documentation

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/08/18 09:03	Singapore Accident Statement and Police Report	Load PDF	
2	17/08/18 09:04	Mark Estimate	Load PDF	
3	17/08/18 16:38	Certificate of Insurance	Load PDF	
4	17/08/18 16:38	Insured's Driving License	Load PDF	
5	30/11/18 15:33	DISCHARGE VOUCHER	Load PDF	
6	30/11/18 15:33	WORKSHOP INVOICE	Load PDF	

Linked Accident Report Documents

View [View in Browser](#)

1 per page
☒

Video

No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	08/08/18 08:59	Video - Accident	Load MP4	
2	08/08/18 08:59	Video - Accident	Load MP4	

1 per page
☒

Assessment Reports

No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	08/08/18 09:06	Accident Statement	Load HTM	
2	16/08/18 21:44	Addendum Sheet	Load JPG	☒
3	16/08/18 21:46	Accident Statement Addm. #1	Load HTM	

Video			1 per page	✓
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
			3 per page	✓
Photos/Images			Thumbnail	Print
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		
1	08/08/18 08:57	Accident Photo	Load JPG	✓
2	08/08/18 08:57	Accident Photo	Load JPG	✓
3	08/08/18 08:57	Accident Photo	Load JPG	✓
4	08/08/18 08:57	Accident Photo	Load JPG	✓
5	08/08/18 08:57	Accident Photo	Load JPG	✓
6	08/08/18 08:57	Accident Photo	Load JPG	✓
7	08/08/18 08:57	Accident Photo	Load JPG	✓
8	08/08/18 08:57	Accident Photo	Load JPG	✓
9	08/08/18 08:57	Accident Photo	Load JPG	✓
10	08/08/18 08:57	Accident Photo	Load JPG	✓
11	08/08/18 08:57	Accident Photo	Load JPG	✓
12	08/08/18 09:04	Police Report	Load JPG	✓
13	08/08/18 09:04	Accident Photo	Load JPG	✓
14	08/08/18 09:04	Accident Photo	Load JPG	✓
Documentation			1 per page	✓
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	08/08/18 09:02	Sketch Plan	Load JPG	✓
2	08/08/18 09:02	Sketch Plan #2	Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18014822/AVBS2

Date: 30/11/2018

REFERENCE

Insured/Claimant: TAN SHEN LEK Policy No: 1800088788
Date of Loss: 07/08/2018 Nature of Claim: OD Claim No: 5369147792SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMD1109P Engine No: CVK063736
Make & Model: AUDI A4, 2.0 (A) Chassis No: WAUZZZF40JA186949
Reg. Date: 01/08/2018 (Man. Year: 2018) Odometer: 855 km
Colour: Black
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$150,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,092.00	1,525.60	2,566.40	62.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,252.00	1,602.00	650.00	28.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,344.00	3,127.60	3,216.40	50.70
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	5,744.00	2,527.60	3,216.40	56.00
+ GST 7.00/7.00% (S\$)	402.08	176.93	225.15	56.00
Nett Amount (S\$)	6,146.08	2,704.53	3,441.55	56.00

INSPECTION

Date of Assignment: 15/08/2018
Date Inspected: 15/08/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER	Deformed	1,907.00 FS	*1,525.60 FS
2	1		*FIXING PARTS FOR BUMPER	Not Necessary	63.00 FS	*- FS
3	1		*SECURING STRIP	Not Necessary	191.00 FS	*- FS
4	1		*SPOILER	Not Necessary	216.00 FS	*- FS
5	2		*REAR LIGHT REFLECTOR - LH/RH	Not Necessary	70.00 FS	*- FS
6	1		*BUMPER CARRIER	Not Necessary	786.00 FS	*- FS
7	2		*SEAL	Not Necessary	24.00 FS	*- FS
8	2		*GUIDE SECTION - LH/RH	Not Necessary	76.00 FS	*- FS
9	2		*GUIDE SECTION - LH/RH	Not Necessary	38.00 FS	*- FS
10	2		*SENSOR - REAR INNER / OUTER	Not Necessary	421.00 FS	*- FS
11	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					4,092.00	1,525.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER.	New	900.00	500.00
3	TO RESPRAY REAR BUMPER.	New	800.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (S\$)			2,252.00	1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >