

ASS. REC. BY:

REF: CS/CTL18014836/Tlgbn2 Special Instruction:

ASSIGNMENT (Office)

From (Person): Elaine Cheong of CTL Date/Time: 15082018 9:19am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 96N 3736J Insured: SKF 5845J

at Workshop m/s Auto Wheels Tel:

of Blk 1 Bukit Butok Crescent #02-40

Policy No: DmpCSN3058681803 Claim No: SNM18D0390802

Sum Insured: Excess:

Make of Veh: D.O.A. 73082018
(Client's Record)

CA / REV / REP. / REV 24 HRS WP H.O.D. Endorsement:

Date/Time: 15082018 10:01am Person Contacted: Louis Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	96N 3736J - NAI / INC080D3636/W1 DUA: 08032008
	SKF 5845J - CS/CTL18000758/Rlv3n2 DUA: 10012018
17/10/18@	3.19pm confirmed with Louis LS to 1600, 4 days. Cred to 7258.63, 82/0.

No photo upload

Tanpoh


TRIP

CTI

ACTUAL

605 2021 Nov

Brand: _____ Date: _____
 Estimated Cost: _____
 GO / TP / WS / TP RES / OD RES / EVA / INV / MV
 Insured: _____
 Policy No: _____
 Claim No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. of Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GNA / EP Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Turn Over: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS **WP.**
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT
 Date / Time: _____ Action / Instruction: _____



Veh No: **SGN 3736J** Reg No: **2006 Nov**
 Type: M/C or / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Toyota Camry** Year: **1998**
 Colour: **Silver** Insured / Std / NI / NA
 Cap. Rating: **156812.** (Radio) Insured / Std / NI / NA
 Eng/No: _____
 C/No: **MR053BK 4107004044**
 Gen. Cond: **G** Good / Fair / Poor / Burnt
 Steering: **G** Inboard / Jammed / Leaked / Burnt or
 Brake: **G** Inboard / Jammed / Leaked / Burnt or
 Mod: **G** Nil / S/Rim / STD A/Rim or
 Tyre Size: F: **215/60R16**
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: **0** mm R/Bal: **6** mm
 L/Bal: **6** mm L/Bal: **6** mm
 D.O.A: _____ D.O.I: **20/8/18 @ 1555**
 Survey held at: **Autobooks Bht Bth**
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
Rear o/s
 The UIC / Chassis frame / Body Structure affected due to collision:

RECEIVED 12 OCT 2018.

Date/Time: Pre Pass to? : Preli. Report

12/10/18 : Final Report

Date/Time: Late Return to?

Days Of Repair: **4**

Resurvey No. of Trip: **1**

Survey Fee

Transportation

Report Format

Lump Sum / LPT

MER-TP 1600

Add Fee: Data Insp. (\$)

Interest (\$)

Tech. Fee (\$)

24 Hrs. (\$)



220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Aug 2018		15 Aug 2018 09:19 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAN JUN YUAN (CHEN JUNYUAN), ID: S8208259Z		
Main Claimant:	LEE WEE KIT MRS GIN WEE KIT, ID: S0272994F		
Vehicle Reg. No.:	SGN3736J	Date of Loss:	13/08/2018 12:00 - :59
Claim Type:	TP / SNM18D03908C02	Policy/Cover Note No.:	DMPCSN3038681803 (Comprehensive)
Vehicle Reg. No. (Insured):	SKF5845J	Policy No. (Claimant):	5024339263-10
		Excess:	S\$0.00
Repairer:	Auto Wheels Motorworks Pte Ltd (HQ) No.1 Bukit Batok Crescent, #02-40 WCEGA PLAZA, 658064 Bukit Batok - Tel: 97684247		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/08/2018]		
Driver/Custodian (Insured):	TAN JUN YUAN (CHEN JUNYUAN) (36 / Male), NRIC: S8208259Z		
Adj Asg. Remarks:	NO EST, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 12 October 2018 3:19 PM
To: 'Louis Ong'; Taufikh (LKKAuto)
Cc: SUR
Subject: RE: Finalize for vehicle SGN3736J lumpsum \$1,600.00 with 4 repair days before GST

Dear Louis,

WITHOUT PREJUDICE

Confirm Lump Sum \$1,600.00 before GST and 4 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Louis Ong <louisongautowheels@yahoo.com>
Sent: Saturday, 15 September 2018 10:03 AM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: Finalize for vehicle SGN3736J lumpsum \$1,600.00 with 4 repair days before GST

Hi Morning Taufikh,

The above attachment is the finalize and after paint photo.

Can help to Finalize for vehicle SGN3736J lumpsum \$1,600.00 with 4 repair days before GST .

No Supplementary.

Please check and revert.

Thanks

Auto Wheels Motorworks PTE LTD
Louis Ong
91928963

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/08/2018 09:03
Date Of Accident	13/08/2018 12:35
Exact Location Of Accident	RIVER VALLEY ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGN3736J
Insured/Policyholder	
Name Of Registered Owner	LEE WEE KIT MRS GIN WEE KIT
NRIC No	S0272994F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94361700
Alternative Phone No	OFFICE-94361700

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5024339263-10
Cover Note Number	

Driver

Name of Driver	GIN HOEY KWAN HOONG KEVIN
NRIC No	S1679468F
Date Of Birth	24/05/1963
Occupation	INDOOR
Date Of Driving Pass	18/01/1982
Driving Experience	36 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94361700
Fax Number	
Contact Number	OFFICE-94361700
EEmail Address	NOEMAIL

Address 62 WHITE HOUSE PARK
 Postcode S257627
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured PARENT
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : -
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE SEE ATTACHED STATEMENT FROM OWNER

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKF5845J
 Vehicle Make/Model/Colour AUDI
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver TAN
 NRIC/Passport Number
 Contact Number 91879147
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	ER35X
Vehicle Make/Model/Colour	AUDI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LAU
NRIC/Passport Number	
Contact Number	96338332
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

14 AUG 2018

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vachb@singnet.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT WCEGA PLAZA

#02-40 SINGAPORE 608064

ATTN: CHINA INSURANCE

DATE: 14/08/2018
 VEHICLE NO: SGN3736J
 MODEL: CAMRY
 YEAR: 2006-2021
 ACCIDENT DATE: 13/08/2018
 TYPE OF CLAIM: TP CLAIM
 CLAIM ADVISOR: LOUIS ONG (91928963)
 EMAIL: louisongautowheels@yahoo.com

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
BOOTLID	1	R RESTORE
BOOTLID LAMP	2	\$491.60
REAR EMBLEM	1	Not consistent with accident. NX \$55.40
REAR LOGO - CAMRY	1	\$43.30
REAR LOGO - 2.0	1	\$41.20
BOOTLID OUTER CHROME GARNISH	1	\$315.80
REAR BUMPER	1	del ✓ \$719.30
REAR BUMPER CLIPS	10	new ✓ \$30.00
REAR BUMPER RETAINER - OUTER	1 ✓	LH - X NN RH - new ✓ \$84.80 42.40
REAR BUMPER REFLECTOR	2	NNX ✓ \$390.40
TAILLAMP	1 ✓	LH - X NN, RH - new ✓ \$948.20 474.10
TAILLAMP LOWER PANEL	2	R RESTORE
REAR WEATHER STRIP	1	X \$156.70
END PANEL TOP GARNISH	1	M X \$178.90
REAR REINFORCEMENT	1	X \$412.80
END PANEL	1	R X \$695.70
SPARE TYRE PANEL	1	X RESTORE
SPARE TYRE BOARD	1	X \$361.20
RH REAR FENDER	1	RESTORE
REAR EXHAUST PIPE	1	X \$930.50
REAR EXHAUST PIPE FINISHER	1	X \$315.70

TOTAL: \$6,171.50
 DISCOUNT 25%: \$1,542.88
\$4,628.63

S/NET		PRICE
REVERSE SENSOR	1	200? \$250.00 X ¹¹¹
END PANEL SEALANT	1	X \$100.00 ¹¹¹
		<u>\$350.00</u>

LABOUR	PRICE
LABOUR FOR FACILITATE REPAIR - REAR	500 \$1,600.00
TO RESRAY AFFECTED AREAS - BOOTLID	111 X \$300.00
TO RESPRAY AFFECTED AREAS - REAR BUMPER	200 \$300.00
TO RESPRAY AFFECTED AREAS - END PANEL	111 X \$300.00
TO RESRAY AFFECTED AREAS - SPARE TYRE PANEL	111 X \$300.00
TO RESPRAY AFFECTED AREAS - RH REAR FENDER	200 \$300.00
TO REMOVE AND REFIT REAR EXHAUST PIPE	111 X \$300.00
RUST PROOFING	30 \$80.00
SUNDARIES	30 \$50.00 ^{nec}
TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR	60 \$200.00
TO REMOVE AND REFIT REVERSE SENSOR	30 \$100.00
TO CHECK AND RECONNECT ALL NECESSARY WIRING	30 \$50.00
TOTAL:	\$3,880.00

TOTAL: \$8,858.63
 7% GST: \$620.10
\$9,478.73

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Taufik 97495749
 'WP'
 sur@lkkauto.com
 Resurvey after repair
 4 days
 20/8/18 @ 1535

[Signature]
 23/8/18

AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT WCEGA PLAZA

#02-40 SINGAPORE 608054

ATTN: CHINA INSURANCE

DATE: 14/08/2018
 VEHICLE NO: SGN3736J
 MODEL: CAMRY
 YEAR: 2006-2021
 ACCIDENT DATE: 13/08/2018
 TYPE OF CLAIM: TP CLAIM
 CLAIM ADVISOR: LOUIS ONG (91928963)
 EMAIL: louisongautowheels@yahoo.com

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
BOOTLID	1	RESTORE
BOOTLID LAMP	2	\$491.60 X
REAR EMBLEM	1	\$55.40 X
REAR LOGO - CAMRY	1	\$43.30 X
REAR LOGO - 2.0	1	\$41.20 X
BOOTLID OUTER CHROME GARNISH	1	\$315.80 X
REAR BUMPER	1	de ✓ \$719.30 ✓
REAR BUMPER CLIPS	10	res ✓ \$30.00 ✓
REAR BUMPER RETAINER - OUTER	1 ✓	LH-X RH-res ✓ \$84.80 42.40
REAR BUMPER REFLECTOR	2	X \$390.40 X
TAILLAMP	1 ✓	LH-X, RH-ov ✓ \$98.20 474.10
TAILLAMP LOWER PANEL	2	RESTORE
REAR WEATHER STRIP	1	X \$156.70 X
END PANEL TOP GARNISH	1	X \$178.90 X
REAR REINFORCEMENT	1	X \$412.80 X
END PANEL	1	R X \$695.70 X
SPARE TYRE PANEL	1	X RESTORE
SPARE TYRE BOARD	1	X \$361.20 X
RH REAR FENDER	1	RESTORE
REAR EXHAUST PIPE	1	X \$930.50 X
REAR EXHAUST PIPE FINISHER	1	X \$315.70 X

1,265.80

SGN/3736J

TOTAL:	\$6,171.50	1,265.80
DISCOUNT 25%:	\$1,542.88	316.45
	<u>\$4,628.63</u>	<u>949.35</u>

S/NET		PRICE
REVERSE SENSOR	1	200? \$250.00 X
END PANEL SEALANT	1	X \$100.00 X
		<u>\$350.00</u>

LABOUR		PRICE
LABOUR FOR FACILITATE REPAIR - REAR		500 \$1,600.00 /
TO RESRAY AFFECTED AREAS - BOOTLID		X \$300.00 X
TO RESPRAY AFFECTED AREAS - REAR BUMPER		200 \$300.00 /
TO RESPRAY AFFECTED AREAS - END PANEL		X \$300.00 X
TO RESRAY AFFECTED AREAS - SPARE TYRE PANEL		X \$300.00 X
TO RESPRAY AFFECTED AREAS - RH REAR FENDER		200 \$300.00 /
TO REMOVE AND REFIT REAR EXHAUST PIPE		X \$300.00 X
RUST PROOFING		30 \$80.00 /
SUNDARIES		30 \$50.00 /
TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR		60 \$200.00 /
TO REMOVE AND REFIT REVERSE SENSOR		30 \$100.00 /
TO CHECK AND RECONNECT ALL NECESSARY WIRING		30 \$50.00 /
		<u>\$3,880.00</u> / 1080

TOTAL:	\$8,858.63
7% GST:	\$620.10
	<u>\$9,478.73</u>

Parts - \$1,265.80
 25% - \$316.45
\$949.35

Labour - \$1,080
Total: \$2,029.35
LS: \$1,600 @ 4 days

Taufiq 97145749
 WP
 sur@kkanto.com
 Respray after repair
 4 days
 20/8/18 @ 1535

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18014836/T1QBN2

Date: 15/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3038681803
Claimant Vehicle No :	SGN3736J	Insured Vehicle No :	SKF5845J
Date of Loss:	13/08/2018	Nature of Claim:	TP
		Claim No:	SNM18D03908C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGN3736J	Engine No:	1AZE015073
Make & Model:	TOYOTA CAMRY, 2.0 (A)	Chassis No:	MR053BK4107004044
Reg. Date:	16/11/2006 (Man. Year: 2006)	Odometer:	156812 km
Colour:	Silver		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,028.62	979.35	4,049.27	80.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,830.00	1,050.00	2,780.00	72.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,858.62	2,029.35	6,829.27	77.09
Approved Total (Overridden) (S\$)		1,600.00		
(S\$)	8,858.62	1,600.00	7,258.62	81.94
+ GST 7.00/7.00% (S\$)	620.10	112.00	508.10	81.94
Nett Amount (S\$)	9,478.72	1,712.00	7,766.72	81.94

INSPECTION

Date of Assignment: 15/08/2018

Date Inspected: 20/08/2018 Inspected At:

Auto Wheels Motorworks Pte Ltd (HQ)
No.1 Bukit Batok Crescent, #02-40
WCEGA PLAZA
Singapore 658064

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Oct 2018)
Parts: 143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGN3736J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID (NPA)	Repair	0.00 FL	*- FL
2	2		*BOOT LID LAMP (NOT NECESSARY)	Not Consistent With The Impact	491.60 FL	*- FL
3	1		*REAR EMBLEM (NOT NECESSARY)	Not Consistent With The Impact	55.40 FL	*- FL
4	1		*REAR LOGO-CAMRY (NOT NECESSARY)	Not Consistent With The Impact	43.30 FL	*- FL
5	1		*REAR LOGO-2.0 (NOT NECESSARY)	Not Consistent With The Impact	41.20 FL	*- FL
6	1		*BOOTLID OUTER CHROME GARNISH (NOT NECESSARY)	Not Consistent With The Impact	315.80 FL	*- FL
7	1		*REAR BUMPER	Deformed	719.30 FL	*719.30 FL
8	10		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
9	1		*REAR BUMPER RETAINER-OUTER	Os Necessary/Ns Not Necessary	84.80 FL	*42.40 FL
10	2		*REAR BUMPER REFLECTOR	Not Necessary	390.40 FL	*- FL
11	1		*TAILLAMP	Os Cracked/Ns Not Necessary	948.20 FL	*474.10 FL
12	2		*TAILLAMP LOWER PANEL (NPA)	Repair	0.00 FL	*- FL
13	1		*REAR WEATHER STRIP	Not Necessary	156.70 FL	*- FL
14	1		*END PANEL TOP GARNISH	Not Necessary	178.90 FL	*- FL
15	1		*REAR REINFORCEMENT	Not Necessary	412.80 FL	*- FL
16	1		*END PANEL	Repair	695.70 FL	*- FL
17	1		*SPARE TYRE PANEL (NPA)	Not Necessary	0.00 FL	*- FL
18	1		*SPARE TYRE BOARD	Not Necessary	361.20 FL	*- FL
19	1		*RH REAR FENDER (NPA)	Not Necessary	0.00 FL	*- FL
20	1		*REAR EXHAUST PIPE	Not Necessary	930.50 FL	*- FL
21	1		*REAR EXHAUST PIPE FINISHER	Not Necessary	315.70 FL	*- FL
22	1		*REVERSE SENSOR	Not Necessary	250.00 FS	*- FS
23	1		*END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
24	1		*SUNDARIES	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,571.50	1,295.80
- List Item Discount on L Items 25.00/25.00% (S\$)	1,542.88	316.45
Total Parts (S\$)	5,028.62	979.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR FACILITATE REPAIR-REAR	New	1,600.00	500.00
2	TO RESPRAY AFFECTED AREAS-BOOTLID	New	300.00	-
3	TO RESPRAY AFFECTED AREAS-REAR BUMPER	New	300.00	200.00
4	TO RESPRAY AFFECTED AREAS-END PANEL	New	300.00	-
5	TO RESPRAY AFFECTED AREAS-SPARE TYRE PANEL	New	300.00	-
6	TO RESPRAY AFFECTED AREAS-RH REAR FENDER	New	300.00	200.00
7	TO REMOVE AND REFIT REAR EXHAUST PIPE	New	300.00	-
8	RUST PROOFING	New	80.00	30.00
9	TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR	New	200.00	60.00
10	TO REMOVE AND REFIT REVERSE SENSOR	New	100.00	30.00
11	TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	50.00	30.00
Gross Labour Cost (S\$)			3,830.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >