

Kh

2-8-18

King's Auto Spray Paint Pte Ltd
160 sin ming drive #05-10 sin ming Autocity
Singapore 575722

TAN SHUHUI GERALDING

4 days

\$2319.70

Not At hand
Manny B. G. pain

Re: Estimate cost for SLG 8464 m mitsudishi outlander

SUPPLY OF PARTS:

1pc rear bumper	R	\$ 916.00	✓
1pc rear bumper beam	R	480.00	X
2pc rear bumper brackets @ 71.00	R	142.00	X
1pc rear bumper center garnish	R	289.00	✓
8pc rear bumper clips @ 3.50	R	28.00	✓
2pc rear bumper side reflector @ 90.00	R	180.00	X
1pc rear center panel	R	369.00	X
2pc rear bumper side retainer @ 28.00	R	56.00	X
		<u>\$ 2460.00</u>	
		246.00	
		<u>\$ 2214.00</u>	

Less 10%

LABOUR:

1 set rear bumper Sensor

Shan \$ 300.00

To dismantle & rear panel top trim & side fender inner trim

\$ 60.00 ✓

Renew the above mentioned parts
Knocking, cutting, welding & straighten rear
damaged parts

spray paintings

\$ 700.00 55d
450d

60d \$ 700.00

\$ 3974.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: SH HUAT
Date: